

iSeries

iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

Version 5 Release 3



iSeries

iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

Version 5 Release 3

#### Note

Before using this information and the product it supports, be sure to read the information in "Safety and Environmental Notices" on page 3 and "Notices," on page 335.

#### Fifth Edition (August 2005)

This version does not run on all reduced instruction set computer (RISC) models nor does it run on CISC models. This edition replaces SY44-5915-01.

© Copyright International Business Machines Corporation 2000, 2004, 2005. All rights reserved. US Government Users Restricted Rights – Use, duplication or disclosure restricted by GSA ADP Schedule Contract with IBM Corp.

# Contents

Chapter 1. System reference codes	. 1
Safety and Environmental Notices	. 3
Danger Notices	. 3
Caution notices	. 4
Attention notices	. 4
Laser Safety Information	. 5
Product Recycling and Disposal	. 5
Battery Return Program	. 5
Environmental Design	. 5
Print this topic.	. 5
(0000) Control panel reference codes	. 6
(1xxx) System power control network (SPCN)	
reference codes	. 9
(1xxx) SPCN reference codes for Models 270 and 820	) 9
(1xxx) SPCN reference codes for Models 800, 810,	
and 825	. 57
(1xxx) SPCN reference codes for Models 830, 840,	
	. 72
(1xxx) SPCN reference codes for Models 870 and	
890.	126
(1750, 2105, 2107) Disk unit reference codes	146
(1766, 2166, 2167) Disk unit reference codes 1 (2629, 2718, 2726, 2728, 2729, 2740, 2741, 2809, 2810,	110
2824, 282C, 6532, 6533, 6534, 671A) Reference codes	147
	147
	151
	151
	152
	152
(2746) Twinaxial – workstation adapter reference	155
	154
codes	134
571B, 571E, 571F) Reference codes	154
	154
(2749, 2767, 2768, 2842, 2843, 2844, 284B, 284C, 284D,	
284D, 284E, 286C, 286D, 286E, 286F, 5702)	1(0
Reference codes	160
	169
(2761) Reference codes	170
(2765, 2766, 2787, 280D, 280E, 5704) Reference	
	170
	172
	173
(2838, 2849) Reference codes	173
(283C, 283D, 283F, 28B9, 28BC, 28CB, 28CC, 28CD,	
506D, 506E, 5306) Device backplane reference codes	
(287F) Reference codes	181
(3490) Tape unit reference codes	182

(3494) Tape library reference codes	187
(3570) Tape unit reference codes	188
(358x, 3592, 4685, 5755, 6279, 6381, 6382, 6383, 6384,	
6386, 6387, 63A0, 7207) Tape unit reference codes .	192
(3590) Tape unit reference codes	196
(432x, 660x, 671x, 673x) Disk unit reference codes	200
(5700, 5701) Reference codes	209
(5708, 574F, 575B) Reference codes	209
(632x, 6330, 6331, 6333, 6336, 6337) Optical storage	
unit reference codes	211
(6A59) Workstation adapter console reference codes	214
(7208) Tape drive reference codes	215
(9348) Tape unit reference codes	225
(9427) Tape unit reference codes	226
(A1xx, B1xx) Service processor reference codes	230
(A6xx, B6xx) Licensed Internal Code reference	
codes	234
(A9xx, B9xx) Reference codes	271
(B003) Asynchronous communications reference	
codes	272
(B006) Common Licensed Internal Code reference	
codes	279
(B070) Reference codes	282
(B075) Workstation adapter console reference codes	290
(B2xx) Logical partition reference codes	295
(B427) System processor reference codes	304
(B428, B448) System processor reference codes	310
(B437) System processor reference codes	316
	321
(B4FF) System processor reference codes	326
(C1xx) Service processor IPL status reference codes	330
(D1xx 3xxx) Service processor main storage dump	
status reference code	330

# Chapter 2. List of system reference codes.

		 •••	· · ·	, -		· · ·	 •	• • • •					
odes.	•	 •		•	•	•		•	•	•	•	331	

Appendix. Notices	335
Trademarks	. 336
Terms and conditions for downloading and	
printing publications	. 336
Electronic Emission Notices	. 337
Federal Communications Commission (FCC)	
Statement	. 337

iv iSeries: iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

# Chapter 1. System reference codes

This topic uses a system reference code (SRC) on the problem summary form to:

- Find a list of possible failing items.
- Point to additional isolation procedures (if available).


SRCs can appear on the control panel, the product activity log (PAL), the Main Storage Dump Manager display, or on various displays within DST or SST.

- 1. Were you directed here from another procedure, including the Starting point for all problems?
  - No: Go to the Starting point for all problems.
  - Yes: Determine which SRC table to use.

For SRCs appearing on the control panel, the first 4 characters represent the SRC type and the second 4 characters represent the unit reference code (URC). For SRCs appearing in the Product Activity Log or on other software displays, use characters 1 through 4 of word 1 for the SRC type and characters 5 through 8 of word 1 for the URC.

The SRC table name is the same as the SRC type. For SRCs appearing on the control panel, the SRC type is the first 4 characters (see Figure 1 on page 2 for control panel layout). For SRCs appearing in the Product Activity Log or on other software displays, use characters 1 through 4 of word 1 for the SRC type. The reference code tables only support 8-character SRC formats. If the SRC provided is in a 4 character format, contact your next level of support for assistance.

You will also need to know what the unit reference code (URC) is. For SRCs appearing on the control panel, the URC is the second 4 characters of the SRC (see Figure 1 on page 2 for control panel layout). For SRCs appearing in the Product Activity Log or on other software displays, use characters 5 through 8 of word 1 for the URC. The URCs are listed within the SRC tables, arranged in hexadecimal sequence with numeric characters listed before alphabetic characters. For example, URCs 0001 through 0009 are listed before URCs 000A through 000F.



#### Figure 1. System Unit Control Panel layout

For additional information about using the Control Panel, see SRC address formats.

Continue with the next step for instructions on finding and using the SRC tables.

2. You can find links to all of the SRC tables in the Chapter 2, "List of system reference codes," on page 331. After you find the correct SRC table, correct the problem by performing the action indicated for the URC in the Description/Action column of the table. If this does not correct the problem, exchange the failing items or parts listed in the Failing Item column in the order that they are listed.

If no action is indicated in the SRC table, exchange the failing items or parts listed in the table.

#### Notes:

- a. When exchanging the failing items, use the Remove and replace procedures.
- b. When instructed to perform problem isolation procedures, go to the Problem isolation procedures.
- **c.** Any additional information you need to complete the procedure, can be found in the Part locations and listings.

The failing item listed first should be exchanged first. If exchanging the first failing item does not correct the problem, reinstall the original item and exchange the next failing item listed. Continue to

exchange and reinstall the failing items, one at a time, until the problem is corrected. If exchanging the failing items does not correct the problem, ask your next level of support for assistance.

Now see the Chapter 2, "List of system reference codes," on page 331 and follow the instructions in the SRC table. The list contains all SRC tables for critical resources available at the time this edition was published. If you cannot find an SRC table, ask your next level of support for assistance.

### This ends the procedure.

Refer to Chapter 2, "List of system reference codes," on page 331 for more information.

# Safety and Environmental Notices

# **Danger Notices**

A danger notice calls attention to a situation that is potentially lethal or extremely hazardous to people.

Use the following danger notices throughout this book:

### DANGER

To prevent a possible electrical shock during an electrical storm, do not connect or disconnect cables or station protectors for communications lines, display stations, printers, or telephones. (RSFTD003)

### DANGER

To prevent a possible electrical shock from touching two surfaces with different electrical grounds, use one hand, when possible, to connect or disconnect signal cables. (RSFTD004)

### DANGER

To prevent a possible electrical shock, do not use the port tester during electrical storms. (RSFTD006)

### DANGER

An electrical outlet that is not correctly wired could place hazardous voltage on metal parts of the system or the products that attach to the system. It is the customer's responsibility to ensure that the outlet is correctly wired and grounded to prevent an electrical shock. (RSFTD201)

### DANGER

To prevent a possible electrical shock when installing the system, ensure that the power cords for all devices are unplugged before installing signal cables. (RSFTD202)

### DANGER

To prevent a possible electrical shock when adding or removing any devices to or from the system, ensure that the power cords for those devices are unplugged before the signal cables are connected or disconnected. If possible, disconnect all power cords from the existing system before you add or remove a device. (RSFTD203)

### DANGER

To prevent power from switching on automatically during service procedures, select manual or secure mode on the system unit control panel or disconnect the cables that connect to J15 and J16 on the frame being serviced. (RSFTD211)

#### DANGER

Use caution when installing or modifying telephone lines. Disconnect the lines at the network interface before working with telephone wires that are not insulated. Never install telephone jacks that are not waterproof in wet locations. Do not install or modify telephone lines or use a telephone (other than a cordless type) during an electrical storm. Do not use a telephone to report a gas leak in the area of the leak. (RSFTD213)

# **Caution notices**

A caution notice calls attention to a situation that is potentially hazardous to people because of some existing condition.

#### **CAUTION:**

Be careful when removing or installing this part or unit. This part or unit is heavy, but has a weight smaller than 18 kilograms (39.7 pounds). (RSFTC201)

#### **CAUTION:**

The weight of this part or unit is between 18 and 32 kilograms (39.7 and 70.5 pounds). It takes two persons to safely lift this part or unit. (RSFTC204)

### CAUTION:

The battery is a lead-acid battery. To avoid possible explosion, do not burn. Exchange only with the IBM-approved part. Recycle or discard the battery as instructed by local regulations.

In the United States, IBM has a process for the collection of this battery. For information, call 1-800-426-4333. Have the IBM part number for the battery unit available when you call. (RSFTC225)

#### **CAUTION:**

The battery is a lithium battery. To avoid possible explosion, do not burn or charge the battery. Exchange only with the IBM-approved part. Discard the battery as instructed by local regulations. (RSFTC227)

#### CAUTION:

The circuit card contains lead solder. To avoid the release of lead (Pb) into the environment, do not burn. Discard the circuit card as instructed by local regulations. (RSFTC234)

#### **CAUTION:**

This assembly has a circuit card that contains lead solder. To avoid the release of lead (Pb) into the environment, do not burn. Discard the assembly as instructed by local regulations. (RSFTC235)

#### **CAUTION:**

The optical link card contains a laser. To avoid the release of toxic substances into the environment, do not burn. Discard the optical link as instructed by local regulations. (RSFTC236)

## **Attention notices**

An attention notice indicates the possibility of damage to a program, device, system, or data.

# Laser Safety Information

CAUTION:

This product may contain a CD-ROM which is a class 1 laser product. (RSFTC240)

# **Product Recycling and Disposal**

Components of the system, such as structural parts and circuit cards, can be recycled where recycling facilities exist. IBM does not currently collect and recycle used IBM products from customers in the United States other than those products that are involved in trade-in programs. Companies are available to disassemble, reutilize, recycle, or dispose of electronic products. Contact an IBM account representative for more information.

The system unit contains batteries and circuit boards with lead solder. Before you dispose of this unit, these batteries and circuit boards must be removed and discarded according to local regulations or recycled where facilities exist. This book contains specific information on each battery type where applicable.

# **Battery Return Program**

In the United States, IBM has established a collection process for reuse, recycling, or proper disposal of used IBM batteries and battery packs. For information on proper disposal of the batteries in this unit, please contact IBM at 1-800-426-4333. Please have the IBM part number that is listed on the battery available when you make your call. For information on battery disposal outside the United States, contact your local waste disposal facility.

# **Environmental Design**

The environmental efforts that have gone into the design of the system signify IBM's commitment to improve the quality of its products and processes. Some of these accomplishments include the elimination of the use of Class I ozone-depleting chemicals in the manufacturing process, reductions in manufacturing wastes, and increased product energy efficiency. For more information, contact an IBM account representative.

# Print this topic

To view or download the PDF version, select System Reference Codes (about xxx KB or xxx pages).

### Other information

You can also view or print any of the following PDFs:

• Manuals:

Note to Writers: If you only have one PDF, use a sentence here instead of this nested list.

- PDF 1 (link to your PDF file) 🂖 (about xxx pages)
- PDF 2 (link to your PDF file) (about xxx pages)

### Saving PDF files

To save a PDF on your workstation for viewing or printing:

- 1. Right-click the PDF in your browser (right-click the link above).
- 2. Click Save Target As...
- 3. Navigate to the directory in which you would like to save the PDF.
- 4. Click Save.

### Downloading Adobe Acrobat Reader

If you need Adobe Acrobat Reader to view or print these PDFs, you can download a copy from

theAdobe Web site (www.adobe.com/products/acrobat/readstep.html)

# (0000) Control panel reference codes

The control panel detected a failure.

- 1. Look at the four rightmost characters of the Data display for word 1. These four characters are the unit reference code.
- 2. Find the unit reference code in the following tables, depending on the system model.

For details on the Failing Item column entries, see the Control Panel Failing Items Detail table, which follows the Reference Code tables below.

Choose from the appropriate model:

- Models 270, 800, 810, 820, 825
- Models 830, 840, 870, 890, SB2, and SB3

### Table 1. (0000) Control panel reference codes for system Models 270, 800, 810, 820, and 825

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1110 to 1113	Failure of CEC power supply not identified by SPCN.	TWRCARD ANYBUS
1114	Failure of CEC power supply not identified by SPCN.	TWRCARD CTLPNL
	This reference code can be caused by something holding the system Power On Reset (POR) line active.	ANYBUS
2222	Service processor failure caused machine check interrupt.	TWRCARD ANYBUS
	Before exchanging the TWRCARD, remove the adapter cards from the TWRCARD and perform an IPL. If the IPL completes successfully, one of the adapter cards you removed is defective.	
3333	SPCN to CSP interface error.	TWRCARD
	An attempt to communicate between the SPCN and the CSP processor failed.	
3334	CSP to VPD Collector interface error.	TWRCARD
	An attempt to communicate between the CSP and the VPD Collector failed.	
4444	Power on request failure	TWRCARD BACKPLN
	A power-on request was not completed successfully. A control panel-detected power-on failure occurred.	DACKI LIV
5553	Incorrect key used or the key is not completely inserted	CTLPNL TWRCARD
	The key inserted is not the correct key or is not completely inserted.	IWREARD
AABB	Remote power-on failure	USER TWRCARD
	An attempt was made to power on the system by a remote power-on operation with the keylock mode on the control panel set to Secure or Manual. To correct the problem, select Normal or Auto mode on the control	CTLPNL
	panel and perform the remote power-on operation again, if necessary.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
AACC	Service processor power-on failure An attempt was made to power on the system from the service processor with Secure or Manual mode selected on the control panel. To correct the problem, select Normal or Auto mode on the control panel and perform the service processor power-on operation again, if necessary. <b>Note:</b> This reference code may occur if the service processor card was exchanged and Manual mode was selected. Select Normal mode on the control panel.	USER CTLPNL TWRCARD
AADD	Manual power-on failure An attempt was made to power on the system manually with Secure or Auto mode selected on the control panel. To correct the problem, select Manual or Normal mode on the control panel and manually power on the system again.	USER CTLPNL
AAEE	SPCN - control panel interface error.An attempt was made to power on the system from the SPCN with Secure or Manual mode selected on the control panel. To correct the problem, select Normal or Auto mode and attempt the remote power-on operation again. If this does not correct the problem, exchange the failing items.	USER CTLPNL TWRCARD
BBBB	Battery not working correctlyA problem was detected with the battery supplying power to the time-of-day clock. The battery is either weak or is not connected securely.Note: This is not a critical failure. However, if there is a power failure, the time of day will be lost.	TOD TWRCARD

# Table 2. (0000) Control panel reference codes for system Models 830, 840, 870, 890, SB2, and SB3

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item		
1110 to 1113	Failure of CEC power supply not identified by SPCN.This reference code can be caused by something holding the system Power On Reset (POR) line active.	TWRCARD ANYBUS		
1114	Operators panel and service processor have been reset This reference code can be caused by something holding the system Power On Reset (POR) line active.	TWRCARD CTLPNL ANYBUS		
2222	Service processor failure caused machine check interrupt. Before exchanging the TWRCARD, remove the adapter cards from the TWRCARD and perform an IPL. If the IPL completes successfully, one of the adapter cards you removed is defective.	TWRCARD ANYBUS		
3333	333 SPCN to CSP interface error. An attempt to communicate between the SPCN and the CSP processor failed.			
3334	334       CSP to VPD Collector interface error.         An attempt to communicate between the CSP and the VPD Collector failed.			
4444	Power on request failure A power-on request was not completed successfully. A control panel-detected power-on failure occurred.	TWRCARD BACKPLN		

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5553	Incorrect key used or the key is not completely inserted The key inserted is not the correct key or is not completely inserted.	CTLPNL TWRCARD
AABB	Remote power-on failure An attempt was made to power on the system by a remote power-on operation with the keylock mode on the control panel set to Secure or Manual. To correct the problem, select Normal or Auto mode on the control panel and perform the remote power-on operation again, if necessary.	USER TWRCARD CTLPNL
AACC Service processor power-on failure An attempt was made to power on the system from the service processor with Secure or Manual mode selected on the control panel. To correct the problem, select Normal or Auto mode on the control panel and perform the service processor power-on operation again, if necessary. <b>Note:</b> This reference code may occur if the service processor card was exchanged and Manual mode was selected. Select Normal mode on the control panel.		USER CTLPNL TWRCARD
AADD	Manual power-on failure An attempt was made to power on the system manually with Secure or Auto mode selected on the control panel. To correct the problem, select Manual or Normal mode on the control panel and manually power on the system again.	USER CTLPNL
AAEE	SPCN - control panel interface error. An attempt was made to power on the system from the SPCN with Secure or Manual mode selected on the control panel. To correct the problem, select Normal or Auto mode and attempt the remote power-on operation again. If this does not correct the problem, exchange the failing items.	
BBBB	Battery not working correctly A problem was detected with the battery supplying power to the time-of-day clock. The battery is either weak or is not connected securely. <b>Note:</b> This is not a critical failure. However, if there is a power failure, the time of day will be lost.	TOD TWRCARD

### Control panel failing items detail

Use these tables for details on the Failing Item column in the Reference Codes table(s) above.

Failing Item	Description	Document Description
ANYBUS	IOP card bus error	Problem Analysis; Symbolic FRU Isolation
CLKCARD	Clock card	Problem Analysis; Symbolic FRU Isolation
CTLPNL	Control Panel	Problem Analysis; Symbolic FRU Isolation
TOD	Control Panel Battery	Problem Analysis; Symbolic FRU Isolation
TWRCARD	Card enclosure or backplane	Problem Analysis; Symbolic FRU Isolation
USER	Operator/User Error	Problem Analysis; Symbolic FRU Isolation

### Table 4. Control panel failing items for system Models 830, 840, 870, 890, SB2, and SB3

Failing Item	Description	Document Description
ANYBUS	IOP card bus error	Problem Analysis; Symbolic FRU Isolation
BACKPLN	Back Plane Unit	Problem Analysis; Symbolic FRU Isolation
CLKCARD	Clock card	Problem Analysis; Symbolic FRU Isolation
CTLPNL	Control Panel	Problem Analysis; Symbolic FRU Isolation
TOD	Control Panel Battery	Problem Analysis; Symbolic FRU Isolation
TWRCARD	Card enclosure or backplane	Problem Analysis; Symbolic FRU Isolation
USER	Operator/User Error	Problem Analysis; Symbolic FRU Isolation

# (1xxx) System power control network (SPCN) reference codes

The system power control network (SPCN) detected a failure.

Note: The second and third characters of the SRC indicate the frame number of the failing unit.

- 1. Look at the four rightmost characters of the SRC for Function 11 or Function 5. These characters are the unit reference code.
- 2. Find the unit reference code in the following tables, depending on the system model.

**Note:** xSeries<sup>®</sup> Server (formerly Netfinity<sup>®</sup>) frames will have only the frame number flashing on the failing unit's PCI (SPCN) card assembly which is visible after removing the cover.

Choose the model you are working on:

- Models 270 and 820
- Models 800, 810, and 825
- Models 830, 840, SB2, and SB3
- Models 870 and 890

# (1xxx) SPCN reference codes for Models 270 and 820

For details on the Failing Item column entries, see the SPCN Failing Items Detail table.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
00A0	SPCN BATs in process	TWRCARD
	No action required. This reference code is logged for information only. If this reference code is present for more than 1 minute, exchange the failing items.	
00A1	Regulator 1 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A2	Regulator 2 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A3	Regulator 3 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A4	Regulator 4 has been turned off by system	
	No action required. This reference code is logged for information only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
00A5	Regulator 5 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A6	Regulator 6 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A7	The system is running on the Battery Power Unit.	
	No action required. This reference code is logged for information only.	
00A8	The Battery Power Unit is not fully charged.	
	No action required. This reference code is logged for information only.	
00A9	Battery Power Unit test is in process.	
	No action required. This reference code is logged for information only.	
00AA	Download in process	
	No action required. This reference code is logged for information only.	
00AB	Rack UEPO switch is OFF.	TWRCARD
	Informational reference code.	CTLPNL 6462417
	The UEPO switch must be returned to the On position to power on the	0402417
	rack.	
00AC	Detected AC loss	ACMODUL
	If system powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	
00BA	The system is running on the Battery Power Unit.	
	No action required. This reference code is displayed for information only.	
00BC	Battery Power Unit test is in process.	
	No action required. This reference code is displayed for information only.	
00CA	CPM power down is complete.	
	No action required. This reference code is displayed for information only.	
00EF	Remote EPO switch is OFF	
0100	Install Disk Unit 1	
	Concurrent maintenance informational reference code.	
0101	Install Disk Unit 2	
	Concurrent maintenance informational reference code.	
0102	Install Disk Unit 3	
	Concurrent maintenance informational reference code.	
0103	Install Disk Unit 4	
	Concurrent maintenance informational reference code.	
0104	Install Disk Unit 5	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0105	Install Disk Unit 6	
	Concurrent maintenance informational reference code.	
0106	Install Disk Unit 7	
	Concurrent maintenance informational reference code.	
0107	Install Disk Unit 8	
	Concurrent maintenance informational reference code.	
0108	Install Disk Unit K1	
	Concurrent maintenance informational reference code.	
0109	Install Disk Unit K2	
	Concurrent maintenance informational reference code.	
010A	Install Disk Unit K3	
	Concurrent maintenance informational reference code.	
010B	Install Disk Unit K4	
	Concurrent maintenance informational reference code.	
010C	Install Disk Unit K5	
	Concurrent maintenance informational reference code.	
010D	Install Disk Unit K6	
	Concurrent maintenance informational reference code.	
010E	Install Disk Unit K7	
010F	Concurrent maintenance informational reference code.         Install Disk Unit K8	
0101		
0110	Concurrent maintenance informational reference code.	
0110	Install Disk Unit K9	
0111	Concurrent maintenance informational reference code.	
0111	Install Disk Unit K10	
	Concurrent maintenance informational reference code.	
0112	Install Disk Unit K11	
	Concurrent maintenance informational reference code.	
0113	Install Disk Unit K12	
	Concurrent maintenance informational reference code.	
0114	Install Disk Unit K13	
	Concurrent maintenance informational reference code.	
0115	Install Disk Unit K14	
	Concurrent maintenance informational reference code.	
0116	Install device 1	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0117	Install device 2	
	Concurrent maintenance informational reference code.	
0118	Install Disk Unit 9	
	Concurrent maintenance informational reference code.	
0119	Install Disk Unit 10	
	Concurrent maintenance informational reference code.	
011A	Install Disk Unit 11	
	Concurrent maintenance informational reference code.	
011B	Install Disk Unit 12	
0112		
011C	Concurrent maintenance informational reference code. Install device 3	
one		
0112	Concurrent maintenance informational reference code.	
011D	Install Disk Unit K15	
	Concurrent maintenance informational reference code.	
011E	Install Disk Unit K16	
	Concurrent maintenance informational reference code.	
011F	Install Device 4	
	Concurrent maintenance informational reference code.	
0120	Install Disk Unit K17	
	Concurrent maintenance informational reference code.	
0121	Install Disk Unit K18	
	Concurrent maintenance informational reference code.	
0122	Install Disk Unit K19	
	Concurrent maintenance informational reference code.	
0123	Install Disk Unit K20	
0120		
0124	Concurrent maintenance informational reference code. Install Disk Unit K21	
0124		
0105	Concurrent maintenance informational reference code.	
0125	Install Disk Unit K22	
	Concurrent maintenance informational reference code.	
0126	Install Disk Unit K23	
	Concurrent maintenance informational reference code.	
0127	Install Disk Unit K24	
	Concurrent maintenance informational reference code.	
0128	Install Disk Unit K25	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0129	Install Disk Unit K26	
	Concurrent maintenance informational reference code.	
012A	Install Disk Unit K27	
	Concurrent maintenance informational reference code.	
012B	Install Disk Unit K28	
	Concurrent maintenance informational reference code.	
012C	Install Disk Unit K29	
	Concurrent maintenance informational reference code.	
012D	Install Disk Unit K30	
	Concurrent maintenance informational reference code.	
012E	Install Disk Unit K31	
	Concurrent maintenance informational reference code.	
012F	Install Disk Unit K32	
	Concurrent maintenance informational reference code.	
0200	Remove Disk Unit 1	
	Concurrent maintenance informational reference code.	
0201	Remove Disk Unit 2	
	Concurrent maintenance informational reference code.	
0202	Remove Disk Unit 3	
0_0_	Concurrent maintenance informational reference code.	
0203	Remove Disk Unit 4	
0205		
0204	Concurrent maintenance informational reference code. Remove Disk Unit 5	
0204		
0205	Concurrent maintenance informational reference code.	
0205	Remove Disk Unit 6	
2207	Concurrent maintenance informational reference code.	
0206	Remove Disk Unit 7	
	Concurrent maintenance informational reference code.	
0207	Remove Disk Unit 8	
	Concurrent maintenance informational reference code.	
0208	Remove Disk Unit K1	
	Concurrent maintenance informational reference code.	
0209	Remove Disk Unit K2	
	Concurrent maintenance informational reference code.	
020A	Remove Disk Unit K3	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
020B	Remove Disk Unit K4	
	Concurrent maintenance informational reference code.	
020C	Remove Disk Unit K5	
	Concurrent maintenance informational reference code.	
020D	Remove Disk Unit K6	
	Concurrent maintenance informational reference code.	
020E	Remove Disk Unit K7	
	Concurrent maintenance informational reference code.	
020F	Remove Disk Unit K8	
	Concurrent maintenance informational reference code.	
0210	Remove Disk Unit K9	
0210		
0011	Concurrent maintenance informational reference code.	
0211	Remove Disk Unit K10	
	Concurrent maintenance informational reference code.	
0212	Remove Disk Unit K11	
	Concurrent maintenance informational reference code.	
0213	Remove Disk unit K12	
	Concurrent maintenance informational reference code.	
0214	Remove Disk Unit K13	
	Concurrent maintenance informational reference code.	
0215	Remove Disk Unit K14	
	Concurrent maintenance informational reference code.	
0216	Remove device 1	
	Concurrent maintenance informational reference code.	
0217	Remove device 2	
	Concurrent maintenance informational reference code.	
0218	Remove Disk Unit 9	
0210		
0219	Concurrent maintenance informational reference code. Remove Disk Unit 10	
0219		
	Concurrent maintenance informational reference code.	
021A	Remove Disk Unit 11	
	Concurrent maintenance informational reference code.	
021B	Remove Disk Unit 12	
	Concurrent maintenance informational reference code.	
021C	Remove device 3	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
021D	Remove Disk Unit K15	
	Concurrent maintenance informational reference code.	
021E	Remove Disk Unit K16	
	Concurrent maintenance informational reference code.	
021F	Remove device 4	
	Concurrent maintenance informational reference code.	
0220	Remove Disk Unit K17	
	Concurrent maintenance informational reference code.	
0221	Remove Disk Unit K18	
	Concurrent maintenance informational reference code.	
0222	Remove Disk Unit K19	
	Concurrent maintenance informational reference code.	
0223	Remove Disk Unit K20	
	Concurrent maintenance informational reference code.	
0224	Remove Disk Unit K21	
	Concurrent maintenance informational reference code.	
0225	Remove Disk Unit K22	
	Concurrent maintenance informational reference code.	
0226	Remove Disk Unit K23	
	Concurrent maintenance informational reference code.	
0227	Remove Disk Unit K24	
0227		
0228	Concurrent maintenance informational reference code. Remove Disk Unit K25	
0220		
0220	Concurrent maintenance informational reference code.	
0229	Remove Disk Unit K26	
000 4	Concurrent maintenance informational reference code.	
022A	Remove Disk Unit K27	
	Concurrent maintenance informational reference code.	
022B	Remove Disk Unit K28	
	Concurrent maintenance informational reference code.	
022C	Remove Disk Unit K29	
	Concurrent maintenance informational reference code.	
022D	Remove Disk Unit K30	
	Concurrent maintenance informational reference code.	
022E	Remove Disk Unit K31	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
022F	Remove Disk Unit K32	
	Concurrent maintenance informational reference code.	
0300	Disk Unit 1 regulator has been turned on	
	Installation of disk unit 1 is complete, and the regulator is turned on.	
0301	Disk Unit 2 regulator has been turned on	
	Installation of disk unit 2 is complete, and the regulator is turned on.	
0302	Disk Unit 3 regulator has been turned on	
	Installation of disk unit 3 is complete, and the regulator is turned on.	
0303	Disk Unit 4 regulator has been turned on	
	Installation of disk unit 4 is complete, and the regulator is turned on.	
0304	Disk Unit 5 regulator has been turned on	
	Installation of disk unit 5 is complete, and the regulator is turned on.	
0305	Disk Unit 6 regulator has been turned on	
	Installation of disk unit 6 is complete, and the regulator is turned on.	
0306	Disk Unit 7 regulator has been turned on	
	Installation of disk unit 7 is complete, and the regulator is turned on.	
0307	Disk Unit 8 regulator has been turned on	
	Installation of disk unit 8 is complete, and the regulator is turned on.	
0308	Disk Unit K1 regulator has been turned on	
	Installation of disk unit K1 is complete, and the regulator is turned on.	
0309	Disk Unit K2 regulator has been turned on	
030A	Installation of disk unit K2 is complete, and the regulator is turned on.Disk Unit K3 regulator has been turned on	
00011		
030B	Installation of disk unit K3 is complete, and the regulator is turned on.Disk Unit K4 regulator has been turned on	
0000		
0200	Installation of disk unit K4 is complete, and the regulator is turned on.	
030C	Disk Unit K5 regulator has been turned on	
0200	Installation of disk unit K5 is complete, and the regulator is turned on.	
030D	Disk Unit K6 regulator has been turned on	
0205	Installation of disk unit K6 is complete, and the regulator is turned on.	
030E	Disk Unit K7 regulator has been turned on	
	Installation of disk unit K7 is complete, and the regulator is turned on.	
030F	Disk Unit K8 regulator has been turned on	
	Installation of disk unit K8 is complete, and the regulator is turned on.	
0310	Disk Unit K9 regulator has been turned on	
	Installation of disk unit K9 is complete, and the regulator is turned on.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0311	Disk Unit K10 regulator has been turned on	
	Installation of disk unit K10 is complete, and the regulator is turned on.	
0312	Disk Unit K11 regulator has been turned on	
	Installation of disk unit K11 is complete, and the regulator is turned on.	
0313	Disk Unit K12 regulator has been turned on	
	Installation of disk unit K12 is complete, and the regulator is turned on.	
0314	Disk Unit K13 regulator has been turned on	
	Installation of disk unit K13 is complete, and the regulator is turned on.	
0315	Disk Unit K14 regulator has been turned on	
	Installation of disk unit K14 is complete, and the regulator is turned on.	
0316	Device 1 regulator has been turned on	
	Installation of device 1 is complete, and the regulator is turned on.	
0317	Device 2 regulator has been turned on	
	Installation of device 2 is complete, and the regulator is turned on.	
0318	Disk Unit 9 regulator has been turned on	
	Installation of disk unit 9 is complete, and the regulator is turned on.	
0319	Disk Unit 10 regulator has been turned on	
	Installation of disk unit 10 is complete, and the regulator is turned on.	
031A	Disk Unit 11 regulator has been turned on	
031B	Installation of disk unit 11 is complete, and the regulator is turned on.Disk Unit 12 regulator has been turned on	
0010		
031C	Installation of disk unit 12 is complete, and the regulator is turned on.Device 3 regulator has been turned on	
0510		
021D	Installation of device 3 is complete, and the regulator is turned on.	
031D	Disk Unit K15 regulator has been turned on	
0017	Installation of disk unit K15 is complete, and the regulator is turned on.	
031E	Disk Unit K16 regulator has been turned on	
	Installation of disk unit K16 is complete, and the regulator is turned on.	
031F	Device 4 regulator has been turned on	
	Installation of device 4 is complete, and the regulator is turned on.	
0320	Disk Unit K17 regulator has been turned on	
	Installation of disk unit K17 is complete, and the regulator is turned on.	
0321	Disk Unit K18 regulator has been turned on	
	Installation of disk unit K18 is complete, and the regulator is turned on.	
0322	Disk Unit K19 regulator has been turned on	
	Installation of disk unit K19 is complete, and the regulator is turned on.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0323	Disk Unit K20 regulator has been turned on	
	Installation of disk unit K20 is complete, and the regulator is turned on.	
0324	Disk Unit K21 regulator has been turned on	
	Installation of disk unit K21 is complete, and the regulator is turned on.	
0325	Disk Unit K22 regulator has been turned on	
	Installation of disk unit K22 is complete, and the regulator is turned on.	
0326	Disk Unit K23 regulator has been turned on	
	Installation of disk unit K23 is complete, and the regulator is turned on.	
0327	Disk Unit K24 regulator has been turned on	
002		
0228	Installation of disk unit K24 is complete, and the regulator is turned on.	
0328	Disk Unit K25 regulator has been turned on	
	Installation of disk unit K25 is complete, and the regulator is turned on.	
0329	Disk Unit K26 regulator has been turned on	
	Installation of disk unit K26 is complete, and the regulator is turned on.	
032A	Disk Unit K27 regulator has been turned on	
	Installation of disk unit K27 is complete, and the regulator is turned on.	
032B	Disk Unit K28 regulator has been turned on	
	Installation of disk unit K28 is complete, and the regulator is turned on.	
032C	Disk Unit K29 regulator has been turned on	
032D	Installation of disk unit K29 is complete, and the regulator is turned on.	
032D	Disk Unit K30 regulator has been turned on	
	Installation of disk unit K30 is complete, and the regulator is turned on.	
032E	Disk Unit K31 regulator has been turned on	
	Installation of disk unit K31 is complete, and the regulator is turned on.	
032F	Disk Unit K32 regulator has been turned on	
	Installation of disk unit K32 is complete, and the regulator is turned on.	
0400	Removal of Disk Unit 1 is complete	
0401	Removal of Disk Unit 2 is complete	
0402	Removal of Disk Unit 3 is complete	
0403	Removal of Disk Unit 4 is complete	
0404	Removal of Disk Unit 5 is complete	
0405	Removal of Disk Unit 6 is complete	
0406	Removal of Disk Unit 7 is complete	
0407	Removal of Disk Unit 8 is complete	
0408	Removal of Disk Unit K1 is complete	
0409	Removal of Disk Unit K2 is complete	
040A	Removal of Disk Unit K3 is complete	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
040B	Removal of Disk Unit K4 is complete	
040C	Removal of Disk Unit K5 is complete	
040D	Removal of Disk Unit K6 is complete	
040E	Removal of Disk Unit K7 is complete	
040F	Removal of Disk Unit K8 is complete	
0410	Removal of Disk Unit K9 is complete	
0411	Removal of Disk Unit K10 is complete	
0412	Removal of Disk Unit K11 is complete	
0413	Removal of Disk Unit K12 is complete	
0414	Removal of Disk Unit K13 is complete	
0415	Removal of Disk Unit K14 is complete	
0416	Removal of device 1 is complete	
0417	Removal of device 2 is complete	
0418	Removal of Disk Unit 9 is complete	
0419	Removal of Disk Unit 10 is complete	
041A	Removal of Disk Unit 11 is complete	
041B	Removal of Disk Unit 12 is complete	
041C	Removal of device 3 is complete	
041D	Removal of Disk Unit K15 is complete	
041E	Removal of Disk Unit K16 is complete	
041F	Removal of device 4 is complete	
0500	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit 1, and the bus was released.	
	You must reinitialize the operation to continue.	
0501	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit 2, and the bus was released.	
	You must reinitialize the operation to continue.	
0502	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit 3, and the bus was released.	
	You must reinitialize the operation to continue.	
0503	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 4, and the bus was released.	
	You must reinitialize the operation to continue.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0504	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 5, and the bus was released.	
	You must reinitialize the operation to continue.	
0505	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 6, and the bus was released.	
	You must reinitialize the operation to continue.	
0506	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 7, and the bus was released.	
	You must reinitialize the operation to continue.	
0507	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 8, and the bus was released.	
	You must reinitialize the operation to continue.	
0508	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K1, and the bus was released.	
	You must reinitialize the operation to continue.	
0509	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K2, and the bus was released.	
	You must reinitialize the operation to continue.	
050A	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K3, and the bus was released.	
	You must reinitialize the operation to continue.	
050B	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K4, and the bus was released.	
	You must reinitialize the operation to continue.	
050C	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K5, and the bus was released.	
	You must reinitialize the operation to continue.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
050D	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K6, and the bus was released.	
	You must reinitialize the operation to continue.	
050E	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K7, and the bus was released.	
	You must reinitialize the operation to continue.	
050F	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K8, and the bus was released.	
	You must reinitialize the operation to continue.	
0510	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K9, and the bus was released.	
	You must reinitialize the operation to continue.	
0511	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K10, and the bus was released.	
	You must reinitialize the operation to continue.	
0512	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K11, and the bus was released.	
	You must reinitialize the operation to continue.	
0513	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K12, and the bus was released.	
	You must reinitialize the operation to continue.	
0514	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K13, and the bus was released.	
	You must reinitialize the operation to continue.	
0515	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K14, and the bus was released.	
	You must reinitialize the operation to continue.	

	bus was released.
	You must reinitialize the operation to continu
0517	Timeout, no action detected. Reinitialize the o
	No action was detected for the installation or bus was released.
	You must reinitialize the operation to continue
0518	Timeout, no action detected. Reinitialize the o
	No action was detected for the installation or the bus was released.
	You must reinitialize the operation to continue
0510	Timeout no action detected Poinitialize the o

You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation	
No action was detected for the installation or removal of device 2, and the bus was released.	
You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation.	
No action was detected for the installation or removal of disk unit 9, and the bus was released.	
You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation.	
No action was detected for the installation or removal of disk unit 10, and the bus was released.	
You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation.	
No action was detected for the installation or removal of disk unit 11, and the bus was released.	
You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation.	
No action was detected for the installation or removal of disk unit 12, and the bus was released.	
You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation	
No action was detected for the installation or removal of device 3, and the bus was released.	
You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation	
No action was detected for the installation or removal of disk unit K15, and the bus was released.	
You must reinitialize the operation to continue.	
Timeout, no action detected. Reinitialize the operation	
No action was detected for the installation or removal of disk unit K16, and the bus was released.	
You must reinitialize the operation to continue.	
	Timeout, no action detected. Reinitialize the operation         No action was detected for the installation or removal of device 2, and the bus was released.         You must reinitialize the operation to continue.         Timeout, no action detected. Reinitialize the operation.         No action was detected for the installation or removal of disk unit 9, and the bus was released.         You must reinitialize the operation to continue.         Timeout, no action detected. Reinitialize the operation.         No action was detected for the installation or removal of disk unit 10, and the bus was released.         You must reinitialize the operation to continue.         Timeout, no action detected. Reinitialize the operation.         No action was detected for the installation or removal of disk unit 10, and the bus was released.         You must reinitialize the operation to continue.         Timeout, no action detected. Reinitialize the operation.         No action was detected for the installation or removal of disk unit 11, and the bus was released.         You must reinitialize the operation to continue.         Timeout, no action detected. Reinitialize the operation.         No action was detected for the installation or removal of disk unit 12, and the bus was released.         You must reinitialize the operation to continue.         Timeout, no action detected. Reinitialize the operation         No action was detected for the installation or removal of device 3, and the bus was released. </td

Description/Action Perform all actions before exchanging Failing Items

No action was detected for the installation or removal of device 1, and the

Timeout, no action detected. Reinitialize the operation

Failing Item

0516

**Reference Code** 

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
051F	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of device 4, and the bus was released.	
	You must reinitialize the operation to continue.	
0700	Timeout, no action detected. Reinitialize the operation	
	Disk unit 1 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0701	Timeout, no action detected. Reinitialize the operation	
	Disk unit 2 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0702	Timeout, no action detected. Reinitialize the operation	
	Disk unit 3 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
	You must reinitialize the operation to continue.	
0703	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 4 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0704	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 5 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0705	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 6 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0706	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 7 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0707	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 8 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0708	Timeout, no action detected. Reinitialize the operation	
	Disk unit K1 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0709	Timeout, no action detected. Reinitialize the operation	
	Disk unit K2 was powered off but not removed.	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
070A	Timeout, no action detected. Reinitialize the operation	
	Disk unit K3 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070B	Timeout, no action detected. Reinitialize the operation	
	Disk unit K4 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070C	Timeout, no action detected. Reinitialize the operation	
	Disk unit K5 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070D	Timeout, no action detected. Reinitialize the operation	
	Disk unit K6 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070E	Timeout, no action detected. Reinitialize the operation	
	Disk unit K7 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070F	Timeout, no action detected. Reinitialize the operation	
	Disk unit K8 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0710	Timeout, no action detected. Reinitialize the operation	
	Disk unit K9 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0711	Timeout, no action detected. Reinitialize the operation	
	Disk unit K10 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0712	Timeout, no action detected. Reinitialize the operation	
	Disk unit K11 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0713	Timeout, no action detected. Reinitialize the operation	
	Disk unit K12 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0714	Timeout, no action detected. Reinitialize the operation	
	Disk unit K13 was powered off but not removed.	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0715	Timeout, no action detected. Reinitialize the operation	
	Disk unit K14 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0716	Timeout, no action detected. Reinitialize the operation	
	Device 1 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0717	Timeout, no action detected. Reinitialize the operation	
	Device 2 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0718	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 9 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0719	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 10 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071A	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 11 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071B	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 12 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071C	Timeout, no action detected. Reinitialize the operation	
	Device 3 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071D	Timeout, no action detected. Reinitialize the operation	
	Disk unit K15 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071E	Timeout, no action detected. Reinitialize the operation	
	Disk unit K16 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071F	Timeout, no action detected. Reinitialize the operation	
	Device 4 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0800	Blower B01 powered off for concurrent maintenance	
0801	Blower B02 powered off for concurrent maintenance	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0802	Blower B03 powered off for concurrent maintenance	
0803	Blower B04 powered off for concurrent maintenance	
0900	Power Supply P01 powered off for concurrent maintenance	
0901	Power Supply P02 powered off for concurrent maintenance	
0902	Power Supply P03 powered off for concurrent maintenance	
0903	Power Supply P04 powered off for concurrent maintenance	
0904	Power Supply P05 powered off for concurrent maintenance	
0905	Power Supply P06 powered off for concurrent maintenance	
0F0F	AC Module Failure	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F12	Undefined box ID, EEPROM test failed	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F13	Undefined box ID, Code type mismatch	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F1F	Undefined box ID, LCD test failed	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F2C	Unknown box ID	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F2D	Unknown box ID, Code level mismatch.	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F2E	SPCN Network Fault	TWRCARD
	The box ID is not defined. A network communications failure occurred.	BACKPLN 21F9429
102B	PCC Overcurrent	TWRCARD
	The power control compartment is causing an over current condition in the FC 5032 Removable Storage Unit power system.	21F5680 21F5793 21F9362
	The ac module and the SPCN port cable should be exchanged together.	
1510	Detected AC loss	PWRSPLY
	Before replacing any parts, verify that the AC input voltage is correct.	TWRCARD
1511	Power supply failure	PWRSPLY
		TWRCARD
1512	Power supply failure	PWRSPLY TWRCARD CBLALL
1513 to 1514	Power supply failure	PWRSPLY TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1516	No Power Supplies Present	PWRSPLY TWRCARD
	The required power supplies are not installed.	
1520	Detected AC loss Before replacing any parts, verify that the AC input voltage is correct.	PWRSPLY TWRCARD
1521	Power supply failure	PWRSPLY TWRCARD
1522	Power supply failure	PWRSPLY TWRCARD CBLALL
1523 to 1524	Power supply failure	PWRSPLY TWRCARD
1526	No Power Supplies Present	PWRSPLY TWRCARD
	The required power supplies are not installed.	
1530	Power Supply P03 fault/AC loss	PWRSPLY TWRCARD
4 = 0.4	Before replacing any parts, verify that the AC input voltage is correct.	
1531	Power Supply P03 fault	PWRSPLY TWRCARD
1532	Power Supply P03 Communication fault	PWRSPLY TWRCARD CBLALL
1533	Power Supply P03 fault	PWRSPLY TWRCARD
1534	Power Supply P03 Fault	PWRSPLY TWRCARD
1611	Regulator Fault on Card Position M01	PWRREG TWRCARD
1612	Regulator Communication Fault on Card Position M01	PWRREG TWRCARD
1613, 1621	Regulator Fault on Card Position M01	PWRREG TWRCARD
1622	Regulator Communication Fault on Card Position M01	PWRREG TWRCARD
1623	Regulator Fault on Card Position M01	PWRREG TWRCARD
1810	Load fault on the +12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1820	Load fault on the +5V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1830	Load fault on the +3.3V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1840		PWROC
1840	Load fault on the -12V bus An isolation procedure is required for identifying which load is at fault.	TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1B01	Load fault on the +12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1B02	Load fault on the +5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B03	Load fault on the +3.3V bus	PWROC
		TWRCARD
1004	An isolation procedure is required for identifying which load is at fault.	DIMPOC
1B04	Load fault on the -12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B05	Load fault on the +1.8V bus	PWROC
		TWRCARD
1000 1 1007	An isolation procedure is required for identifying which load is at fault.	DWDOC
1B06 to 1B07	Load fault on the +2.5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B11	Load fault on the +12V bus	PWROC
	An isolation procedure is required for identifying which load is at fault.	TWRCARD
1212		DWDOC
1B12	Load fault on the +5V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1B13	Load fault on the +3.3V bus	PWROC TWRCARD
1B14	Load fault on the -12V bus	PWROC TWRCARD
1B16 to 1B17	Load fault on the +2.5V bus	PWROC TWRCARD
2131	Power Supply P01 Fault	PWRSPLY
	A fault has been detected for Power Supply P01.	SPNLCRD
2132	Power Supply P02 Fault	PWRSPLY
	A fault has been detected for Power Supply P02.	SPNLCRD
2133	Power Supply P03 Fault	PWRSPLY
	A fault has been detected for Power Supply P03.	SPNLCRD
2134	Power Supply P04 Fault	PWRSPLY
		SPNLCRD
01.41	A fault has been detected for Power Supply P04.	
2141	Power Supply P01 Fault	PWRSPLY SPNLCRD
	A fault has been detected for Power Supply P01.	
2142	Power Supply P02 Fault	PWRSPLY
	A fault has been detected for Power Supply P02.	SPNLCRD
2143	Power Supply P03 Fault	PWRSPLY
		SPNLCRD
	A fault has been detected for Power Supply P03.	
2144	Power Supply P04 Fault A fault has been detected for Power Supply P04.	PWRSPLY SPNLCRD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
2151	Power Supply P01 Fault	PWRSPLY SPNLCRD
	A fault has been detected for Power Supply P01.	
2152	Power Supply P02 Fault A fault has been detected for Power Supply P02.	PWRSPLY SPNLCRD
2153	Power Supply P03 Fault	PWRSPLY SPNLCRD
	A fault has been detected for Power Supply P03.	
2154	Power Supply P04 Fault A fault has been detected for Power Supply P04.	PWRSPLY SPNLCRD
2201	Power Supply P01 or P02 Overcurrent Fault	PWROC
2201	A POW-PIP is required for identifying which load is at fault.	SPNLCRD CBLALL
2202	Power Supply P03 or P04 Overcurrent Fault	PWROC SPNLCRD
	A POW-PIP is required for identifying which load is at fault.	CBLALL
2210	One of the CPM regulators has reported a fault	PWRSPLY SPNLCRD
2211	CPM Regulator 1 Fault	PWRSPLY SPNLCRD
2212	CPM Regulator 2 Fault	PWRSPLY SPNLCRD
2213	CPM Regulator 3 Fault	PWRSPLY SPNLCRD
2221	Power Good Fault	SPNLCRD PGDPART
	A MFIOP power good fault occurred.	CBLALL
2222	Power Good Type M Fault A Memory power good fault occurred.	SPNLCRD PGDPART CBLALL
2223	Power Good Type P Fault	SPNLCRD
	A Processor power good fault occurred.	PGDPART CBLALL
2224	Power Good Type I Fault	SPNLCRD PGDPART
	A Internal expansion power good fault occurred.	CBLALL
2231	System Unit Interlock Failure	INTRLCK SPNLCRD CBLALL
2232	Secondary Frame Interlock Failure	INTRLCK SPNLCRD CBLALL
2240	Air Moving Device Panel Fault	AIRMOVR PWRSPLY
2241	Air Moving Device 1 Fault A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	AIRMOVR SPNLCRD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
2242	Air Moving Device 2 Fault	AIRMOVR SPNLCRD
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	
2244	Air Moving Device 4 Fault	AIRMOVR SPNLCRD
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	SFILCKD
2245	Air Moving Device 5 Fault	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	SPNLCRD
2246	Air Moving Device 6 Fault	AIRMOVR SPNLCRD
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	SFILLERD
2260	Timeout on Panel for Request of VPD	CTLPNL
2301	Power Supply P01 or P02 Overcurrent error	PWROC SPNLCRD
	A POW-PIP is required for identifying which load is at fault.	CBLALL
2302	Power Supply P03 or P04 Overcurrent error	PWROC SPNLCRD
	A POW-PIP is required for identifying which load is at fault.	CBLALL
2311	Power Supply P01 error	PWRSPLY SPNLCRD
	A fault detection failure occurred for Power Supply P01.	CBLALL
2312	Power Supply P02 error	PWRSPLY SPNLCRD
	A fault detection failure occurred for Power Supply P02.	CBLALL
2313	Power Supply P03 error	PWRSPLY SPNLCRD
	A fault detection failure occurred for Power Supply P03.	CBLALL
2314	Power Supply P04 error	PWRSPLY
	A fault detection failure occurred for Power Supply P04.	SPNLCRD CBLALL
2321	Power Good Fault	SPNLCRD
	A MFIOP power good error was detected.	CBLALL PGDPART
2322	Power Good Type M error	SPNLCRD CBLALL
	A Memory power good error was detected.	PGDPART
2323	Power Good Type P error	SPNLCRD CBLALL

A Processor power good error was detected.

A Internal expansion power good error was detected.

Power Good Type I error

Power Supply P01 not installed

CBLALL

PGDPART

SPNLCRD

PGDPART

PWRSPLY SPNLCRD

CBLALL

2324

2330

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
2331	Power Supply P01 ID is Invalid	PWRSPLY SPNLCRD
2332	Power Supply P02 ID is Invalid	PWRSPLY SPNLCRD
2333	Power Supply P03 ID is Invalid	PWRSPLY SPNLCRD
2334	Power Supply P04 ID is Invalid	PWRSPLY SPNLCRD
2400 to 2402	UPS Enable/Disable Failure	UPSUNIT SPNLCRD
2403	UPS CPM Failure	UPSUNIT SPNLCRD
2404	UPS Battery Failure	BATRY UPSUNIT
2405	UPS Unit Failure	UPSUNIT SPNLCRD
2406 to 2407	UPS Enable/Disable Failure	UPSUNIT SPNLCRD
2410 to 2411	UPS Test Failure	UPSUNIT SPNLCRD
2413	UPS Interface Failure	UPSUNIT SPNLCRD
2600	Power Good Fault	PGDPART TWRCARD PWRSPLY
2601 to 2606	Power Good Fault	PGDPART TWRCARD
2610	Processor/Memory Card not installed	PWRSPLY TWRCARD
2611	Processor Regulator fault	PWRREG TWRCARD
2612	Optical Converter 5V Fault	CBLALL TWRCARD
2/12	The SPCN detected a fault on the SPCN card optical converter 5V.	CDI ALL
2613	Configuration Requires 200V Input Configuration now requires 200V AC power.	CBLALL
300E	EPO Circuit Fault	TWRCARD
	The ac module installed in the 9406 Expansion Unit (FC 504x) detected a fault in the UEPO signal. The signal was active and the incoming ac voltage was still present.	21F9362 21F5680
302B	PCC Overcurrent	TWRCARD
	The power control compartment is causing an over current condition in the 9406 Expansion Unit power system.	21F5680 21F9631 21F9362
	Exchange the ac module and the SPCN port cable at the same time.	
3100	I2C Bus Controller Communication fault	I2CBUS TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3101	I2C Bus 1 Communication fault	I2CBUS TWRCARD
3102	I2C Bus 2 Communication fault	I2CBUS TWRCARD
3103	I2C Bus 3 Communication fault	I2CBUS TWRCARD
3104	I2C Bus 4 Communication fault	I2CBUS TWRCARD
3105	I2C Bus 5 Communication fault	I2CBUS TWRCARD
3106	I2C Bus 6 Communication fault	I2CBUS TWRCARD
3110	I2C Bus DASD Backplane 1 Communication fault	I2CBUS TWRCARD
3111	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD
3112	I2C Bus DASD Backplane 3 Communication fault	I2CBUS TWRCARD
3113	I2C Bus Adapter Communication fault	I2CBUS TWRCARD
3114	I2C Bus PCI Backplane Communication fault	I2CBUS TWRCARD
3115	I2C Bus Panel Communication fault	I2CBUS TWRCARD
3116	I2C Bus Fan Local Controller Communication fault	I2CBUS TWRCARD
3117	I2C Bus Fan Remote Controller Communication fault	I2CBUS TWRCARD
3118	I2C Bus SPCN VPD Communication fault	I2CBUS TWRCARD
311C	I2C Bus Panel Communication fault	I2CBUS TWRCARD
311D	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD
311E	I2C Bus DASD Backplane 3 Communication fault	I2CBUS TWRCARD
4410	Internal Battery Power Unit Fault	BATRY
	Internal Battery Power Unit in the system has failed.	BATCHGR TWRCARD CBLALL
4411	Internal Battery Power Unit Charger Fault	BATCHGR
	Internal Battery Power Unit Charger in the system has failed.	TWRCARD CBLALL
4412	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR BATRY TWRCARD CBLALL

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4413	Internal Battery Power Unit Charger Fault	BATCHGR TWRCARD
4414	Internal Battery Power Unit Charger in the system has failed.       Battery Charger Load fault	CBLALL PWROC BATRY TWRCARD CBLALL
4415	Battery Power Unit missing	BATRY TWRCARD CBLALL
4416	Internal Battery Power Unit Charger Fault	BATCHGR TWRCARD CBLALL
4417	Battery Charger Unit missing	BATCHGR TWRCARD CBLALL
4500 to 4502	UPS Enable/Disable Failure	UPSUNIT TWRCARD
4503	UPS CPM Failure	UPSUNIT TWRCARD
4504	UPS Battery Failure	BATRY UPSUNIT
4505	UPS Unit Failure	UPSUNIT TWRCARD
4507	UPS Enable/Disable Failure	UPSUNIT TWRCARD
4510	UPS Test Failure	UPSUNIT TWRCARD
4513	UPS Interface Failure	UPSUNIT TWRCARD
6018	One of the regulators has reported a fault	PWRREG BKSPCN
601A	A regulator fault was detected.         One of the CPM regulators has reported a fault         A CPM regulator fault was detected.	PWRREG BKSPCN FI00030
6118	Regulator over current fault One of the regulators detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	PWRREG BKSPCN
6218	Regulator over current fault Regulator 1 detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	PWRREG BKSPCN
6238	Regulator over current fault Regulator 2 detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	PWRREG BKSPCN
6258	Regulator over current fault Regulator 3 detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	PWRREG ACMODUL

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6318	Regulator Fault	PWRREG
	Regulator 1 has reported a fault.	BKSPCN
631A	Regulator Fault	PWRREG
	Regulator 1 has reported a fault.	ACMODUL FI00030
6338	Regulator Fault	PWRREG
	Regulator 2 reported a fault.	BKSPCN
633A	Regulator Fault	PWRREG
	Regulator 2 reported a fault.	ACMODUL FI00030
6358	Regulator Fault	PWRREG
	A regulator 3 reported a fault.	ACMODUL
6400 to 6401	Power Good Fault	PGDPART
		FI00065 BKSPCN
6518	One of the regulators has reported a fault	PWRREG
	An over current sensor failure occurred for a regulator. The ac module or	BKSPCN
	one of the regulators can cause this fault.	
6618	Regulator over current fault	PWRREG BKSPCN
	Regulator 1 reported a false over current condition.	DKSICIN
	Fault tolerance may allow continued system operation.	
6638	Regulator over current fault	PWRREG
	Regulator 2 reported a false over current condition.	BKSPCN
	Fault tolerance may allow continued system operation.	
6658	Regulator over current fault	PWRREG
	Regulator 3 reported a false over current condition.	ACMODUL
	Fault tolerance may allow continued system operation.	
6718	Regulator fault	PWRREG
	Regulator 1 reported a fault.	BKSPCN
	Fault tolerance may allow continued system operation.	
671A	Regulator fault	PWRREG
		BKSPCN FI00030
6738	Regulator fault	PWRREG
	Regulator 2 reported a fault.	BKSPCN
	Fault tolerance may allow continued system operation.	
673A	Regulator fault	PWRREG
		BKSPCN
		F100030
	Regulator 18 reported a fault. Fault tolerance may allow continued system operation.	FI00030

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6758	Regulator fault	PWRREG ACMODUL
	Regulator 3 reported a fault.	
	Fault tolerance may allow continued system operation.	
6818	One of the regulators has reported a fault	PWRREG BKSPCN
	A fault detection failure occurred for a regulator. The regulator or the ac module/SPCN card can cause this fault.	DKSICIN
6918	One of the regulators has reported a fault	PWRREG
	An over current fault detection failure occurred for a regulator. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
6A18	Regulator Fault	PWRREG
	A regulator fault detection failure occurred for regulator 1. The ac module or the regulator can cause this fault.	BKSPCN BACKPLN
6A38	Regulator Fault	PWRREG
	A regulator fault detection failure occurred for regulator 2. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN BACKPLN
6A58	Regulator Fault	PWRREG
	A regulator fault detection failure occurred for regulator 3. The regulator or the ac module/SPCN card can cause this fault.	ACMODUL BACKPLN
6B00	Disk Unit 1 regulator fault	DISKTRY
	The regulator that powers disk unit 1 reported a fault.	DISKDRV BKSPCN
6B01	Disk Unit 2 regulator fault	DISKTRY
	The regulator that powers disk unit 2 reported a fault.	DISKDRV BKSPCN
6B02	Disk Unit 3 regulator fault	DISKTRY
	The regulator that powers disk unit 3 reported a fault.	DISKDRV
6B03	Disk Unit 4 regulator fault	BKSPCN DISKTRY
0003		DISKDRV
	The regulator that powers disk unit 4 reported a fault.	BKSPCN
6B04	Disk Unit 5 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 5 reported a fault.	BKSPCN
6B05	Disk Unit 6 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 6 reported a fault.	BKSPCN
6B06	Disk Unit 7 regulator fault	DISKTRY
	The regulator that powers disk unit 7 reported a fault.	DISKDRV BKSPCN
6B07	Disk Unit 8 regulator fault	DISKTRY
	The regulator that powers disk unit 8 reported a fault.	DISKDRV BKSPCN
6B08	Disk Unit K1 regulator fault	DISKTRY
	The regulator that powers disk unit K1, located in slot K1 of the disk expansion unit, reported a fault.	DISKDRV BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items
6B09	Disk Unit K2 regulator fault
	The regulator that powers disk unit K2, located in slot K2 of the disk expansion unit, reported a fault.
6B0A	Disk Unit K3 regulator fault
	The regulator that powers disk unit K3, located in slot K3 of the disk expansion unit, reported a fault.
6B0B	Disk Unit K4 regulator fault

	DISKDRV
The regulator that powers disk unit K2, located in slot K2 of the disk	
expansion unit, reported a fault.	DIGICIN
6B0A Disk Unit K3 regulator fault	DISKTRY
The regulator that nervers disk unit $K^2$ located in slot $K^2$ of the disk	DISKDRV
The regulator that powers disk unit K3, located in slot K3 of the disk expansion unit, reported a fault.	k BKSPCN
6B0B Disk Unit K4 regulator fault	DISKTRY
The regulator that powers disk unit K4, located in slot K4 of the disk	DISKDRV k BKSPCN
expansion unit, reported a fault.	
6B0C Disk Unit K5 regulator fault	DISKTRY
The merulater that merupe dials witt WE leasted in alst E of the dials	DISKDRV
The regulator that powers disk unit K5, located in slot 5 of the disk expansion unit, reported a fault.	BKSPCN
6B0D Disk Unit K6 regulator fault	DISKTRY
	DISKDRV
The regulator that powers disk unit K6, located in slot K6 of the disk expansion unit, reported a fault.	K BKSPCN
6B0E Disk Unit K7 regulator fault	DISKTRY
	DISKDRV
The regulator that powers disk unit K7, located in slot K7 of the disk expansion unit, reported a fault.	K BKSPCN
6B0F Disk Unit K8 regulator fault	DISKTRY
	DISKDRV
The regulator that powers disk unit K8, located in slot K8 of the disk expansion unit, reported a fault.	K BKSPCN
6B10 Disk Unit K9 regulator fault	DISKTRY
The needlater that resume disk wit K0 leasted in slat K0 of the disk	DISKDRV
The regulator that powers disk unit K9, located in slot K9 of the disk expansion unit, reported a fault.	K BKSPCN
6B11 Disk Unit K10 regulator fault	DISKTRY
The reculator that pervers disk unit K10 leasted in slat K10 of the	DISKDRV
The regulator that powers disk unit K10, located in slot K10 of the d expansion unit, reported a fault.	lisk BKSPCN
6B12 Disk Unit K11 regulator fault	DISKTRY
	DISKDRV
The regulator that powers disk unit K11, located in slot K11 of the d expansion unit, reported a fault.	isk BKSPCN
6B13 Disk Unit K12 regulator fault	DISKTRY
	DISKDRV
The regulator that powers disk unit K12, located in slot K12 of the d expansion unit, reported a fault.	lisk BKSPCN
6B14 Disk Unit K13 regulator fault	DISKTRY
	DISKDRV
The regulator that powers disk unit K13, located in slot K13 of the d expansion unit, reported a fault.	lisk BKSPCN
6B15 Disk Unit K14 regulator fault	DISKTRY
	DISKDRV
The regulator that powers disk unit K14, located in slot K14 of the d expansion unit, reported a fault.	lisk BKSPCN
6B16 Device 1 regulator fault	RMDEV
	BKSPCN
The regulator for device 1 or D01 reported a fault.	

Failing Item

DISKTRY

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6B17	Device 2 regulator fault	RMDEV BKSPCN
	The regulator for device 2 or D02 reported a fault.	
6B18	Disk Unit 9 regulator fault The regulator that powers disk unit 9 reported a fault.	DISKTRY DISKDRV BKSPCN
6B19	Disk Unit 10 regulator fault The regulator that powers disk unit 10 reported a fault.	DISKTRY DISKDRV BKSPCN
6B1A	Disk Unit 11 regulator fault The regulator that powers disk unit 11 reported a fault.	DISKTRY DISKDRV BKSPCN
6B1B	Disk Unit 12 regulator fault The regulator that powers disk unit 12 reported a fault.	DISKTRY DISKDRV BKSPCN
6B1C	Device 3 regulator fault The regulator for device 3 reported a fault.	RMDEV BKSPCN
6B1D	Disk Unit K15 regulator fault	DISKTRY
	The regulator that powers disk unit K15, located in slot K15 of the disk expansion unit, reported a fault.	DISKIRI DISKDRV BKSPCN
6B1E	Disk Unit K16 regulator fault The regulator that powers disk unit K16, located in slot K16 of the disk expansion unit, reported a fault.	DISKTRY DISKDRV BKSPCN
6B1F	Device 4 regulator fault       The regulator for device 4 reported a fault.	RMDEV BKSPCN
6B20	Disk Unit K17 regulator fault         The regulator that powers disk unit K17 reported a fault.	DISKTRY DISKDRV BKSPCN
6B21	Disk Unit K18 regulator fault The regulator that powers disk unit K18 reported a fault.	DISKTRY DISKDRV BKSPCN
6B22	Disk Unit K19 regulator fault The regulator that powers disk unit K19 reported a fault.	DISKTRY DISKDRV BKSPCN
6B23	Disk Unit K20 regulator fault The regulator that powers disk unit K20 reported a fault.	DISKTRY DISKDRV BKSPCN
6B24	Disk Unit K21 regulator fault The regulator that powers disk unit K21 reported a fault.	DISKTRY DISKDRV BKSPCN
6B25	Disk Unit K22 regulator fault The regulator that powers disk unit K22 reported a fault.	DISKTRY DISKDRV BKSPCN
6B26	Disk Unit K23 regulator fault The regulator that powers disk unit K23 reported a fault.	DISKTRY DISKDRV BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6B27	Disk Unit K24 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K24 reported a fault.	BKSPCN
6B28	Disk Unit K25 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K25 reported a fault.	BKSPCN
6B29	Disk Unit K26 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K26 reported a fault.	BKSPCN
6B2A	Disk Unit K27 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K27 reported a fault.	BKSPCN
6B2B	Disk Unit K28 regulator fault	DISKTRY
	The regulator that powers disk unit K28 reported a fault.	DISKDRV BKSPCN
5B2C	Disk Unit K29 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K29 reported a fault.	BKSPCN
6B2D	Disk Unit K30 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K30 reported a fault.	BKSPCN
6B2E	Disk Unit K31 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K31 reported a fault.	BKSPCN
6B2F	Disk Unit K32 regulator fault	DISKTRY
	The regulator that powers disk unit K32 reported a fault.	DISKDRV BKSPCN
5C00	Disk Unit 1 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit 1 or F01. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
5C01	Disk Unit 2 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit 2 or F02. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
5C02	Disk Unit 3 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit 3 or F03. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
5C03	Disk Unit 4 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit 4 or F04. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
6C04	Disk Unit 5 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit 5 or F05. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
6C05	Disk Unit 6 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit 6 or F06. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5C06	Disk Unit 7 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit 7 or F07. The regulator or the ac module/SPCN card can cause this fault.	
6C07	Disk Unit 8 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit 8 or F08. The regulator or the ac module/SPCN card can cause this fault.	
6C08	Disk Unit K1 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K1, located in slot 1 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	
6C09	Disk Unit K2 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K2, located in slot 2 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DK3I CIV
6C0A	Disk Unit K3 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K3, located in slot 3 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DKOI CIV
6C0B	Disk Unit K4 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K4, located in slot 4 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DKSPCIN
6C0C	Disk Unit K5 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K5, located in slot 5 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DK51 CIV
6C0D	Disk Unit K6 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K6, located in slot 6 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DK51 CIV
6C0E	Disk Unit K7 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K7, located in slot 7 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
6C0F	Disk Unit K8 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K8, located in slot 8 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	BKSPCN
6C10	Disk Unit K9 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K9, located in slot 9 of the disk expansion unit. The regulator or the ac	BKSPCN
	module/SPCN card can cause this fault.	

1xxx	
1xxx	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6C11	Disk Unit K10 regulator fault A fault detection failure occurred for the regulator that powers disk unit K10, located in slot 10 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C12	Disk Unit K11 regulator fault A fault detection failure occurred for the regulator that powers disk unit K11, located in slot 11 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C13	Disk Unit K12 regulator fault A fault detection failure occurred for the regulator that powers disk unit K12, located in slot 12 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C14	Disk Unit K13 regulator fault A fault detection failure occurred for the regulator that powers disk unit K13, located in slot 13 of the disk expansion unit. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C15	Disk Unit K14 regulator fault A fault detection failure occurred for the regulator that powers disk unit K14, located in slot 14 of the disk expansion unit. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C16	Device 1 regulator fault A fault detection failure occurred for the regulator that powers device 1 or D01. The regulator or the ac module can cause this fault.	RMDEV BKSPCN
6C17	Device 2 regulator fault A fault detection failure occurred for the regulator that powers device 2 or D02. The regulator or the ac module can cause this fault.	RMDEV BKSPCN
6C18	Disk Unit 9 regulator fault A fault detection failure occurred for the regulator that powers disk unit 9. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C19	Disk Unit 10 regulator fault A fault detection failure occurred for the regulator that powers disk unit 10. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C1A	Disk Unit 11 regulator fault A fault detection failure occurred for the regulator that powers disk unit 11. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C1B	Disk Unit 12 regulator fault A fault detection failure occurred for the regulator that powers disk unit 12. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C1C	Device 3 regulator fault A fault detection failure occurred for the regulator that powers device 3. The regulator or the ac module can cause this fault.	RMDEV BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6C1D	Disk Unit K15 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K15, located in slot 15 of the disk expansion unit. The regulator or the ac module can cause this fault.	
6C1E	Disk Unit K16 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K16, located in slot 16 of the disk expansion unit. The regulator or the ac module can cause this fault.	DKSICN
6C1F	Device 4 regulator fault	RMDEV BKSPCN
	A fault detection failure occurred for the regulator that powers device 4. The regulator or the ac module can cause this fault.	DKSPCIN
6C20	Disk Unit K17 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K17.	BKSPCN
6C21	Disk Unit K18 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K18.	BKSPCN
6C22	Disk Unit K19 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K19.	BKSPCN
6C23	Disk Unit K20 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K20.	DKSPCIN
6C24	Disk Unit K21 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K21.	BKSPCN
6C25	Disk Unit K22 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K22.	BKSPCN
6C26	Disk Unit K23 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K23.	BKSPCN
6C27	Disk Unit K24 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K24.	BKSPCN
6C28	Disk Unit K25 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K25.	BKSPCN
6C29	Disk Unit K26 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K26.	BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items
6C2A	Disk Unit K27 regulator fault
	A fault detection failure occurred for the regulator that powers disk unit K27.
6C2B	Disk Unit K28 regulator fault
	A fault detection failure occurred for the regulator that powers disk unit K28.
6C2C	Disk Unit K29 regulator fault
	A fault detection failure occurred for the regulator that powers disk unit K29.
6C2D	Disk Unit K30 regulator fault
	A fault detection failure occurred for the regulator that powers disk unit K30.
6C2E	Disk Unit K31 regulator fault
	A fault detection failure occurred for the regulator that powers disk unit K31.
6C2F	Disk Unit K32 regulator fault
	A fault detection failure occurred for the regulator that powers disk unit K32.
7000 to 7004	Air Moving Device Fault
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.
7101	Power supply failure
	The ac power supply module reported a fault. One of the other power supplies may also cause this error.
7102	Power supply failure

**Failing Item** DISKTRY BKSPCN

DISKTRY BKSPCN

DISKTRY BKSPCN

DISKTRY BKSPCN

DISKTRY BKSPCN

DISKTRY BKSPCN

AIRMOVR BKSPCN

PWRSPLY

#### PWRSPLY ACMODUL Feature power supply 2 reported a fault. An ac module or one of the other feature power supplies may also cause this error. 7103 Power supply failure PWRSPLY ACMODUL Feature power supply 1 reported a fault. The ac module or one of the other feature power supplies may also cause this error. 7201 PWRREG Power Supply over current fault PWRSPLY The ac module reported an over current condition. This is usually caused ACMODUL by one of the regulators. Perform SPCN-PIP10. 7202 PWRREG Power Supply over current fault PWRSPLY Feature power supply 2 reported an over current condition. This is usually ACMODUL caused by one of the regulators. Perform SPCN-PIP10.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7203	Power Supply over current fault Feature power supply 1 reported an over current condition. This is usually	PWRREG PWRSPLY ACMODUL
	caused by one of the regulators.	ACMODUL
	Perform SPCN-PIP10.	
7300	AC Module Over current	ACMODUL PWRSPLY
	The ac module or one of the feature power supplies reported an over current condition.	
	Perform SPCN-PIP10.	
7400	Control Supply fault	ACMODUL BKSPCN
	A control supply fault was reported in the ac module.	DKJICIN
7401	Control Supply over current	ACMODUL PWRREG
	A control supply over current condition was detected in the ac module.	BKSPCN
7402	Control Supply 5V regulator fault	ACMODUL
	The SPCN detected a fault in the +5 V dc regulator of the control supply in the ac module.	BKSPCN
7403	Control Supply 12V regulator fault	ACMODUL
	The SPCN detected a fault in the +12 V dc regulator of the control supply in the ac module.	
7404	Control Supply 12V regulator over current	ACMODUL
	An over current condition was detected in the +12 V dc regulator of the control supply in the ac module.	PWRSPLY FI00251
	Perform SPCN-PIP10.	
7407	Optical Converter 5V Fault	90H6287
	The SPCN detected a fault on the SPCN card optical converter 5V.	SPNLCRD
7500 to 7503	Air Moving Device missing error	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	BKSPCN
7610	Air Moving Device Fault	AIRMOVR
	The Air Moving Device is operating at the wrong speed.	TWRCARD
7611	Air Moving Device missing error	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	TWRCARD
7620	Air Moving Device Fault	AIRMOVR
	The Air Moving Device is operating at the wrong speed.	TWRCARD
7621	Air Moving Device missing error	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7630	Air Moving Device Fault	AIRMOVR TWRCARD
	The Air Moving Device is operating at the wrong speed.	
7631	Air Moving Device missing error A problem was dectected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	AIRMOVR TWRCARD
7640	Air Moving Device Fault	AIRMOVR
	The Air Moving Device is operating at the wrong speed.	TWRCARD
7641	Air Moving Device missing error A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	AIRMOVR TWRCARD
7710	Air Moving Device BP1 Fault A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	AIRMOVR TWRCARD
7711	Air Moving Device BP1 Not Present A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	AIRMOVR TWRCARD
7720	Air Moving Device BP2 Fault A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	AIRMOVR TWRCARD
7721	Air Moving Device BP2 Not Present A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	AIRMOVR TWRCARD
8001	A Battery Power Unit 1 Failed A response was received from battery power unit 1 charger that was not valid.	46G3890 ACMODUL BACKPLN
8002	Battery Power Unit 2 Failed         A response was received from battery power unit 2 charger that was not valid.	46G3890 ACMODUL BACKPLN
8101	A Battery Power Unit 1 Failed Battery power unit 1 capacity test failed.	46G3890
8102	Battery Power Unit 2 FailedBattery power unit 2 capacity test failed.	46G3890
8110	Battery Power Unit 1 and 2 Failed	BATRY
	Replace both batteries.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
8201	A Battery Power Unit 1 Failed	46G3890
	Battery power unit 1 charging fault was detected.	
8202	Battery Power Unit 2 Failed	46G3890
	Battery power unit 2 charging fault was detected.	
8301	A Battery Power Unit 1 Failed	46G3890
	Battery power unit 1 load test fault occurred.	
8302	Battery Power Unit 2 Failed	46G3890
	Battery power unit 2 load test fault occurred.	
8400	No VPD Found due to Invalid Bypass	TWRCARD
8401	Timeout on Panel for Request of VPD	VPDPART
		TWRCARD
8402	Unable to Collect VPD	VPDPART BKSPCN
8403	VPD Critical Mismatch	VPDPART
		BKSPCN
8404 to 8406	Processor Unit VPD Mismatch	VPDPART
840A	VPD 5V Power Off Failure	BKSPCN VPDPART
040A	VED SV Fower On Failure	TWRCARD
840B	VPD 5V Power On Failure	VPDPART
		TWRCARD
840C	Memory Module Misplug	VPDPART TWRCARD
840D	SPCN Configuration mismatch	IDPART
		TWRCARD
840E	SPCN Default Configuration loaded	IDPART TWRCARD
840F	SPCN Configuration mismatch	IDPART
0101		TWRCARD
8413 to 8416	Invalid Processor VPD	VPDPART
9400 to 9404	N. Brosser VDD	TWRCARD
8423 to 8426	No Processor VPD	VPDPART TWRCARD
8610	Air Moving Device B01 Not Present	AIRMOVR
		TWRCARD
8620	Air Moving Device B02 Not Present	AIRMOVR TWRCARD
8810	Battery Power Unit missing	BATRY
8811	Battery Charger Unit missing	BATCHGR
8910	External Netfinity Server 3.3V fault	ALTMANL
		TWRCARD
8920	External Netfinity Server Power Good fault	TWRCARD ALTMANL
8930	Integrated Netfinity Adapter fault	TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
8940 to 8943	External Netfinity Server R485 Communication fault	TWRCARD CBLALL ALTMANL
9012	Address not valid.	TWRCARD CBLALL
	LIC command had a frame address that was not valid.	
	Exchange the SPCN frame-to-frame cables to the failing frame.	
9013	Invalid Node Address.	TWRCARD
	The address in the SPCN command does not match the secondary nodes assigned address.	CBLALL
	Exchange the failing items for the SPCN node reporting the error.	
9014	A command has an invalid address mode.	AJDG301
	A command from the system unit specified a unit address of D or E or had a frame address of 00.	TWRCARD
	Exchange the failing items in the system unit.	
9016, 9021	A command to an SPCN node was rejected.	
	No action required. This reference code is logged for information only.	
9022	Addressed Unit not in frame.	
	The addressed unit does not exist in the addressed frame.	
	No action required. This reference code is logged for information only.	
9023	Addressed Unit exists, but the frame is powered off.	
	The addressed unit is in a frame that is powered off.	
	No action required. This reference code is logged for information only.	
9024	SPCN Licensed Internal Code not valid.	
	The Licensed Internal Code in one of the secondary nodes is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9025	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in one of the frames is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9026	Battery Power Unit is reporting a low charge.	
	The battery power unit is not charged enough to run a test.	
	No action required. This reference code is logged for information only.	
9027	Battery Power Unit is defective.	
	No action required. This reference code is logged for information only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9028	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in the primary node is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9029	SPCN VPD Damaged	TWRCARD
	The VPD record in the EEPROM has bad data.	
	Exchange the failing items for the node reporting the failure.	
902C	Battery Power Unit test was aborted.	
	The battery power unit test was aborted.	
	No action required. This reference code is logged for information only.	
902D	Addressed frame is not in SPCN configuration table.	
	The addressed frame is not in the SPCN configuration table.	
	No action required. This reference code is logged for information only.	
9031	Frame-to-Frame Communications Failure	
	The SPCN detected a BCC error on a transmission from another frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9032	SPCN Communications Failure, unit to rack.	
	The frame detected a BCC error on a transmission from a secondary node to the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9033	SPCN Communications Failure, rack to unit.	
	A secondary node detected a BCC error on a transmission from the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9034	Unsupported Packet Size	
	The receiving node detected a packet exceeding 70 bytes. The frame can also return this code if a secondary node returns more than 10 bytes to a PAS command.	
	No action required. This reference code is logged for error analysis only.	
9035	Secondary SPCN node timeout.	
	A secondary SPCN node did not respond to a command. The command was attempted again and failed.	
	No action required. This reference code is logged for error analysis only.	
9036	Frame Timeout	
	One or more frames did not respond to a command. The command is attempted again.	
	No action required. This reference code is logged for error analysis only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
903B	Invalid Packet Length for data sent.	
	The number of bytes sent or received does not match the number of bytes specified in the command.	
	No action required. This reference code is logged for error analysis only.	
9041	Invalid Load Type	AJDG301
	The down load was successful, but the wrong type of Licensed Internal Code was loaded. The operation was attempted again but was not successful. Exchange the failing items for the node reporting the fault.	TWRCARD
9042	EEPROM Failure	TWRCARD
	The EEPROM in an SPCN node cannot be written successfully.	
	Exchange the SPCN node reported in the failure.	
9043	Download Failure	TWRCARD
	The Licensed Internal Code download to an SPCN node was completed but was not successful.	
	Exchange the failing SPCN node.	
9046	QDS Packet Sequence Error	TWRCARD
	The Packet Sequence number is wrong. The download was stopped.	
9047	QDS Block Sequence Error	TWRCARD
	The Block Sequence number is wrong. The download was stopped.	
9048	The SPCN ROS and EEPROM LIC is not compatable.	TWRCARD
	The LIC levels in the nodes ROS and EEPROM are not compatible.	AJDG301
	Exchange the failing items for the failing node.	
9080	Undefined Status Code	TWRCARD
	An SPCN node returned an unknown status code.	BACKPLN
	Exchange the failing SPCN node.	
90F0	A frame was dropped from the SPCN configuration.	TWRCARD
	A frame was dropped from the SPCN configuration. This is usually caused by a loss of ac power or a problem with the frame-to-frame cable.	CBLALL
90F1	A frame was added to the SPCN configuration.	
	No action required. This reference code is logged for information only.	
9100	Battery capacity test completed.	
	No action required. This reference code is logged for information only.	
9101	VLIC-SPCN Timeout	TWRCARD
	A Licensed Internal Code timeout occurred. The SPCN failed to respond to a Licensed Internal Code command.	CTLPNL SVCPROC
9102	Assign Permanent Address command failure	TWRCARD

A node failed to perform an Assign Permanent Address command.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9103	Download Initialize Timeout	TWRCARD
	An SPCN node failed to enter the download state after an Initialize for Download command.	
	Exchange the failing SPCN node.	
9104	Download Completion Timeout	TWRCARD
	An SPCN node failed to leave the download state.	
	Exchange the failing SPCN node.	
9105	Load Damaged Timeout	TWRCARD
	An SPCN node failed to enter the operational state.	
	Exchange the failing SPCN node.	
9106	An SPCN LID was not found.	
	No action required. This reference code is logged for information only.	
9107	An SPCN microcode download is required.	
	No action required. This reference code is logged for error analysis only.	
9108	A status change occured in one of the SPCN nodes.	
	No action required. This reference code is logged for information only.	
0109	Licensed Internal Code part number is not correct.	TWRCARD
	The AROS part number field was not updated to the correct level after the system attempted to load new Licensed Internal Code.	
9110	Battery Power Unit capacity test failed.	BATRY
	The battery power unit was not able to pass the capacity test.	
0111	SPCN is too large for VLIC.	AJDG301
	There are more nodes in the network than VLIC can service.	
0112	Primary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the primary SPCN node is damaged. The reload failed because the code could not be found.	
113	Secondary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the secondary SPCN node is damaged. The reload failed because the code could not be found.	
0114	Frame SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for a SPCN node is damaged. The reload failed because the code could not be found.	
9115	SPCN Command rejected by the Service Processor.	
	The service processor rejected an SPCN command from the Licensed Internal Code.	
	No action required. This reference code is logged for information only.	
9116	SPCN - Control Panel interface failure.	
	The SPCN to control panel interface is not working.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9117	SPCN - Control Panel interface is now working.	
	The SPCN to control panel interface is now working.	
	No action required. This reference code is logged for information only.	
9212	Frame Address field not valid.	TWRCARD
	A Licensed Internal Code command had a frame address that is not valid.	
	Exchange the failing items for the failing node.	
9213	Invalid Address status, secondary node.	TWRCARD
	The address in the SPCN command does not match the assigned address of the secondary node.	
	Exchange the failing items for the failing node.	
9214	Invalid Address Mode status	TWRCARD
	Invalid Address Mode occurred during Frame Command processing.	AJDG301
9215	Invalid Frame Command status	TWRCARD
	Invalid Frame Command occurred during Frame Command processing.	AJDG301
921B	System Unit SPCN Port Fault status.	TWRCARD
	System Unit Port Fault occurred during Command processing.	AJDG301
922B	Address Unassigned status	TWRCARD
	A secondary node has no address assigned during Command processing.	AJDG301
9231	Frame-to-Frame Communications Failure	TWRCARD
	A frame-to-frame communications failure occurred during STF processing.	CBLALL
9232	Intrarack Communications Failure	TWRCARD
	An SPCN secondary node to frame communications failure occurred	CBLALL
	during Command processing.	
9233	Intrarack Communications Failure	TWRCARD
	An SPCN frame to secondary node communications failure occurred during Command processing.	CBLALL
9234	Unsupported Packet Size status	TWRCARD
	Unsupported Packet Size occurred during STF and Secondary Node Command processing.	CTLPNL SVCPROC
9235	SPCN Secondary Node Timeout status	TWRCARD
	An SPCN Secondary Node Timeout occurred during Command processing.	AJDG301 CBLALL
	If the failing secondary node is in a 9337, go to the "Analyzing Problems" section in the 9337 Disk Array Service Information manual.	
9236	Frame Timeout status	TWRCARD
	An SPCN Frame Node Timeout occurred during Network post processing.	CBLALL
9238	Secondary Node Fault	TWRCARD AJDG301
	An SPCN Secondary Node Fault occurred during Command processing.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9239	Frame Node Fault	TWRCARD AJDG301
	An internal error in the SPCN frame node prevents the running of a Frame command.	
923A	ASA Failure	TWRCARD
	The frame address returned by a secondary node does not match the address of the frame.	AJDG301
923B	Invalid Packet Length for data sent.	AJDG301 TWRCARD
	An Invalid Packet Length occurred for data exchanged.	
9280	Response Stack Overflow	CBLALL
	Too many responses were received during System Frame command processing.	AJDG301 TWRCARD
9281	Response Overrun	CBLALL
	Response Overrun occurred during System Frame processing.	AJDG301 TWRCARD
9282	No Free Entries	CBLALL
	No free entries were found during System Frame processing.	AJDG301 TWRCARD
9283	ARA Failure	TWRCARD
	An Assign Frame Address Failure occurred during ARA Preprocessing.	AJDG301
9284	Undefined status	TWRCARD
	Undefined Status occurred during Frame or STF processing.	AJDG301
9285	BCC Fault	TWRCARD
	A BCC Error was detected during Network post processing.	
9286	Length Check Error.	TWRCARD
	Length Check occurred during SPCN post processing.	AJDG301
9287	Undefined status	TWRCARD
	Undefined Status occurred during Command processing.	AJDG301
9288	Configuration Error	TWRCARD
		AJDG301
9289	A configuration error was detected during System Frame processing. Invalid Packet Length for data sent.	AJDG301
7207		TWRCARD
4.100	Invalid Packet Length occurred for data exchanged.	
A100	Battery Power Unit capacity test failure	
	The battery power unit capacity test time exceeds the installed battery capacity. The battery power may not be enough to provide a controlled stop during a loss of incoming ac voltage.	
	This reference code is logged for information only.	
A201	A Battery Power Unit 1 Failed	BATRY
	Battery power unit 1 capacity test failed.	BATCHGR
A202	Battery Power Unit 2 Failed	BATRY
	Battery power unit 2 capacity test failed.	BATCHGR

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
A300	Battery Power Unit missing The existing number of battery power units installed may not be adequate for the current configuration. If the battery power units are installed, insure that they are properly connected before replacing any FRUs.	BATCHGR BATRY
A301	A Battery Power Unit 1 Failed The installed SPCN Licensed Internal Code does not give support to the type of battery power unit installed. Install the latest SPCN code.	AJDG301 BATCHGR
A302	Battery Power Unit 2 Failed The installed SPCN Licensed Internal Code does not give support to the type of battery power unit installed. Install the latest SPCN code.	AJDG301 BATCHGR
AC01 to AC02	Internal Battery Power Unit Charger Fault	BATCHGR BKSPCN
B101	A Battery Power Unit 1 Failed Battery power unit reported an over current condition on the +29 V dc bus.	PWRREG BATCHGR BACKPLN
B102	Battery Power Unit 2 Failed Battery power unit 2 reported an over current condition on the +29 V dc bus.	PWRREG BATCHGR BACKPLN
B201	A Battery Power Unit 1 Failed Battery power unit 1 reported an over current condition on the +31 V dc bus.	PWRREG BATCHGR BACKPLN
B202	Battery Power Unit 2 Failed Battery power unit 2 reported an over current condition on the +31 V dc bus.	PWRREG BATCHGR BACKPLN
C510	A Battery Power Unit 1 Failed SPCN-to-battery power unit 1 or 3 communications fault occurred.	BATCHGR ACMODUL BACKPLN
C511	Battery Power Unit 2 Failed SPCN-to-battery power unit 2 communications fault occurred.	BATCHGR ACMODUL BACKPLN
C512	AC Module Failure SPCN serial port communications fault occurred.	ACMODUL
C600	AC Module Failure The AC module control supply failed to turn off.	ACMODUL
C601	AC Module Failure AC module bus voltage control test fault occurred.	ACMODUL
C602	AC Module Failure AC module fault detection failure occurred.	ACMODUL
C609	Clock Card Failure The clock card in slot 17 is missing or defective.	CLKCARD BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
C62E	SPCN Network Fault	TWRCARD CBLALL
	An SPCN frame-to-frame communication failure was detected.	
	SRNPU or POSORMU.	
C701 to C703	SPCN Frame-to-Frame Communication fault	TWRCARD CBLALL
CB00	Unknown box ID	TWRCARD BACKPLN
	The SPCN node cannot determine the machine type of the box in which it is installed.	DACKI LIN
CB05 to CB06	AC Module Failure	ACMODUL
	The SPCN ROS and EPROMs test failed.	
CB1D	AC Module Failure	ACMODUL
	The LCD test failure was detected on an Extension/Expansion Unit.	17G0573
CC00	AC Module Failure	ACMODUL
	An unknown fault was detected. The machine failed to power up.	FI00065 BKSPCN
CD00	No Power Supplies Present	BKSPCN
	SPCN cannot detect any power supplies installed.	PWRSPLY
CE18	Regulator Not Present	PWRREG
	No regulators can be found.	ACMODUL
	If the regulators are installed, exchange the failing items.	
CE1A	Regulator Not Present	PWRREG BKSPCN
	If regulator 3 in slot R03 is installed, exchange the failing items.	DIGICIN
D001	A Battery Power Unit 1 Failed	86G8020 ACMODUL
	A response was received from battery power unit 1 charger that was not valid.	BACKPLN
D002	Battery Power Unit 2 Failed	86G8020
	A response was received from battery power unit 2 charger that was not valid.	ACMODUL BACKPLN
D101	A Battery Power Unit 1 Failed	86G8040
	Battery power unit 1 capacity test failed.	86G8020
D102	Battery Power Unit 2 Failed	86G8040
	Battery power unit 2 capacity test failed.	86G8020
D110	Battery Power Unit 1 and 2 Failed	BATRY
	Replace both batteries.	
D201	A Battery Power Unit 1 Failed	86G8020
	Battery power unit 1 charging fault was detected.	86G8040
D202	Battery Power Unit 2 Failed	86G8020
	Battery power unit 2 charging fault was detected.	86G8040

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
D301	A Battery Power Unit 1 Failed	86G8020
	Battery power unit 1 load test fault occurred.	86G8040
D302	Battery Power Unit 2 Failed	86G8020
	Battery power unit 2 load test fault occurred.	86G8040
E002	Battery Power Unit 2 Failed	86G7750
	A response was received from battery power unit 2 charger that was not valid.	ACMODUL BACKPLN
E102	Battery Power Unit 2 Failed	86G7714
	External battery power unit 2 capacity test failed.	86G7750
E202	Battery Power Unit 2 Failed	86G7750
	External battery power unit 2 charging fault was detected.	86G7714
E302	Battery Power Unit 2 Failed	86G7750
	External battery power unit 2 load test fault occurred.	86G7714
F401	Internal Battery Power Unit Charger Fault	BATCHGR BKSPCN
F501	Internal Battery Power Unit Fault	BATRY BATCHGR
F601	Internal Battery Power Unit or Charger Fault	BATCHGR BATRY
F701	Internal Battery Power Unit Charger Fault	BATCHGR BATRY
F802	External Battery Power Unit Charger Fault	BATCHGR BKSPCN
F902	External Battery Power Unit Fault	BATRY BATCHGR
FA02	External Battery Power Unit or Charger Fault	BATCHGR BATRY
FB02	External Battery Power Unit Charger Fault	BATCHGR BATRY

### Table 2. SPCN failing items for system Models 270 and 820:

Failing Item	Description	Document Description
16G6379	I/O Regulator.	Repair and Parts
16G8716	Cable assembly	Repair and Parts
16G8717	Cable assembly	Repair and Parts
16G8748	Planar board	Repair and Parts
16G8760	System Expansion Unit Board assembly with RAID	Repair and Parts
16G8763	Planar board	Repair and Parts
16G8769	Cable Carrier, System Unit with RAID.	Repair and Parts
16G8771	Cable Carrier, System Expansion Unit with RAID.	Repair and Parts

Failing Item	Description	Document Description
16G8806	Planar board	Repair and Parts
16G8807	System Unit Board assembly model G46 with RAID	Repair and Parts
17G0566	System Unit Control Panel	Repair and Parts
17G0567	System Unit Control Panel Card Assembly	Repair and Parts
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0574	Expansion Unit Control Panel Card Assembly	Repair and Parts
17G1150	Power Supply	Repair and Parts
17G1150	Feature Power Supply	Repair and Parts
17G1179	Current Share I/O Regulator	Repair and Parts
17G1189	I/O Regulator.	Repair and Parts
17G1199	3.6V I/O Regulator	Repair and Parts
17G1209	I/O Regulator.	Repair and Parts
17G2539	Cable Carrier, 9406 System Unit.	Repair and Parts
17G2598	Power regulator card	Repair and Parts
17G2695	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5521	Blower Assembly	Repair and Parts
21F5620	Regulator in 280X Disk Unit.	Repair and Parts
21F5650	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5680	AC Module, SPCN Secondary node.	Repair and Parts
21F5774	Cable Carrier, 9406 System Unit.	Repair and Parts
21F5793	Fan assembly.	Repair and Parts
21F8872	5032 Cable Carrier.	Repair and Parts
21F8888	Expansion Unit/Extension Unit Control Panel	Repair and Parts
21F8888	Control Panel on 5032 box.	Repair and Parts
21F8890	D-SE Converter Module.	Repair and Parts
21F9052	Card Enclosure, 9406 System Unit.	Repair and Parts
21F9215	I/O Regulator.	Repair and Parts
21F9216	3.6V Regulator, 9406 System Unit.	Repair and Parts
21F9316	Power Control Compartment (PCC)	Repair and Parts
21F9362	SPCN Port Cable	Repair and Parts
21F9380	Battery Power Unit	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9530	DC Bulk Module.	Repair and Parts
21F9631	Fan assembly.	Repair and Parts
46G3510	Fan assembly.	Repair and Parts
46G3587	Blower Assembly	Repair and Parts
46G3626	Contol Panel FRU Kit	Repair and Parts
46G3680	AC Module	Repair and Parts

Failing Item	Description	Document Description
46G3890	Internal Battery Power Unit	Repair and Parts
6462417	Rack Control Panel cable.	Repair and Parts
73F9166	System Unit Board assembly model G46 without RAID	Repair and Parts
74F1541	Card Enclosure, 9406 System Unit.	Repair and Parts
74F1542	Card Enclosure, 9406 System Unit.	Repair and Parts
74F1760	DC Bulk Module.	Repair and Parts
74F1919	I/O Regulator.	Repair and Parts
74F1922	3.6V Regulator, 9406 System Unit.	Repair and Parts
85F8220	Base Power Supply	Repair and Parts
85F8250	Feature Power Supply	Repair and Parts
86G7660	AC Module	Repair and Parts
86G7712	External Battery Power Unit cable	Repair and Parts
86G7714	External Battery Power Unit	Repair and Parts
86G7750	Battery Power Unit Charger	Repair and Parts
86G8020	Battery Power Unit Charger	Repair and Parts
86G8040	Battery Power Unit	Repair and Parts
87G6029	Regulator.	Repair and Parts
87G6060	Battery Power Unit	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6235	SPCN Frame-to-Frame or PCC port cable.	Repair and Parts
87G6300	AC Module	Repair and Parts
90H6287	Optical Converter	Repair and Parts
90H6360	Cable assembly	Repair and Parts
ACMODUL	AC Module	See the service documentation for instructions.
AIRMOVR	Fan and Blower assemblies	See the service documentation for instructions.
AJDG301	Vertical Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Rack SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Secondary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ04	System Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ05	Expansion Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
ALTMANL	Alternate Manual Required	See the service documentation for instructions.
BACKPLN	Back Plane Unit	See the service documentation for instructions.
BATCHGR	Battery Power Unit Charger	See the service documentation for instructions.
BATRY	Battery Power Unit	See the service documentation for instructions.
BKSPCN	SPCN card	See the service documentation for instructions.
BUSPWR	Domain 29V Bus	See the service documentation for instructions.
CBLALL	Cable Failure	See the service documentation for instructions.

Failing Item	Description	Document Description
CLKCARD	Clock card	See the service documentation for instructions.
CTLPNL	Control Panel	See the service documentation for instructions.
DISKDRV	Disk Unit Power regulator	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk Unit Power regulator	See the service documentation for instructions.
DISKTRY	Disk Unit or Removable Media Device	Repair and Parts
DMREG	Domain Regulator	See the service documentation for instructions.
I2CBUS	I2C Bus Part	See the service documentation for instructions.
IDPART	Vital Product Data Parts	See the service documentation for instructions.
INTRLCK	Interlock part	See the service documentation for instructions.
PGDPART	Power Good Part	See the service documentation for instructions.
PWROC	Power Supply overcurrent	See the service documentation for instructions.
PWRREG	Regulator.	See the service documentation for instructions.
PWRSPLY	Power Supply	See the service documentation for instructions.
RMDEV	Disk Unit or Removable Media Device	See the service documentation for instructions.
SPNLCRD	SPCN panel card	See the service documentation for instructions.
SVCPROC	Service Processor Card	See the service documentation for instructions.
TWRCARD	Card enclosure or backplane	See the service documentation for instructions.
UPSUNIT	UPS unit part	See the service documentation for instructions.
VPDPART	VPD Communication Part	See the service documentation for instructions.

### (1xxx) SPCN reference codes for Models 800, 810, and 825

For details on the Failing Item column entries, see the SPCN Failing Items Detail table.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
00A0	SPCN BATs in process	TWRCARD
	No action required. This reference code is logged for information only. If this reference code is present for more than 1 minute, exchange the failing items.	
00AA	Download in process	
	No action required. This reference code is logged for information only.	
00AB	Rack UEPO switch is OFF.	TWRCARD CTLPNL
	Informational reference code.	6462417
	The UEPO switch must be returned to the On position to power on the rack.	
00AC	Detected AC loss	ACMODUL
	If system powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	

Table 1. SPCN reference codes for Models 800, 810, and 825:

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
DOBA	The system is running on the Battery Power Unit.	
	No action required. This reference code is displayed for information only.	
00BC	Battery Power Unit test is in process.	
	No action required. This reference code is displayed for information only.	
00CA	Thermal calibration in progress	
00EF	Remote EPO switch is OFF	
1500	Detected AC loss	PWRSPLY TWRCARD
. =	Before replacing any parts, verify that the AC input voltage is correct.	
1501	Power supply failure	PWRSPLY TWRCARD
1502	Power supply failure	PWRSPLY TWRCARD CBLALL
1503	Power supply failure	PWRSPLY TWRCARD
1510	Detected AC loss	PWRSPLY TWRCARD
1511	Before replacing any parts, verify that the AC input voltage is correct.	PWRSPLY
1311	Power supply failure	TWRCARD
1512	Power supply failure	PWRSPLY TWRCARD CBLALL
1513 to 1514	Power supply failure	PWRSPLY TWRCARD
1516	No Power Supplies Present	PWRSPLY
	The required power supplies are not installed.	TWRCARD
1517	Power supply failure	PWRSPLY TWRCARD
1520	Detected AC loss	PWRSPLY
	Before replacing any parts, verify that the AC input voltage is correct.	TWRCARD
1521	Power supply failure	PWRSPLY TWRCARD
1522	Power supply failure	PWRSPLY TWRCARD CBLALL
1523 to 1524	Power supply failure	PWRSPLY TWRCARD
1526	No Power Supplies Present	PWRSPLY TWRCARD
	The required power supplies are not installed.	
1527	Power supply failure	PWRSPLY TWRCARD
1530	Detected AC loss	PWRSPLY TWRCARD
	Before replacing any parts, verify that the AC input voltage is correct.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1531	Power supply failure	PWRSPLY TWRCARD
1532	Power supply failure	PWRSPLY TWRCARD CBLALL
1533	Power supply failure	PWRSPLY TWRCARD
1534	Power Supply P03 fault	PWRSPLY TWRCARD
1B01	Load fault on the +12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B02	Load fault on the +5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B03	Load fault on the +3.3V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B04	Load fault on the -12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B05	Load fault on the +1.8V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B06 to 1B07	Load fault on the +2.5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B0A	Load Fault on the +12V/-12v bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B0B	Load fault on the +1.8V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B0C	Load Fault on the +3.3V/+1.5v bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B0D	Load fault on the +2.5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B0E	Load fault on the +5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B0F	Load Fault on the +1.5V/+1.3v bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B11	Load fault on the +12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B12	Load fault on the +5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B13	Load fault on the +3.3V bus	PWROC TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1B14	Load fault on the -12V bus	PWROC TWRCARD
1B16 to 1B17	Load fault on the +2.5V bus	PWROC TWRCARD
1C01	Load fault on the +12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1C03	Load fault on the +3.3V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1C05	Load fault on the +1.8V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1C06 to 1C08	Load fault on the +2.5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1F01	No SRC Translate	
2600	Power Good Fault	PGDPART TWRCARD PWRSPLY
2601 to 2606	Power Good Fault	PGDPART TWRCARD
2610	Processor/Memory Card not installed	PWRSPLY TWRCARD
2611	Processor Regulator fault	PWRREG TWRCARD
2612	Optical Converter 5V Fault	CBLALL TWRCARD
	The SPCN detected a fault on the SPCN card optical converter 5V.	
2613	Configuration Requires 200V Input Configuration now requires 200V AC power.	CBLALL
3100	I2C Bus Controller Communication fault	I2CBUS TWRCARD
3101	I2C Bus 1 Communication fault	I2CBUS TWRCARD
3102	I2C Bus 2 Communication fault	I2CBUS TWRCARD
3103	I2C Bus 3 Communication fault	I2CBUS TWRCARD
3104	I2C Bus 4 Communication fault	I2CBUS TWRCARD
3105	I2C Bus 5 Communication fault	I2CBUS TWRCARD
3106	I2C Bus 6 Communication fault	I2CBUS TWRCARD
3110	I2C Bus DASD Backplane 1 Communication fault	I2CBUS TWRCARD
3111	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3112	I2C Bus DASD Backplane 3 Communication fault	I2CBUS TWRCARD
3113	I2C Bus Adapter Communication fault	I2CBUS TWRCARD
3114	I2C Bus PCI Backplane Communication fault	I2CBUS TWRCARD
3115	I2C Bus Panel Communication fault	I2CBUS TWRCARD
3116	I2C Bus Fan Local Controller Communication fault	I2CBUS TWRCARD
3117	I2C Bus Fan Remote Controller Communication fault	I2CBUS TWRCARD
3118	I2C Bus SPCN VPD Communication fault	I2CBUS TWRCARD
3119	I2C Bus 4 Communication fault	I2CBUS TWRCARD
311A	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD
311C	I2C Bus Panel Communication fault	I2CBUS TWRCARD
311D	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD
311E	I2C Bus DASD Backplane 3 Communication fault	I2CBUS TWRCARD
3121	I2C Bus DASD Backplane 1 Communication fault	I2CBUS TWRCARD
3122	I2C Bus Device Backplane 4 Communication fault	I2CBUS TWRCARD
4410	Internal Battery Power Unit Fault Internal Battery Power Unit in the system has failed.	BATRY BATCHGR TWRCARD CBLALL
4411	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR TWRCARD CBLALL
4412	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR BATRY TWRCARD CBLALL
4413	Internal Battery Power Unit Charger Fault	BATCHGR TWRCARD
4414	Internal Battery Power Unit Charger in the system has failed.       Battery Charger Load fault	CBLALL PWROC BATRY TWRCARD CBLALL
4415	Battery Power Unit missing	BATRY TWRCARD CBLALL

1xxx		
Reference Code	Description/Action Perform all actions before exchanging Failing Items	
4417	Battery Charger Unit missing	
7(10		

Reference coue	Description/Action remonit an actions before exchanging ranning terms	I anning item
4417	Battery Charger Unit missing	BATCHGR TWRCARD CBLALL
7610	Air Moving Device Fault The Air Moving Device is operating at the wrong speed.	AIRMOVR TWRCARD
7611	Air Moving Device missing error A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	AIRMOVR TWRCARD
7620	Air Moving Device Fault The Air Moving Device is operating at the wrong speed.	AIRMOVR TWRCARD
7621	Air Moving Device missing error A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	AIRMOVR TWRCARD
7630	Air Moving Device Fault The Air Moving Device is operating at the wrong speed.	AIRMOVR TWRCARD
7631	Air Moving Device missing error A problem was dectected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	AIRMOVR TWRCARD
7640	Air Moving Device Fault The Air Moving Device is operating at the wrong speed.	AIRMOVR TWRCARD
7641	Air Moving Device missing error A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	AIRMOVR TWRCARD
7690	Air Moving Device Fault	AIRMOVR TWRCARD
7691	Air Moving Device missing error	AIRMOVR TWRCARD
8400	No VPD Found due to Invalid Bypass	TWRCARD
8401	Timeout on Panel for Request of VPD	VPDPART TWRCARD
8402	Unable to Collect VPD	VPDPART TWRCARD
8403	VPD Critical Mismatch	VPDPART TWRCARD
8404 to 8406	Processor Unit VPD Mismatch	VPDPART TWRCARD
8409	No Processor Installed	VPDPART TWRCARD
840A	VPD 5V Power Off Failure	VPDPART TWRCARD

Failing Item

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
840B	VPD 5V Power On Failure	VPDPART TWRCARD
840C	Memory Module Misplug	VPDPART TWRCARD
840D	SPCN Configuration mismatch	IDPART TWRCARD
840E	SPCN Default Configuration loaded	IDPART TWRCARD
840F	SPCN Configuration mismatch	IDPART TWRCARD
8410 to 8412	Invalid Processor VPD	TWRCARD
8413 to 8416	Invalid Processor VPD	VPDPART TWRCARD
8417 to 841F	Invalid Processor VPD	TWRCARD
8423 to 8426	No Processor VPD	VPDPART TWRCARD
8610	Air Moving Device B01 Not Present	AIRMOVR TWRCARD
8620	Air Moving Device B02 Not Present	AIRMOVR TWRCARD
8910	External Netfinity Server 3.3V fault	ALTMANL TWRCARD
8920	External Netfinity Server Power Good fault	TWRCARD ALTMANL
8930	Integrated Netfinity Adapter fault	TWRCARD
8940 to 8943	External Netfinity Server R485 Communication fault	TWRCARD CBLALL ALTMANL
9012	Address not valid.	TWRCARD
	LIC command had a frame address that was not valid.	CBLALL
	Exchange the SPCN frame-to-frame cables to the failing frame.	
9013	Invalid Node Address.	TWRCARD
	The address in the SPCN command does not match the secondary nodes assigned address.	CBLALL
	Exchange the failing items for the SPCN node reporting the error.	
9014	A command has an invalid address mode.	AJDG301
	A command from the system unit specified a unit address of D or E or had a frame address of 00.	TWRCARD
	Exchange the failing items in the system unit.	
9016, 9021	A command to an SPCN node was rejected.	
	No action required. This reference code is logged for information only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9022	Addressed Unit not in frame.	
	The addressed unit does not exist in the addressed frame.	
	No action required. This reference code is logged for information only.	
9023	Addressed Unit exists, but the frame is powered off.	
	The addressed unit is in a frame that is powered off.	
	No action required. This reference code is logged for information only.	
9024	SPCN Licensed Internal Code not valid.	
	The Licensed Internal Code in one of the secondary nodes is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9025	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in one of the frames is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9026	Battery Power Unit is reporting a low charge.	
	The battery power unit is not charged enough to run a test.	
	No action required. This reference code is logged for information only.	
9027	Battery Power Unit might be defective.	BATRY
	If the 1xxx9027 SRC is logged on two consecutive days, replace the FRUs listed.	BATCHGR
9028	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in the primary node is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9029	SPCN VPD Damaged	TWRCARD
	The VPD record in the EEPROM has bad data.	
	Exchange the failing items for the node reporting the failure.	
902C	Battery Power Unit test was aborted.	
	The battery power unit test was aborted.	
	No action required. This reference code is logged for information only.	
902D	Addressed frame is not in SPCN configuration table.	
	The addressed frame is not in the SPCN configuration table.	
	No action required. This reference code is logged for information only.	
9031	Frame-to-Frame Communications Failure	
	The SPCN detected a BCC error on a transmission from another frame. The transmission is attempted again.	

No action required. This reference code is logged for error analysis only.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9032	SPCN Communications Failure, unit to rack.	
	The frame detected a BCC error on a transmission from a secondary node to the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9033	SPCN Communications Failure, rack to unit.	
	A secondary node detected a BCC error on a transmission from the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9034	Unsupported Packet Size	
	The receiving node detected a packet exceeding 70 bytes. The frame can also return this code if a secondary node returns more than 10 bytes to a PAS command.	
	No action required. This reference code is logged for error analysis only.	
9035	Secondary SPCN node timeout.	
	A secondary SPCN node did not respond to a command. The command was attempted again and failed.	
	No action required. This reference code is logged for error analysis only.	
9036	Frame Timeout	
	One or more frames did not respond to a command. The command is attempted again.	
	No action required. This reference code is logged for error analysis only.	
903B	Invalid Packet Length for data sent.	
	The number of bytes sent or received does not match the number of bytes specified in the command.	
	No action required. This reference code is logged for error analysis only.	
9041	Invalid Load Type	AJDG301
	The down load was successful, but the wrong type of Licensed Internal Code was loaded. The operation was attempted again but was not successful. Exchange the failing items for the node reporting the fault.	TWRCARD
9042	EEPROM Failure	TWRCARD
	The EEPROM in an SPCN node cannot be written successfully.	
	Exchange the SPCN node reported in the failure.	
9043	Download Failure	TWRCARD
	The Licensed Internal Code download to an SPCN node was completed but was not successful.	
	Exchange the failing SPCN node.	
9046	QDS Packet Sequence Error	TWRCARD
	The Packet Sequence number is wrong. The download was stopped.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9047	QDS Block Sequence Error	TWRCARD
	The Block Sequence number is wrong. The download was stopped.	
9048	The SPCN ROS and EEPROM LIC is not compatable.	TWRCARD
	The LIC levels in the nodes ROS and EEPROM are not compatible.	AJDG301
	Exchange the failing items for the failing node.	
9080	Undefined Status Code	TWRCARD
	An SPCN node returned an unknown status code.	BACKPLN
	Exchange the failing SPCN node.	
90F0	A frame was dropped from the SPCN configuration.	TWRCARD
	A frame was dropped from the SPCN configuration. This is usually caused by a loss of ac power or a problem with the frame-to-frame cable.	CBLALL
90F1	A frame was added to the SPCN configuration.	
	No action required. This reference code is logged for information only.	
9100	Battery capacity test completed.	
	No action required. This reference code is logged for information only.	
9101	VLIC-SPCN Timeout	TWRCARD
	A Licensed Internal Code timeout occurred. The SPCN failed to respond to a Licensed Internal Code command.	CTLPNL SVCPROC
9102	Assign Permanent Address command failure	TWRCARD
	A node failed to perform an Assign Permanent Address command.	
9103	Download Initialize Timeout	TWRCARD
	An SPCN node failed to enter the download state after an Initialize for Download command.	
	Exchange the failing SPCN node.	
9104	Download Completion Timeout	TWRCARD
	An SPCN node failed to leave the download state.	
	Exchange the failing SPCN node.	
9105	Load Damaged Timeout	TWRCARD
	An SPCN node failed to enter the operational state.	
	Exchange the failing SPCN node.	
9106	An SPCN LID was not found.	
	No action required. This reference code is logged for information only.	
9107	An SPCN microcode download is required.	
	No action required. This reference code is logged for error analysis only.	
9108	A status change occured in one of the SPCN nodes.	
	No action required. This reference code is logged for information only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9109	Licensed Internal Code part number is not correct.	TWRCARD
	The AROS part number field was not updated to the correct level after the system attempted to load new Licensed Internal Code.	
9110	Battery Power Unit capacity test failed.	BATRY
	The battery power unit was not able to pass the capacity test.	
9111	SPCN is too large for VLIC.	AJDG301
	There are more nodes in the network than VLIC can service.	
9112	Primary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the primary SPCN node is damaged. The reload failed because the code could not be found.	
9113	Secondary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the secondary SPCN node is damaged. The reload failed because the code could not be found.	
9114	Frame SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for a SPCN node is damaged. The reload failed because the code could not be found.	
9115	SPCN Command rejected by the Service Processor.	
	The service processor rejected an SPCN command from the Licensed Internal Code.	
	No action required. This reference code is logged for information only.	
9116	SPCN - Control Panel interface failure.	
	The SPCN to control panel interface is not working.	
9117	SPCN - Control Panel interface is now working.	
	The SPCN to control panel interface is now working.	
	No action required. This reference code is logged for information only.	
91DD	All SPCN Downloads Complete	
9212	Frame Address field not valid.	TWRCARD
	A Licensed Internal Code command had a frame address that is not valid.	
	Exchange the failing items for the failing node.	
9213	Invalid Address status, secondary node.	TWRCARD
	The address in the SPCN command does not match the assigned address of the secondary node.	
	Exchange the failing items for the failing node.	
9214	Invalid Address Mode status	TWRCARD
	Invalid Address Mode occurred during Frame Command processing.	AJDG301
9215	Invalid Frame Command status	TWRCARD
	Invalid Frame Command occurred during Frame Command processing.	AJDG301

Description/Action Perform all actions before exchanging Failing Items	Failing Item
System Unit SPCN Port Fault status.	TWRCARD AJDG301
System Unit Port Fault occurred during Command processing.	
Address Unassigned status	TWRCARD AJDG301
	TWRCARD
	CBLALL
	TWRCARD
	CBLALL
An SPCN secondary node to frame communications failure occurred during Command processing.	
Intrarack Communications Failure	TWRCARD
An SPCN frame to secondary node communications failure occurred during Command processing.	CBLALL
Unsupported Packet Size status	TWRCARD
Unsupported Packet Size occurred during STF and Secondary Node Command processing.	CTLPNL SVCPROC
SPCN Secondary Node Timeout status	TWRCARD
An SPCN Secondary Node Timeout occurred during Command processing.	AJDG301 CBLALL
If the failing secondary node is in a 9337, go to the "Analyzing Problems" section in the 9337 Disk Array Service Information manual.	
Frame Timeout status	TWRCARD CBLALL
An SPCN Frame Node Timeout occurred during Network post processing.	
Secondary Node Fault	TWRCARD
An SPCN Secondary Node Fault occurred during Command processing.	AJDG301
Frame Node Fault	TWRCARD
An internal error in the SPCN frame node provents the running of a Frame	AJDG301
command.	
ASA Failure	TWRCARD
The frame address returned by a secondary node does not match the address of the frame.	AJDG301
Invalid Packet Length for data sent.	AJDG301
	TWRCARD
	CBLALL
* 	AJDG301
Too many responses were received during System Frame command processing.	TWRCARD
Response Overrun	CBLALL
Response Overrun occurred during System Frame processing.	AJDG301 TWRCARD
No Free Entries	CBLALL
	AJDG301
	System Unit SPCN Port Fault status.         System Unit SPCN Port Fault status.         System Unit Port Fault occurred during Command processing.         Address Unassigned status         A secondary node has no address assigned during Command processing.         Frame-to-Frame Communications Failure         A frame-to-frame communications failure occurred during STF processing.         Intrarack Communications Failure         An SPCN secondary node to frame communications failure occurred during Command processing.         Intrarack Communications Failure         An SPCN frame to secondary node communications failure occurred during Command processing.         Unsupported Packet Size status         Unsupported Packet Size occurred during STF and Secondary Node Command processing.         SPCN Secondary Node Timeout status         An SPCN Secondary node is in a 9337, go to the "Analyzing Problems" section in the 9337 Disk Array Service Information manual.         Frame Timeout status         An SPCN Frame Node Timeout occurred during Command processing.         Secondary Node Fault         An SPCN Frame Node Timeout occurred during Command processing.         Secondary Node Fault         An SPCN Frame Node Timeout occurred during Command processing.         Secondary Node Fault         An internal error in the SPCN frame node prevents the running of a Frame command.         ASA Failure

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9283	ARA Failure An Assign Frame Address Failure occurred during ARA Preprocessing.	TWRCARD AJDG301
9284	Undefined Status occurred during Frame or STF processing.	TWRCARD AJDG301
9285	BCC Fault A BCC Error was detected during Network post processing.	TWRCARD
9286	Length Check Error. Length Check occurred during SPCN post processing.	TWRCARD AJDG301
9287	Undefined status Undefined Status occurred during Command processing.	TWRCARD AJDG301
9288	Configuration Error A configuration error was detected during System Frame processing.	TWRCARD AJDG301
9289	Invalid Packet Length for data sent. Invalid Packet Length occurred for data exchanged.	AJDG301 TWRCARD
C62E	SPCN Network Fault An SPCN frame-to-frame communication failure was detected. SRNPU or POSORMU.	TWRCARD CBLALL
CB15	EEPROM Failure	TWRCARD

## Table 2. SPCN failing items for Models 800, 810, and 825:

Failing Item	Description	Document Description
16G6379	I/O Regulator.	Repair and Parts
16G8716	Cable assembly	Repair and Parts
16G8717	Cable assembly	Repair and Parts
16G8748	Planar board	Repair and Parts
16G8760	System Expansion Unit Board assembly with RAID	Repair and Parts
16G8763	Planar board	Repair and Parts
16G8769	Cable Carrier, System Unit with RAID.	Repair and Parts
16G8771	Cable Carrier, System Expansion Unit with RAID.	Repair and Parts
16G8806	Planar board	Repair and Parts
16G8807	System Unit Board assembly model G46 with RAID	Repair and Parts
17G0566	System Unit Control Panel	Repair and Parts
17G0567	System Unit Control Panel Card Assembly	Repair and Parts
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0574	Expansion Unit Control Panel Card Assembly	Repair and Parts

Failing Item	Description	Document Description
17G1150	Power Supply	Repair and Parts
17G1150	Feature Power Supply	Repair and Parts
17G1179	Current Share I/O Regulator	Repair and Parts
17G1189	I/O Regulator.	Repair and Parts
17G1199	3.6V I/O Regulator	Repair and Parts
17G1209	I/O Regulator.	Repair and Parts
17G2539	Cable Carrier, 9406 System Unit.	Repair and Parts
17G2598	Power regulator card	Repair and Parts
17G2695	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5521	Blower Assembly	Repair and Parts
21F5620	Regulator in 280X Disk Unit.	Repair and Parts
21F5650	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5680	AC Module, SPCN Secondary node.	Repair and Parts
21F5774	Cable Carrier, 9406 System Unit.	Repair and Parts
21F5793	Fan assembly.	Repair and Parts
21F8872	5032 Cable Carrier.	Repair and Parts
21F8888	Expansion Unit/Extension Unit Control Panel	Repair and Parts
21F8888	Control Panel on 5032 box.	Repair and Parts
21F8890	D-SE Converter Module.	Repair and Parts
21F9052	Card Enclosure, 9406 System Unit.	Repair and Parts
21F9215	I/O Regulator.	Repair and Parts
21F9216	3.6V Regulator, 9406 System Unit.	Repair and Parts
21F9316	Power Control Compartment (PCC)	Repair and Parts
21F9362	SPCN Port Cable	Repair and Parts
21F9380	Battery Power Unit	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9530	DC Bulk Module.	Repair and Parts
21F9631	Fan assembly.	Repair and Parts
46G3510	Fan assembly.	Repair and Parts
46G3587	Blower Assembly	Repair and Parts
46G3626	Contol Panel FRU Kit	Repair and Parts
46G3680	AC Module	Repair and Parts
46G3890	Internal Battery Power Unit	Repair and Parts
6462417	Rack Control Panel cable.	Repair and Parts
73F9166	System Unit Board assembly model G46 without RAID	Repair and Parts
74F1541	Card Enclosure, 9406 System Unit.	Repair and Parts
74F1542	Card Enclosure, 9406 System Unit.	Repair and Parts
74F1760	DC Bulk Module.	Repair and Parts
74F1919	I/O Regulator.	Repair and Parts

Failing Item	Description	Document Description
74F1922	3.6V Regulator, 9406 System Unit.	Repair and Parts
85F8220	Base Power Supply	Repair and Parts
85F8250	Feature Power Supply	Repair and Parts
86G7660	AC Module	Repair and Parts
86G7712	External Battery Power Unit cable	Repair and Parts
86G7714	External Battery Power Unit	Repair and Parts
86G7750	Battery Power Unit Charger	Repair and Parts
86G8020	Battery Power Unit Charger	Repair and Parts
86G8040	Battery Power Unit	Repair and Parts
87G6029	Regulator.	Repair and Parts
87G6060	Battery Power Unit	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6235	SPCN Frame-to-Frame or PCC port cable.	Repair and Parts
87G6300	AC Module	Repair and Parts
90H6287	Optical Converter	Repair and Parts
90H6360	Cable assembly	Repair and Parts
ACMODUL	AC Module	See the service documentation for instructions.
AIRMOVR	Fan and Blower assemblies	See the service documentation for instructions.
AJDG301	Vertical Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Rack SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Secondary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ04	System Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ05	Expansion Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
ALTMANL	Alternate Manual Required	See the service documentation for instructions.
BACKPLN	Back Plane Unit	See the service documentation for instructions.
BATCHGR	Battery Power Unit Charger	See the service documentation for instructions.
BATRY	Battery Power Unit	See the service documentation for instructions.
BKSPCN	SPCN card	See the service documentation for instructions.
BUSPWR	Domain 29V Bus	See the service documentation for instructions.
CBLALL	Cable Failure	See the service documentation for instructions.
CLKCARD	Clock card	See the service documentation for instructions.
CTLPNL	Control Panel	See the service documentation for instructions.
DISKDRV	Disk Unit Power regulator	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk Unit Power regulator	See the service documentation for instructions.
DISKTRY	Disk Unit or Removable Media Device	Repair and Parts
DMREG	Domain Regulator	See the service documentation for instructions.
I2CBUS	I2C Bus Part	See the service documentation for instructions.

Failing Item	Description	Document Description
IDPART	Vital Product Data Parts	See the service documentation for instructions.
INTRLCK	Interlock part	See the service documentation for instructions.
PGDPART	Power Good Part	See the service documentation for instructions.
PWROC	Power Supply overcurrent	See the service documentation for instructions.
PWRREG	Regulator.	See the service documentation for instructions.
PWRSPLY	Power Supply	See the service documentation for instructions.
RMDEV	Disk Unit or Removable Media Device	See the service documentation for instructions.
SPNLCRD	SPCN panel card	See the service documentation for instructions.
SVCPROC	Service Processor Card	See the service documentation for instructions.
TWRCARD	Card enclosure or backplane	See the service documentation for instructions.
UPSUNIT	UPS unit part	See the service documentation for instructions.
VPDPART	VPD Communication Part	See the service documentation for instructions.

# (1xxx) SPCN reference codes for Models 830, 840, SB2, and SB3

For details on the Failing Item column entries, see the SPCN Failing Items Detail table, which follows the Reference Code table below.

**Note:** On Models 840/SB3, the C in the SRC (1xxC xxxx) indicates that the failure is on the processor frame, not on the FC 9079 Base I/O Tower.

Table 1. SPCN reference codes for Models 830, 840, SB2, and SB3:

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
00A0	SPCN BATs in process	TWRCARD
	No action required. This reference code is logged for information only. If this reference code is present for more than 1 minute, exchange the failing items.	
00A1	Regulator 1 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A2	Regulator 2 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A3	Regulator 3 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A4	Regulator 4 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A5	Regulator 5 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A6	Regulator 6 has been turned off by system	
	No action required. This reference code is logged for information only.	
00A7	The system is running on the Battery Power Unit.	
	No action required. This reference code is logged for information only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
00A8	The Battery Power Unit is not fully charged.	
	No action required. This reference code is logged for information only.	
00A9	Battery Power Unit test is in process.	
	No action required. This reference code is logged for information only.	
00AA	Download in process	
	No action required. This reference code is logged for information only.	
00AB	Rack UEPO switch is OFF.	TWRCARD
	Informational reference code.	CTLPNL 6462417
	The UEPO switch must be returned to the On position to power on the rack.	
00AC	Detected AC loss	ACMODUL
	If system powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	
00BA	The system is running on the Battery Power Unit.	
	No action required. This reference code is displayed for information only.	
00BC	Battery Power Unit test is in process.	
	No action required. This reference code is displayed for information only.	
00CA	CPM power down is complete.	
	No action required. This reference code is displayed for information only.	
00EF	Remote EPO switch is OFF	
0100	Install Disk Unit 1	
	Concurrent maintenance informational reference code.	
0101	Install Disk Unit 2	
	Concurrent maintenance informational reference code.	
0102	Install Disk Unit 3	
	Concurrent maintenance informational reference code.	
0103	Install Disk Unit 4	
	Concurrent maintenance informational reference code.	
0104	Install Disk Unit 5	
	Concurrent maintenance informational reference code.	
0105	Install Disk Unit 6	
	Concurrent maintenance informational reference code.	
0106	Install Disk Unit 7	
	Concurrent maintenance informational reference code.	
0107	Install Disk Unit 8	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0108	Install Disk Unit K1	
	Concurrent maintenance informational reference code.	
0109	Install Disk Unit K2	
	Concurrent maintenance informational reference code.	
010A	Install Disk Unit K3	
	Concurrent maintenance informational reference code.	
010B	Install Disk Unit K4	
	Concurrent maintenance informational reference code.	
010C	Install Disk Unit K5	
	Concurrent maintenance informational reference code.	
010D	Install Disk Unit K6	
0102		
010E	Concurrent maintenance informational reference code. Install Disk Unit K7	
UIUE		
	Concurrent maintenance informational reference code.	
010F	Install Disk Unit K8	
	Concurrent maintenance informational reference code.	
0110	Install Disk Unit K9	
	Concurrent maintenance informational reference code.	
0111	Install Disk Unit K10	
	Concurrent maintenance informational reference code.	
0112	Install Disk Unit K11	
	Concurrent maintenance informational reference code.	
0113	Install Disk Unit K12	
	Concurrent maintenance informational reference code.	
0114	Install Disk Unit K13	
	Concurrent maintenance informational reference code.	
0115	Install Disk Unit K14	
	Concurrent maintenance informational reference code.	
0116	Install device 1	
	Concurrent maintenance informational reference code.	
0117	Install device 2	
·/		
0118	Concurrent maintenance informational reference code. Install Disk Unit 9	
0110		
0110	Concurrent maintenance informational reference code.	
0119	Install Disk Unit 10	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
011A	Install Disk Unit 11	
	Concurrent maintenance informational reference code.	
011B	Install Disk Unit 12	
	Concurrent maintenance informational reference code.	
011C	Install device 3	
	Concurrent maintenance informational reference code.	
011D	Install Disk Unit K15	
	Concurrent maintenance informational reference code.	
011E	Install Disk Unit K16	
	Concurrent maintenance informational reference code.	
011F	Install Device 4	
	Concurrent maintenance informational reference code.	
0120	Install Disk Unit K17	
	Concurrent maintenance informational reference code.	
0121	Install Disk Unit K18	
	Concurrent maintenance informational reference code.	
0122	Install Disk Unit K19	
	Concurrent maintenance informational reference code.	
0123	Install Disk Unit K20	
	Concurrent maintenance informational reference code.	
0124	Install Disk Unit K21	
0124		
0125	Concurrent maintenance informational reference code. Install Disk Unit K22	
0125		
012(	Concurrent maintenance informational reference code.	
0126	Install Disk Unit K23	
0105	Concurrent maintenance informational reference code.	
0127	Install Disk Unit K24	
	Concurrent maintenance informational reference code.	
0128	Install Disk Unit K25	
	Concurrent maintenance informational reference code.	
0129	Install Disk Unit K26	
	Concurrent maintenance informational reference code.	
012A	Install Disk Unit K27	
	Concurrent maintenance informational reference code.	
012B	Install Disk Unit K28	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
012C	Install Disk Unit K29	
	Concurrent maintenance informational reference code.	
012D	Install Disk Unit K30	
	Concurrent maintenance informational reference code.	
012E	Install Disk Unit K31	
	Concurrent maintenance informational reference code.	
012F	Install Disk Unit K32	
	Concurrent maintenance informational reference code.	
01AC	Detected AC loss	ACMODUL
	If system powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	
0200	Remove Disk Unit 1	
	Concurrent maintenance informational reference code.	
0201	Remove Disk Unit 2	
	Concurrent maintenance informational reference code.	
0202	Remove Disk Unit 3	
	Concurrent maintenance informational reference code.	
0203	Remove Disk Unit 4	
	Concurrent maintenance informational reference code.	
0204	Remove Disk Unit 5	
	Concurrent maintenance informational reference code.	
0205	Remove Disk Unit 6	
0_00	Concurrent maintenance informational reference code.	
0206	Remove Disk Unit 7	
0207	Concurrent maintenance informational reference code. Remove Disk Unit 8	
0207		
0208	Concurrent maintenance informational reference code. Remove Disk Unit K1	
0200		
0200	Concurrent maintenance informational reference code.	
0209	Remove Disk Unit K2	
020.4	Concurrent maintenance informational reference code.	
020A	Remove Disk Unit K3	
	Concurrent maintenance informational reference code.	
020B	Remove Disk Unit K4	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
020C	Remove Disk Unit K5	
	Concurrent maintenance informational reference code.	
020D	Remove Disk Unit K6	
	Concurrent maintenance informational reference code.	
020E	Remove Disk Unit K7	
	Concurrent maintenance informational reference code.	
020F	Remove Disk Unit K8	
	Concurrent maintenance informational reference code.	
0210	Remove Disk Unit K9	
	Concurrent maintenance informational reference code.	
0211	Remove Disk Unit K10	
0211		
	Concurrent maintenance informational reference code.	
0212	Remove Disk Unit K11	
	Concurrent maintenance informational reference code.	
0213	Remove Disk unit K12	
	Concurrent maintenance informational reference code.	
0214	Remove Disk Unit K13	
	Concurrent maintenance informational reference code.	
0215	Remove Disk Unit K14	
	Concurrent maintenance informational reference code.	
0216	Remove device 1	
	Concurrent maintenance informational reference code.	
0217	Remove device 2	
	Concurrent maintenance informational reference code.	
0218	Remove Disk Unit 9	
	Concurrent maintenance informational reference code.	
0219	Remove Disk Unit 10	
0217		
021 4	Concurrent maintenance informational reference code.	
021A	Remove Disk Unit 11	
	Concurrent maintenance informational reference code.	
021B	Remove Disk Unit 12	
	Concurrent maintenance informational reference code.	
021C	Remove device 3	
	Concurrent maintenance informational reference code.	
021D	Remove Disk Unit K15	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
021E	Remove Disk Unit K16	
	Concurrent maintenance informational reference code.	
021F	Remove device 4	
	Concurrent maintenance informational reference code.	
0220	Remove Disk Unit K17	
	Concurrent maintenance informational reference code.	
0221	Remove Disk Unit K18	
	Concurrent maintenance informational reference code.	
0222	Remove Disk Unit K19	
	Concurrent maintenance informational reference code.	
0223	Remove Disk Unit K20	
0225		
0004	Concurrent maintenance informational reference code.	
0224	Remove Disk Unit K21	
	Concurrent maintenance informational reference code.	
0225	Remove Disk Unit K22	
	Concurrent maintenance informational reference code.	
0226	Remove Disk Unit K23	
	Concurrent maintenance informational reference code.	
0227	Remove Disk Unit K24	
	Concurrent maintenance informational reference code.	
0228	Remove Disk Unit K25	
	Concurrent maintenance informational reference code.	
0229	Remove Disk Unit K26	
	Concurrent maintenance informational reference code.	
022A	Remove Disk Unit K27	
	Concurrent maintenance informational reference code.	
022B	Remove Disk Unit K28	
0220		
022C	Concurrent maintenance informational reference code. Remove Disk Unit K29	
0220		
0000	Concurrent maintenance informational reference code.	
022D	Remove Disk Unit K30	
	Concurrent maintenance informational reference code.	
022E	Remove Disk Unit K31	
	Concurrent maintenance informational reference code.	
022F	Remove Disk Unit K32	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
02AC	Detected AC loss	ACMODUL
	If system powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	
0300	Disk Unit 1 regulator has been turned on	
	Installation of disk unit 1 is complete, and the regulator is turned on.	
0301	Disk Unit 2 regulator has been turned on	
	Installation of disk unit 2 is complete, and the regulator is turned on.	
0302	Disk Unit 3 regulator has been turned on	
	Installation of disk unit 3 is complete, and the regulator is turned on.	
0303	Disk Unit 4 regulator has been turned on	
	Installation of disk unit 4 is complete, and the regulator is turned on.	
0304	Disk Unit 5 regulator has been turned on	
	Installation of disk unit 5 is complete, and the regulator is turned on.	
0305	Disk Unit 6 regulator has been turned on	
	Installation of disk unit 6 is complete, and the regulator is turned on.	
0306	Disk Unit 7 regulator has been turned on	
	Installation of disk unit 7 is complete, and the regulator is turned on.	
0307	Disk Unit 8 regulator has been turned on	
	Installation of disk unit 8 is complete, and the regulator is turned on.	
0308	Disk Unit K1 regulator has been turned on	
	Installation of disk unit K1 is complete, and the regulator is turned on.	
0309	Disk Unit K2 regulator has been turned on	
	Installation of disk unit K2 is complete, and the regulator is turned on.	
030A	Disk Unit K3 regulator has been turned on	
00011		
030B	Installation of disk unit K3 is complete, and the regulator is turned on.Disk Unit K4 regulator has been turned on	
0000		
030C	Installation of disk unit K4 is complete, and the regulator is turned on.Disk Unit K5 regulator has been turned on	
0000		
030D	Installation of disk unit K5 is complete, and the regulator is turned on.Disk Unit K6 regulator has been turned on	
0000		
020E	Installation of disk unit K6 is complete, and the regulator is turned on.	
030E	Disk Unit K7 regulator has been turned on	
0005	Installation of disk unit K7 is complete, and the regulator is turned on.	
030F	Disk Unit K8 regulator has been turned on	
	Installation of disk unit K8 is complete, and the regulator is turned on.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0310	Disk Unit K9 regulator has been turned on	
	Installation of disk unit K9 is complete, and the regulator is turned on.	
0311	Disk Unit K10 regulator has been turned on	
	Installation of disk unit K10 is complete, and the regulator is turned on.	
0312	Disk Unit K11 regulator has been turned on	
	Installation of disk unit K11 is complete, and the regulator is turned on.	
0313	Disk Unit K12 regulator has been turned on	
	Installation of disk unit K12 is complete, and the regulator is turned on.	
0314	Disk Unit K13 regulator has been turned on	
	Installation of disk unit K13 is complete, and the regulator is turned on.	
0315	Disk Unit K14 regulator has been turned on	
	Installation of disk unit K14 is complete, and the regulator is turned on.	
0316	Device 1 regulator has been turned on	
	Installation of device 1 is complete, and the regulator is turned on.	
0317	Device 2 regulator has been turned on	
	Installation of device 2 is complete, and the regulator is turned on.	
0318	Disk Unit 9 regulator has been turned on	
	Installation of disk unit 9 is complete, and the regulator is turned on.	
0319	Disk Unit 10 regulator has been turned on	
	Installation of disk unit 10 is complete, and the regulator is turned on.	
031A	Disk Unit 11 regulator has been turned on	
	Installation of disk unit 11 is complete, and the regulator is turned on.	
031B	Disk Unit 12 regulator has been turned on	
	Installation of disk unit 12 is complete, and the regulator is turned on.	
031C	Device 3 regulator has been turned on	
	Installation of device 3 is complete, and the regulator is turned on.	
031D	Disk Unit K15 regulator has been turned on	
	Installation of disk unit K15 is complete, and the regulator is turned on.	
031E	Disk Unit K16 regulator has been turned on	
031F	Installation of disk unit K16 is complete, and the regulator is turned on.Device 4 regulator has been turned on	
0320	Installation of device 4 is complete, and the regulator is turned on.Disk Unit K17 regulator has been turned on	
0020		
0321	Installation of disk unit K17 is complete, and the regulator is turned on.	
0021	Disk Unit K18 regulator has been turned on	
	Installation of disk unit K18 is complete, and the regulator is turned on.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0322	Disk Unit K19 regulator has been turned on	
	Installation of disk unit K19 is complete, and the regulator is turned on.	
0323	Disk Unit K20 regulator has been turned on	
	Installation of disk unit K20 is complete, and the regulator is turned on.	
0324	Disk Unit K21 regulator has been turned on	
0021		
	Installation of disk unit K21 is complete, and the regulator is turned on.	
0325	Disk Unit K22 regulator has been turned on	
	Installation of disk unit K22 is complete, and the regulator is turned on.	
0326	Disk Unit K23 regulator has been turned on	
	Installation of disk unit K23 is complete, and the regulator is turned on.	
0327	Disk Unit K24 regulator has been turned on	
	Installation of disk unit K24 is complete, and the regulator is turned on.	
0328	Disk Unit K25 regulator has been turned on	
0329	Installation of disk unit K25 is complete, and the regulator is turned on.	
0329	Disk Unit K26 regulator has been turned on	
	Installation of disk unit K26 is complete, and the regulator is turned on.	
032A	Disk Unit K27 regulator has been turned on	
	Installation of disk unit K27 is complete, and the regulator is turned on.	
032B	Disk Unit K28 regulator has been turned on	
	Installation of disk unit K28 is complete, and the regulator is turned on.	
032C	Disk Unit K29 regulator has been turned on	
	Installation of disk unit K29 is complete, and the regulator is turned on.	
032D	Disk Unit K30 regulator has been turned on	
032E	Installation of disk unit K30 is complete, and the regulator is turned on.Disk Unit K31 regulator has been turned on	
052E		
	Installation of disk unit K31 is complete, and the regulator is turned on.	
032F	Disk Unit K32 regulator has been turned on	
	Installation of disk unit K32 is complete, and the regulator is turned on.	
0400	Removal of Disk Unit 1 is complete	
0401	Removal of Disk Unit 2 is complete	
0402	Removal of Disk Unit 3 is complete	
0403	Removal of Disk Unit 4 is complete	
0404	Removal of Disk Unit 5 is complete	
0405	Removal of Disk Unit 6 is complete	
0406	Removal of Disk Unit 7 is complete	
0407	Removal of Disk Unit 8 is complete	
0408	Removal of Disk Unit K1 is complete	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
)409	Removal of Disk Unit K2 is complete	
040A	Removal of Disk Unit K3 is complete	
040B	Removal of Disk Unit K4 is complete	
040C	Removal of Disk Unit K5 is complete	
040D	Removal of Disk Unit K6 is complete	
040E	Removal of Disk Unit K7 is complete	
040F	Removal of Disk Unit K8 is complete	
0410	Removal of Disk Unit K9 is complete	
0411	Removal of Disk Unit K10 is complete	
0412	Removal of Disk Unit K11 is complete	
0413	Removal of Disk Unit K12 is complete	
0414	Removal of Disk Unit K13 is complete	
0415	Removal of Disk Unit K14 is complete	
0416	Removal of device 1 is complete	
0417	Removal of device 2 is complete	
0418	Removal of Disk Unit 9 is complete	
0419	Removal of Disk Unit 10 is complete	
041A	Removal of Disk Unit 11 is complete	
041B	Removal of Disk Unit 12 is complete	
041C	Removal of device 3 is complete	
041D	Removal of Disk Unit K15 is complete	
041E	Removal of Disk Unit K16 is complete	
041F	Removal of device 4 is complete	
0500	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit 1, and the bus was released.	
	You must reinitialize the operation to continue.	
0501	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit 2, and the bus was released.	
	You must reinitialize the operation to continue.	
0502	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit 3, and the bus was released.	
	You must reinitialize the operation to continue.	
0503	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 4, and the bus was released.	
	You must reinitialize the operation to continue.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0504	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 5, and the bus was released.	
	You must reinitialize the operation to continue.	
0505	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 6, and the bus was released.	
	You must reinitialize the operation to continue.	
0506	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 7, and the bus was released.	
	You must reinitialize the operation to continue.	
0507	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 8, and the bus was released.	
	You must reinitialize the operation to continue.	
0508	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K1, and the bus was released.	
	You must reinitialize the operation to continue.	
0509	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K2, and the bus was released.	
	You must reinitialize the operation to continue.	
050A	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K3, and the bus was released.	
	You must reinitialize the operation to continue.	
050B	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K4, and the bus was released.	
	You must reinitialize the operation to continue.	
050C	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K5, and the bus was released.	
	You must reinitialize the operation to continue.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
050D	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K6, and the bus was released.	
	You must reinitialize the operation to continue.	
050E	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K7, and the bus was released.	
	You must reinitialize the operation to continue.	
050F	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K8, and the bus was released.	
	You must reinitialize the operation to continue.	
0510	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K9, and the bus was released.	
	You must reinitialize the operation to continue.	
0511	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K10, and the bus was released.	
	You must reinitialize the operation to continue.	
0512	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K11, and the bus was released.	
	You must reinitialize the operation to continue.	
0513	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K12, and the bus was released.	
	You must reinitialize the operation to continue.	
0514	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K13, and the bus was released.	
	You must reinitialize the operation to continue.	
0515	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K14, and the bus was released.	
	You must reinitialize the operation to continue.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0516	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of device 1, and the bus was released.	
	You must reinitialize the operation to continue.	
0517	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of device 2, and the bus was released.	
	You must reinitialize the operation to continue.	
0518	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 9, and the bus was released.	
	You must reinitialize the operation to continue.	
0519	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 10, and the bus was released.	
	You must reinitialize the operation to continue.	
051A	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 11, and the bus was released.	
	You must reinitialize the operation to continue.	
051B	Timeout, no action detected. Reinitialize the operation.	
	No action was detected for the installation or removal of disk unit 12, and the bus was released.	
	You must reinitialize the operation to continue.	
051C	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of device 3, and the bus was released.	
	You must reinitialize the operation to continue.	
051D	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K15, and the bus was released.	
	You must reinitialize the operation to continue.	
051E	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of disk unit K16, and the bus was released.	
	You must reinitialize the operation to continue.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
051F	Timeout, no action detected. Reinitialize the operation	
	No action was detected for the installation or removal of device 4, and the bus was released.	
	You must reinitialize the operation to continue.	
0700	Timeout, no action detected. Reinitialize the operation	
	Disk unit 1 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0701	Timeout, no action detected. Reinitialize the operation	
	Disk unit 2 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0702	Timeout, no action detected. Reinitialize the operation	
	Disk unit 3 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
	You must reinitialize the operation to continue.	
0703	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 4 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0704	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 5 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0705	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 6 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0706	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 7 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0707	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 8 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0708	Timeout, no action detected. Reinitialize the operation	
	Disk unit K1 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0709	Timeout, no action detected. Reinitialize the operation	
	Disk unit K2 was powered off but not removed.	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
070A	Timeout, no action detected. Reinitialize the operation	
	Disk unit K3 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070B	Timeout, no action detected. Reinitialize the operation	
	Disk unit K4 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070C	Timeout, no action detected. Reinitialize the operation	
	Disk unit K5 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070D	Timeout, no action detected. Reinitialize the operation	
	Disk unit K6 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070E	Timeout, no action detected. Reinitialize the operation	
	Disk unit K7 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
070F	Timeout, no action detected. Reinitialize the operation	
	Disk unit K8 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0710	Timeout, no action detected. Reinitialize the operation	
	Disk unit K9 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0711	Timeout, no action detected. Reinitialize the operation	
	Disk unit K10 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0712	Timeout, no action detected. Reinitialize the operation	
	Disk unit K11 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0713	Timeout, no action detected. Reinitialize the operation	
	Disk unit K12 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0714	Timeout, no action detected. Reinitialize the operation	
	Disk unit K13 was powered off but not removed.	
	Concurrent maintenance informational reference code.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0715	Timeout, no action detected. Reinitialize the operation	
	Disk unit K14 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0716	Timeout, no action detected. Reinitialize the operation	
	Device 1 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0717	Timeout, no action detected. Reinitialize the operation	
	Device 2 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0718	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 9 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0719	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 10 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071A	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 11 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071B	Timeout, no action detected. Reinitialize the operation.	
	Disk unit 12 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071C	Timeout, no action detected. Reinitialize the operation	
	Device 3 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071D	Timeout, no action detected. Reinitialize the operation	
	Disk unit K15 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071E	Timeout, no action detected. Reinitialize the operation	
	Disk unit K16 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
071F	Timeout, no action detected. Reinitialize the operation	
	Device 4 was powered off but not removed.	
	Concurrent maintenance informational reference code.	
0800	Blower B01 powered off for concurrent maintenance	
0801	Blower B02 powered off for concurrent maintenance	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0802	Blower B03 powered off for concurrent maintenance	
0803	Blower B04 powered off for concurrent maintenance	
0900	Power Supply P01 powered off for concurrent maintenance	
0901	Power Supply P02 powered off for concurrent maintenance	
0902	Power Supply P03 powered off for concurrent maintenance	
0903	Power Supply P04 powered off for concurrent maintenance	
0904	Power Supply P05 powered off for concurrent maintenance	
0905	Power Supply P06 powered off for concurrent maintenance	
0F0F	AC Module Failure	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F12	Undefined box ID, EEPROM test failed	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F13	Undefined box ID, Code type mismatch	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F1F	Undefined box ID, LCD test failed	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F2C	Unknown box ID	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F2D	Unknown box ID, Code level mismatch.	TWRCARD
	The SPCN node cannot determine the machine type of the box in which it is installed.	BACKPLN 21F9429
0F2E	SPCN Network Fault	TWRCARD
	The box ID is not defined. A network communications failure occurred.	BACKPLN 21F9429
102B	PCC Overcurrent	TWRCARD
	The power control compartment is causing an over current condition in the FC 5032 Removable Storage Unit power system.	21F5680 21F5793 21F9362
	The ac module and the SPCN port cable should be exchanged together.	
1100	Power Supply P01 error	PWRSPLY
	A fault detection failure occurred for Power Supply P01.	ACMODUL BKSPCN CBLALL
1101	Power Supply P02 error	PWRSPLY
	A fault detection failure occurred for Power Supply P02.	ACMODUL BKSPCN CBLALL

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1102	Power Supply P03 error A fault detection failure occurred for Power Supply P03.	PWRSPLY ACMODUL BKSPCN CBLALL
1103	Power Supply P04 error A fault detection failure occurred for Power Supply P04.	PWRSPLY ACMODUL BKSPCN CBLALL
1104	Power Supply P05 error A fault detection failure occured for Power Supply P05.	PWRSPLY ACMODUL BKSPCN CBLALL
1105	Power Supply P06 error A fault detection failure occured for Power Supply P06.	PWRSPLY ACMODUL BKSPCN CBLALL
1108	Regulator R01 error A fault detection failure occurred for Regulator R01.	PWRREG BKSPCN
1109	Regulator R02 error A fault detection failure occurred for Regulator R02.	PWRREG BKSPCN
110A	Regulator R03 error A fault detection failure occurred for Regulator R03.	PWRREG BKSPCN
110B	Regulator R04 error A fault has been detected for Regulator R04.	PWRREG BKSPCN
110C	Regulator R05 errorA fault detection failure occurred for Regulator R05.	PWRREG BKSPCN
110D	Regulator R06 error A fault detection failure occurred for Regulator R06.	PWRREG BKSPCN
110E	Regulator R07 error A fault detection failure occurred for Regulator R07.	PWRREG BKSPCN
110F	Regulator R08 errorA fault detection failure occurred for Regulator R08.	PWRREG BKSPCN
1110	Regulator R09 error A fault detection failure occurred for regulator R09.	PWRREG BKSPCN
1111	Regulator R10 error A fault detection failure occurred for Regulator R10.	PWRREG BKSPCN
1112	Regulator R11 error A fault detection failure occurred for Regulator R11.	PWRREG BKSPCN
1113	Regulator R12 error         A fault detection failure occurred for Regulator R12.	BKSPCN BACKPLN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1114	Regulator R13 error	BKSPCN BACKPLN
	A fault detection failure occurred for Regulator R13.	
1115	Regulator R14 error A fault detection failure occurred for Regulator R14.	BKSPCN BACKPLN
1116	Regulator R15 error	BKSPCN
1110		BACKPLN
	A fault detection failure occurred for Regulator R15.	
1117	Regulator R16 error A fault detection failure occurred for Regulator R16.	BKSPCN BACKPLN
1118	Regulator R17 error	BKSPCN
		BACKPLN
	A fault detection failure occurred for Regulator R17.	
1119	Regulator R18 error A fault detection failure occurred for Regulator R18.	BKSPCN BACKPLN
111A	Regulator R19 error	BKSPCN
	A fault detection failure occurred for Regulator R19.	BACKPLN
111B	Regulator R20 error	PWRREG BKSPCN
	A fault detection failure occurred for Regulator R20.	
111C	Regulator R21 error A fault detection failure occurred for Regulator R21.	PWRREG BKSPCN
111D	Regulator R22 error	PWRREG
1110		BKSPCN
	A fault detection failure occurred for Regulator R22.	
111E	Regulator R23 error A fault detection failure occurred for Regulator R23.	PWRREG BKSPCN
1200	29V Buss Fault	BUSPWR
1200		BKSPCN
	A 29V Bus fault has been detected.	
1201	3.3V Memory 2 Control Regulator Fault	DMREG BKSPCN
	A 3.3V Memory 2 Control Regulator fault has been detected.	DIGICIV
1202	2.5V Memory Control Regulator Fault	DMREG
	A 2.5V Memory Control Regulator fault has been detected.	BKSPCN
1203	Cache Regulator Fault	DMREG
	A Cache Regulator fault has been detected.	BKSPCN
1204	3.3V Memory 1 Control Regulator Fault	DMREG
	A 3.3V Memory 1 Control Regulator fault has been detected.	BKSPCN
1205	Processor 1 Regulator Fault	DMREG
	A Processor 1 Regulator fault has been detected.	BKSPCN
1206	Processor 2 Regulator Fault	DMREG
	A Processor 2 Regulator fault has been detected.	BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1207	Clock Regulator Fault	DMREG BKSPCN
	.A Clock Regulator fault has been detected.	
1300	Power Supply P01 Fault A fault has been detected for Power Supply P01.	PWRSPLY BKSPCN
1301	Power Supply P02 Fault	PWRSPLY
1501		BKSPCN
	A fault has been detected for Power Supply P02.	
1302	Power Supply P03 Fault	PWRSPLY BKSPCN
	A fault has been detected for Power Supply P03.	DRSICI
1303	Power Supply P04 Fault	PWRSPLY
	A fault has been detected for Power Supply P04.	BKSPCN
1304	Power Supply P05 Fault	PWRSPLY
		BKSPCN
1005	A fault has been detected for Power Supply P05.	
1305	Power Supply P06 Fault	PWRSPLY BKSPCN
	A fault has been detected for Power Supply P06.	
1308	Regulator R01 Fault	PWRREG
	A fault has been detected for Regulator R01.	BKSPCN
1309	Regulator R02 Fault	PWRREG
	A fault has been detected for Regulator R02.	BKSPCN
130A	Regulator R03 Fault	PWRREG
		BKSPCN
130B	A fault has been detected for Regulator R03. Regulator R04 Fault	PWRREG
1500		BKSPCN
	A fault has been detected for Regulator R04.	
130C	Regulator R05 Fault	PWRREG BKSPCN
	A fault has been detected for Regulator R05.	DIGICIV
130D	Regulator R06 Fault	PWRREG
	A fault has been detected for Regulator R06.	BKSPCN
130E	Regulator R07 Fault	PWRREG
	A fault has been detected for Regulator R07.	BKSPCN
130F	Regulator R08 Fault	PWRREG
1001		BKSPCN
1010	A fault has been detected for Reulator R08.	
1310	Regulator R09 Fault	PWRREG BKSPCN
	A fault has been detected for Regulator R09.	
1311	Regulator R10 Fault	PWRREG
	A fault has been detected for Regulator R10.	BKSPCN
1312	Regulator R11 Fault	PWRREG
		BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1313	Regulator R12 Fault	BKSPCN BACKPLN
	A fault has been detected for Regulator R12.	
1314	Regulator R13 Fault A fault has been detected for Regulator R13.	BKSPCN BACKPLN
1315	Regulator R14 Fault	BKSPCN
1515		BACKPLN
	A fault has been detected for Regulator R14.	
1316	Regulator R15 Fault A fault has been detected for Regulator R15.	BKSPCN BACKPLN
1317	Regulator R16 Fault	BKSPCN
1517		BACKPLN
	A fault has been detected for Regulator R16.	
1318	Regulator R17 Fault A fault has been detected for Regulator R17.	BKSPCN BACKPLN
1319	Regulator R18 Fault	BKSPCN
1519		BACKPLN
	A fault has been detected for Regulator R18.	
131A	Regulator R19 Fault	BKSPCN
	A fault has been detected for Regulator R19.	BACKPLN
131B	Regulator R20 Fault	PWRREG
	A fault has been detected for Regulator R20.	BKSPCN
131C	Regulator R21 Fault	PWRREG
	A fault has been detected for Regulator R21.	BKSPCN
131D	Regulator R22 Fault	PWRREG
151D		BKSPCN
	A fault has been detected for Regulator R22.	
131E	Regulator R23 Fault	PWRREG BKSPCN
	A fault has been detected for Regulator R23.	DIGICIV
1401	3.3V Memory Control 2 Domain Fault	DMREG
	A 3.3V Memory 2 Control Domain fault has been detected.	BKSPCN
1402	2.5V Memory Control Domain Fault	DMREG
	A 2.5V Memory Control Domain fault has been detected.	BKSPCN
1403	Cache Regulator Domain Fault	DMREG
1400		BKSPCN
	A Cache Regulator Domain fault has been detected.	
1404	3.3V Memory Control 1 Domain Fault	DMREG BKSPCN
	A 3.3V Memory Control 1 Domain fault has been detected.	
1405	Processor 1 Regulator Domain Fault	DMREG
	A Processor 1 Regulator Domain fault has been detected.	BKSPCN
1406	Processor 2 Regulator Domain Fault	DMREG
		BKSPCN
	A Processor 2 Regulator Domain fault has been detected.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1407	Clock Regulator Domain Fault	DMREG BKSPCN
	.A Clock Regulator Domain fault has been detected.	
1510	Detected AC loss Before replacing any parts, verify that the AC input voltage is correct.	PWRSPLY TWRCARD
1511	Power supply failure	PWRSPLY TWRCARD
1512	Power supply failure	PWRSPLY TWRCARD CBLALL
1513 to 1514	Power supply failure	PWRSPLY TWRCARD
1516	No Power Supplies Present	PWRSPLY TWRCARD
	The required power supplies are not installed.	
1520	Detected AC loss	PWRSPLY TWRCARD
	Before replacing any parts, verify that the AC input voltage is correct.	
1521	Power supply failure	PWRSPLY TWRCARD
1522	Power supply failure	PWRSPLY TWRCARD CBLALL
1523 to 1524	Power supply failure	PWRSPLY TWRCARD
1526	No Power Supplies Present	PWRSPLY TWRCARD
	The required power supplies are not installed.	
1530	Power Supply P03 fault/AC loss Before replacing any parts, verify that the AC input voltage is correct.	PWRSPLY TWRCARD
1531	Power Supply P03 fault	PWRSPLY TWRCARD
1532	Power Supply P03 Communication fault	PWRSPLY TWRCARD CBLALL
1533 to 1534	Power Supply P03 fault	PWRSPLY TWRCARD
1611	Regulator Fault on Card Position M01	PWRREG TWRCARD
1612	Regulator Communication Fault on Card Position M01	PWRREG TWRCARD
1613, 1621	Regulator Fault on Card Position M01	PWRREG TWRCARD
1622	Regulator Communication Fault on Card Position M01	PWRREG TWRCARD
1623	Regulator Fault on Card Position M01	PWRREG TWRCARD
1631	Regulator Fault on Card Position M06	PWRREG TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1632	Regulator Communication Fault on Card Position M06	PWRREG TWRCARD
1633	Regulator Fault on Card Position M06	PWRREG TWRCARD
1810	Load fault on the +12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1820	Load fault on the +5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1830	Load fault on the +3.3V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1840	Load fault on the -12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1910	Power Supply PP1 fault/AC loss	PWRSPLY
	If the Power Supply PP1 powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	TWRCARD
1911	Power Supply PP1 fault	PWRSPLY TWRCARD
1912	Power Supply PP1 Communication fault	PWRSPLY TWRCARD
1913	Power Supply PP1 fault	PWRSPLY TWRCARD
1920	Power Supply PP2 fault/AC loss If the Power Supply PP2 powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	PWRSPLY TWRCARD
1921	Power Supply PP2 fault	PWRSPLY TWRCARD
1922	Power Supply PP2 Communication fault	PWRSPLY TWRCARD
1923	Power Supply PP2 fault	PWRSPLY TWRCARD
1A00	CPM Regulator Load Fault	PWRSPLY TWRCARD
1A10	CPM Regulator PP1 Fault	PWRSPLY TWRCARD
1A20	CPM Regulator PP2 Fault	PWRSPLY TWRCARD
1B01	Load fault on the +12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1B02	Load fault on the +5V bus	PWROC TWRCARD
1202	An isolation procedure is required for identifying which load is at fault.	DWDOC
1B03	Load fault on the +3.3V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1B04	Load fault on the -12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1B05	Load fault on the +1.8V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B06 to 1B07	Load fault on the +2.5V bus	PWROC
1000 to 1007	An isolation procedure is required for identifying which load is at fault.	TWRCARD
1B09	CPM Regulator Load Fault	PWROC TWRCARD
1C01	Load fault on the +12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1C03	Load fault on the +3.3V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1005		PWROC
1C05	Load fault on the +1.8V bus An isolation procedure is required for identifying which load is at fault.	TWRCARD
1C06 to 1C08	Load fault on the +2.5V bus	PWROC
	An isolation procedure is required for identifying which load is at fault.	TWRCARD
1C09	CPM Regulator Load Fault	PWRREG BKSPCN
1F00	No SRC Translate	AJSDJ04
2131	Power Supply P01 Fault	PWRSPLY SPNLCRD
	A fault has been detected for Power Supply P01.	
2132	Power Supply P02 Fault	PWRSPLY SPNLCRD
	A fault has been detected for Power Supply P02.	
2133	Power Supply P03 Fault A fault has been detected for Power Supply P03.	PWRSPLY SPNLCRD
2134	Power Supply P04 Fault	PWRSPLY
2134	A fault has been detected for Power Supply P04.	SPNLCRD
2141	Power Supply P01 Fault	PWRSPLY
	A fault has been detected for Power Supply P01.	SPNLCRD
2142	Power Supply P02 Fault	PWRSPLY
	A fault has been detected for Power Supply P02.	SPNLCRD
2143	Power Supply P03 Fault	PWRSPLY
	A fault has been detected for Power Supply P03.	SPNLCRD
2144	Power Supply P04 Fault	PWRSPLY
	A fault has been detected for Power Supply P04.	SPNLCRD
2151	Power Supply P01 Fault	PWRSPLY SPNLCRD
	A fault has been detected for Power Supply P01.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
2152	Power Supply P02 Fault	PWRSPLY
	A fault has been detected for Power Supply P02.	SPNLCRD
2153	Power Supply P03 Fault	PWRSPLY
	A fault has been detected for Power Supply P03.	SPNLCRD
2154	Power Supply P04 Fault	PWRSPLY
	A fault has been detected for Power Supply P04.	SPNLCRD
2201	Power Supply P01 or P02 Overcurrent Fault	PWROC
	A POW-PIP is required for identifying which load is at fault.	SPNLCRD CBLALL
2202	Power Supply P03 or P04 Overcurrent Fault	PWROC
	A POW-PIP is required for identifying which load is at fault.	SPNLCRD CBLALL
2210	One of the CPM regulators has reported a fault	PWRSPLY SPNLCRD
2211	CPM Regulator 1 Fault	PWRSPLY SPNLCRD
2212	CPM Regulator 2 Fault	PWRSPLY SPNLCRD
2213	CPM Regulator 3 Fault	PWRSPLY SPNLCRD
2221	Power Good Fault	SPNLCRD
	A MFIOP power good fault occurred.	PGDPART CBLALL
2222	Power Good Type M Fault	SPNLCRD
	A Memory power good fault occurred.	PGDPART CBLALL
2223	Power Good Type P Fault	SPNLCRD
	A Processor power good fault occurred.	PGDPART CBLALL
2224	Power Good Type I Fault	SPNLCRD
±		PGDPART
2221	A Internal expansion power good fault occurred.	CBLALL
2231	System Unit Interlock Failure	INTRLCK SPNLCRD CBLALL
2232	Secondary Frame Interlock Failure	INTRLCK SPNLCRD CBLALL
2240	Air Moving Device Panel Fault	AIRMOVR PWRSPLY
2241	Air Moving Device 1 Fault	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	SPNLCRD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Iten
2242	Air Moving Device 2 Fault	AIRMOVR SPNLCRD
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	
2244	Air Moving Device 4 Fault	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	SPNLCRD
2245	Air Moving Device 5 Fault	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	SPNLCRD
2246	Air Moving Device 6 Fault	AIRMOVR SPNLCRD
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	SINLERD
2260	Timeout on Panel for Request of VPD	CTLPNL
2301	Power Supply P01 or P02 Overcurrent error	PWROC SPNLCRD
	A POW-PIP is required for identifying which load is at fault.	CBLALL
2302	Power Supply P03 or P04 Overcurrent error	PWROC SPNLCRD
	A POW-PIP is required for identifying which load is at fault.	CBLALL
2311	Power Supply P01 error	PWRSPLY SPNLCRD
	A fault detection failure occurred for Power Supply P01.	CBLALL
2312	Power Supply P02 error	PWRSPLY SPNLCRD
	A fault detection failure occurred for Power Supply P02.	CBLALL
2313	Power Supply P03 error	PWRSPLY
	A fault detection failure occurred for Power Supply P03.	SPNLCRD CBLALL
2314	Power Supply P04 error	PWRSPLY
	A fault detection failure occurred for Power Supply P04.	SPNLCRD CBLALL
2321	Power Good Fault	SPNLCRD
	A MFIOP power good error was detected.	CBLALL PGDPART
2322	Power Good Type M error	SPNLCRD
	A Memory power good error was detected.	CBLALL PGDPART

2323

2324

2330

Power Good Type P error

Power Good Type I error

Power Supply P01 not installed

A Processor power good error was detected.

A Internal expansion power good error was detected.

SPNLCRD

PGDPART

SPNLCRD

CBLALL

PGDPART

PWRSPLY SPNLCRD

CBLALL

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
2331	Power Supply P01 ID is Invalid	PWRSPLY SPNLCRD
2332	Power Supply P02 ID is Invalid	PWRSPLY SPNLCRD
2333	Power Supply P03 ID is Invalid	PWRSPLY SPNLCRD
2334	Power Supply P04 ID is Invalid	PWRSPLY SPNLCRD
2400 to 2402	UPS Enable/Disable Failure	UPSUNIT SPNLCRD
2403	UPS CPM Failure	UPSUNIT SPNLCRD
2404	UPS Battery Failure	BATRY UPSUNIT
2405	UPS Unit Failure	UPSUNIT SPNLCRD
2406 to 2407	UPS Enable/Disable Failure	UPSUNIT SPNLCRD
2410 to 2411	UPS Test Failure	UPSUNIT SPNLCRD
2413	UPS Interface Failure	UPSUNIT SPNLCRD
2600	Power Good Fault	PGDPART TWRCARD PWRSPLY
2601 to 2606	Power Good Fault	PGDPART TWRCARD
2610	Processor/Memory Card not installed	PWRSPLY TWRCARD
2612	Optical Converter 5V Fault	CBLALL TWRCARD
2/12	The SPCN detected a fault on the SPCN card optical converter 5V.	CDL 411
2613	Configuration Requires 200V Input Configuration now requires 200V AC power.	CBLALL
300E	EPO Circuit Fault	TWRCARD
	The ac module installed in the 9406 Expansion Unit (FC 504x) detected a fault in the UEPO signal. The signal was active and the incoming ac voltage was still present.	21F9362 21F5680
302B	PCC Overcurrent	TWRCARD
	The power control compartment is causing an over current condition in the 9406 Expansion Unit power system.	21F5680 21F9631 21F9362
	Exchange the ac module and the SPCN port cable at the same time.	
3100	I2C Bus Controller Communication fault	I2CBUS TWRCARD
3101	I2C Bus 1 Communication fault	I2CBUS TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3102	I2C Bus 2 Communication fault	I2CBUS TWRCARD
3103	I2C Bus 3 Communication fault	I2CBUS TWRCARD
3104	I2C Bus 4 Communication fault	I2CBUS TWRCARD
3105	I2C Bus 5 Communication fault	I2CBUS TWRCARD
3106	I2C Bus 6 Communication fault	I2CBUS TWRCARD
3110	I2C Bus DASD Backplane 1 Communication fault	I2CBUS TWRCARD
3111	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD
3112	I2C Bus DASD Backplane 3 Communication fault	I2CBUS TWRCARD
3113	I2C Bus Adapter Communication fault	I2CBUS TWRCARD
3114	I2C Bus PCI Backplane Communication fault	I2CBUS TWRCARD
3115	I2C Bus Panel Communication fault	I2CBUS TWRCARD
3116	I2C Bus Fan Local Controller Communication fault	I2CBUS TWRCARD
3117	I2C Bus Fan Remote Controller Communication fault	I2CBUS TWRCARD
3118	I2C Bus SPCN VPD Communication fault	I2CBUS TWRCARD
311C	I2C Bus Panel Communication fault	I2CBUS TWRCARD
4410	Internal Battery Power Unit Fault Internal Battery Power Unit in the system has failed.	BATRY BATCHGR TWRCARD CBLALL
4411	Internal Battery Power Unit Charger Fault	BATCHGR TWRCARD
	Internal Battery Power Unit Charger in the system has failed.	CBLALL
4412	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR BATRY TWRCARD CBLALL
4413	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR TWRCARD CBLALL
4414	Battery Charger Load fault	PWROC BATRY TWRCARD CBLALL

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4415	Battery Power Unit missing	BATRY TWRCARD CBLALL
4416	Internal Battery Power Unit Charger Fault	BATCHGR TWRCARD CBLALL
4417	Battery Charger Unit missing	BATCHGR TWRCARD CBLALL
4500 to 4502	UPS Enable/Disable Failure	UPSUNIT TWRCARD
4503	UPS CPM Failure	UPSUNIT TWRCARD
4504	UPS Battery Failure	BATRY UPSUNIT
4505	UPS Unit Failure	UPSUNIT TWRCARD
4507	UPS Enable/Disable Failure	UPSUNIT TWRCARD
4510	UPS Test Failure	UPSUNIT TWRCARD
4513	UPS Interface Failure	UPSUNIT TWRCARD
6018	One of the regulators has reported a fault	PWRREG BKSPCN
	A regulator fault was detected.	DUDDEC
601A	One of the CPM regulators has reported a fault A CPM regulator fault was detected.	PWRREG BKSPCN FI00030
6118	Regulator over current fault	PWRREG BKSPCN
	One of the regulators detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	
6218	Regulator over current fault Regulator 1 detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	PWRREG BKSPCN
6238	Regulator over current fault	PWRREG BKSPCN
	Regulator 2 detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	
6258	Regulator over current fault	PWRREG
	Regulator 3 detected an over current condition. This may be caused by the regulator or one of cards powered by the regulator.	ACMODUL
6318	Regulator Fault Regulator 1 has reported a fault.	PWRREG BKSPCN
631A		PWRREG
	Regulator Fault Regulator 1 has reported a fault.	ACMODUL FI00030

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6338	Regulator Fault	PWRREG
	Regulator 2 reported a fault.	BKSPCN
633A	Regulator Fault	PWRREG
	Regulator 2 reported a fault.	ACMODUL FI00030
6358	Regulator Fault	PWRREG
	A regulator 3 reported a fault.	ACMODUL
6400 to 6401	Power Good Fault	PGDPART FI00065
		BKSPCN
6518	One of the regulators has reported a fault	PWRREG
	An over current sensor failure occurred for a regulator. The ac module or one of the regulators can cause this fault.	BKSPCN
6618	Regulator over current fault	PWRREG BKSPCN
	Regulator 1 reported a false over current condition.	
	Fault tolerance may allow continued system operation.	
6638	Regulator over current fault	PWRREG
	Regulator 2 reported a false over current condition.	BKSPCN
	Fault tolerance may allow continued system operation.	
6658	Regulator over current fault	PWRREG
	Regulator 3 reported a false over current condition.	ACMODUL
	Fault tolerance may allow continued system operation.	
6718	Regulator fault	PWRREG
	Regulator 1 reported a fault.	BKSPCN
	Fault tolerance may allow continued system operation.	
671A	Regulator fault	PWRREG BKSPCN
		FI00030
6738	Regulator fault	PWRREG BKSPCN
	Regulator 2 reported a fault.	
	Fault tolerance may allow continued system operation.	
673A	Regulator fault	PWRREG
	Regulator 18 reported a fault.	BKSPCN FI00030
	Fault tolerance may allow continued system operation.	
6758	Regulator fault	PWRREG
	Regulator 3 reported a fault.	ACMODUL
	Fault tolerance may allow continued system operation.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6818	One of the regulators has reported a fault	PWRREG BKSPCN
	A fault detection failure occurred for a regulator. The regulator or the ac module/SPCN card can cause this fault.	
5918	One of the regulators has reported a fault	PWRREG BKSPCN
	An over current fault detection failure occurred for a regulator. The regulator or the ac module/SPCN card can cause this fault.	
6A18	Regulator Fault	PWRREG BKSPCN
	A regulator fault detection failure occurred for regulator 1. The ac module or the regulator can cause this fault.	BACKPLN
5A38	Regulator Fault	PWRREG BKSPCN
	A regulator fault detection failure occurred for regulator 2. The regulator or the ac module/SPCN card can cause this fault.	BACKPLN
6A58	Regulator Fault	PWRREG ACMODUL
	A regulator fault detection failure occurred for regulator 3. The regulator or the ac module/SPCN card can cause this fault.	BACKPLN
6B00	Disk Unit 1 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 1 reported a fault.	BKSPCN
5B01	Disk Unit 2 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 2 reported a fault.	BKSPCN
6B02	Disk Unit 3 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 3 reported a fault.	BKSPCN
6B03	Disk Unit 4 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 4 reported a fault.	BKSPCN
5B04	Disk Unit 5 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 5 reported a fault.	BKSPCN
6B05	Disk Unit 6 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 6 reported a fault.	BKSPCN
6806	Disk Unit 7 regulator fault	DISKTRY
	The regulator that powers disk unit 7 reported a fault.	DISKDRV BKSPCN
5B07	Disk Unit 8 regulator fault	DISKTRY
	The regulator that powers disk unit 8 reported a fault.	DISKDRV BKSPCN
5B08	Disk Unit K1 regulator fault	DISKTRY
	The regulator that powers disk unit K1, located in slot K1 of the disk expansion unit, reported a fault.	DISKDRV BKSPCN
6B09	Disk Unit K2 regulator fault	DISKTRY
	The regulator that powers disk unit K2, located in slot K2 of the disk expansion unit, reported a fault.	DISKDRV BKSPCN

1xxx		

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6B0A	Disk Unit K3 regulator fault	DISKTRY
	The regulator that necessary disk unit K2 laceted in slat K2 of the disk	DISKDRV
	The regulator that powers disk unit K3, located in slot K3 of the disk expansion unit, reported a fault.	BKSPCN
6B0B	Disk Unit K4 regulator fault	DISKTRY
	The regulator that powers disk unit K4, located in slot K4 of the disk	DISKDRV
	expansion unit, reported a fault.	BKSPCN
6B0C	Disk Unit K5 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K5, located in slot 5 of the disk	BKSPCN
	expansion unit, reported a fault.	
6B0D	Disk Unit K6 regulator fault	DISKTRY
	The regulator that powers disk unit K6, located in slot K6 of the disk	DISKDRV
	expansion unit, reported a fault.	BKSPCN
6B0E	Disk Unit K7 regulator fault	DISKTRY
	The regulator that powers disk unit K7, located in slot K7 of the disk	DISKDRV
	expansion unit, reported a fault.	BKSPCN
6B0F	Disk Unit K8 regulator fault	DISKTRY
	The monulator that more an $\frac{1}{2}$ is write $V_0$ is set $\frac{1}{2}$ is the $V_0$ of the $\frac{1}{2}$	DISKDRV
	The regulator that powers disk unit K8, located in slot K8 of the disk expansion unit, reported a fault.	BKSPCN
6B10	Disk Unit K9 regulator fault	DISKTRY
	The merulator that merupan disk write VO leasts his shet VO of the disk	DISKDRV
	The regulator that powers disk unit K9, located in slot K9 of the disk expansion unit, reported a fault.	BKSPCN
6B11	Disk Unit K10 regulator fault	DISKTRY
		DISKDRV
	The regulator that powers disk unit K10, located in slot K10 of the disk expansion unit, reported a fault.	BKSPCN
6B12	Disk Unit K11 regulator fault	DISKTRY
		DISKDRV
	The regulator that powers disk unit K11, located in slot K11 of the disk expansion unit, reported a fault.	BKSPCN
6B13	Disk Unit K12 regulator fault	DISKTRY
	The regulator that powers disk unit K12, located in slot K12 of the disk	DISKDRV
	expansion unit, reported a fault.	BKSPCN
6B14	Disk Unit K13 regulator fault	DISKTRY
	The regulator that powers disk unit K13, located in slot K13 of the disk	DISKDRV
	expansion unit, reported a fault.	BKSPCN
6B15	Disk Unit K14 regulator fault	DISKTRY
	The regulator that powers disk unit K14, located in slot K14 of the disk	DISKDRV
	expansion unit, reported a fault.	BKSPCN
6B16	Device 1 regulator fault	RMDEV
	The regulator for device 1 or D01 reported a fault.	BKSPCN
6B17	Device 2 regulator fault	RMDEV
		BKSPCN
	The regulator for device 2 or D02 reported a fault.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6B18	Disk Unit 9 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 9 reported a fault.	BKSPCN
6B19	Disk Unit 10 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 10 reported a fault.	BKSPCN
6B1A	Disk Unit 11 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit 11 reported a fault.	BKSPCN
6B1B	Disk Unit 12 regulator fault	DISKTRY
	The regulator that powers disk unit 12 reported a fault.	DISKDRV BKSPCN
6B1C	Device 3 regulator fault	RMDEV
	The regulator for device 3 reported a fault.	BKSPCN
6B1D	Disk Unit K15 regulator fault	DISKTRY DISKDRV
	The regulator that powers disk unit K15, located in slot K15 of the disk expansion unit, reported a fault.	BKSPCN
6B1E	Disk Unit K16 regulator fault	DISKTRY
	The regulator that powers disk unit K16, located in slot K16 of the disk expansion unit, reported a fault.	DISKDRV BKSPCN
6B1F	Device 4 regulator fault	RMDEV
	The regulator for device 4 reported a fault.	BKSPCN
6B20	Disk Unit K17 regulator fault	DISKTRY
	The regulator that powers disk unit K17 reported a fault.	DISKDRV BKSPCN
6B21	Disk Unit K18 regulator fault	DISKTRY
	The regulator that powers disk unit K18 reported a fault.	DISKDRV BKSPCN
6B22	Disk Unit K19 regulator fault	DISKTRY
	The regulator that powers disk unit K19 reported a fault.	DISKDRV BKSPCN
6B23	Disk Unit K20 regulator fault	DISKTRY
	The regulator that powers disk unit K20 reported a fault.	DISKDRV BKSPCN
6B24	Disk Unit K21 regulator fault	DISKTRY
	The regulator that powers disk unit K21 reported a fault.	DISKDRV BKSPCN
6B25	Disk Unit K22 regulator fault	DISKTRY
	The regulator that powers disk unit K22 reported a fault.	DISKDRV BKSPCN
6B26	Disk Unit K23 regulator fault	DISKTRY
	The regulator that powers disk unit K23 reported a fault.	DISKDRV BKSPCN
6B27	Disk Unit K24 regulator fault	DISKTRY
	The regulator that powers disk unit K24 reported a fault.	DISKDRV BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6B28	Disk Unit K25 regulator fault The regulator that powers disk unit K25 reported a fault.	DISKTRY DISKDRV BKSPCN
6B29	Disk Unit K26 regulator fault The regulator that powers disk unit K26 reported a fault.	DISKTRY DISKDRV BKSPCN
6B2A	Disk Unit K27 regulator fault The regulator that powers disk unit K27 reported a fault.	DISKTRY DISKDRV BKSPCN
6B2B	Disk Unit K28 regulator fault The regulator that powers disk unit K28 reported a fault.	DISKTRY DISKDRV BKSPCN
6B2C	Disk Unit K29 regulator fault The regulator that powers disk unit K29 reported a fault.	DISKTRY DISKDRV BKSPCN
6B2D	Disk Unit K30 regulator fault The regulator that powers disk unit K30 reported a fault.	DISKTRY DISKDRV BKSPCN
6B2E	Disk Unit K31 regulator fault The regulator that powers disk unit K31 reported a fault.	DISKTRY DISKDRV BKSPCN
6B2F	Disk Unit K32 regulator fault The regulator that powers disk unit K32 reported a fault.	DISKTRY DISKDRV BKSPCN
6C00	Disk Unit 1 regulator fault A fault detection failure occurred for the regulator that powers disk unit 1 or F01. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C01	Disk Unit 2 regulator fault A fault detection failure occurred for the regulator that powers disk unit 2 or F02. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C02	Disk Unit 3 regulator fault A fault detection failure occurred for the regulator that powers disk unit 3 or F03. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C03	Disk Unit 4 regulator fault A fault detection failure occurred for the regulator that powers disk unit 4 or F04. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C04	Disk Unit 5 regulator fault A fault detection failure occurred for the regulator that powers disk unit 5 or F05. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C05	Disk Unit 6 regulator fault A fault detection failure occurred for the regulator that powers disk unit 6 or F06. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C06	Disk Unit 7 regulator fault A fault detection failure occurred for the regulator that powers disk unit 7 or F07. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6C07	Disk Unit 8 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit 8 or F08. The regulator or the ac module/SPCN card can cause this fault.	
6C08	Disk Unit K1 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K1, located in slot 1 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	
6C09	Disk Unit K2 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K2, located in slot 2 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	
6C0A	Disk Unit K3 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K3, located in slot 3 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DKSICIN
6C0B	Disk Unit K4 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K4, located in slot 4 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DK51 CIV
6C0C	Disk Unit K5 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K5, located in slot 5 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DIGICIN
6C0D	Disk Unit K6 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K6, located in slot 6 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	
6C0E	Disk Unit K7 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K7, located in slot 7 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DKSPCIN
6C0F	Disk Unit K8 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K8, located in slot 8 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DKSPCIN
6C10	Disk Unit K9 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K9, located in slot 9 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DKJI CIN
6C11	Disk Unit K10 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K10, located in slot 10 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6C12	Disk Unit K11 regulator fault A fault detection failure occurred for the regulator that powers disk unit K11, located in slot 11 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C13	Disk Unit K12 regulator fault A fault detection failure occurred for the regulator that powers disk unit K12, located in slot 12 of the disk expansion unit. The regulator or the ac module/SPCN card can cause this fault.	DISKTRY BKSPCN
6C14	Disk Unit K13 regulator fault A fault detection failure occurred for the regulator that powers disk unit K13, located in slot 13 of the disk expansion unit. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C15	Disk Unit K14 regulator fault A fault detection failure occurred for the regulator that powers disk unit K14, located in slot 14 of the disk expansion unit. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C16	Device 1 regulator fault A fault detection failure occurred for the regulator that powers device 1 or D01. The regulator or the ac module can cause this fault.	RMDEV BKSPCN
6C17	Device 2 regulator fault A fault detection failure occurred for the regulator that powers device 2 or D02. The regulator or the ac module can cause this fault.	RMDEV BKSPCN
6C18	Disk Unit 9 regulator fault A fault detection failure occurred for the regulator that powers disk unit 9. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C19	Disk Unit 10 regulator fault A fault detection failure occurred for the regulator that powers disk unit 10. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C1A	Disk Unit 11 regulator fault A fault detection failure occurred for the regulator that powers disk unit 11. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C1B	Disk Unit 12 regulator fault A fault detection failure occurred for the regulator that powers disk unit 12. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN
6C1C	Device 3 regulator fault A fault detection failure occurred for the regulator that powers device 3. The regulator or the ac module can cause this fault.	RMDEV BKSPCN
6C1D	Disk Unit K15 regulator fault A fault detection failure occurred for the regulator that powers disk unit K15, located in slot 15 of the disk expansion unit. The regulator or the ac module can cause this fault.	DISKTRY BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6C1E	Disk Unit K16 regulator fault A fault detection failure occurred for the regulator that powers disk unit	DISKTRY BKSPCN
	K16, located in slot 16 of the disk expansion unit. The regulator or the ac module can cause this fault.	
6C1F	Device 4 regulator fault A fault detection failure occurred for the regulator that powers device 4.	RMDEV BKSPCN
	The regulator or the ac module can cause this fault.	
6C20	Disk Unit K17 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K17.	
6C21	Disk Unit K18 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K18.	
6C22	Disk Unit K19 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K19.	
6C23	Disk Unit K20 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K20.	
6C24	Disk Unit K21 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K21.	
6C25	Disk Unit K22 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K22.	
6C26	Disk Unit K23 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K23.	
6C27	Disk Unit K24 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K24.	
6C28	Disk Unit K25 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K25.	
6C29	Disk Unit K26 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K26.	
6C2A	Disk Unit K27 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K27.	DIGICIN

1xxx		

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6C2B	Disk Unit K28 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K28.	DIGUERY
6C2C	Disk Unit K29 regulator fault A fault detection failure occurred for the regulator that powers disk unit	DISKTRY BKSPCN
6C2D	K29. Disk Unit K30 regulator fault	DISKTRY
C2D	A fault detection failure occurred for the regulator that powers disk unit	BKSPCN
	K30.	
5C2E	Disk Unit K31 regulator fault	DISKTRY BKSPCN
	A fault detection failure occurred for the regulator that powers disk unit K31.	
6C2F	Disk Unit K32 regulator fault	DISKTRY
	A fault detection failure occurred for the regulator that powers disk unit K32.	BKSPCN
7000 to 7004	Air Moving Device Fault	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	BKSPCN
7101	Power supply failure	PWRSPLY
	The ac power supply module reported a fault. One of the other power supplies may also cause this error.	
7102	Power supply failure	PWRSPLY
	Feature power supply 2 reported a fault. An ac module or one of the other feature power supplies may also cause this error.	ACMODUL
7103	Power supply failure	PWRSPLY
	Feature power supply 1 reported a fault. The ac module or one of the other feature power supplies may also cause this error.	ACMODUL
7201	Power Supply over current fault	PWRREG
	The ac module reported an over current condition. This is usually caused by one of the regulators.	PWRSPLY ACMODUL
	Perform SPCN-PIP10.	
7202	Power Supply over current fault	PWRREG
	Feature power supply 2 reported an over current condition. This is usually caused by one of the regulators.	PWRSPLY ACMODUL
	Perform SPCN-PIP10.	
7203	Power Supply over current fault	PWRREG
	Feature power supply 1 reported an over current condition. This is usually caused by one of the regulators.	PWRSPLY ACMODUL
	Perform SPCN-PIP10.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7300	AC Module Over current	ACMODUL PWRSPLY
	The ac module or one of the feature power supplies reported an over current condition.	
	Perform SPCN-PIP10.	
7400	Control Supply fault	ACMODUL BKSPCN
	A control supply fault was reported in the ac module.	
7401	Control Supply over current A control supply over current condition was detected in the ac module.	ACMODUL PWRREG BKSPCN
7402		
7402	Control Supply 5V regulator fault The SPCN detected a fault in the +5 V dc regulator of the control supply in the ac module.	ACMODUL BKSPCN
7403	Control Supply 12V regulator fault	ACMODUL
	The SPCN detected a fault in the +12 V dc regulator of the control supply in the ac module.	
7404	Control Supply 12V regulator over current	ACMODUL
	An over current condition was detected in the +12 V dc regulator of the control supply in the ac module.	PWRSPLY FI00251
	Perform SPCN-PIP10.	
7405	Control Supply 5VSW Regulator Fault	IDPART TWRCARD
7406	Control Supply 5VSW power off failure	ACMODUL
	This failure must be corrected before removing powered VPDPART to avoid damage.	CTLPNL BKSPCN
7407	Optical Converter 5V Fault	90H6287
	The SPCN detected a fault on the SPCN card optical converter 5V.	SPNLCRD
7410 to 7411	AC Module Failure	ACMODUL BKSPCN
7412 to 7413	Control Supply 5VSW Regulator Fault	ACMODUL BKSPCN
7414 to 7415	Control Supply 5VSW power off failure	ACMODUL BKSPCN
	This failure must be corrected before removing powered VPDPART to avoid damage.	
7416	VPD 5V Power On Failure	ACMODUL BKSPCN
7417	Optical Converter 5V Fault	BKSPCN CBLALL
7500 to 7503	Air Moving Device missing error	AIRMOVR
	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	BKSPCN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7610	Air Moving Device Fault	AIRMOVR TWRCARD
	The Air Moving Device is operating at the wrong speed.	
7611	Air Moving Device missing error A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	AIRMOVR TWRCARD
7620	Air Moving Device Fault	AIRMOVR TWRCARD
	The Air Moving Device is operating at the wrong speed.	
7621	Air Moving Device missing error A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	AIRMOVR TWRCARD
7630	Air Moving Device Fault	AIRMOVR TWRCARD
7(01	The Air Moving Device is operating at the wrong speed.	
7631	Air Moving Device missing error A probelm was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	AIRMOVR TWRCARD
7640	Air Moving Device Fault The Air Moving Device is operating at the wrong speed.	AIRMOVR TWRCARD
7641	Air Moving Device missing error         A probelm was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if	AIRMOVR TWRCARD
	missing, replace if already installed.	
7710	Air Moving Device BP1 Fault A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	AIRMOVR TWRCARD
7711	Air Moving Device BP1 Not Present A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	AIRMOVR TWRCARD
7720	Air Moving Device BP2 Fault A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed or operating at the wrong speed.	AIRMOVR TWRCARD
7721	Air Moving Device BP2 Not Present A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	AIRMOVR TWRCARD
7730	Air Moving Device BP1 Fault	AIRMOVR TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7731	Air Moving Device BP1 Not Present	AIRMOVR TWRCARD
7740	Air Moving Device BP2 Fault	AIRMOVR TWRCARD
7741	Air Moving Device BP2 Not Present	AIRMOVR TWRCARD
8001	A Battery Power Unit 1 Failed	46G3890 ACMODUL
	A response was received from battery power unit 1 charger that was not valid.	BACKPLN
8002	Battery Power Unit 2 Failed	46G3890
	A response was received from battery power unit 2 charger that was not valid.	ACMODUL BACKPLN
8101	A Battery Power Unit 1 Failed	46G3890
	Battery power unit 1 capacity test failed.	
8102	Battery Power Unit 2 Failed	46G3890
	Battery power unit 2 capacity test failed.	
8110	Battery Power Unit 1 and 2 Failed	BATRY
~-**		
8201	Replace both batteries.         A Battery Power Unit 1 Failed	46G3890
0201	Battery power unit 1 charging fault was detected.	400000
8202	Battery Power Unit 2 Failed	46G3890
	Battery power unit 2 charging fault was detected.	
8301	A Battery Power Unit 1 Failed	46G3890
0001		1000070
8302	Battery power unit 1 load test fault occurred.Battery Power Unit 2 Failed	46G3890
0302		40G3890
P100	Battery power unit 2 load test fault occurred.         Na VPD Found due to Invialid Purpose	
8400 8401	No VPD Found due to Invalid Bypass         Timeout on Panel for Request of VPD	TWRCARD VPDPART
0401		TWRCARD
8402	Unable to Collect VPD	VPDPART TWRCARD
8403	VPD Critical Mismatch	VPDPART TWRCARD
8404 to 8406	Processor Unit VPD Mismatch	VPDPART TWRCARD
8409	No Processor Installed	VPDPART BKSPCN
840A	VPD 5V Power Off Failure	VPDPART TWRCARD
840B	VPD 5V Power On Failure	VPDPART TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
840C	Memory Module Misplug	VPDPART TWRCARD
840D	SPCN Configuration mismatch	IDPART TWRCARD
840E	SPCN Default Configuration loaded	IDPART TWRCARD
840F	SPCN Configuration mismatch	IDPART TWRCARD
8413 to 8416	Invalid Processor VPD	VPDPART TWRCARD
8423 to 8426	No Processor VPD	VPDPART TWRCARD
8430	SPCN Configuration mismatch The V/S Comm cable is required, but not connected.	IDPART TWRCARD
8431	SPCN Configuration mismatch The V/S Comm cable is connected, but not supported by current configuration.	IDPART TWRCARD
8440	SPCN Configuration mismatch The V/S Comm cable is required, but not connected.	IDPART TWRCARD
8441	SPCN Configuration mismatch The V/S Comm cable is connected, but not supported by current configuration.	IDPART TWRCARD
8450	SPCN Configuration mismatch	IDPART
8610	Air Moving Device B01 Not Present	AIRMOVR TWRCARD
8620	Air Moving Device B02 Not Present	AIRMOVR TWRCARD
8810	Battery Power Unit missing	BATRY
8811	Battery Charger Unit missing	BATCHGR
8910	External Netfinity Server 3.3V fault	ALTMANL TWRCARD
8920	External Netfinity Server Power Good fault	TWRCARD ALTMANL
8930	Integrated Netfinity Adapter fault	TWRCARD
8940 to 8943	External Netfinity Server R485 Communication fault	TWRCARD CBLALL ALTMANL
9012	Address not valid. LIC command had a frame address that was not valid.	TWRCARD CBLALL
	Exchange the SPCN frame-to-frame cables to the failing frame.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9013	Invalid Node Address.	TWRCARD
	The address in the SPCN command does not match the secondary nodes assigned address.	CBLALL
	Exchange the failing items for the SPCN node reporting the error.	
9014	A command has an invalid address mode.	AJDG301
	A command from the system unit specified a unit address of D or E or had a frame address of 00.	TWRCARD
	Exchange the failing items in the system unit.	
9016, 9021	A command to an SPCN node was rejected.	
	No action required. This reference code is logged for information only.	
9022	Addressed Unit not in frame.	
	The addressed unit does not exist in the addressed frame.	
	No action required. This reference code is logged for information only.	
9023	Addressed Unit exists, but the frame is powered off.	
	The addressed unit is in a frame that is powered off.	
	No action required. This reference code is logged for information only.	
9024	SPCN Licensed Internal Code not valid.	
	The Licensed Internal Code in one of the secondary nodes is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9025	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in one of the frames is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9026	Battery Power Unit is reporting a low charge.	
	The battery power unit is not charged enough to run a test.	
	No action required. This reference code is logged for information only.	
9027	Battery Power Unit is defective.	
	No action required. This reference code is logged for information only.	
9028	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in the primary node is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9029	SPCN VPD Damaged	TWRCARD
	The VPD record in the EEPROM has bad data.	
	Exchange the failing items for the node reporting the failure.	

XXX	
oforonco Codo	Das

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
902C	Battery Power Unit test was aborted.	
	The battery power unit test was aborted.	
	No action required. This reference code is logged for information only.	
902D	Addressed frame is not in SPCN configuration table.	
	The addressed frame is not in the SPCN configuration table.	
	No action required. This reference code is logged for information only.	
9031	Frame-to-Frame Communications Failure	
	The SPCN detected a BCC error on a transmission from another frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9032	SPCN Communications Failure, unit to rack.	
	The frame detected a BCC error on a transmission from a secondary node to the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9033	SPCN Communications Failure, rack to unit.	
	A secondary node detected a BCC error on a transmission from the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9034	Unsupported Packet Size	
	The receiving node detected a packet exceeding 70 bytes. The frame can also return this code if a secondary node returns more than 10 bytes to a PAS command.	
	No action required. This reference code is logged for error analysis only.	
9035	Secondary SPCN node timeout.	
	A secondary SPCN node did not respond to a command. The command was attempted again and failed.	
	No action required. This reference code is logged for error analysis only.	
9036	Frame Timeout	
	One or more frames did not respond to a command. The command is attempted again.	
	No action required. This reference code is logged for error analysis only.	
903B	Invalid Packet Length for data sent.	
	The number of bytes sent or received does not match the number of bytes specified in the command.	
	No action required. This reference code is logged for error analysis only.	
9041	Invalid Load Type	AJDG301
	The down load was successful, but the wrong type of Licensed Internal Code was loaded. The operation was attempted again but was not successful. Exchange the failing items for the node reporting the fault.	TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9042	EEPROM Failure	TWRCARD
	The EEPROM in an SPCN node cannot be written successfully.	
	Exchange the SPCN node reported in the failure.	
9043	Download Failure	TWRCARD
	The Licensed Internal Code download to an SPCN node was completed but was not successful.	
	Exchange the failing SPCN node.	
9046	QDS Packet Sequence Error	TWRCARD
	The Packet Sequence number is wrong. The download was stopped.	
9047	QDS Block Sequence Error	TWRCARD
	The Block Sequence number is wrong. The download was stopped.	
9048	The SPCN ROS and EEPROM LIC is not compatable.	TWRCARD
	The LIC levels in the nodes ROS and EEPROM are not compatible.	AJDG301
	Exchange the failing items for the failing node.	
9080	Undefined Status Code	TWRCARD
	An SPCN node returned an unknown status code.	BACKPLN
	Exchange the failing SPCN node.	
90F0	A frame was dropped from the SPCN configuration.	TWRCARD
	A frame was dropped from the SPCN configuration. This is usually caused by a loss of ac power or a problem with the frame-to-frame cable.	CBLALL
90F1	A frame was added to the SPCN configuration.	
	No action required. This reference code is logged for information only.	
9100	Battery capacity test completed.	
	No action required. This reference code is logged for information only.	
9101	VLIC-SPCN Timeout	TWRCARD
	A Licensed Internal Code timeout occurred. The SPCN failed to respond to a Licensed Internal Code command.	CTLPNL SVCPROC
9102	Assign Permanent Address command failure	TWRCARD
	A node failed to perform an Assign Permanent Address command.	
9103	Download Initialize Timeout	TWRCARD
	An SPCN node failed to enter the download state after an Initialize for Download command.	
	Exchange the failing SPCN node.	
9104	Download Completion Timeout	TWRCARD
	An SPCN node failed to leave the download state.	
	Exchange the failing SPCN node.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9105	Load Damaged Timeout	TWRCARD
	An SPCN node failed to enter the operational state.	
	Exchange the failing SPCN node.	
9106	An SPCN LID was not found.	
	No action required. This reference code is logged for information only.	
9107	An SPCN microcode download is required.	
	No action required. This reference code is logged for error analysis only.	
9108	A status change occured in one of the SPCN nodes.	
	No action required. This reference code is logged for information only.	
9109	Licensed Internal Code part number is not correct.	TWRCARD
	The AROS part number field was not updated to the correct level after the system attempted to load new Licensed Internal Code.	
9110	Battery Power Unit capacity test failed.	BATRY
	The battery power unit was not able to pass the capacity test.	
9111	SPCN is too large for VLIC.	AJDG301
	There are more nodes in the network than VLIC can service.	
9112	Primary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the primary SPCN node is damaged. The reload failed because the code could not be found.	
9113	Secondary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the secondary SPCN node is damaged. The reload failed because the code could not be found.	
9114	Frame SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for a SPCN node is damaged. The reload failed because the code could not be found.	
9115	SPCN Command rejected by the Service Processor.	
	The service processor rejected an SPCN command from the Licensed Internal Code.	
	No action required. This reference code is logged for information only.	
9116	SPCN - Control Panel interface failure.	
	The SPCN to control panel interface is not working.	
9117	SPCN - Control Panel interface is now working.	
	The SPCN to control panel interface is now working.	
	No action required. This reference code is logged for information only.	
9212	Frame Address field not valid.	TWRCARD
	A Licensed Internal Code command had a frame address that is not valid.	
	Exchange the failing items for the failing node.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9213	Invalid Address status, secondary node.	TWRCARD
	The address in the SPCN command does not match the assigned address of the secondary node.	
	Exchange the failing items for the failing node.	
9214	Invalid Address Mode status	TWRCARD AJDG301
0015	Invalid Address Mode occurred during Frame Command processing.	
9215	Invalid Frame Command status Invalid Frame Command occurred during Frame Command processing.	TWRCARD AJDG301
921B	System Unit SPCN Port Fault status.	TWRCARD
	System Unit Port Fault occurred during Command processing.	AJDG301
922B	Address Unassigned status       A secondary node has no address assigned during Command processing.	TWRCARD AJDG301
9231	Frame-to-Frame Communications Failure	TWRCARD
7201	A frame-to-frame communications failure occurred during STF processing.	CBLALL
9232	Intrarack Communications Failure	TWRCARD
	An SPCN secondary node to frame communications failure occurred during Command processing.	CBLALL
9233	Intrarack Communications Failure	TWRCARD
	An SPCN frame to secondary node communications failure occurred during Command processing.	CBLALL
9234	Unsupported Packet Size status	TWRCARD
	Unsupported Packet Size occurred during STF and Secondary Node Command processing.	CTLPNL SVCPROC
9235	SPCN Secondary Node Timeout status	TWRCARD
	An SPCN Secondary Node Timeout occurred during Command processing.	AJDG301 CBLALL
	If the failing secondary node is in a 9406 Expansion Unit (FC 504x), go to the "Analyzing Problems" section in the in the SY44-4934-00, FC 504x Problem Analysis and Repair and Parts information.	
9236	Frame Timeout status	TWRCARD
	An SPCN Frame Node Timeout occurred during Network post processing.	CBLALL
9238	Secondary Node Fault	TWRCARD
	An SPCN Secondary Node Fault occurred during Command processing.	AJDG301
9239	Frame Node Fault	TWRCARD
	An internal error in the SPCN frame node prevents the running of a Frame command.	AJDG301
923A	ASA Failure	TWRCARD
	The frame address returned by a secondary node does not match the address of the frame.	AJDG301

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
923B	Invalid Packet Length for data sent.	AJDG301 TWRCARD
	An Invalid Packet Length occurred for data exchanged.	
9280	Response Stack Overflow Too many responses were received during System Frame command	CBLALL AJDG301
	processing.	TWRCARD
9281	Response Overrun	CBLALL
	Response Overrun occurred during System Frame processing.	AJDG301 TWRCARD
9282	No Free Entries	CBLALL
	No free entries were found during System Frame processing.	AJDG301 TWRCARD
9283	ARA Failure	TWRCARD AJDG301
	An Assign Frame Address Failure occurred during ARA Preprocessing.	1100001
9284	Undefined status	TWRCARD
	Undefined Status occurred during Frame or STF processing.	AJDG301
9285	BCC Fault	TWRCARD
	A BCC Error was detected during Network post processing.	
9286	Length Check Error.	TWRCARD
	Length Check occurred during SPCN post processing.	AJDG301
9287	Undefined status	TWRCARD AJDG301
	Undefined Status occurred during Command processing.	1,2,0001
9288	Configuration Error	TWRCARD
	A configuration error was detected during System Frame processing.	AJDG301
9289	Invalid Packet Length for data sent.	AJDG301
	Invalid Packet Length occurred for data exchanged.	TWRCARD
A100	Battery Power Unit capacity test failure	
	The battery power unit capacity test time exceeds the installed battery capacity. The battery power may not be enough to provide a controlled stop during a loss of incoming ac voltage.	
	This reference code is logged for information only.	
A201	A Battery Power Unit 1 Failed	BATRY
	Battery power unit 1 capacity test failed.	BATCHGR
A202	Battery Power Unit 2 Failed	BATRY
	Battery power unit 2 capacity test failed.	BATCHGR
A300	Battery Power Unit missing	BATCHGR
	The existing number of battery power units installed may not be adequate for the current configuration. If the battery power units are installed, insure that they are properly connected before replacing any FRUs.	BATRY

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
A301	A Battery Power Unit 1 Failed	AJDG301 BATCHGR
	The installed SPCN Licensed Internal Code does not give support to the type of battery power unit installed. Install the latest SPCN code.	
A302	Battery Power Unit 2 Failed	AJDG301 BATCHGR
	The installed SPCN Licensed Internal Code does not give support to the type of battery power unit installed. Install the latest SPCN code.	DATCHGK
AC01 to AC02	Internal Battery Power Unit Charger Fault	BATCHGR BKSPCN
B101	A Battery Power Unit 1 Failed	PWRREG BATCHGR
	Battery power unit reported an over current condition on the +29 V dc bus.	BACKPLN
B102	Battery Power Unit 2 Failed Battery power unit 2 reported an over current condition on the +29 V dc	PWRREG BATCHGR BACKPLN
	bus.	
B201	A Battery Power Unit 1 Failed	PWRREG BATCHGR
	Battery power unit 1 reported an over current condition on the +31 V dc bus.	BACKPLN
B202	Battery Power Unit 2 Failed	PWRREG
	Battery power unit 2 reported an over current condition on the +31 V dc bus.	BATCHGR BACKPLN
C510	A Battery Power Unit 1 Failed	BATCHGR
	SPCN-to-battery power unit 1 or 3 communications fault occurred.	ACMODUL BACKPLN
C511	Battery Power Unit 2 Failed	BATCHGR
	SPCN-to-battery power unit 2 communications fault occurred.	ACMODUL BACKPLN
C512	AC Module Failure	ACMODUL
	SPCN serial port communications fault occurred.	
C600	AC Module Failure	ACMODUL
	The AC module control supply failed to turn off.	
C601	AC Module Failure	ACMODUL
	AC module bus voltage control test fault occurred.	
C602	AC Module Failure	ACMODUL
	AC module fault detection failure occurred.	
C609	Clock Card Failure	CLKCARD
	The clock card in slot 17 is missing or defective.	BKSPCN
C62E	SPCN Network Fault	TWRCARD
	An SPCN frame-to-frame communication failure was detected.	CBLALL
	SRNPU or POSORMU.	
C701 to C703	SPCN Frame-to-Frame Communication fault	TWRCARD CBLALL

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
CB00	Unknown box ID	TWRCARD BACKPLN
	The SPCN node cannot determine the machine type of the box in which it is installed.	
CB05 to CB06	AC Module Failure	ACMODUL
	The SPCN ROS and EPROMs test failed.	
CB1D	AC Module Failure	ACMODUL
	The LCD test failure was detected on an Extension/Expansion Unit.	17G0573
CC00	AC Module Failure	ACMODUL
	An unknown fault was detected. The machine failed to power up.	FI00065 BKSPCN
CD00	No Power Supplies Present	BKSPCN
	SPCN cannot detect any power supplies installed.	PWRSPLY
CE18	Regulator Not Present	PWRREG
	No regulators can be found.	ACMODUL
	If the regulators are installed, exchange the failing items.	
CE1A	Regulator Not Present	PWRREG
	If regulator 3 in slot R03 is installed, exchange the failing items.	BKSPCN
D001	A Battery Power Unit 1 Failed	86G8020
	A response was received from battery power unit 1 charger that was not valid.	ACMODUL BACKPLN
D002	Battery Power Unit 2 Failed	86G8020
	A response was received from battery power unit 2 charger that was not valid.	ACMODUL BACKPLN
D101	A Battery Power Unit 1 Failed	86G8040
	Battery power unit 1 capacity test failed.	86G8020
D102	Battery Power Unit 2 Failed	86G8040
	Battery power unit 2 capacity test failed.	86G8020
D110	Battery Power Unit 1 and 2 Failed	BATRY
	Replace both batteries.	
D201	A Battery Power Unit 1 Failed	86G8020
	Battery power unit 1 charging fault was detected.	86G8040
D202	Battery Power Unit 2 Failed	86G8020
	Battery power unit 2 charging fault was detected.	86G8040
D301	A Battery Power Unit 1 Failed	86G8020
	Battery power unit 1 load test fault occurred.	86G8040
D302	Battery Power Unit 2 Failed	86G8020
	Battery power unit 2 load test fault occurred.	86G8040

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
E002	Battery Power Unit 2 Failed	86G7750 ACMODUL
	A response was received from battery power unit 2 charger that was not valid.	BACKPLN
E102	Battery Power Unit 2 Failed	86G7714 86G7750
	External battery power unit 2 capacity test failed.	0001100
E202	Battery Power Unit 2 Failed	86G7750
	External battery power unit 2 charging fault was detected.	86G7714
E302	Battery Power Unit 2 Failed	86G7750 86G7714
	External battery power unit 2 load test fault occurred.	86G7714
F401	Internal Battery Power Unit Charger Fault	BATCHGR BKSPCN
F501	Internal Battery Power Unit Fault	BATRY BATCHGR
F601	Internal Battery Power Unit or Charger Fault	BATCHGR BATRY
F701	Internal Battery Power Unit Charger Fault	BATCHGR BATRY
F802	External Battery Power Unit Charger Fault	BATCHGR BKSPCN
F902	External Battery Power Unit Fault	BATRY BATCHGR
FA02	External Battery Power Unit or Charger Fault	BATCHGR BATRY
FB02	External Battery Power Unit Charger Fault	BATCHGR BATRY

# Table 2. SPCN failing items for Models 830, 840, SB2, and SB3:

Failing Item	Description	Document Description
16G6379	I/O Regulator.	Repair and Parts
16G8716	Cable assembly	Repair and Parts
16G8717	Cable assembly	Repair and Parts
16G8748	Planar board	Repair and Parts
16G8760	System Expansion Unit Board assembly with RAID	Repair and Parts
16G8763	Planar board	Repair and Parts
16G8769	Cable Carrier, System Unit with RAID.	Repair and Parts
16G8771	Cable Carrier, System Expansion Unit with RAID.	Repair and Parts
16G8806	Planar board	Repair and Parts
16G8807	System Unit Board assembly model G46 with RAID	Repair and Parts
17G0566	System Unit Control Panel	Repair and Parts
17G0567	System Unit Control Panel Card Assembly	Repair and Parts

Failing Item	Description	Document Description
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0574	Expansion Unit Control Panel Card Assembly	Repair and Parts
17G1150	Power Supply	Repair and Parts
17G1150	Feature Power Supply	Repair and Parts
17G1179	Current Share I/O Regulator	Repair and Parts
17G1189	I/O Regulator.	Repair and Parts
17G1199	3.6V I/O Regulator	Repair and Parts
17G1209	I/O Regulator.	Repair and Parts
17G2539	Cable Carrier, 9406 System Unit.	Repair and Parts
17G2598	Power regulator card	Repair and Parts
17G2695	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5521	Blower Assembly	Repair and Parts
21F5620	Regulator in 280X Disk Unit.	Repair and Parts
21F5650	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5680	AC Module, SPCN Secondary node.	Repair and Parts
21F5774	Cable Carrier, 9406 System Unit.	Repair and Parts
21F5793	Fan assembly.	Repair and Parts
21F8872	5032 Cable Carrier.	Repair and Parts
21F8888	Expansion Unit/Extension Unit Control Panel	Repair and Parts
21F8888	Control Panel on 5032 box.	Repair and Parts
21F8890	D-SE Converter Module.	Repair and Parts
21F9052	Card Enclosure, 9406 System Unit.	Repair and Parts
21F9215	I/O Regulator.	Repair and Parts
21F9216	3.6V Regulator, 9406 System Unit.	Repair and Parts
21F9316	Power Control Compartment (PCC)	Repair and Parts
21F9362	SPCN Port Cable	Repair and Parts
21F9380	Battery Power Unit	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9530	DC Bulk Module.	Repair and Parts
21F9631	Fan assembly.	Repair and Parts
46G3510	Fan assembly.	Repair and Parts
46G3587	Blower Assembly	Repair and Parts
46G3626	Contol Panel FRU Kit	Repair and Parts
46G3680	AC Module	Repair and Parts
46G3890	Internal Battery Power Unit	Repair and Parts
6462417	Rack Control Panel cable.	Repair and Parts
73F9166	System Unit Board assembly model G46 without RAID	Repair and Parts
74F1541	Card Enclosure, 9406 System Unit.	Repair and Parts

124 iSeries: iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

Failing Item	Description	Document Description
74F1542	Card Enclosure, 9406 System Unit.	Repair and Parts
74F1760	DC Bulk Module.	Repair and Parts
74F1919	I/O Regulator.	Repair and Parts
74F1922	3.6V Regulator, 9406 System Unit.	Repair and Parts
85F8220	Base Power Supply	Repair and Parts
85F8250	Feature Power Supply	Repair and Parts
86G7660	AC Module	Repair and Parts
86G7712	External Battery Power Unit cable	Repair and Parts
86G7714	External Battery Power Unit	Repair and Parts
86G7750	Battery Power Unit Charger	Repair and Parts
86G8020	Battery Power Unit Charger	Repair and Parts
86G8040	Battery Power Unit	Repair and Parts
87G6029	Regulator.	Repair and Parts
87G6060	Battery Power Unit	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6235	SPCN Frame-to-Frame or PCC port cable.	Repair and Parts
87G6300	AC Module	Repair and Parts
90H6287	Optical Converter	Repair and Parts
90H6360	Cable assembly	Repair and Parts
ACMODUL	AC Module	See the service documentation for instructions.
AIRMOVR	Fan and Blower assemblies	See the service documentation for instructions.
AJDG301	Vertical Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Rack SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Secondary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ04	System Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ05	Expansion Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
ALTMANL	Alternate Manual Required	See the service documentation for instructions.
BACKPLN	Back Plane Unit	See the service documentation for instructions.
BATCHGR	Battery Power Unit Charger	See the service documentation for instructions.
BATRY	Battery Power Unit	See the service documentation for instructions.
BKSPCN	SPCN card	See the service documentation for instructions.
BUSPWR	Domain 29V Bus	See the service documentation for instructions.
CBLALL	Cable Failure	See the service documentation for instructions.
CLKCARD	Clock card	See the service documentation for instructions.
CTLPNL	Control Panel	See the service documentation for instructions.
DISKDRV	Disk Unit Power regulator	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk Unit Power regulator	See the service documentation for instructions.

Failing Item	Description	Document Description
DISKTRY	Disk Unit or Removable Media Device	Repair and Parts
DMREG	Domain Regulator	See the service documentation for instructions.
I2CBUS	I2C Bus Part	See the service documentation for instructions.
IDPART	Vital Product Data Parts	See the service documentation for instructions.
INTRLCK	Interlock part	See the service documentation for instructions.
PGDPART	Power Good Part	See the service documentation for instructions.
PWROC	Power Supply overcurrent	See the service documentation for instructions.
PWRREG	Regulator.	See the service documentation for instructions.
PWRSPLY	Power Supply	See the service documentation for instructions.
RMDEV	Disk Unit or Removable Media Device	See the service documentation for instructions.
SPNLCRD	SPCN panel card	See the service documentation for instructions.
SVCPROC	Service Processor Card	See the service documentation for instructions.
TWRCARD	Card enclosure or backplane	See the service documentation for instructions.
UPSUNIT	UPS unit part	See the service documentation for instructions.
VPDPART	VPD Communication Part	See the service documentation for instructions.

# (1xxx) SPCN reference codes for Models 870 and 890

If you reached this point from the Service Action Log (SAL), return to the SAL and display the failing item information for this entry. Go directly to the symbolic FRU specified in the failing items list.

**Note:** On Models 870 and 890, the two rightmost characters on the control panel display (following the dash) are the table identifier (-xx). The table identifier is required to determine which Model 870 or 890 reference code table applies to the unit reference code recorded.

For details on the Failing Item column entries, see the SPCN Failing Items Detail table, which follow the Reference Code tables below.

#### For system Models 870 and 890, SPCN reference codes:

Choose from the following code format and table identifier:

Note: On Models 870 and 890, the A, B, or C in the SRC (1xxA xxxx, 1xxB xxxx, or 1xxC xxxx) indicates that the failure is on the processor frame, not on the FC 9094 Base I/O Tower.

- Table 1. SPCN reference codes for system Models 870 and 890 with table identifier 90
- Table 2. SPCN reference codes for system Models 870 and 890 with table identifier A0
- Table 3. SPCN reference codes for system Models 870 and 890 with table identifier B0

#### Table 1. SPCN reference codes for system Models 870 and 890 with table identifier 90:

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
00A0	SPCN BATs in process No action required. This reference code is logged for information only. If this reference code is present for more than 1 minute, exchange the failing items.	TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
00AA	Download in process	
	No action required. This reference code is logged for information only.	
00AB	Rack UEPO switch is OFF.         Informational reference code.	TWRCARD CTLPNL 6462417
	The UEPO switch must be returned to the On position to power on the rack.	
00AC	Detected AC loss	ACMODUL
	If system powers on normally or stays powered on after AC power failure, no replacement of parts may be needed.	
00BA	The system is running on the Battery Power Unit.	
	No action required. This reference code is displayed for information only.	
00BC	Battery Power Unit test is in process.	
	No action required. This reference code is displayed for information only.	
00CA	Thermal calibration in progress	
00EF	Remote EPO switch is OFF	
1500	Detected AC loss	PWRSPLY
	Before replacing any parts, verify that the AC input voltage is correct.	TWRCARD
1501	Power supply failure	PWRSPLY TWRCARD
1502	Power supply failure	PWRSPLY TWRCARD CBLALL
1503	Power supply failure	PWRSPLY TWRCARD
1510	Detected AC loss Before replacing any parts, verify that the AC input voltage is correct.	PWRSPLY TWRCARD
1511		PWRSPLY
1511	Power supply failure	TWRCARD
1512	Power supply failure	PWRSPLY TWRCARD CBLALL
1513 to 1514	Power supply failure	PWRSPLY TWRCARD
1516	No Power Supplies Present	PWRSPLY TWRCARD
	The required power supplies are not installed.	
1517	Power supply failure	PWRSPLY TWRCARD
1520	Detected AC loss	PWRSPLY
	Before replacing any parts, verify that the AC input voltage is correct.	TWRCARD
1521	Power supply failure	PWRSPLY TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1522	Power supply failure	PWRSPLY TWRCARD CBLALL
1523 to 1524	Power supply failure	PWRSPLY TWRCARD
1526	No Power Supplies Present The required power supplies are not installed.	PWRSPLY TWRCARD
1527	Power supply failure	PWRSPLY TWRCARD
1530	Detected AC loss	PWRSPLY TWRCARD
1531	Before replacing any parts, verify that the AC input voltage is correct.         Power supply failure	PWRSPLY TWRCARD
1532	Power supply failure	PWRSPLY TWRCARD CBLALL
1533	Power supply failure	PWRSPLY TWRCARD
1534	Power Supply P03 fault	PWRSPLY TWRCARD
1B01	Load fault on the +12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B02	An isolation procedure is required for identifying which load is at fault.         An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B03	Load fault on the +3.3V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B04	Load fault on the -12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B05	Load fault on the +1.8V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B06 to 1B07	Load fault on the +2.5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B11	Load fault on the +12V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B12	Load fault on the +5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1B13	Load fault on the +3.3V bus	PWROC TWRCARD
1B14	Load fault on the -12V bus	PWROC TWRCARD
1B16 to 1B17	Load fault on the +2.5V bus	PWROC TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1C01	Load fault on the +12V bus	PWROC TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1C03	Load fault on the +3.3V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1C05	Load fault on the +1.8V bus	PWROC
1005		TWRCARD
	An isolation procedure is required for identifying which load is at fault.	
1C06 to 1C08	Load fault on the +2.5V bus An isolation procedure is required for identifying which load is at fault.	PWROC TWRCARD
1F01	No SRC Translate	
2600	Power Good Fault	PGDPART
2000	rower Good Fault	TWRCARD
2601 to 2606	Power Good Fault	PGDPART TWRCARD
2610	Processor/Memory Card not installed	PWRSPLY TWRCARD
2612	Optical Converter 5V Fault	CBLALL TWRCARD
2 / 1 2	The SPCN detected a fault on the SPCN card optical converter 5V.	
2613	Configuration Requires 200V Input Configuration now requires 200V AC power.	CBLALL
3100	I2C Bus Controller Communication fault	I2CBUS TWRCARD
3101	I2C Bus 1 Communication fault	I2CBUS TWRCARD
3102	I2C Bus 2 Communication fault	I2CBUS TWRCARD
3103	I2C Bus 3 Communication fault	I2CBUS TWRCARD
3104	I2C Bus 4 Communication fault	I2CBUS TWRCARD
3105	I2C Bus 5 Communication fault	I2CBUS TWRCARD
3106	I2C Bus 6 Communication fault	I2CBUS TWRCARD
3110	I2C Bus DASD Backplane 1 Communication fault	I2CBUS TWRCARD
3111	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD
3112	I2C Bus DASD Backplane 3 Communication fault	I2CBUS TWRCARD
3113	I2C Bus Adapter Communication fault	I2CBUS TWRCARD
3114	I2C Bus PCI Backplane Communication fault	I2CBUS TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3115	I2C Bus Panel Communication fault	I2CBUS TWRCARD
3116	I2C Bus Fan Local Controller Communication fault	I2CBUS TWRCARD
3117	I2C Bus Fan Remote Controller Communication fault	I2CBUS TWRCARD
3118	I2C Bus SPCN VPD Communication fault	I2CBUS TWRCARD
3119	I2C Bus 4 Communication fault	I2CBUS TWRCARD
311C	I2C Bus Panel Communication fault	I2CBUS TWRCARD
311D	I2C Bus DASD Backplane 2 Communication fault	I2CBUS TWRCARD
311E	I2C Bus DASD Backplane 3 Communication fault	I2CBUS TWRCARD
3123	I2C Bus 6 Communication fault	I2CBUS TWRCARD
4410	Internal Battery Power Unit Fault Internal Battery Power Unit in the system has failed.	BATRY BATCHGR TWRCARD CBLALL
4411	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR TWRCARD CBLALL
4412	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR BATRY TWRCARD CBLALL
4413	Internal Battery Power Unit Charger Fault Internal Battery Power Unit Charger in the system has failed.	BATCHGR TWRCARD CBLALL
4414	Battery Charger Load fault	PWROC BATRY TWRCARD CBLALL
4415	Battery Power Unit missing	BATRY TWRCARD CBLALL
4417	Battery Charger Unit missing	BATCHGR TWRCARD CBLALL
7610	Air Moving Device Fault The Air Moving Device is operating at the wrong speed.	AIRMOVR TWRCARD
7611	<ul> <li>Air Moving Device is operating at the wrong speed.</li> <li>Air Moving Device missing error</li> <li>A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.</li> </ul>	AIRMOVR TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7620	Air Moving Device Fault	AIRMOVR TWRCARD
	The Air Moving Device is operating at the wrong speed.	
7621	Air Moving Device missing error A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving device if missing, replace if already installed.	AIRMOVR TWRCARD
7630	Air Moving Device Fault The Air Moving Device is operating at the wrong speed.	AIRMOVR TWRCARD
7631	Air Moving Device missing error	AIRMOVR
	A problem was dectected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	TWRCARD
7640	Air Moving Device Fault	AIRMOVR
	The Air Moving Device is operating at the wrong speed.	TWRCARD
7641	Air Moving Device missing error	AIRMOVR
7011	A problem was detected with an Air Moving Device which can be caused by an Air Moving Device not being installed. Install Air Moving Device if missing, replace if already installed.	TWRCARD
7690	Air Moving Device Fault	AIRMOVR TWRCARD
7691	Air Moving Device missing error	AIRMOVR TWRCARD
8400	No VPD Found due to Invalid Bypass	TWRCARD
8401	Timeout on Panel for Request of VPD	VPDPART TWRCARD
8402	Unable to Collect VPD	VPDPART TWRCARD
8403	VPD Critical Mismatch	VPDPART TWRCARD
8404 to 8406	Processor Unit VPD Mismatch	VPDPART TWRCARD
8409	No Processor Installed	VPDPART TWRCARD
840A	VPD 5V Power Off Failure	VPDPART TWRCARD
840B	VPD 5V Power On Failure	VPDPART TWRCARD
840C	Memory Module Misplug	VPDPART TWRCARD
840D	SPCN Configuration mismatch	IDPART TWRCARD
840E	SPCN Default Configuration loaded	IDPART TWRCARD
840F	SPCN Configuration mismatch	IDPART TWRCARD

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
8413 to 8416	Invalid Processor VPD	VPDPART TWRCARD
8423 to 8426	No Processor VPD	VPDPART TWRCARD
8430	SPCN Configuration mismatch The V/S Comm cable is required, but not connected.	IDPART TWRCARD
8431	SPCN Configuration mismatch	IDPART TWRCARD
	The V/S Comm cable is connected, but not supported by current configuration.	
8440	SPCN Configuration mismatch The V/S Comm cable is required, but not connected.	IDPART TWRCARD
8441	SPCN Configuration mismatch	IDPART
	The V/S Comm cable is connected, but not supported by current configuration.	TWRCARD
8450	SPCN Configuration mismatch	IDPART
8468 to 8469	Capacitor card fault	CAPPWR
8610	Air Moving Device B01 Not Present	AIRMOVR TWRCARD
8620	Air Moving Device B02 Not Present	AIRMOVR TWRCARD
8700	BPA A AC loss	MAPPWR
8701	BPA B AC loss	MAPPWR
8710	BPC A communication failure	CBLPWR BPCPWR
8711	BPC B communication failure	CBLPWR BPCPWR
8722	BPC-A and -B are not at standby	BPCPWR
8731	A DCA or fan has dropped to N-mode status in MCM subsystem	BPCPWR
8750	BPC download failure on BPA A	BPCPWR
8751	BPC download failure on BPA B	BPCPWR
8800	BPC A cable missing	CBLPWR
8801	BPC B cable missing	CBLPWR
8910	External Netfinity Server 3.3V fault	ALTMANL TWRCARD
8920	External Netfinity Server Power Good fault	TWRCARD ALTMANL
8930	Integrated Netfinity Adapter fault	TWRCARD
8940 to 8943	External Netfinity Server R485 Communication fault	TWRCARD CBLALL ALTMANL
8A00	SPCN Configuration mismatch	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9012	Address not valid.	TWRCARD CBLALL
	LIC command had a frame address that was not valid.	CBLALL
	Exchange the SPCN frame-to-frame cables to the failing frame.	
9013	Invalid Node Address.	TWRCARD
	The address in the SPCN command does not match the secondary nodes assigned address.	CBLALL
	Exchange the failing items for the SPCN node reporting the error.	
9014	A command has an invalid address mode.	AJDG301
	A command from the system unit specified a unit address of D or E or had a frame address of 00.	TWRCARD
	Exchange the failing items in the system unit.	
9016, 9021	A command to an SPCN node was rejected.	
	No action required. This reference code is logged for information only.	
9022	Addressed Unit not in frame.	
	The addressed unit does not exist in the addressed frame.	
	No action required. This reference code is logged for information only.	
9023	Addressed Unit exists, but the frame is powered off.	
	The addressed unit is in a frame that is powered off.	
	No action required. This reference code is logged for information only.	
9024	SPCN Licensed Internal Code not valid.	
	The Licensed Internal Code in one of the secondary nodes is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9025	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in one of the frames is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	
9026	Battery Power Unit is reporting a low charge.	
	The battery power unit is not charged enough to run a test.	
	No action required. This reference code is logged for information only.	
9027	Battery Power Unit might be defective.	BATRY
	If the 1xxx9027 SRC is logged on two consecutive days, replace the FRUs listed.	BATCHGR
9028	SPCN Licensed Internal Code is not valid.	
	The Licensed Internal Code in the primary node is not valid. The code will be reloaded.	
	No action required. This reference code is logged for error analysis only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9029	SPCN VPD Damaged	TWRCARD
	The VPD record in the EEPROM has bad data.	
	Exchange the failing items for the node reporting the failure.	
902C	Battery Power Unit test was aborted.	
	The battery power unit test was aborted.	
	No action required. This reference code is logged for information only.	
902D	Addressed frame is not in SPCN configuration table.	
	The addressed frame is not in the SPCN configuration table.	
	No action required. This reference code is logged for information only.	
9031	Frame-to-Frame Communications Failure	
	The SPCN detected a BCC error on a transmission from another frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9032	SPCN Communications Failure, unit to rack.	
	The frame detected a BCC error on a transmission from a secondary node to the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9033	SPCN Communications Failure, rack to unit.	
	A secondary node detected a BCC error on a transmission from the frame. The transmission is attempted again.	
	No action required. This reference code is logged for error analysis only.	
9034	Unsupported Packet Size	
	The receiving node detected a packet exceeding 70 bytes. The frame can also return this code if a secondary node returns more than 10 bytes to a PAS command.	
	No action required. This reference code is logged for error analysis only.	
9035	Secondary SPCN node timeout.	
	A secondary SPCN node did not respond to a command. The command was attempted again and failed.	
	No action required. This reference code is logged for error analysis only.	
9036	Frame Timeout	
	One or more frames did not respond to a command. The command is attempted again.	
	No action required. This reference code is logged for error analysis only.	
903B	Invalid Packet Length for data sent.	
	The number of bytes sent or received does not match the number of bytes specified in the command.	
	No action required. This reference code is logged for error analysis only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9041	Invalid Load Type	AJDG301 TWRCARD
	The down load was successful, but the wrong type of Licensed Internal Code was loaded. The operation was attempted again but was not successful. Exchange the failing items for the node reporting the fault.	
9042	EEPROM Failure	TWRCARD
	The EEPROM in an SPCN node cannot be written successfully.	
	Exchange the SPCN node reported in the failure.	
9043	Download Failure	TWRCARD
	The Licensed Internal Code download to an SPCN node was completed but was not successful.	
	Exchange the failing SPCN node.	
9046	QDS Packet Sequence Error	TWRCARD
	The Packet Sequence number is wrong. The download was stopped.	
9047	QDS Block Sequence Error	TWRCARD
	The Block Sequence number is wrong. The download was stopped.	
9048	The SPCN ROS and EEPROM LIC is not compatable.	TWRCARD
	The LIC levels in the nodes ROS and EEPROM are not compatible.	AJDG301
	Exchange the failing items for the failing node.	
9080	Undefined Status Code	TWRCARD
	An SPCN node returned an unknown status code.	BACKPLN
	Exchange the failing SPCN node.	
90F0	A frame was dropped from the SPCN configuration.	TWRCARD
	A frame was dropped from the SPCN configuration. This is usually caused by a loss of ac power or a problem with the frame-to-frame cable.	CBLALL
90F1	A frame was added to the SPCN configuration.	
	No action required. This reference code is logged for information only.	
9100	Battery capacity test completed.	
	No action required. This reference code is logged for information only.	
9101	VLIC-SPCN Timeout	TWRCARD
	A Licensed Internal Code timeout occurred. The SPCN failed to respond to a Licensed Internal Code command.	CTLPNL SVCPROC
9102	Assign Permanent Address command failure	TWRCARD
	A node failed to perform an Assign Permanent Address command.	
9103	Download Initialize Timeout	TWRCARD
	An SPCN node failed to enter the download state after an Initialize for Download command.	
	Exchange the failing SPCN node.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9104	Download Completion Timeout	TWRCARD
	An SPCN node failed to leave the download state.	
	Exchange the failing SPCN node.	
9105	Load Damaged Timeout	TWRCARD
	An SPCN node failed to enter the operational state.	
	Exchange the failing SPCN node.	
9106	An SPCN LID was not found.	
	No action required. This reference code is logged for information only.	
9107	An SPCN microcode download is required.	
	No action required. This reference code is logged for error analysis only.	
9108	A status change occured in one of the SPCN nodes.	
	No action required. This reference code is logged for information only.	
9109	Licensed Internal Code part number is not correct.	TWRCARD
	The AROS part number field was not updated to the correct level after the system attempted to load new Licensed Internal Code.	
9110	Battery Power Unit capacity test failed.	BATRY
	The battery power unit was not able to pass the capacity test.	
9111	SPCN is too large for VLIC.	AJDG301
	There are more nodes in the network than VLIC can service.	
9112	Primary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the primary SPCN node is damaged. The reload failed because the code could not be found.	
9113	Secondary SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for the secondary SPCN node is damaged. The reload failed because the code could not be found.	
9114	Frame SPCN node is reporting load damaged.	TWRCARD
	The Licensed Internal Code for a SPCN node is damaged. The reload failed because the code could not be found.	
9115	SPCN Command rejected by the Service Processor.	
	The service processor rejected an SPCN command from the Licensed Internal Code.	
	No action required. This reference code is logged for information only.	
9116	SPCN - Control Panel interface failure.	
	The SPCN to control panel interface is not working.	
9117	SPCN - Control Panel interface is now working.	
	The SPCN to control panel interface is now working.	
	No action required. This reference code is logged for information only.	
91DD	All SPCN Downloads Complete	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9212	Frame Address field not valid.	TWRCARD
	A Licensed Internal Code command had a frame address that is not valid.	
	Exchange the failing items for the failing node.	
9213	Invalid Address status, secondary node.	TWRCARD
	The address in the SPCN command does not match the assigned address of the secondary node.	
	Exchange the failing items for the failing node.	
9214	Invalid Address Mode status	TWRCARD AJDG301
	Invalid Address Mode occurred during Frame Command processing.	AJDG501
9215	Invalid Frame Command status Invalid Frame Command occurred during Frame Command processing.	TWRCARD AJDG301
921B	System Unit SPCN Port Fault status.	TWRCARD
) <u></u>		AJDG301
922B	System Unit Port Fault occurred during Command processing.         Address Unassigned status	TWRCARD
9220	Ŭ,	AJDG301
	A secondary node has no address assigned during Command processing.	
9231	Frame-to-Frame Communications Failure A frame-to-frame communications failure occurred during STF processing.	TWRCARD CBLALL
9232	Intrarack Communications Failure	TWRCARD
9232	An SPCN secondary node to frame communications failure occurred during Command processing.	CBLALL
9233	Intrarack Communications Failure	TWRCARD
7233	An SPCN frame to secondary node communications failure occurred during Command processing.	CBLALL
9234	Unsupported Packet Size status	TWRCARD
	Unsupported Packet Size occurred during STF and Secondary Node Command processing.	CTLPNL SVCPROC
9235	SPCN Secondary Node Timeout status	TWRCARD
	An SPCN Secondary Node Timeout occurred during Command processing.	AJDG301 CBLALL
	If the failing secondary node is in a 9337, go to the "Analyzing Problems" section in the 9337 Disk Array Service Information manual.	
9236	Frame Timeout status	TWRCARD
	An SPCN Frame Node Timeout occurred during Network post processing.	CBLALL
9238	Secondary Node Fault	TWRCARD AJDG301
	An SPCN Secondary Node Fault occurred during Command processing.	y
9239	Frame Node Fault An internal error in the SPCN frame node prevents the running of a Frame command.	TWRCARD AJDG301

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
923A	ASA Failure The frame address returned by a secondary node does not match the address of the frame.	TWRCARD AJDG301
923B	Invalid Packet Length for data sent. An Invalid Packet Length occurred for data exchanged.	AJDG301 TWRCARD
9280	Response Stack Overflow Too many responses were received during System Frame command processing.	CBLALL AJDG301 TWRCARD
9281	Response Overrun Response Overrun occurred during System Frame processing.	CBLALL AJDG301 TWRCARD
9282	No Free Entries No free entries were found during System Frame processing.	CBLALL AJDG301 TWRCARD
9283	ARA Failure An Assign Frame Address Failure occurred during ARA Preprocessing.	TWRCARD AJDG301
9284	Undefined status Undefined Status occurred during Frame or STF processing.	TWRCARD AJDG301
9285	BCC Fault A BCC Error was detected during Network post processing.	TWRCARD
9286	Length Check Error. Length Check occurred during SPCN post processing.	TWRCARD AJDG301
9287	Undefined status Undefined Status occurred during Command processing.	TWRCARD AJDG301
9288	Configuration Error A configuration error was detected during System Frame processing.	TWRCARD AJDG301
9289	Invalid Packet Length for data sent. Invalid Packet Length occurred for data exchanged.	AJDG301 TWRCARD
C62E	SPCN Network Fault An SPCN frame-to-frame communication failure was detected. SRNPU or POSORMU.	TWRCARD CBLALL
CB15	EEPROM Failure	TWRCARD

#### Table 2. SPCN reference codes for system Models 870 and 890 with table identifier A0:

For SRCs in this table, where x is a variable number or character, xnnn or xxnn will appear in the table representing the variable.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0856	BPR-1 communication fault	MAPPWR
0866	BPR-2 communication fault	MAPPWR

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0876	BPR-3 communication fault	MAPPWR
0D06	BPA 350V power failure	MAPPWR
1C06	Cage air flow cooling problem	MAPPWR
CE16	BPC-A to BPC-B communication fault	BPCPWR
	Check cable and connector pins between the two BPCs before replacing BPCs.	
D216	BPA-A to BPA-B communication fault	MAPPWR
D616	UPS utility failure	UPSUNIT
D716	UPS battery low condition was detected	UPSUNIT
D816	UPS reported a bypass active	UPSUNIT
D916	UPS utility power restored	UPSUNIT
DA16	UPS installed	UPSUNIT
DB16	UPS not available	UPSUNIT
DC16	UPS battery low condition was reset	UPSUNIT
DD16	UPS reported bypass no longer active	UPSUNIT
DF16	UPS failure	UPSUNIT
E106	Critical logic overtemperature	MAPPWR
E206	Ambient room temperature limit exceeded	MAPPWR
F4X6	Hardware configuration cannot support N-mode power	
F806, F906, FA06	BPC AC power loss or phase missing	MAPPWR
FDX6	PC Room EPO switch has been detected open MAPPWR	
FE06, FE16	BPC UEPO switch is in the bypass position	MAPPWR
FE56	BPR-1 communication fault	MAPPWR
FE66	BPR-2 communication fault	MAPPWR
FE76	BPR-3 communication fault	MAPPWR
X115	Processor MDA-1 cable fault	MAPPWR
X215	Processor MDA-2 cable fault	MAPPWR
X315	Processor MDA-3 cable fault	MAPPWR
X415	Processor MDA-4 cable fault	MAPPWR
X515	Processor DCA-1 cable fault	MAPPWR
X615	Processor DCA-2 cable fault	MAPPWR
X715	Processor DCA-3 cable fault	MAPPWR
X925	Processor DCA-4 cable fault	MAPPWR
XA25	Processor DCA-5 cable fault	MAPPWR
XX0X	BPA FRU failure not isolated	MAPPWR
XX11	BPC fault	BPCPWR
XX13	BPC Seeprom VPD fault	BPCPWR
XX17	BPF Fan fault	BPFPWR
XX21	BPD-1 fault	BPDPWR

## 1xxx

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
XX22	BPC to BPD-1 communication fault	BPDPWR BPCPWR MAPPWR
XX23	BPD-1 Seeprom VPD fault	BPDPWR
XX31	BPD-2 fault	BPDPWR
XX32	BPC to BPD-2 communication fault	BPDPWR BPCPWR MAPPWR
XX33	BPD-2 Seeprom VPD fault	BPDPWR
XX51	BPR-1 fault	BPRPWR
XX52	BPC to BPR-1 communication fault	BPRPWR BPCPWR MAPPWR
XX53	BPR-1 Seeprom VPD fault	BPRPWR
XX61	BPR-2 fault	BPRPWR
XX62	BPC to BPR-2 communication fault	BPRPWR BPCPWR MAPPWR
XX63	BPR-2 Seeprom VPD fault	BPRPWR
XX71	BPR-3 fault	BPRPWR
XX72	BPC to BPR-3 communication fault	BPRPWR BPCPWR MAPPWR
XX73	BPR-3 Seeprom VPD fault	BPRPWR
XXB1	BPA EPO Switch fault	MAPPWR

#### Table 3. SPCN reference codes for system Models 870 and 890 with table identifier B0:

For SRCs in this table where x is a variable number or character, xxnn will appear in the table representing the variable.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0FB6, 0FC6, 0FD6, 0FE6	MCM running over temperature	MAPPWR
1C06	Airflow loss in MCM subsystem resulting in over-temperature	MAPPWR
6014	2.5V bus processor subsystem load fault	MAPPWR
6114	1.8V bus processor subsystem load fault	MAPPWR
6124, 6134	1.5V bus processor subsystem load fault	MAPPWR
6144	3.3V bus processor subsystem load fault	MAPPWR
6514	5.0V bus processor subsystem load fault	MAPPWR
6814	2.5V bus processor subsystem load fault	MAPPWR
6914	1.8V bus processor subsystem load fault	MAPPWR
6924, 6934	1.5V bus processor subsystem load fault	MAPPWR
6944	3.3V bus processor subsystem load fault	MAPPWR
6D14	5.0V bus processor subsystem load fault	MAPPWR

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7E06	No MCMs detected or MCMs mismatch	MAPPWR
7EB6, 7EC6, 7ED6, 7EE6	MCM running over temperature	MAPPWR
7F06	No MCMs detected or MCMs mismatch	MAPPWR
B014	2.5V bus processor subsystem load fault	MAPPWR
B114	1.8V bus processor subsystem load fault	MAPPWR
B124, B134	1.5V bus processor subsystem load fault	MAPPWR
B144	3.3V bus processor subsystem load fault	MAPPWR
B514, B544	5.0V bus processor subsystem load fault	MAPPWR
B814	2.5V bus processor subsystem load fault	MAPPWR
B914	1.8V bus processor subsystem load fault	MAPPWR
B924, B934	1.5V bus processor subsystem load fault	MAPPWR
B944	3.3V bus processor subsystem load fault	MAPPWR
BD14, BD44	5.0V bus processor subsystem load fault	MAPPWR
E006, E106	Processor over-temperature detected	MAPPWR
E1B6, E1C6, E1D6, E1E6	MCM running over temperature	MAPPWR
F206	Error not isolated; VPD on BPR may be corrupted	MAPPWR
F306	SPCN Configuration mismatch	MAPPWR
F406	Hardware configuration cannot support N-mode power	MAPPWR
F516, F526, F536, F546, F556, F566, F576, F586, F596, F5A6	A DCA or fan has dropped to N-mode status in MCM subsystem	
F606	SPCN Configuration mismatch	MAPPWR
XX11	Processor DCA-1 fault	DCAPWR
XX13	Processor DCA-1 Seeprom VPD fault	DCAPWR
XX15	Processor DCA-1 cable fault	CBLPWR
XX21	Processor DCA-2 fault	DCAPWR
XX23	Processor DCA-2 Seeprom VPD fault	DCAPWR
XX25	Processor DCA-2 cable fault	CBLPWR
XX31	Processor DCA-3 fault	DCAPWR
XX33	Processor DCA-3 Seeprom VPD fault	DCAPWR
XX35	Processor DCA-3 cable fault	CBLPWR
XX41	Processor DCA-4 fault	DCAPWR
XX43	Processor DCA-4 Seeprom VPD fault	DCAPWR
XX45	Processor DCA-4 cable fault	CBLPWR
XX51	Processor DCA-5 fault	DCAPWR
XX53	Processor DCA-5 Seeprom VPD fault	DCAPWR
XX55	Processor DCA-5 cable fault	CBLPWR
XX61	Processor DCA-6 fault	DCAPWR
XX63	Processor DCA-6 Seeprom VPD fault	DCAPWR

#### 1xxx

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
XX65	Processor DCA-6 cable fault	CBLPWR
XX71	Processor MDA-1 fault	MDAPWR
XX73	Processor MDA-1 Seeprom VPD fault	MDAPWR
XX75	Processor MDA-1 cable fault	CBLPWR
XX77	Processor Fan 1 fault	MDAPWR MSAPWR
XX81	Processor MDA-2 fault	MDAPWR
XX83	Processor MDA-2 Seeprom VPD fault	MDAPWR
XX85	Processor MDA-2 cable fault	CBLPWR
XX87	Processor Fan 2 fault	MDAPWR MSAPWR
XX91	Processor MDA-3 fault	MDAPWR
XX93	Processor MDA-3 Seeprom VPD fault	MDAPWR
XX95	Processor MDA-3 cable fault	CBLPWR
XX97	Processor Fan 3 fault	MDAPWR MSAPWR
XXA1	Processor MDA-4 fault	MDAPWR
XXA3	Processor MDA-4 Seeprom VPD fault	MDAPWR
XXA5	Processor MDA-4 cable fault	CBLPWR
XXA7	Processor Fan 4 fault	MDAPWR MSAPWR

#### SPCN failing items for Models 870 and 890:

Choose from the following code format and table identifier:

- Table 4. SPCN failing items for Models 870 and 890 with table identifier 90
- Table 5. SPCN failing items for Models 870 and 890 with table identifier A0
- Table 6. SPCN failing items for Models 870 and 890 with table identifier B0

#### Table 4. SPCN failing items for Models 870 and 890 with table identifier 90:

Failing Item	Description	Document Description
16G6379	I/O Regulator.	Repair and Parts
16G8716	Cable assembly	Repair and Parts
16G8717	Cable assembly	Repair and Parts
16G8748	Planar board	Repair and Parts
16G8760	System Expansion Unit Board assembly with RAID	Repair and Parts
16G8763	Planar board	Repair and Parts
16G8769	Cable Carrier, System Unit with RAID.	Repair and Parts
16G8771	Cable Carrier, System Expansion Unit with RAID.	Repair and Parts
16G8806	Planar board	Repair and Parts

Failing Item	Description	Document Description
16G8807	System Unit Board assembly model G46 with RAID	Repair and Parts
17G0566	System Unit Control Panel	Repair and Parts
17G0567	System Unit Control Panel Card Assembly	Repair and Parts
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0573	Expansion Unit Control Panel	Repair and Parts
17G0574	Expansion Unit Control Panel Card Assembly	Repair and Parts
17G1150	Feature Power Supply	Repair and Parts
17G1150	Power Supply	Repair and Parts
17G1179	Current Share I/O Regulator	Repair and Parts
17G1189	I/O Regulator.	Repair and Parts
17G1199	3.6V I/O Regulator	Repair and Parts
17G1209	I/O Regulator.	Repair and Parts
17G2539	Cable Carrier, 9406 System Unit.	Repair and Parts
17G2598	Power regulator card	Repair and Parts
17G2695	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5521	Blower Assembly	Repair and Parts
21F5620	Regulator in 280X Disk Unit.	Repair and Parts
21F5650	AC Module in 9406 System Unit power supply.	Repair and Parts
21F5680	AC Module, SPCN Secondary node.	Repair and Parts
21F5774	Cable Carrier, 9406 System Unit.	Repair and Parts
21F5793	Fan assembly.	Repair and Parts
21F8872	5032 Cable Carrier.	Repair and Parts
21F8888	Expansion Unit/Extension Unit Control Panel	Repair and Parts
21F8888	Control Panel on 5032 box.	Repair and Parts
21F8890	D-SE Converter Module.	Repair and Parts
21F9052	Card Enclosure, 9406 System Unit.	Repair and Parts
21F9215	I/O Regulator.	Repair and Parts
21F9216	3.6V Regulator, 9406 System Unit.	Repair and Parts
21F9316	Power Control Compartment (PCC)	Repair and Parts
21F9362	SPCN Port Cable	Repair and Parts
21F9380	Battery Power Unit	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9429	Cable Carrier, 5040 and 5042 feature.	Repair and Parts
21F9530	DC Bulk Module.	Repair and Parts
21F9631	Fan assembly.	Repair and Parts
46G3510	Fan assembly.	Repair and Parts
46G3587	Blower Assembly	Repair and Parts
46G3626	Contol Panel FRU Kit	Repair and Parts
46G3680	AC Module	Repair and Parts
46G3890	Internal Battery Power Unit	Repair and Parts

Failing Item	Description	Document Description
6462417	Rack Control Panel cable.	Repair and Parts
73F9166	System Unit Board assembly model G46 without RAID	Repair and Parts
74F1541	Card Enclosure, 9406 System Unit.	Repair and Parts
74F1542	Card Enclosure, 9406 System Unit.	Repair and Parts
74F1760	DC Bulk Module.	Repair and Parts
74F1919	I/O Regulator.	Repair and Parts
74F1922	3.6V Regulator, 9406 System Unit.	Repair and Parts
85F8220	Base Power Supply	Repair and Parts
85F8250	Feature Power Supply	Repair and Parts
86G7660	AC Module	Repair and Parts
86G7712	External Battery Power Unit cable	Repair and Parts
86G7714	External Battery Power Unit	Repair and Parts
86G7750	Battery Power Unit Charger	Repair and Parts
86G8020	Battery Power Unit Charger	Repair and Parts
86G8040	Battery Power Unit	Repair and Parts
87G6029	Regulator.	Repair and Parts
87G6060	Battery Power Unit	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6110	Power Supply	Repair and Parts
87G6235	SPCN Frame-to-Frame or PCC port cable.	Repair and Parts
87G6300	AC Module	Repair and Parts
90H6287	Optical Converter	Repair and Parts
90H6360	Cable assembly	Repair and Parts
ACMODUL	AC Module	See the service documentation for instructions.
AIRMOVR	Fan and Blower assemblies	See the service documentation for instructions.
AJDG301	Vertical Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Secondary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Primary SPCN node Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ01	Rack SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ04	System Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
AJSDJ05	Expansion Unit SPCN Licensed Internal Code.	Service Functions; APAR or LICTR
ALTMANL	Alternate Manual Required	See the service documentation for instructions.
BACKPLN	Back Plane Unit	See the service documentation for instructions.
BATCHGR	Battery Power Unit Charger	See the service documentation for instructions.
BATRY	Battery Power Unit	See the service documentation for instructions.
BKSPCN	SPCN card	See the service documentation for instructions.
BPCPWR	Power Controller Part	See the service documentation for instructions.
BUSPWR	Domain 29V Bus	See the service documentation for instructions.
CAPPWR	Capacitor card part	See the service documentation for instructions.

Failing Item	Description	Document Description
CBLALL	Cable Failure	See the service documentation for instructions.
CBLPWR	Cable Unit Part	See the service documentation for instructions.
CLKCARD	Clock card	See the service documentation for instructions.
CTLPNL	Control Panel	See the service documentation for instructions.
DISKDRV	Disk Unit Power regulator	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk Unit Power regulator	See the service documentation for instructions.
DISKTRY	Disk Unit or Removable Media Device	Repair and Parts
DMREG	Domain Regulator	See the service documentation for instructions.
I2CBUS	I2C Bus Part	See the service documentation for instructions.
IDPART	Vital Product Data Parts	See the service documentation for instructions.
INTRLCK	Interlock part	See the service documentation for instructions.
MAPPWR	MAP Power Problem	See the service documentation for instructions.
PGDPART	Power Good Part	See the service documentation for instructions.
PWROC	Power Supply overcurrent	See the service documentation for instructions.
PWRREG	Regulator.	See the service documentation for instructions.
PWRSPLY	Power Supply	See the service documentation for instructions.
RMDEV	Disk Unit or Removable Media Device	See the service documentation for instructions.
SPNLCRD	SPCN panel card	See the service documentation for instructions.
SVCPROC	Service Processor Card	See the service documentation for instructions.
TWRCARD	Card enclosure or backplane	See the service documentation for instructions.
UPSUNIT	UPS unit part	See the service documentation for instructions.
VPDPART	VPD Communication Part	See the service documentation for instructions.

Table 5. SPCN failing items for Models 870 and 890 with table identifier A0:

Failing Item	Description	Document Description
BPCPWR	Power Controller Part	See the service documentation for instructions.
BPDPWR	Power Distribution Part	See the service documentation for instructions.
BPFPWR	Fan and Blower assemblies	See the service documentation for instructions.
BPRPWR	Power Regulator Part	See the service documentation for instructions.
IBFPWR	Battery Power Unit	See the service documentation for instructions.
MAPPWR	MAP Power Problem	See the service documentation for instructions.
UPSUNIT	UPS unit part	See the service documentation for instructions.

Table 6. SPCN failing items for Models 870 and 890 with table identifier B0:

Failing Item	Description	Document Description
CBLPWR	Cable Unit Part	Problem Analysis; Symbolic FRU Isolation
DCAPWR	DC Converter Assembly	Problem Analysis; Symbolic FRU Isolation
MAPPWR	MAP Power Problem	Problem Analysis; Symbolic FRU Isolation
MDAPWR	Fan and Blower Drive Assembly	Problem Analysis; Symbolic FRU Isolation

Failing Item	Description	Document Description
MSAPWR	Fan and Blower assemblies	Problem Analysis; Symbolic FRU Isolation

# (1750, 2105, 2107) Disk unit reference codes

- 1. If the error is reported on the control panel, the unit reference code is characters 5 through 8 of the top 16 character line of function 11. If the error is reported on the console, the unit reference code is the 4 rightmost characters of word 1.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Disk unit failing items details, which follows the reference code table below.

Table 1. (1750, 2105, 2107) Disk unit reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3002	Addressed device is not responding	FCPORT FCDEV FCIOA FCINTF OPT_CLN
3010	Disk device returned wrong response to IOP	FCDEV FCIOA OPT_CLN
3020	Storage subsystem configuration error If an MES is being installed, verify the configuration.	FCDEV FCIOA OPT_CLN
3029	A device replacement has occurred	
	No action required. This reference code is logged for information only.	
3100	Fibre Channel interface error occurred	FCINTF FCDEV FCIOA OPT_CLN
3109	IOP timed out a disk command	FCDEV FCINTF FCIOA OPT_CLN
34FF	Format in progress	
	The device indicated that a format is in progress. When the format is complete, the device should be useable. No action is required. This reference code is logged for information only.	
FFF3	Disk media format bad	FCDEV
FFF4	Disk device problem	FCDEV
FFF5	Disk sector read error	FCDEV
FFF6	Disk device detected recoverable error A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	FCDEV

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
FFFA	Disk device wrong response was recovered by the IOP A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	FCDEV FCIOA OPT_CLN
FFFE	Temporary Fibre Channel interface error A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	FCINTF FCDEV FCIOA OPT_CLN

#### Table 2. Disk Unit failing items details

Failing Item	Description	Document Description
FCDEV	Fibre Channel device	Problem Analysis; Symbolic FRU Isolation
FCINTF	Fibre Channel interface	Problem Analysis; Symbolic FRU Isolation
FCIOA	Fibre Channel IOA	Problem Analysis; Symbolic FRU Isolation
FCPORT	Port not operational	Problem Analysis; Symbolic FRU Isolation
IOP	I/O processor card	Problem Analysis; Symbolic FRU Isolation
OPT_CLN	Fiber optic cleaning kit	Problem Analysis; Symbolic FRU Isolation

# (2629, 2718, 2726, 2728, 2729, 2740, 2741, 2809, 2810, 2824, 282C, 6532, 6533, 6534, 671A) Reference codes

For use by authorized service providers.

These Storage IOAs are allowed only on migrated towers. See the Migrated Expansion Unit Problem Analysis, Repair and Parts, SY44-5968-00 book on the V5R1 Supplemental Manuals Web site.

# (2689) Reference codes

For use by authorized service providers.

Find the unit reference code in the following table. For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0A17	A permanent I/O processor failure occurred	2689 AJDG301 AJDGP01
0A22	Adapter card storage error	AJDGP01 AJDG301 2689
1307	I/O adapter resource not available.	AJDGP01 AJDG301

#### Table 1. (2689) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1310	I/O adapter resource not available. The INA processor error log is being filled faster than the errors are being reported to the system. Check other errors reported to the system and correct them.	2689 AJDGP01
3000	An I/O adapter failure occurred.	2689 AJDGP01
3001	I/O adapter Licensed Internal Code failed.	2689 AJDGP01
3006	An I/O adapter failure occurred.	2689 ANYBUS
3080	I/O adapter Licensed Internal Code failed.	AJDGP01
3081	I/O adapter error; logged only.	
3084	An I/O adapter failure occurred.	AJDGP01 2689
3087	I/O adapter resource not available.	AJDGP01 AJDG301 NTUSER
6070	An I/O adapter failure occurred.	2689
6071	I/O adapter Licensed Internal Code failed.	AJDGP01
6072	I/O adapter Licensed Internal Code failed.	AJDGP01 2689
6075	I/O adapter resource not available.	AJDGP01
6083, 6085	I/O adapter Licensed Internal Code failed.	AJDGP01 2689
6201	A permanent I/O processor failure occurred	2689 AJDGP01
6202	I/O processor Licensed Internal Code error	AJDGP01 2689
6203	A permanent I/O processor failure occurred	NETSERV 2689 AJDGP01
6210	I/O processor Licensed Internal Code error	NETSERV AJDGP01
6222	A permanent I/O processor failure occurred	AJDGP01 2689
6223	A permanent I/O processor failure occurred	2689 AJDGP01
6225	A permanent I/O processor failure occurred	AJDGP01 AJDG301 2689
6226	I/O processor card detected device error	AJDG301 AS4NTDD
6227	A HostLAN error was detected	NTUSER AJDGP01 2689
6228	Windows initiated a warm boot	AJDGP01 2689

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6501	A Windows fatal error occurred	2689 AJDGP01
6502	A Windows fatal error occurred	AJDGP01 2689
6530	A Virtual SCSI error was detected	NTVSCSI NTOPSYS
6531	A Virtual SCSI error was detected	NTVSCSI AS4NTDD NTOPSYS AJDGP01
6532	A Virtual SCSI error was detected	NTOPSYS AJDGP01 AS4NTDD
6533	A Virtual SCSI error was detected	NTUSER NTOPSYS AS4NTDD
6534	A Virtual SCSI error was detected	AS4NTDD AJDGP01 NTOPSYS
6535	A Virtual SCSI error was detected	NTUSER NTDEVDR AJDGP01
6538	A Virtual SCSI error was detected	NTVSCSI NTOPSYS
6539	A Virtual SCSI error was detected	NTVSCSI AS4NTDD NTOPSYS AJDGP01
653A	A Virtual SCSI error was detected	NTOPSYS AJDGP01 AS4NTDD
653B	A Virtual SCSI error was detected	NTUSER NTOPSYS AS4NTDD
653C	A Virtual SCSI error was detected	AS4NTDD AJDGP01 NTOPSYS
653D	A Virtual SCSI error was detected	NTUSER NTDEVDR AJDGP01
653F	A Virtual SCSI error was detected	NTDEVDR NTOPSYS AJDG301
6540	A Virtual SCSI error was detected	NTVSCSI AJDGP01 AJDG301
6541	A permanent I/O processor failure occurred	2689 AJDGP01
6542	Licensed Internal Code error detected.	AJDG301 AJDGP01

#### 2689

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6543	A Windows fatal error occurred	NTOPSYS NTVSCSI
6544	A Virtual SCSI error was detected	NTVSCSI NTOPSYS
6580	A Windows fatal error occurred	DISKIMG 2689 AJDGP01
6590	A Netfinity Server error was detected	
65B0	A HostLAN error was detected	NTLANDD NTOPSYS
65B1	A HostLAN error was detected	NTLANDD NTOPSYS AJDG301
65B2	A HostLAN error was detected	NTDEVDR NTOPSYS AJDG301
8301	An I/O adapter failure occurred.	AJDGP01 2689
B3B1 to B3B7	A permanent I/O processor failure occurred	2689
B3B8	An I/O adapter failure occurred.	2689
B3B9	A permanent I/O processor failure occurred	2689
B3E0	I/O processor detected a fault condition	2689
B3E1	An I/O adapter failure occurred.	2689
B4B0	I/O adapter hardware error detected	2689
B4B1	A Netfinity Server error was detected	NETSERV AJDGP01
B4B9	An I/O adapter failure occurred.	2689
B4BC	A Netfinity Server error was detected	NETSERV
B4BF	A Netfinity Server error was detected	NSCABLE
B904	A permanent I/O processor failure occurred	AJDGP01 2689
B935	Incompatible hardware detected.	AJDGP01 2689
B960	I/O processor Licensed Internal Code error	AJDGP01 2689
BE00	An I/O adapter failure occurred.	AJDGP01 2689
-		

# Table 2. Failing items details

Failing Item	Description	Document Description
2689	I/O adapter card	Repair and Parts; removal and installation procedures
AJDG301	Licensed Internal Code	See the service documentation for instructions.
AJDGP01	I/O card Licensed Internal Code	See the service documentation for instructions.
ANYBUS	Remote HSL Network Bus	See the service documentation for instructions.

Failing Item	Description	Document Description
AS4NTDD	Device Driver	See the service documentation for instructions.
DISKIMG	Server Storage Space Object	See the service documentation for instructions.
NETSERV	Direct Attach Netfinity Server	See the service documentation for instructions.
NSCABLE	Direct Attach Netfinity Server cable	See the service documentation for instructions.
NTDEVDR	Device Driver	See the service documentation for instructions.
NTLANDD	Device Driver	See the service documentation for instructions.
NTOPSYS	Windows Operating System	See the service documentation for instructions.
NTUSER	User-initiated action	See the service documentation for instructions.
NTVSCSI	Device Driver	See the service documentation for instructions.

# (2724, 2744, 6149) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B904	I/O adapter Licensed Internal Code failed.	AJDGP01 FI00719
B920	I/O adapter Licensed Internal Code failed.	AJDGP01 FI00718 FI00719
B921	I/O adapter hardware error detected	FI00719 FI00718 AJDGP01 MA_BRDG
B934	Incompatible hardware detected.	FI00719 FI00718

#### Table 1. (2724, 2744, 6149) Reference codes

Failing Item	Description	Document Description
AJDGP01	Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.

# (2742, 2793, 2805) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (Word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Table 1. (2742, 2793, 2805) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B940	I/O adapter hardware error detected	FI00719 AJDGP01 MA_BRDG
B941	One of the ports on the IOA has failed.	FI00719 AJDGP01

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDGP01	Licensed Internal Code	Service Functions; APAR or LICTR
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.

# (2743, 2760) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (Word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Table 1.	(2743,	2760)	Reference	codes
----------	--------	-------	-----------	-------

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B950	Licensed Internal Code error	AJDGP01 FI00718 FI00719

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B951	I/O adapter hardware error detected	FI00719 FI00718 AJDGP01 MA_BRDG

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDGP01	LIC - Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.

# (2745) Reference Codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B904	I/O adapter Licensed Internal Code failed.	AJDGP01 FI00719
B934	Incompatible hardware detected.	FI00719 FI00718
B940	I/O adapter hardware error detected	FI00719 FI00718 AJDGP01 MA_BRDG
B941 to B942	One half of I/O adapter failed.	FI00719 FI00718 AJDGP01

#### Table 1. (2745) Reference codes

Failing Item	Description	Document Description
AJDGP01	LIC - Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR
MA_BRDG	Multi-adapter bridge	INFORMATION

# (2746) Twinaxial – workstation adapter reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (Word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Workstation adapter failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B904	I/O adapter Licensed Internal Code failed.	AJDGP01 FI00719
B934	Incompatible hardware detected.	FI00719 FI00718
B940	I/O adapter hardware error detected	FI00719 FI00718 AJDGP01 MA_BRDG
B941 to B942	One half of I/O adapter failed.	FI00719 FI00718 AJDGP01

Table 1. (2746) Twinaxial – workstation adapter reference codes

#### Table 2. Workstation adapter failing items details

Failing Item	Description	Document Description
AJDGP01	LIC - Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.

# (2748, 2757, 2763, 2778, 2780, 2782, 5703, 571A, 571B, 571E, 571F) Reference codes

For use by authorized service providers.

If the error is reported on the control panel, the unit reference code is characters 5 through 8 of the top 16 character line of function 11. If the error is reported on the console, the unit reference code is the 4 rightmost characters of word 1.

Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing Items Details, which follows the reference code table below.

Table 1. (2748, 2757, 2763, 2778, 2780, 2782, 5703, 571A, 571B, 571E, 571F) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1310	I/O processor resource not available	
	The I/O processor error log is being filled faster than the errors are being reported to the system. Check other errors reported to the system and correct them.	
3006	System bus error	IOP ANYBUS STORIOA
3020	I/O processor detected a SCSI bus configuration error	USER FI01107
	Error occurred on SCSI bus 0. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	STORIOA
3021	I/O processor detected a SCSI bus configuration error	USER
	Error occurred on SCSI bus 1. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	FI01107 STORIOA
3022	I/O processor detected a SCSI bus configuration error	USER
	Error occurred on SCSI bus 2. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	FI01107 STORIOA
3023	I/O processor detected a SCSI bus configuration error	USER
	Error occurred on SCSI bus 3. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	FI01107 STORIOA
3100	I/O processor card detected interface error	FI01107
	Error occurred on SCSI bus 0.	STORIOA FI01140 BACKPLN
	Perform IOPIP13.	
3101	I/O processor card detected interface error	FI01107 STORIOA
	Error occurred on SCSI bus 1.	FI01140
	Perform IOPIP13.	BACKPLN
3102	I/O processor card detected interface error	FI01107
	Error occurred on SCSI bus 2.	STORIOA FI01140
	Perform IOPIP13.	BACKPLN
3103	I/O processor card detected interface error	FI01107
	Error occurred on SCSI bus 3.	STORIOA FI01140
	Perform IOPIP13.	BACKPLN
3120		SVCDOCS
5120	I/O Processor detected that the bus is not operational A device was added to SCSI bus 0 of the I/O Adapter and caused the bus	510005
	to become not operational. Remove the device.	
3121	I/O Processor detected that the bus is not operational	SVCDOCS
	A device was added to SCSI bus 1 of the I/O Adapter and caused the bus to become not operational. Remove the device.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3122	I/O Processor detected that the bus is not operational	SVCDOCS
	A device was added to SCSI bus 2 of the I/O Adapter and caused the bus to become not operational. Remove the device.	
3123	I/O Processor detected that the bus is not operational	SVCDOCS
	A device was added to SCSI bus 3 of the I/O Adapter and caused the bus to become not operational. Remove the device.	
3140	I/O Processor detected that the bus is now operational	
	This reference code and the 3120 reference code that occurred before it require no service action, since SCSI bus 0 is now operational.	
3141	I/O Processor detected that the bus is now operational	
	This reference code and the 3121 reference code that occurred before it require no service action, since SCSI bus 1 is now operational.	
3142	I/O Processor detected that the bus is now operational	
	This reference code and the 3122 reference code that occurred before it require no service action, since SCSI bus 2 is now operational.	
3143	I/O Processor detected that the bus is now operational	
	This reference code and the 3123 reference code that occurred before it require no service action, since SCSI bus 3 is now operational.	
3150	I/O processor detected a SCSI bus configuration error	SVCDOCS
	Internal and external SCSI cables are connected to SCSI bus 0 at the same time. Correct the SCSI bus 0 configuration.	
3151	I/O processor detected a SCSI bus configuration error	SVCDOCS
	Internal and external SCSI cables are connected to SCSI bus 1 at the same time. Correct the SCSI bus 1 configuration.	
3400	I/O processor card detected device error	FI02112 STORIOA FI01106 DEVTERM FI01140
3401	Device backplane problem	DEVBPLN
3501	I/O processor Licensed Internal Code error	AJDGP01 IOP
3600 to 3601	System log entry only, no service action required	
8008	A permanent cache battery pack failure occurred	CACHBAT STORIOA
8009	Impending cache battery pack failure	САСНВАТ
8012	Attached read cache devices exceed capacity supported by IOA	SVCDOCS
	Reduce the number of read caches on the IOA.	
8100	I/O processor Licensed Internal Code error	AJDGP01 IOP
8130	IOA detected recoverable device bus error	
	An error occurred on SCSI bus 0. No action is required. This reference code is logged for information only.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
8131	IOA detected recoverable device bus error	
	An error occurred on SCSI bus 1. No action is required. This reference code is logged for information only.	
8132	IOA detected recoverable device bus error	
	An error occurred on SCSI bus 2. No action is required. This reference code is logged for information only.	
8133	IOA detected recoverable device bus error	
	An error occurred on SCSI bus 3. No action is required. This reference code is logged for information only.	
8140	IOA detected recoverable device bus error	
	No action is required. This reference code is logged for information only.	
8141	IOA detected recoverable device error	
	No action is required. This reference code is logged for information only.	
8145	A recoverable I/O processor error occurred.	STORIOA
8146	Disk device detected recoverable error	FI01105
8150	A permanent I/O processor failure occurred	STORIOA ANYBRDG
8151	I/O processor Licensed Internal Code error	AJDGP01 STORIOA
8155 to 8156	A permanent I/O processor failure occurred	AJDGP01 STORIOA
8157	I/O adapter card error	SVCDOCS
	Display the Service Action Log entry for this SRC. If the Failing Item indicates I/O adapter, then replace the I/O adapter. If the Failing Item indicates SVCDOCS, then do NOT replace the I/O adapter. This is a recoverable error. Perform the following for the I/O processor that the I/O adapter is attached to: 1. If the I/O Processor is not operable and disk units are attached, use	
	Hardware Service Manager to re-IPL the IOP. Other resources attached to the IOP may then need to be Varied On.	
	2. If disk units are not attached, perform the VRYCFG RESET(*YES) command to reset the IOP and Vary On attached resources.	
8200	I/O processor Licensed Internal Code error	AJDGP01 IOP
9000	I/O processor card detected device error	FI01105 STORIOA
9001	I/O processor card detected device configuration error	SVCDOCS
	Perform IOPIP33.	
9002	I/O processor card detected device error	FI01105
	Perform IOPIP16.	STORIOA FI01140 BACKPLN
		FI01106

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9008	I/O card does not support functions expected by devices	SVCDOCS
	Perform IOPIP25.	
9009	Call your next level of support for assistance	SVCDOCS
9010	Cache data associated with attached devices cannot be found	SVCDOCS
	Perform IOPIP31.	
9011	Cache data belongs to devices other than those attached	SVCDOCS
	Perform IOPIP32.	
9014	Mode jumper overridden due to cache data in conflicting mode	SVCDOCS
	See JOVERRIDE.	
9015	Mode jumper missing	SVCDOCS
	See JMISSING.	
9020 to 9021	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP20.	
9022 to 9024	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP22.	
9025	Disk unit is not supported at its physical location.	SVCDOCS
	Perform IOPIP21.	
9026	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP22.	
9027	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP34.	
9028	Incorrect hardware configuration change has been detected.	SVCDOCS
	Reduce the number of arrays on IOP. Either move all devices in an array to another IOP that supports arrays, or stop an array on this IOP.	
9029	Incorrect hardware configuration change has been detected.	SVCDOCS
	Contact your next level of support.	
902F	Array addendum Product Activity Log entry	
	This entry contains additional array information for 90xx reference codes when the array contains more than 10 array members. Use the 90xx entry that occurred at the same time as this reference code as the starting point for this problem.	
9030	Array no longer protected due to missing or failed disk unit	SVCDOCS
	Perform IOPIP21.	
9031	Array protection temporarily suspended	
	No action required. Protection will be automatically restarted.	
9032	A disk unit in a RAID array is missing or failed	FI02112
	The array is still protected, but the disk unit should be replaced.	SVCDOCS
	Perform IOPIP21.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9040	Array protection temporarily suspended	
	No action required. Protection will be automatically restarted.	
9041	Background array parity check detected and corrected errors	AJDGP01
	Call your next level of support to report the problem.	
9042	An array parity error has been detected and corrected	NEXTLVL
	Call your next level of support to report the problem.	
9050	Required cache data cannot be located for a disk unit.	SVCDOCS
	Perform IOPIP30.	
9051	IOP cache data exists for a missing or failed device.	SVCDOCS
	If all configured units are missing, a 9054 reference code may appear in the product activity log. If so, perform the action indicated for the 9054 reference code.	
	Otherwise, perform IOPIP27.	
9052	Cache data exists for device that has been modified.	SVCDOCS
	Contact your next level of support.	
9053	IOP resources not available due to previous problems.	SVCDOCS
	Take action on other IOP reference codes which have surfaced.	
	If you cannot get to SST or DST, and cannot perform a type A or B IPL, perform a type D IPL from removable media. Look for Product Activity Log entries for other IOP reference codes and take action on them.	
9054	IOP resources not available due to previous problems.	SVCDOCS
	Power off the system and remove all new or replacement disk units. IPL the system to DST. If you cannot perform a type A or B IPL, perform a type D IPL from removable media.	
	Look for Product Activity Log entries for other IOP reference codes and take action on them.	
9071	Link from IOA to auxiliary cache IOA went operational	
	No service action required.	
9072	Link from IOA to auxiliary cache IOA went non-operational	
	No service action required.	
9073	Incompatible or non-operational auxiliary cache IOA attached	SVCDOCS
	Perform IOPIP40.	
9081	I/O processor card detected device error	FI01105 STORIOA
9082	I/O processor card detected device error	FI01105
	Perform IOPIP16.	STORIOA FI01140 BACKPLN FI01106

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9090	Disk unit has been modified after the last known status.	SVCDOCS
	Re-IPL the system. If any reference codes are surfaced, go to List of system reference codes and use the new reference code as the entry point to the problem.	
	If you cannot resolve the problem, contact your next level of support.	
9091	Incorrect hardware configuration change has been detected.	SVCDOCS
	Re-IPL the system. If any reference codes are surfaced, go to List of system reference codes and use the new reference code as the entry point to the problem.	
	If you cannot resolve the problem, contact your next level of support.	
9092	Disk unit requires initialization before use.	SVCDOCS
	Perform IOPIP26.	
9093	Read cache device not in correct format	SVCDOCS
	Contact your next level of support.	
B934	Incompatible hardware detected.	STORIOA
FF3D	I/O adapter detected a recoverable error	STORIOA ANYBRDG
FF6D	I/O processor detected a recoverable system bus error	IOP ANYBUS

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDGP01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
ANYBRDG	System I/O bus or any attached card	See the service documentation for instructions.
ANYBUS	IOP card bus error	See the service documentation for instructions.
BACKPLN	Card Enclosure or Planar Board	See the service documentation for instructions.
САСНВАТ	Cache battery pack	See the service documentation for instructions.
DEVBPLN	Device backplane	See the service documentation for instructions.
DEVTERM	Terminating plug	See the service documentation for instructions.
IOP	I/O processor card	See the service documentation for instructions.
NEXTLVL	Call your next level of support for assistance	See the service documentation for instructions.
PCIBUS	Any PCI card on the PCI bus	See the service documentation for instructions.
STORIOA	Storage I/O adapter	See the service documentation for instructions.
SVCDOCS	Customer engineer directed to system problem analysis	See the service documentation for instructions.
USER	System Operator/User	See the service documentation for instructions.

# (2749, 2767, 2768, 2842, 2843, 2844, 284B, 284C, 284D, 284E, 286C, 286D, 286E, 286F, 5702) Reference codes

For use by authorized service providers.

<sup>160</sup> iSeries: iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

- 1. If the error is reported on the control panel, the unit reference code is characters 5 through 8 of the top 16 character line of function 11. If the error is reported on the console, the unit reference code is the 4 rightmost characters of word 1.
- 2. Find the unit reference code in the following table.

**Attention:** The 673x is a read cache. Perform all actions required for 673x as a disk drive and logic card except where separate 673x cache instructions are provided.

For more on the Failing Item column entries, see Table 2. Failing Items Details, which follows the reference code table below.

Table 1. (2749, 2767, 2768, 2842, 2843, 2844, 284B, 284C, 284D, 284E, 286C,	286D, 286E, 286F, 5702)
Reference codes	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0A17	A permanent I/O processor failure occurred	IOP MA_BRDG AJDGP01 AJDG301
0A22	I/O processor detected a storage transfer error	AJDGP01 AJDG301 IOP MA_BRDG
102E	Out of alternate sectors for disk storage	FI01105
1306	I/O processor card or Licensed Internal Code error A microprocessor exception occurred on the I/O processor.	AJDGP01 IOP FI01104 BACKPLN
1307	I/O processor resource not available	AJDGP01 AJDG301
1310	I/O processor resource not available The I/O processor error log is being filled faster than the errors are being reported to the system. Check other errors reported to the system and correct them.	
1317	<ul> <li>I/O processor card error</li> <li>Display the Service Action Log entry for this SRC. If the Failing Item indicates IOP, then replace the IOP. If the Failing Item indicates SVCDOCS, then do NOT replace the IOP. This is a recoverable error. Perform the following:</li> <li>1. If the I/O Processor is not operable and disk units are attached, use Hardware Service Manager to re-IPL the IOP. Other resources attached to the IOP may then need to be Varied On.</li> <li>2. If disk units are not attached, perform the VRYCFG RESET(*YES) command to reset the IOP and Vary On attached resources.</li> </ul>	SVCDOCS
2200	I/O processor Licensed Internal Code error	AJDGP01
2201	Removable media error during IPL	USER FI01105
2202	Removable media error during IPL	FI00022 FI01105

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3000	A permanent I/O processor failure occurred	FI01101 IOP MA_BRDG
3001	Not valid condition in I/O Processor Licensed Internal Code The Licensed Internal Code found a condition that should not have occurred.	IOP AJDGP01
3002	Addressed device failed to respond to selection Perform IOPIP16.	FI01105 STORIOA FI01140 FI01141 FI01106
3006	System bus error	IOP ANYBUS FI01101
3020	I/O processor detected a SCSI bus configuration error Error occurred on SCSI bus 0. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	USER FI01107 STORIOA
3021	I/O processor detected a SCSI bus configuration error Error occurred on SCSI bus 1. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	USER FI01107 STORIOA
3022	I/O processor detected a SCSI bus configuration error Error occurred on SCSI bus 2. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	USER FI01107 STORIOA
3023	I/O processor detected a SCSI bus configuration error Error occurred on SCSI bus 3. To correct or isolate a possible user error or configuration error, perform IOPIP17. Use the failing item (FI) codes to find failing devices.	USER FI01107 STORIOA
3080	I/O processor Licensed Internal Code error	AJDGP01
3081	System log entry only, no service action required	
3084	I/O processor card or Licensed Internal Code error A microprocessor exception occurred on the I/O processor.	AJDGP01 IOP FI01104 MA_BRDG
3087	I/O processor resource not available The Licensed Internal Code could not allocate resources on the I/O processor card.	AJDGP01 AJDG301 IOACNFG FI01104
3100	I/O processor card detected interface error Error occurred on SCSI bus 0. Perform IOPIP13.	FI01107 STORIOA FI01140 BACKPLN
3101	I/O processor card detected interface error Error occurred on SCSI bus 1. Perform IOPIP13.	FI01107 STORIOA FI01140 BACKPLN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3102	I/O processor card detected interface error Error occurred on SCSI bus 2. Perform IOPIP13.	FI01107 STORIOA FI01140 BACKPLN
3103	I/O processor card detected interface error Error occurred on SCSI bus 3. Perform IOPIP13.	FI01107 STORIOA FI01140 BACKPLN
3109	I/O processor timed out a device command Perform IOPIP16.	FI01105 STORIOA FI01140 BACKPLN FI01106
3110	I/O processor card detected interface error Perform IOPIP16.	FI01105 STORIOA FI01140 BACKPLN FI01106
3120	I/O Processor detected that the bus is not operational A device was added to SCSI bus 0 of the I/O Adapter and caused the bus to become not operational. Remove the device.	SVCDOCS
3121	I/O Processor detected that the bus is not operational A device was added to SCSI bus 1 of the I/O Adapter and caused the bus to become not operational. Remove the device.	SVCDOCS
3122	I/O Processor detected that the bus is not operational A device was added to SCSI bus 2 of the I/O Adapter and caused the bus to become not operational. Remove the device.	SVCDOCS
3123	I/O Processor detected that the bus is not operationalA device was added to SCSI bus 3 of the I/O Adapter and caused the busto become not operational. Remove the device.	SVCDOCS
3136	The removable media device is assigned elsewhere	USER FI01105
3140	I/O Processor detected that the bus is now operational This reference code and the 3120 reference code that occurred before it require no service action, since SCSI bus 0 is now operational.	
3141	I/O Processor detected that the bus is now operational This reference code and the 3121 reference code that occurred before it require no service action, since SCSI bus 1 is now operational.	
3142	I/O Processor detected that the bus is now operationalThis reference code and the 3122 reference code that occurred before itrequire no service action, since SCSI bus 2 is now operational.	
3143	I/O Processor detected that the bus is now operational This reference code and the 3123 reference code that occurred before it require no service action, since SCSI bus 3 is now operational.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3150	I/O processor detected a SCSI bus configuration error	SVCDOCS
	Internal and external SCSI cables are connected to SCSI bus 0 at the same time. Correct the SCSI bus 0 configuration.	
3151	I/O processor detected a SCSI bus configuration error	SVCDOCS
	Internal and external SCSI cables are connected to SCSI bus 1 at the same time. Correct the SCSI bus 1 configuration.	
3200	A tape/CD or disk device reported a failure	FI01105 STORIOA IOP MEDIA
3203	Disk media format bad	FI01105
3205, 3215	Disk sector read error	FI01105
	Disk unit data may need to be reloaded, but the disk unit does not need to be replaced.	
3250	Disk unit requires initialization before use.	USER
	Perform a D-IPL and work on errors found in the log.	
3300	Storage unit detected a media problem	MEDIA
	Perform IOPIP01.	FI00121 FI01141
3400	I/O processor card detected device error	FI02112
	NOTE: If external devices are attached check EXTSCSI and DEVTERM first.	STORIOA FI01106 DEVTERM FI01140
3401	Device backplane problem	DEVBPLN
3501	I/O processor Licensed Internal Code error	AJDGP01 IOP
3600 to 3601	System log entry only, no service action required	
6070	A permanent I/O processor failure occurred	IOP
6071	I/O processor Licensed Internal Code error	AJDGP01
6072	I/O processor Licensed Internal Code error	AJDGP01 IOP
6073	IPL device not ready	MEDIA FI01105 USER
6075	I/O processor resource not available	AJDGP01
6076	I/O processor card detected media error	MEDIA AJDGP01 FI01105
6081 to 6083	I/O processor Licensed Internal Code error	AJDGP01 IOP
6085	I/O processor Licensed Internal Code error	AJDGP01 IOP MA_BRDG
6200	A permanent IOA hardware error occurred	FCIOA OPT_CLN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6201	IOA LID is not valid	AJDGP01
6602	An I/O processor Licensed Internal Code error occurred.	AJDGP01
8000	A permanent IOP or cache adaptor card failure occurred. <b>Note:</b> DO NOT replace both FRUs at the same time. Exchange the FRUs one at a time in the order shown.	STORIOA CACHE
8002	A permanent cache adaptor card failure occurred. <b>Note:</b> DO NOT replace both FRUs at the same time. Exchange the FRUs one at a time in the order shown.	CACHE STORIOA
8004	Voltage drop detected on I/O processor 5 volt power supply.	FI01141 STORIOA
8005	A recoverable IOP or cache adaptor card error occurred. <b>Note:</b> DO NOT replace both FRUs at the same time. Exchange the FRUs one at a time in the order shown.	STORIOA CACHE
8007	A recoverable cache adaptor card error occurred. <b>Note:</b> DO NOT replace both FRUs at the same time. Exchange the FRUs one at a time in the order shown.	CACHE STORIOA
8010 to 8011	A permanent cache adaptor card failure occurred. The cache adaptor card may be missing, broken or incompatible. <b>Note:</b> DO NOT replace both FRUs at the same time. Exchange the FRUs one at a time in the order shown.	CACHE STORIOA
8100	I/O processor Licensed Internal Code error	AJDGP01 IOP
8130	IOA detected recoverable device bus error An error occurred on SCSI bus 0. No action is required. This reference code is logged for information only.	
8131	IOA detected recoverable device bus error An error occurred on SCSI bus 1. No action is required. This reference code is logged for information only.	
8132	IOA detected recoverable device bus error An error occurred on SCSI bus 2. No action is required. This reference code is logged for information only.	
8133	IOA detected recoverable device bus error An error occurred on SCSI bus 3. No action is required. This reference code is logged for information only.	
8140	IOA detected recoverable device bus error No action is required. This reference code is logged for information only.	
8141	IOA detected recoverable device error No action is required. This reference code is logged for information only.	
8145	A recoverable I/O processor error occurred.	STORIOA
8146	Disk device detected recoverable error	FI01105
8150	A permanent I/O processor failure occurred	STORIOA ANYBRDG

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
8151	I/O processor Licensed Internal Code error	AJDGP01 STORIOA
8155 to 8156	A permanent I/O processor failure occurred	AJDGP01 STORIOA
8157	I/O adapter card error	SVCDOCS
	Display the Service Action Log entry for this SRC. If the Failing Item indicates I/O adapter, then replace the I/O adapter. If the Failing Item indicates SVCDOCS, then do NOT replace the I/O adapter. This is a recoverable error. Perform the following for the I/O processor that the I/O adapter is attached to:	
	1. If the I/O Processor is not operable and disk units are attached, use Hardware Service Manager to re-IPL the IOP. Other resources attached to the IOP may then need to be Varied On.	
	2. If disk units are not attached, perform the VRYCFG RESET(*YES) command to reset the IOP and Vary On attached resources.	
8200	I/O processor Licensed Internal Code error	AJDGP01 IOP
8300	I/O processor card or Licensed Internal Code error	STORIOA IOP
	A microprocessor exception occurred on the I/O processor.	AJDGP01
8301	Not valid condition in I/O Processor Licensed Internal Code	FI01101
	The Licensed Internal Code found a condition that should not have occurred.	AJDGP01 IOP
8400	I/O processor Licensed Internal Code error	AJDGP01
9000	I/O processor card detected device error	FI01105 STORIOA
9001	I/O processor card detected device configuration error	SVCDOCS
	Perform IOPIP33.	
9002	I/O processor card detected device error Perform IOPIP16.	FI01105 STORIOA FI01140 BACKPLN FI01106
9008	I/O card does not support functions expected by devices	SVCDOCS
	Perform IOPIP25.	
9009	Call your next level of support for assistance	SVCDOCS
9010	Cache data associated with attached devices cannot be found Perform IOPIP31.	SVCDOCS
9011	Cache data belongs to devices other than those attached	SVCDOCS
	Perform IOPIP32.	
9012	IOP requires a cache adaptor card but cannot find it.	CACHE
	The cache adapter card is missing or broken.	
	Perform IOPIP29.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9013	The IOP and attached cache adaptor card are not compatible.	SVCDOCS
	Perform IOPIP19.	
9020 to 9021	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP20.	
9022 to 9024	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP22.	
9025	Disk unit is not supported at its physical location.	SVCDOCS
	Perform IOPIP21.	
9026	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP22.	
9027	Array not functional due to present hardware configuration.	SVCDOCS
	Perform IOPIP34.	
9028	Incorrect hardware configuration change has been detected.	SVCDOCS
	Reduce the number of arrays on IOP. Either move all devices in an array to	
	another IOP that supports arrays, or stop an array on this IOP.	
9029	Incorrect hardware configuration change has been detected.	SVCDOCS
	Contact your next level of support.	
902F	Array addendum Product Activity Log entry	
	This entry contains additional array information for 90xx reference codes when the array contains more than 10 members. Use the 90xx entry that occurred at the same time as this reference code as the starting point for this problem.	
9030	Array no longer protected due to missing or failed disk unit	SVCDOCS
	Perform IOPIP21.	
9031, 9040	Array protection temporarily suspended	
	No action required. Protection will be automatically restarted.	
9041	Background array parity check detected and corrected errors	AJDGP01
	Call your next level of support to report the problem.	
9050	Required cache data cannot be located for a disk unit.	SVCDOCS
	Perform IOPIP30.	
9051	IOP cache data exists for a missing or failed device.	SVCDOCS
	If all configured units are missing, a 9054 reference code may appear in the product activity log. If so, perform the action indicated for the 9054 reference code.	
	Otherwise, perform IOPIP27.	
9052	Cache data exists for device that has been modified.	SVCDOCS
	Perform IOPIP28.	

Reference Code		
9053	IOP resources not available due to previous problems.	SVCDOCS
	Take action on other IOP reference codes which have surfaced.	
	If you cannot get to SST or DST, and cannot perform a type A or B IPL, perform a type D IPL from removable media. Look for Product Activity Log entries for other IOP reference codes and take action on them.	
9054	IOP resources not available due to previous problems.	SVCDOCS
	Power off the system and remove all new or replacement disk units. IPL the system to DST. If you cannot perform a type A or B IPL, perform a type D IPL from removable media.	
	Look for Product Activity Log entries for other IOP reference codes and take action on them.	
9081	I/O processor card detected device error	FI01105 STORIOA
9082	I/O processor card detected device error	FI01105
	Perform IOPIP16.	STORIOA FI01140 BACKPLN FI01106
9090	Disk unit has been modified after the last known status.	SVCDOCS
	Re-IPL the system. If any reference codes are surfaced, go to List of system reference codes and use the new reference code as the entry point to the problem.	
	If you cannot resolve the problem, contact your next level of support.	
9091	Incorrect hardware configuration change has been detected.	SVCDOCS
	Re-IPL the system. If any reference codes are surfaced, go to List of system reference codes and use the new reference code as the entry point to the problem.	
	If you cannot resolve the problem, contact your next level of support.	
9092	Disk unit requires initialization before use.	SVCDOCS
	Perform IOPIP26.	
B3B1 to B3B7	A permanent I/O processor failure occurred	IOP
B3B8	Multi-adapter bridge error detected. MA_BRDG IOP	
B3B9	A permanent I/O processor failure occurred	IOP
B3E0 to B3E1	I/O processor detected a fault condition. IOP MA_BRDG	
B410 to B411	A permanent I/O processor failure occurred STORIOA	
B412	Tape/CD or disk bus interface error occurred       FI01107         FI01140       FI01140         Perform IOPIP16.       STORIOA         DEVTERM	
B935	Unknown hardware detected	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
BE00	I/O processor detected a fault condition.	AJDGP01 IOP FI01104 MA_BRDG
FF3D	I/O adapter detected a recoverable error	STORIOA ANYBRDG
FF6D	I/O processor detected a recoverable system bus error	IOP ANYBUS

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDG301	Vertical Licensed Internal Code	Service Functions; APAR or LICTR
AJDGP01	I/O card Licensed Internal Code	Service Functions; APAR or LICTR
AJDGP01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
ANYBRDG	System I/O bus or any attached card	See the service documentation for instructions.
ANYBUS	IOP card bus error	See the service documentation for instructions.
BACKPLN	Card Enclosure or Planar Board	See the service documentation for instructions.
САСНВАТ	Cache battery pack	See the service documentation for instructions.
CACHE	Cache adaptor card	See the service documentation for instructions.
CMPRES1	Compressed device and compression IOA are not compatible	See the service documentation for instructions.
CTLPNL	Control panel, or the interface to the Control panel	See the service documentation for instructions.
DEVBPLN	Device backplane	See the service documentation for instructions.
DEVTERM	Terminating plug	See the service documentation for instructions.
FCIOA	Fibre Channel IOA	See the service documentation for instructions.
IOACNFG	Configuration error	See the service documentation for instructions.
IOP	I/O processor card	See the service documentation for instructions.
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.
MEDIA	Defective media	See the service documentation for instructions.
OPT_CLN	Fiber optic cleaning kit	See the service documentation for instructions.
PCIBUS	Any PCI card on the PCI bus	See the service documentation for instructions.
STORIOA	Storage I/O adapter	See the service documentation for instructions.
SVCDOCS	Customer engineer directed to system problem analysis	See the service documentation for instructions.
USER	System Operator/User	See the service documentation for instructions.

# (2750, 2751) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is

characters 1 through 8 of the bottom 16 character line of function 11 (Word 4). Card locations can be found using the 16 character address. See SRC Address Formats.

3. Find the unit reference code in the following table.

#### Table 1. (2750, 2751) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B980 to B983	I/O adapter hardware error detected	FI00719 FI00730

# (2761) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

#### Table 1. (2761) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B980 to B983	I/O adapter hardware error detected	FI00719
	•	FI00730

# (2765, 2766, 2787, 280D, 280E, 5704) Reference Codes

For use by authorized service providers.

If the error is reported on the control panel, the unit reference code is characters 5 through 8 of the top 16 character line of function 11. If the error is reported on the console, the unit reference code is the 4 rightmost characters of word 1.

Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing Items Details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items Failing Item	
3020	I/O processor detected a configuration error Either too many devices or the wrong kind of devices have been configured under the IOA. Change the configuration.	SVCDOCS
3100	I/O processor card detected interface error	FCINTF ANYFC FCIOA OPT_CLN

Reference Code	ference Code Description/Action Perform all actions before exchanging Failing Items	
3120	I/O processor detected a port failure	FCPORT FCIOA FCDEV OPT_CLN
3140	I/O Processor detected that a port is now operational This reference code and the 3120 reference code that occurred before it require no service action, since the port is now operational.	
3400	I/O processor card detected device error	FCDEV FCINTF ANYFC FCIOA OPT_CLN
34FF	Format in progress The device indicated that a format is in progress. When the format is complete, the device should be useable. No action is required. This reference code is logged for information only.	
8130, 8140	Recovered Fibre Channel interface error No action required. This reference code is logged for information only.	
8141	IOA detected recoverable device error         No action required. This reference code is logged for information only.	
8145	A recoverable I/O processor error occurred.	FCIOA OPT_CLN
8146	Disk device detected recoverable error	FCDEV
8150	A permanent I/O processor failure occurred	FCIOA ANYBRDG OPT_CLN
8151	I/O processor Licensed Internal Code error FCIOA IOP OPT_CLN	
8155 to 8156	A permanent I/O processor failure occurred AJDGP01 FCIOA OPT_CLN	
9091 to 9092	Incorrect hardware configuration change has been detected.SVCDOCSReset the I/O processor and then IPL the I/O processor. For information on how to reset and IPL the I/O processor, see "Debug the Resource" in the "Hardware Service Manager" section of the <i>iSeries Service Functions</i> . If an I/O processor reset and I/O processor IPL does not resolve the problem, contact your next level of support.	
FF3D	Recovered IOA error	FCIOA ANYBRDG OPT_CLN

Failing Item	Description	Document Description
AJDGP01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR

#### 2765, 2766, 2787, 280D, 280E, 5704

Failing Item	Description	Document Description
ANYBRDG	System I/O bus or any attached card	Problem Analysis; Symbolic FRU Isolation
ANYFC	Any Fibre Channel device	Problem Analysis; Symbolic FRU Isolation
FCDEV	Fibre Channel device	Problem Analysis; Symbolic FRU Isolation
FCINTF	Fibre Channel interface	Problem Analysis; Symbolic FRU Isolation
FCIOA	Fibre Channel IOA	Problem Analysis; Symbolic FRU Isolation
FCPORT	Port not operational	Problem Analysis; Symbolic FRU Isolation
IOP	I/O processor card	Problem Analysis; Symbolic FRU Isolation
OPT_CLN	Fiber optic cleaning kit	Problem Analysis; Symbolic FRU Isolation
SVCDOCS	Customer engineer directed to system problem analysis	Problem Analysis; Symbolic FRU Isolation

# (2771, 2772) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (Word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items Failing Item	
B904	I/O adapter Licensed Internal Code failed.	AJDGP01 FI00719
B934	Incompatible hardware detected.	FI00719 FI00718
B940	I/O adapter hardware error detected	FI00719 FI00718 AJDGP01 MA_BRDG
B941 to B942	One half of I/O adapter failed.	FI00719 FI00718 AJDGP01

#### Table 1. (2771, 2772) Reference codes

Failing Item	Description	Document Description
AJDGP01	LIC - Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- **3**. Find the unit reference code in the following table.

#### Table 1. (281x) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B910	I/O adapter hardware error detected	FI00719 FI00730 FI00718

# (2838, 2849) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (Word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- **3**. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B904	I/O adapter Licensed Internal Code failed.	AJDGP01 FI00719
B930	I/O adapter Licensed Internal Code failed.	AJDGP01 FI00718 FI00719
B931	I/O adapter hardware error detected	FI00719 FI00718 AJDGP01 MA_BRDG
B933	Incompatible hardware detected.	FI00719 AJDGP01

#### Table 1. (2838, 2849) Reference codes

Failing Item	Description	Document Description
AJDGP01	LIC - Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR

Failing Item	Description	Document Description
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.

# (283C, 283D, 283F, 28B9, 28BC, 28CB, 28CC, 28CD, 506D, 506E, 5306) Device backplane reference codes

For use by authorized service providers.

- 1. If the error is reported on the control panel, the unit reference code is characters 5 through 8 of the top 16 character line of function 11. If the error is reported on the console, the unit reference code is the 4 rightmost characters of word 1.
- 2. Find the unit reference code in the following table.

**Attention:** The 673x is a read cache. Perform all actions required for 673x as a disk drive and logic card except where separate 673x cache instructions are provided.

For more on the Failing Item column entries, see Table 2. Device backplane failing items details, which follows the reference code table below.

Table 1. (283C, 283D, 283F, 28B9, 28BC, 28CB, 28CC, 28CD, 506D, 506E, 5306) Device backpla	ane
reference codes	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1511	A non-fatal error occurred on power supply 1	DISKPWR DISKFAN FI01106 DEVBPLN
1515	A fatal error occurred on power supply 1	DISKPWR DISKFAN FI01106 DEVBPLN
1521	A non-fatal error occurred on power supply 2	DISKPWR DISKFAN FI01106 DEVBPLN
1525	A fatal error occurred on power supply 2	DISKPWR DISKFAN FI01106 DEVBPLN
3002	Addressed device backplane failed to respond to selection	DEVBPLN STORIOA FI01140 FI01106
3109	I/O adapter timed out a device backplane command	DEVBPLN STORIOA FI01140 FI01106
7611	A fatal error occurred on redundant fan 1	DISKFAN
7614	A fatal error occurred on fan 1	DISKFAN
7621	A fatal error occurred on redundant fan 2	DISKFAN
7624	A fatal error occurred on fan 2	DISKFAN
7631	A fatal error occurred on redundant fan 3	DISKFAN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7634	A fatal error occurred on fan 3	DISKFAN
8401	Removable media power fault	DEVBPLN
8404	System log entry only, no service action required	
FFF4	Device backplane problem	DEVBPLN STORIOA FI01140 FI01106

#### Table 2. Device backplane failing items details

Failing Item	Description	Document Description
08F5352	Token-ring network adapter	Repair and Parts; removal and installation procedures
08F5361	Communications input/output processor card	Repair and Parts; removal and installation procedures
17G2504	Tape Unit	Repair and Parts; removal and installation procedures
21F1511	Internal power cable	Repair and Parts; removal and installation procedures
21F1512	Internal power cable	Repair and Parts; removal and installation procedures
21F1512	Internal power cable	Repair and Parts; removal and installation procedures
21F1513	Internal signal cable	Repair and Parts; removal and installation procedures
21F1514	Internal power cable	Repair and Parts; removal and installation procedures
21F1519	Internal signal cable	Repair and Parts; removal and installation procedures
21F1530	Card enclosure	Repair and Parts; removal and installation procedures
21F1687	Diskette adapter card	Repair and Parts; removal and installation procedures
21F1688	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
21F1689	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
21F2070	Bus cable	Repair and Parts; removal and installation procedures
21F3986	Tape I/O processor card	Repair and Parts; removal and installation procedures
21F4383	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
21F4493	Ethernet controller card	Repair and Parts; removal and installation procedures
21F4579	Disk drive logic card	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description
21F4863	Magnetic storage device IOP card	Repair and Parts; removal and installation procedures
21F4867	Communication adapter	Repair and Parts; removal and installation procedures
21F4868	Communication adapter	Repair and Parts; removal and installation procedures
21F4869	Token-ring controller card	Repair and Parts; removal and installation procedures
21F4882	Diskette adapter card	Repair and Parts; removal and installation procedures
21F4882	Diskette adapter card	Repair and Parts; removal and installation procedures
21F5620	Disk unit power regulator	Repair and Parts; removal and installation procedures
21F5620	Disk unit power regulator	Repair and Parts; removal and installation procedures
21F5650	AC Module	Repair and Parts; removal and installation procedures
21F5680	AC Module	Repair and Parts; removal and installation procedures
21F5772	Control panel	Repair and Parts; removal and installation procedures
21F5774	External signal cable	Repair and Parts; removal and installation procedures
21F5774	Cable assembly	Repair and Parts; removal and installation procedures
21F5861	Tape Unit	Repair and Parts; removal and installation procedures
21F8566	Tape Unit	Repair and Parts; removal and installation procedures
21F8633	Tape Unit	Repair and Parts; removal and installation procedures
21F8719	Tape Unit	Repair and Parts; removal and installation procedures
21F8872	Cable Carrier	Repair and Parts; removal and installation procedures
21F8890	D/SE Module	Repair and Parts; removal and installation procedures
21F9208	ISDN adapter card	Repair and Parts; removal and installation procedures
21F9215	Power regulator card	Repair and Parts; removal and installation procedures
21F9586	Cable assembly	Repair and Parts; removal and installation procedures
21F9907	Cable assembly	Repair and Parts; removal and installation procedures
21F9937	Cable assembly	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description
21F9951	Tape Unit	Repair and Parts; removal and installation procedures
21F9987	Tape unit IOP card	Repair and Parts; removal and installation procedures
2452557	Fan	9346 Service Guide; Installation and Removal, SY31-0688
26F5028	Communication adapter	Repair and Parts; removal and installation procedures
375892	Power cord; U.S.A., Asia-Pacific group, Americas group	
4234002	Test diskette (8 inch)	System operation information
46F4115	Ethernet network adapter card	Repair and Parts; removal and installation procedures
46F4239	Token-ring network adapter	Repair and Parts; removal and installation procedures
55F5199	Disk drive logic card	Repair and Parts; removal and installation procedures
55F5209	Disk drive and logic card	Repair and Parts; Recovery Procedures
59X4718	Communications input/output processor card	Repair and Parts; removal and installation procedures
59X4723	Tape unit IOP card	Repair and Parts; removal and installation procedures
59X4723	Tape I/O processor card	Repair and Parts; removal and installation procedures
59X4723	Token-ring network adapter	Repair and Parts; removal and installation procedures
59X4819	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
6369759	Test diskette (5-1/4 inch)	System operation information
6369881	Diskette unit	Repair and Parts; removal and installation procedures
6462385	Power cord; Europe, Mid-East, Asia	
6495268	External signal cable	9346 Service Guide; Installation and Removal, SY31-0688
72X5631	Terminating plug	Repair and Parts; removal and installation procedures
72X5631	Terminating plug	9346 Service Guide; Installation and Removal, SY31-0688
72X5631	Terminating plug	Repair and Parts; removal and installation procedures
72X6361	Diskette unit	Repair and Parts; removal and installation procedures
72X6374	Work station attachment	Repair and Parts; removal and installation procedures
72X6385	Magnetic storage device IOP card	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description
72X6386	Diskette adapter card	Repair and Parts; removal and installation procedures
72X6387	Communications I/O processor card	Repair and Parts; removal and installation procedures
72X6388	Communications adapter card	Repair and Parts; removal and installation procedures
72X6389	Multiple interface adapter	Repair and Parts; removal and installation procedures
72X6390	Communications adapter card	Repair and Parts; removal and installation procedures
72X6391	Token-ring network adapter	Repair and Parts; removal and installation procedures
73F8987	Disk drive and logic card	Repair and Parts; Recovery Procedures
73F8994	Disk drive logic card	Repair and Parts; removal and installation procedures
73F9138	Planar board	Repair and Parts; removal and installation procedures
73F9139	Planar board	Repair and Parts; removal and installation procedures
73F9166	Planar board	Repair and Parts; removal and installation procedures
73F9193	Power regulator card	Repair and Parts; removal and installation procedures
73F9232	Cable assembly	Repair and Parts; removal and installation procedures
73F9244	Disk unit power regulator	Repair and Parts; removal and installation procedures
73F9267	ASCII work station IOP card	Repair and Parts; removal and installation procedures
73F9290	Control panel	Repair and Parts; removal and installation procedures
73F9290	Control panel	Repair and Parts; removal and installation procedures
73F9345	Tape Unit	Repair and Parts; removal and installation procedures
73F9393	Tape Unit	Repair and Parts; removal and installation procedures
74F1541	Card enclosure	Repair and Parts; removal and installation procedures
74F1542	Card enclosure	Repair and Parts; removal and installation procedures
74F1543	Card enclosure	Repair and Parts; removal and installation procedures
74F1544	Card enclosure	Repair and Parts; removal and installation procedures
74F1649	Tape Unit	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description
74F1760	DC Bulk Module	Repair and Parts; removal and installation procedures
74F2201	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
74F2232	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
79X3795	Terminating plug	Repair and Parts; removal and installation procedures
8266352	Power supply	9346 Service Guide; Installation and Removal, SY31-0688
85F7295	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
85F7305	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
85F7405	Base power supply	Repair and Parts; removal and installation procedures
85F7418	Cable assembly	Repair and Parts; removal and installation procedures
85F7646	Magnetic storage device IOP card	Repair and Parts; removal and installation procedures
85F7846	Terminating plug	Repair and Parts; removal and installation procedures
85F9785	Control panel	Repair and Parts; removal and installation procedures
85F9840	Internal signal cable	Repair and Parts; removal and installation procedures
85F9845	Internal power cable	Repair and Parts; removal and installation procedures
92X3030	Feature power supply	Repair and Parts; removal and installation procedures
92X3080	Disk unit power regulator	Repair and Parts; removal and installation procedures
92X4041	Diskette unit	Repair and Parts; removal and installation procedures
92X4044	Cable assembly	Repair and Parts; removal and installation procedures
92X4091	Cable assembly	Repair and Parts; removal and installation procedures
92X4143	Planar board	Repair and Parts; removal and installation procedures
92X6551	Planar board	Repair and Parts; removal and installation procedures
92X7512	Flex cable	9346 Service Guide; Installation and Removal, SY31-0688
92X7514	Internal tape unit signal cable	9346 Service Guide; Installation and Removal, SY31-0688
92X7515	Internal signal cable	9346 Service Guide; Installation and Removal, SY31-0688

Failing Item	Description	Document Description
92X7516	Internal power cable	9346 Service Guide; Installation and Removal, SY31-0688
93X0901	Disk drive logic card	Repair and Parts; removal and installation procedures
93X0911	Disk drive and logic card	Repair and Parts; Recovery Procedures
93X2520	Disk drive and logic card	Repair and Parts; Recovery Procedures
93X2701	I/O processor card	Repair and Parts; removal and installation procedures
93X2730	9346 IOP card	Repair and Parts; removal and installation procedures
93X2777	I/O processor card	Repair and Parts; removal and installation procedures
A0B00E1	Licensed Internal Code for programmable tape unit	Service Functions; APAR or LICTR
AJDG301	Vertical Licensed Internal Code	Service Functions; APAR or LICTR
AJEDA00	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
AJEDA00	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
AJEH901	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
AJGJQ01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
AJSLC01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
AJSLC01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
BACKPLN	Card enclosure or backplane	See the service documentation for instructions.
CMPRES1	Compressed device and compression IOA are not compatible	See the service documentation for instructions.
DEVBPLN	Device backplane	See the service documentation for instructions.
DEVTERM	Device terminator	See the service documentation for instructions.
DISKDRV	Disk drive and logic card	See the service documentation for instructions.
DISKDRV	Disk drive and logic card	See the service documentation for instructions.
DISKDRV	Disk drive and logic card	See the service documentation for instructions.
DISKDRV	Disk drive and logic card	See the service documentation for instructions.
DISKDRV	Disk drive and logic card	See the service documentation for instructions.
DISKDRV	Disk drive and logic card	See the service documentation for instructions.
DISKDRV	Disk drive and logic card	See the service documentation for instructions.
DISKFAN	Fan assembly	See the service documentation for instructions.
DISKLC	Disk drive logic card	See the service documentation for instructions.
DISKLC	Disk drive logic card	See the service documentation for instructions.
DISKLC	Disk drive logic card	See the service documentation for instructions.
DISKLC	Disk drive logic card	See the service documentation for instructions.
DISKLC	Disk drive logic card	See the service documentation for instructions.
DISKLC	Disk drive logic card	See the service documentation for instructions.
DISKLC	Disk drive logic card	See the service documentation for instructions.
DISKPWR	Power Supply	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.

Failing Item	Description	Document Description
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
MSEDMED	Defective diskette	System operation information
MSETCAR	Defective tape or damaged cartridge	System operation information
MSETFOR	The data format is incorrect; the tape cannot be read	System operation information
MSETMED	Defective removable media	System operation information
STORIOA	Storage I/O adapter	See the service documentation for instructions.
SVCDOCS	Customer engineer directed to system problem analysis	See the service documentation for instructions.
USEUSER	System Operator/User	System operation information

## (287F) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

#### Table 1. (287F) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B9A0	I/O adapter hardware error detected	FI00719 AJDGP01

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDGP01	Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR

# (3490) Tape unit reference codes

For use by authorized service providers.

A tape or a 3490 Tape Unit failure occurred.

Note: For tape device and IOP reset procedures, see TU-PIP4.

- 1. Is the operating system available and can you enter commands from the command line?
  - **Yes**: Is OS/400<sup>®</sup> available on the system (see "Determining the Dominant Operating System" in the *iSeries Service Functions*)?
    - Yes: Use the online problem analysis procedures to isolate the problem. Use the Work with Problem (WRKPRB) command to determine if a recent problem was entered in the problem log, or use the Verify Tape (VFYTAP) command to run verification tests.
    - **No**: Continue with the next step.
  - No: Continue with the next step.
- 2. Verify that the 3490 is powered on.
- 3. Verify that the channel Enable/Disable switches are set to the Enable position.
- 4. Verify that the 3490 online/offline switches are set to the online position.
- 5. Load the first tape.
- 6. Start a type **D** IPL from the system unit control panel.

Does the IPL complete successfully?

• Yes: The problem has been corrected.

#### This ends the procedure.

- No: Obtain another copy of the tape. Repeat steps 5 and 6 using the new tape. If this does not correct the problem, continue with the next step.
- 7. Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code.
- **8**. If the 3490 indicator panel shows a check (CHK) code or an error code, see the "Start" section of the 3490 service information.
- 9. See SRC Address Formats to determine the IOP, IOA, and device address.
- 10. Find the unit reference code in the following table.
- 11. See the "Start" section of the 3490 service information.

For more on the Failing Item column entries, see Table 2. Tape unit failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0xxx, 1xxx, 2000	Tape unit failure Use online problem analysis and the 3490 Tape Unit service information to	
	analyze the problem.	
2001	Tape path dirty or write data check error	MHK0001
	Clean the tape path using the cleaning procedures in the 3490 Magnetic Tape Subsystem Operator's Guide, GA32-0124.	DHK0002
	Use the 3490 Tape Unit service information to continue analyzing the problem.	

#### Table 1. (3490) Tape unit reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
2003	Tape path dirty or write identification record error	MHK0001 DHK0002
	Clean the tape path using the cleaning procedures in the 3490 Magnetic Tape Subsystem Operator's Guide, GA32-0124.	
	Use the 3490 Tape Unit service information to continue analyzing the problem.	
2008	Tape path dirty or read data check error	MHK0001
	Clean the tape path using the cleaning procedures in the 3490 Magnetic Tape Subsystem Operator's Guide, GA32-0124.	DHK0002
	Use the 3490 Tape Unit service information to continue analyzing the problem.	
2009	Tape path dirty or read identification record error	MHK0001
	Clean the tape path using the cleaning procedures in the 3490 Magnetic Tape Subsystem Operator's Guide, GA32-0124.	DHK0002
	Use the 3490 Tape Unit service information to continue analyzing the problem.	
2010	Tape unit failure	
	Use online problem analysis and the 3490 Tape Unit service information to continue analyzing the problem.	
2014	Recoverable tape unit failure; logged only	
	No action required. This reference code is logged for information only.	
2015	Tape unit failure	DHK0002
	Clean the tape path using the cleaning procedures in the 3490 Magnetic Tape Subsystem Operator's Guide, GA32-0124.	FI00856 FI00845
	Use the 3490 Tape Unit service information to continue analyzing the problem.	
2017	Write Protect violation reported by tape unit; logged only	
	No action required. This reference code is logged for information only.	
202x, 205x, 206x,	Tape unit failure	
21xx, 22xx	Use online problem analysis and the 3490 Tape Unit service information to continue analyzing the problem.	
23xx	Tape Library failure	
	Use the 3494 Tape Library Dataserver Maintenance Information to analyze the problem.	
26xx, 27xx, 3xxx,	Tape unit failure	
4xxx, 5xxx, 6xxx, 7xxx, 8xxx	Use online problem analysis and the 3490 Tape Unit service information to continue analyzing the problem.	
9020	I/O processor detected a SCSI bus configuration error	UHKCNFG
	Before exchanging any parts, verify that the following conditions are not present:	FI00851 FI00130
	• Tape and DASD devices attached to the same type 6501 I/O processor	
	• A device type or model that is not given support	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9100	Interface error detected by I/O processor or by tape unit	FI00851
	Before exchanging any parts, do the following:	FI00856 05H3834
	1. Ensure that an interposer is connected between the I/O processor and the SCSI cable.	EXTSCSI 61G8324
	2. Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	<b>3</b> . Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9200	I/O processor addressed the tape unit; no response	FI00851
	Before exchanging any parts, do the following:	FI00856 05H3834
	1. Ensure that the device is powered on.	EXTSCSI
	2. Ensure that an interposer is connected between the I/O processor and the SCSI cable.	61G8324
	<b>3</b> . Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9201	Tape unit command timeout	FI00851 FI00856
	Before exchanging any parts, do the following:	05H3834
	1. Ensure that the device is powered on.	EXTSCSI
	2. Ensure that an interposer is connected between the I/O processor and the SCSI cable.	61G8324
	<b>3</b> . Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9210	Illegal or unsupported tape unit response	FI00851 FI00856 FI00130
9300	Tape unit failure	DHK0002
9301	Tape device failure, redundancy lost	DHK0002
	The tape unit detected a hardware failure that does not prevent the tape unit from completing the present operation.	
	See the 3590 Tape Unit service information to determine the failing item.	
9302	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, take a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i> information or ask your next level of support for assistance.	
9310	Licensed Internal Code for the tape unit is not correct	FI00851 FI00130

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9320	Tape device Licensed Internal Code failure	FI00851
	Do the following:	
	<ol> <li>Take a dump of the tape device Licensed Internal Code (see the 3490 Tape Drive service information).</li> </ol>	
	2. Power off the tape unit. Then power on the tape unit to resume operation.	
9350	Tape unit detected a read or write error on tape medium	MHKTMED
	A permanent read or write error occurred, and the tape unit determined that the tape cartridge is defective. Exchange the tape cartridge.	UHKCLN FI00851
9351	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, take a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i> information or ask your next level of support for assistance.	
9355	The data format is incorrect; the tape cannot be read	MHKTMED
	The tape device does not give support to the data format on the tape cartridge. Re-initialize the tape cartridge or use a different tape cartridge.	UHKCLN FI00851
9500	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, take a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i> information or ask your next level of support for assistance.	
96xx	Tape unit failure	
	Use online problem analysis and the 3490 Tape Unit service information to continue analyzing the problem.	
9800 to 9803	I/O processor successfully recovered from temporary error	
	No action required. This reference code is logged for information only.	
9810	Problem analysis has determined a part should be replaced.	
	This reference code is used for ending Online Problem Analysis with a list of failing items. (Information Only)	
9899	Problem analysis completed, the problem has been corrected.	UHKFIXD
	This reference code is used for ending Online Problem Analysis when no problem was found or the problem was corrected.	
9900	Licensed Internal Code for tape unit was not upgraded	
	The I/O processor loading of Licensed Internal Code (LIC) to the programmable tape unit was not completed.	
	The tape unit will continue to operate with the previous LIC. You may do either of the following:	
	• Wait for next IPL when the system will attempt to load the LIC for the tape unit again.	
	• Perform TU-PIP4 to reset the IOP and the tape unit. When the IOP is reset, if the device has the wrong level of LIC, the IOP will attempt to load the new LIC.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
Axxx, Bxxx, Cxxx, Dxxx, Exxx, F00x	Tape unit failure	
	Use online problem analysis and the 3490 Tape Unit service information to continue analyzing the problem.	
FFD5	Device error reported; tape I/O processor	UHK0003 DHK0002
	Verify the following:	
	1. That power is switched on in the 3490 Tape Unit Rack:	
	• Set the 3490 Rack Unit Emergency Power Off switch to the On position.	
	• Ensure that the 3490 Rack Enable/Off switch is set to the Enable position.	
	Press the 3490 Rack Power On button.	
	2. Verify the following on 3490 Tape Unit:	
	• The Channel Enable/Disable switches are set to the Enable position.	
	• The Normal/Test switch is set to the Normal position.	
	• The CU Online/Offline switch is set to the Online position.	
	The Drive Address Online/Offline switches are set to the Online position.	
	• The Drive DC Power switches are set to the On position.	
	If you are attempting to perform an IPL from the device that had the error, verify that the drive control unit address switch has an address of hexadecimal 7 and the drive unit address switch has an address of 0.	
	Use the 3490 Tape Unit service information to continue analyzing the problem.	
FFF6	Volume statistics; logged only	
	No action required. This reference code is logged for information only.	

## Table 2. Tape unit failing items details

Failing Item	Description	Document Description
05H3834	Interposer	Magnetic tape subsystem service information
61G8324	Terminating plug	Magnetic tape subsystem service information
DHK0002	I/O device	Use the sense bytes and 3490 MI to find the failing items
EXTSCSI	External signal cable	Problem Analysis; Symbolic FRU Isolation
MHK0001	Таре	Magnetic tape subsystem operator's information
MHKTMED	Defective tape	Magnetic tape subsystem operator's information
UHK0003	I/O device not communicating	Magnetic tape subsystem operator's information
UHKCLN	Tape unit needs cleaning	Magnetic tape subsystem operator's information
UHKCNFG	Tape configuration detected by I/O processor; not valid	Installation
UHKUSRT	System Operator/User	System operation information

## (3494) Tape library reference codes

For use by authorized service providers.

A tape or a tape library failure occurred.

Note: For tape device and IOP reset procedures, see TU-PIP4.

- 1. Is the operating system available and can you enter commands from the command line?
  - Yes: Is OS/400 available on the system (see "Determining the Dominant Operating System" in the *iSeries Service Functions*)?
    - Yes: Use the online problem analysis procedures to isolate the problem. Use the Work with Problem (WRKPRB) command to determine if a recent problem was entered in the problem log, or use the Verify Tape (VFYTAP) command to run verification tests.
    - No: Continue with the next step.
  - No: Continue with the next step.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Tape library failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item	
2301	Library device failure	3494	
	Library attachment facility equipment check.		
	Use the 3494 Tape Library Dataserver Maintenance Information and follow the procedures for analyzing a "LIBRARY PROBLEM - NO ERROR MESSAGE."		
2303	Library device failure	DHALIBC	
	Device control unit and library manager Licensed Internal Code are incompatible.	DHADEVC	
	Use the 3494 Tape Library Dataserver Maintenance Information and follow the procedures for analyzing a "LIBRARY PROBLEM - NO ERROR MESSAGE."		
2306 to 2307	Library device failure	3494	
	Library vision failure.		
	Use the 3494 Tape Library Dataserver Maintenance Information and follow the procedures for analyzing a "LIBRARY PROBLEM - NO ERROR MESSAGE."		
2308	Library device failure	3494	
	Library manager equipment check.		
	Use the 3494 Tape Library Dataserver Maintenance Information and follow the procedures for analyzing a "LIBRARY MANAGER HARDWARE PROBLEM"		

Table 1. (3494) Tape library reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item	
2309	Library device failure	3494	
	Library equipment check.		
	Use the 3494 Tape Library Dataserver Maintenance Information and follow the procedures for analyzing a "LIBRARY PROBLEM - NO ERROR MESSAGE."		
2310 to 2311	Library device requires operator intervention		
	Put the library into pause mode and perform the intervention indicated on the library manager console.		
2319	Tape unit failure	FI00851	
	Use the tape unit service information to analyze the failure.		
2321	Library enclosure environmental alert was detected.	3494	
	Use the 3494 Tape Library Dataserver Maintenance Information and follow the procedures for analyzing a "LIBRARY PROBLEM - NO ERROR MESSAGE."		

#### Table 2. Tape library failing items details

Failing Item	Description	Document Description
3494	Library device	IBM 3494 Maintenance Information, SA37-0270
DHADEVC	3490 Control Unit Licensed Internal Code	Refer to I/O device service information
DHALIBC	3494 Library Manager Licensed Internal Code	IBM 3494 Maintenance Information, SA37-0270

# (3570) Tape unit reference codes

For use by authorized service providers.

A tape or a 3570 Tape Unit failure occurred.

Note: For tape device and IOP reset procedures, see TU-PIP4.

- 1. Is the operating system available and can you enter commands from the command line?
  - Yes: Is OS/400 available on the system (see "Determining the Dominant Operating System" in the *iSeries Service Functions*)?
    - Yes: Use the online problem analysis procedures to isolate the problem. Use the Work with Problem (WRKPRB) command to determine if a recent problem was entered in the problem log, or use the Verify Tape (VFYTAP) command to run verification tests.
  - No: Continue with the next step.
  - No: Continue with the next step.
- 2. Verify that the 3570 is powered on.
- 3. Ensure that the 3570 SCSI address is set to "0".
- 4. Load the first tape.
- 5. Start a type **D** IPL from the system unit control panel. Does the IPL complete successfully?
  - Yes: The problem has been corrected. This ends the procedure.

- No: Obtain another copy of the tape. Repeat this step using the new tape. If this does not correct the problem, continue with the next step of this procedure.
- **6**. Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code.
- 7. If the amber light on the 3570 indicator panel is on continuously, see the "Start" section of the 3570 service information.
- 8. See SRC Address Formats to determine the IOP, IOA, and device address.
- 9. Find the unit reference code in the following table.
- 10. See the "Start" section of the 3570 service information.

For more on the Failing Item column entries, see Table 2. Tape unit failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9020	I/O processor detected a SCSI bus configuration error	UHZCNFG DHZDEV
	Before exchanging any parts, verify that the following conditions are not present:	FI00130
	• Tape and DASD devices attached to an I/O processor that does not support tape and DASD devices at the same time.	
	• A device type or model that is not given support.	
9100	Interface error detected by I/O processor or by tape unit Before exchanging any parts, do the following:	DHZDEV FI00131 05H3834
	<ol> <li>Ensure that an interposer is connected between the I/O processor and the SCSI cable.</li> </ol>	EXTSCSI 61G8324
	2. Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	<b>3.</b> Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9101	Fibre Channel interface error detected	FCIOA FCDEV
	If the attached device is an external device, do the following before exchanging any parts:	FCCABLE
	1. Ensure that the Fibre Channel cable is correctly connected to the ports.	
	2. Clean the Fibre Channel connectors.	
	<b>3</b> . If there is a hub attached, verify that the hub is operational.	
	4. If there is a gateway device attached, refer to the gateway device service documentation for additional problem analysis procedures.	
	5. refer to the tape device service documentation for additonal problem analysis procedures.	
9102	Gateway device detected a SCSI interface error	DHZDEV FCGATE
	Use the gateway device service documentation to analyze the problem.	EXTSCSI 61G8324

Table 1. (3570) Tape unit reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9200	I/O processor addressed the tape unit; no response	DHZDEV FI00131
	Before exchanging any parts, do the following:	05H3834
	1. Ensure that the device is powered on.	EXTSCSI
	2. Ensure that an interposer is connected between the I/O processor and the SCSI cable.	61G8324
	<b>3</b> . Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9201	Tape unit command timeout	DHZDEV FI00131
	Before exchanging any parts, do the following:	05H3834
	1. Ensure that the device is powered on.	EXTSCSI
	2. Ensure that an interposer is connected between the I/O processor and the SCSI cable.	61G8324
	<b>3</b> . Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9202	Tape unit failed after Licensed Internal Code was loaded	DHZDEV
	Before exchanging any parts, do the following:	FI00131 05H3834
	1. Ensure that the device is powered on.	EXTSCSI
	<ol> <li>Ensure that an interposer is connected between the I/O processor and the SCSI cable.</li> </ol>	61G8324
	<b>3</b> . Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9210	Illegal or unsupported tape unit response	DHZDEV FI00131 FI00130
9211	Gateway device detected a bus protocol error	FCGATE
	Use the gateway device service documentation to analyze the problem.	FCIOA DHZDEV ANYFC FCCABLE EXTSCSI 61G8324
9300	Tape unit failure	DHZDEV
9301	Tape device failure, redundancy lost	DHZDEV
	The tape unit detected a hardware failure that does not prevent the tape unit from completing the current operation.	
	Refer to the 3570 Tape Unit service information to determine the failing item.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9302	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, perform a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i>	
9303	Gateway device failure	FCGATE
	Use the gateway device service documenation to analyze the problem.	
9310	Licensed Internal Code for the tape unit is not correct	DHZDEV FI00130
9320	Tape device Licensed Internal Code failure	FI00130 DHZDEV
	Perform the following:	
	1. Take a dump of the tape unit Licensed Internal Code (see the 3570 Tape Unit service information).	
	2. Power off the tape unit. Then power on the tape unit to resume operation.	
	3. Ask your next level of support for assistance.	
9321	Gateway device Licensed Internal Code error	FCCODE
	Use the gateway device service documenation to analyze the problem.	
9350	Tape unit detected a read or write error on tape medium	MHZTMED UHZCLN
	A permanent read or write error occurred, and the tape unit determined that the tape cartridge is defective. Exchange the tape cartridge.	DHZDEV
9351	Tape with excessive error rate was mounted in tape device.	MHZTMED
	The tape unit detected that the mounted tape cartridge has a history of excessive read and write errors. It is recommended that you exchange the tape cartridge.	UHZCLN DHZDEV
9355	The data format is incorrect; the tape cannot be read	UHZUSER
	The tape unit does not give support to the data format on the tape cartridge. Use a different tape cartridge.	MHZTMED UHZCLN DHZDEV
9500	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, perform a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i>	
9800 to 9803	I/O processor successfully recovered from temporary error	
	No action required. This reference code is logged for information only.	
9810	Problem analysis has determined a part should be replaced.	
	This reference code is used for ending Online Problem Analysis with a list of failing items. (Information Only)	
9899	Problem analysis completed, the problem has been corrected.	UHZFIXD
	This reference code is used for ending Online Problem Analysis when no problem was found or the problem was corrected.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item	
9900	Licensed Internal Code for tape unit was not upgraded	UHZUSER	
	The I/O processor loading of Licensed Internal Code (LIC) to the programmable tape unit was not completed.		
	The tape unit will continue to operate with the previous LIC. You may do either of the following:		
	• Wait for next IPL when the system will attempt to load the LIC for the tape drive again.		
	• Perform TU-PIP4 to reset the IOP and the tape unit. When the IOP is reset, if the device has the wrong level of LIC, the IOP will attempt to load the new LIC.		
FFF6	Tape volume statistics logged (no action required)		

Table 2. Tape unit failing items details

Failing Item	Description	Document Description
05H3834	Interposer	IBM 3570 Tape Drive Service Guide
61G8324	Terminating plug	IBM 3570 Tape Drive Service Guide
ANYFC	Any device on Fibre Channel interface	Problem Analysis; Symbolic FRU Isolation
DHZDEV	Tape unit failure	IBM 3570 Tape Drive Service Guide
EXTSCSI	External signal cable	Problem Analysis; Symbolic FRU Isolation
FCCABLE	Fibre Channel cable	Problem Analysis; Symbolic FRU Isolation
FCCODE	Gateway device Licensed Internal Code	Problem Analysis; Symbolic FRU Isolation
FCDEV	Fibre Channel device	Problem Analysis; Symbolic FRU Isolation
FCGATE	Gateway device	IBM SAN Data Gateway Service Guide
FCIOA	Fibre Channel IOA	Problem Analysis; Symbolic FRU Isolation
MHZTMED	Defective tape	Magnetic tape subsystem service information
UHZCLN	Tape unit needs cleaning	Magnetic tape subsystem operator's information
UHZCNFG	Tape configuration detected by I/O processor; not valid	Installation
UHZUSER	Operator action required	System operation information

# (358x, 3592, 4685, 5755, 6279, 6381, 6382, 6383, 6384, 6386, 6387, 63A0, 7207) Tape unit reference codes

A tape unit failure occurred.

Note: For tape device and IOP reset procedures, see TU-PIP4.

- 1. Is the operating system available and can you enter commands from the command line?
  - Yes: Is OS/400 available on the system (see "Determining the Dominant Operating System" in the *iSeries Service Functions*)?
    - Yes: Use the online problem analysis procedures to isolate the problem. Use the Work with Problem (WRKPRB) command to determine if a recent problem was entered in the problem log, or use the Verify Tape (VFYTAP) command to run verification tests.
    - No: Continue with the next step.
  - No: Continue with the next step.

**<sup>192</sup>** iSeries: iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

- 2. Clean the recording head in the tape unit.
- **3**. Attempt the failing operation again.

Does the operation complete successfully?

- Yes: The original data cartridge is defective. The problem has been corrected.
- This ends the procedure.
- No: Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Tape unit failing items details, which follows the reference code table below.

Table 1. (358x, 3592, 4685, 5755, 6279, 6381, 6382, 6383, 6384, 6386, 6387, 63A0, 7207) Tape unit reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9020	I/O processor detected a SCSI bus configuration error	UH7CNFG FI00871
	Before exchanging any parts, verify that the following condition is not present:	FI00130
	• Tape and DASD devices attached to an I/O Processor that does not support Tape and Dasd devices at the same time.	
9100	Interface error detected by I/O processor or by tape unit	FI00871 FI01112
	If the attached device is an external device, do the following before exchanging any parts:	FI01112 FI00872 DEVTERM
	1. If an interposer is required, make sure that it is connected between the I/O processor and the SCSI cable.	
	2. Ensure that the SCSI cable is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	<b>3</b> . Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9101	Fibre Channel interface error detected	FCIOA FCDEV
	If the attached device is an external device, do the following before exchanging any parts:	FCCABLE
	1. Ensure that the Fibre Channel cable is correctly connected to the ports.	
	2. Clean the Fibre Channel connectors.	
	<b>3</b> . If there is a hub attached, verify that the hub is operational.	
	4. If there is a gateway device attached, refer to the gateway device service documentation for additional problem analysis procedures.	
	5. refer to the tape device service documentation for additonal problem analysis procedures.	
9102	Gateway device detected a SCSI interface error	FI00871
	Use the gateway device service documentation to analyze the problem.	FCGATE FI00872 DEVTERM

## 358x, 3592, 4685, 5755, 6279, 6381, 6382, 6383, 6384, 6386, 6387, 63A0, 7207

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9200	I/O processor addressed the tape unit; no response	FI00871 FI01112
	If the attached device is an external device, do the following before exchanging any parts:	FI00872 DEVTERM
	1. Ensure that the device is powered on.	
	2. If an interposer is required, make sure that it is connected between the I/O processor and the SCSI cable.	
	<b>3.</b> Ensure that the SCSI cable is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9201	Tape unit command timeout	FI00871 FI01112
	If the attached device is an external device, do the following before exchanging any parts:	FI00872 DEVTERM
	1. Ensure that the device is powered on.	MH7TMED
	2. If an interposer is required, make sure that it is connected between the I/O processor and the SCSI cable.	
	<b>3.</b> Ensure that the SCSI cable is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9202	Tape unit failed after Licensed Internal Code was loaded	FI00871
	If the attached device is an external device, do the following before exchanging any parts:	FI01112 FI00872 DEVTERM
	1. Ensure that the device is powered on.	
	2. If an interposer is required, make sure that it is connected between the I/O processor and the SCSI cable.	
	<b>3</b> . Ensure that the SCSI cable is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	4. Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9210	Illegal or unsupported tape unit response	FI00871 FI01112 FI00130
9211	Gateway device detected a bus protocol error	FCGATE FCIOA
	Use the gateway device service documentation to analyze the problem.	FI00871 ANYFC FCCABLE FI00872 DEVTERM
9300	Tape unit failure	FI00871
9301	Tape device failure, redundancy lost	FI00871
	The tape unit detected a hardware failure that does not prevent the tape unit from completing the current operation.	

## 358x, 3592, 4685, 5755, 6279, 6381, 6382, 6383, 6384, 6386, 6387, 63A0, 7207

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9302	Tape device failure or media error	MH7TMED FI00871
	The tape unit detected a failure that may be caused by a hardware failure or a media error.	
	Refer to the tape unit service information for possible information on diagnositic tests that can be run to isolate between hardware and media failures.	
9303	Gateway device failure	FCGATE
	Use the gateway device service documenation to analyze the problem.	
9310	Licensed Internal Code for the tape unit is not correct	FI00130 FI00871
9320	Tape device Licensed Internal Code failure	FI00130 FI00871
9321	Gateway device Licensed Internal Code error	FCCODE
	Use the gateway device service documenation to analyze the problem.	
9350	Tape unit detected a read or write error on tape medium	MH7TMED
	A permanent read or write error occurred. Clean the tape unit and retry the operation.	UH7CLN FI00871
	If cleaning the tape unit does not correct the problem, exchange the tape media.	
9351	Tape with excessive error rate was mounted in tape device.	MH7TMED UH7CLN
	The tape unit detected that the mounted tape cartridge has a history of excessive read and write errors. It is recommended that you exchange the tape cartridge.	FI00871
9355	The data format is incorrect; the tape cannot be read	UH7USER
	The tape unit has detected that the data format on the tape media is not supported.	MH7TMED UH7CLN FI00871
	Clean the tape unit and retry the operation.	
	If the operation continues to fail, use a different tape cartridge.	
9500	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, perform a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i>	
9800 to 9803	I/O processor successfully recovered from temporary error	
	No action required. This reference code is logged for information only.	
9810	Problem analysis has determined a part should be replaced.	
	This reference code is used for ending Online Problem Analysis with a list of failing items. (Information Only)	
9899	Problem analysis completed, the problem has been corrected.	UH7FIXD
	This reference code is used for ending Online Problem Analysis when no problem was found or the problem was corrected.	

### 358x, 3592, 4685, 5755, 6279, 6381, 6382, 6383, 6384, 6386, 6387, 63A0, 7207

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9900	Licensed Internal Code for tape unit was not upgraded	UH7USER
	The I/O processor loading of Licensed Internal Code (LIC) to the programmable tape unit was not completed.	
	The tape unit will continue to operate with the previous LIC. You may do either of the following:	
	• Wait for next IPL when the system will attempt to load the LIC for the tape drive again.	
	• Perform TU-PIP4 to reset the IOP and the tape unit. When the IOP is reset, if the device has the wrong level of LIC, the IOP will attempt to load the new LIC.	
FFF6	Tape volume statistics logged (no action required)	

Table 2. Tape unit failing items details

Failing Item	Description	Document Description
ANYFC	Any device on Fibre Channel interface	Problem Analysis; Symbolic FRU Isolation
DEVTERM	Terminating plug	Problem Analysis; Symbolic FRU Isolation
FCCABLE	Fibre Channel cable	Problem Analysis; Symbolic FRU Isolation
FCCODE	Gateway device Licensed Internal Code	Problem Analysis; Symbolic FRU Isolation
FCDEV	Fibre Channel device	Problem Analysis; Symbolic FRU Isolation
FCGATE	Gateway device	IBM SAN Data Gateway Service Guide
FCIOA	Fibre Channel IOA	Problem Analysis; Symbolic FRU Isolation
MH7TMED	Defective tape	Magnetic tape subsystem service information
UH7CLN	Tape unit needs cleaning	Magnetic tape subsystem operator's information
UH7CNFG	Tape configuration detected by I/O processor; not valid	Installation
UH7USER	Operator action required	System operation information

# (3590) Tape unit reference codes

For use by authorized service providers.

A tape or a 3590 Tape Unit failure occurred.

Note: For tape device and IOP reset procedures, see TU-PIP4.

1. Is the operating system available and can you enter commands from the command line?

- Yes: Is OS/400 available on the system (see "Determining the Dominant Operating System" in the *iSeries Service Functions*)?
  - Yes: Use the online problem analysis procedures to isolate the problem. Use the Work with Problem (WRKPRB) command to determine if a recent problem was entered in the problem log, or use the Verify Tape (VFYTAP) command to run verification tests.
  - No: Continue with the next step.
- No: Continue with the next step.
- 2. Verify that the 3590 is powered on.
- 3. Ensure that the 3590 SCSI address is set to "0".
- 4. Verify that the 3590 online/offline switches are set to the online position.

- 5. Load the first tape.
- 6. Start a type **D** IPL from the system unit control panel.

Does the IPL complete successfully?

- Yes: The problem has been corrected.
- This ends the procedure.
- No: Obtain another copy of the tape. Repeat this step using the new tape. If this does not correct the problem, continue with the next step.
- 7. If the 3590 indicator panel shows a FRU identifier (FID) code, see the "Start" section of the 3590 service information.
- **8**. Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code.
- 9. See SRC Address Formats to determine the IOP, IOA, and device address.
- 10. Find the unit reference code in the following table.
- 11. See the "Start" section of the 3590 service information.

For more on the Failing Item column entries, see Table 2. Tape unit failing items details, which follows the reference code table below.

Reference Code	eference Code Description/Action Perform all actions before exchanging Failing Items	
9020	I/O processor detected a SCSI bus configuration error	UHQCNFG FI00851
	Before exchanging any parts, verify that the following conditions are <i>not</i> present:	FI00130
	• Tape and DASD devices attached to an I/O processor that does not support tape and DASD devices at the same time.	
	• A device type or model that is not given support	
9100	Interface error detected by I/O processor or by tape unit	FI00851
	Before exchanging any parts, do the following:	FI00131 05H3834
	1. Ensure that an interposer is connected between the I/O processor and the SCSI cable.	EXTSCSI 61G8324
	2. Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	
	<b>3</b> . Ensure that a terminating plug is attached to the device end of the SCSI cable.	
9101	Fibre Channel interface error detected	FCIOA
	If the attached device is an external device, do the following before exchanging any parts:	FCDEV FCCABLE
	1. Ensure that the Fibre Channel cable is correctly connected to the ports.	
	2. Clean the Fibre Channel connectors.	
	<b>3</b> . If there is a hub attached, verify that the hub is operational.	
	4. If there is a gateway device attached, refer to the gateway device service documentation for additional problem analysis procedures.	
	5. refer to the tape device service documentation for additonal problem analysis procedures.	

Table 1. (3590) Tape unit reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9102	Gateway device detected a SCSI interface error Use the gateway device service documentation to analyze the problem.	FI00851 FCGATE EXTSCSI 61G8324
9200	<ul> <li>I/O processor addressed the tape unit; no response</li> <li>Before exchanging any parts, do the following: <ol> <li>Ensure that the device is powered on.</li> </ol> </li> <li>Ensure that an interposer is connected between the I/O processor and the SCSI cable.</li> <li>Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.</li> <li>Ensure that a terminating plug is attached to the device end of the SCSI cable.</li> </ul>	FI00851 FI00131 05H3834 EXTSCSI 61G8324
9201	<ul> <li>Tape unit command timeout</li> <li>Before exchanging any parts, do the following: <ol> <li>Ensure that the device is powered on.</li> </ol> </li> <li>Ensure that an interposer is connected between the I/O processor and the SCSI cable.</li> <li>Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.</li> <li>Ensure that a terminating plug is attached to the device end of the SCSI cable.</li> </ul>	FI00851 FI00131 05H3834 EXTSCSI 61G8324
9202	<ul> <li>Tape unit failed after Licensed Internal Code was loaded</li> <li>Before exchanging any parts, do the following: <ol> <li>Ensure that the device is powered on.</li> </ol> </li> <li>Ensure that an interposer is connected between the I/O processor and the SCSI cable.</li> <li>Ensure that the SCSI cable between the interposer and the device is seated correctly, and that there are no bent or damaged pins on the SCSI cable.</li> <li>Ensure that a terminating plug is attached to the device end of the SCSI cable.</li> </ul>	FI00851 FI00131 05H3834 EXTSCSI 61G8324
9210	Illegal or unsupported tape unit response	FI00851 FI00131 FI00130
9211	Gateway device detected a bus protocol error Use the gateway device service documentation to analyze the problem.	FCGATE FCIOA FI00851 ANYFC FCCABLE EXTSCSI 61G8324
9300	Tape unit failure	FI00851

## 3590

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9301	Tape device failure, redundancy lost	FI00851
	The tape unit detected a hardware failure that does not prevent the tape unit from completing the present operation.	
	See the 3590 Tape Unit service information to determine the failing item.	
9302	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, perform a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i>	
9303	Gateway device failure	FCGATE
	Use the gateway device service documenation to analyze the problem.	
9310	Licensed Internal Code for the tape unit is not correct	FI00851 FI00130
9320	Tape device Licensed Internal Code failure	FI00130
	Do the following:	FI00851
	<ol> <li>Take a dump of the tape device Licensed Internal Code (see the 3590 Tape Unit service information).</li> </ol>	
	2. Power off the tape unit. Then power on the tape unit to resume operation.	
9321	Gateway device Licensed Internal Code error	FCCODE
	Use the gateway device service documenation to analyze the problem.	
9350	Tape unit detected a read or write error on tape medium	MHQTMED
	A permanent read or write error occurred, and the tape unit determined that the tape cartridge is defective. Exchange the tape cartridge.	UHQCLN FI00851
9351	Tape with excessive error rate was mounted in tape device.	MHQTMED
	The tape unit detected that the installed tape cartridge has a history of excessive read and write errors. It is recommended that you exchange the tape cartridge.	UHQCLN FI00851
9355	The data format is incorrect; the tape cannot be read	MHQTMED
	The tape device does not give support to the data format on the tape cartridge. Format the tape cartridge again or use a different tape cartridge.	UHQCLN FI00851
	See the 3590 Tape Drive Operator's Guide for instructions on formatting a tape cartridge.	
9500	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, perform a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i>	
9800 to 9803	I/O processor successfully recovered from temporary error	
	No action required. This reference code is logged for information only.	
9810	Problem analysis has determined a part should be replaced.	
	This reference code is used for ending Online Problem Analysis with a list of failing items. (Information Only)	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9899	Problem analysis completed, the problem has been corrected.	UHQFIXD
	This reference code is used for ending Online Problem Analysis when no problem was found or the problem was corrected.	
9900	Licensed Internal Code for tape unit was not upgraded	
	The I/O processor loading of Licensed Internal Code (LIC) to the programmable tape unit was not completed.	
	The tape unit will continue to operate with the previous LIC. You may do either of the following:	
	• Wait for next IPL when the system will attempt to load the LIC for the tape unit again.	
	• Perform TU-PIP4 to reset the IOP and the tape unit. When the IOP is reset, if the device has the wrong level of LIC, the IOP will attempt to load the new LIC.	
FFF6	Tape volume statistics logged (no action required)	

#### Table 2. Tape unit failing items details

Failing Item	Description	Document Description
05H3834	Interposer	IBM 3590 Tape Drive Service Guide
61G8324	Terminating plug	IBM 3590 Tape Drive Service Guide
ANYFC	Any device on Fibre Channel interface	Problem Analysis; Symbolic FRU Isolation
EXTSCSI	External signal cable	Problem Analysis; Symbolic FRU Isolation
FCCABLE	Fibre Channel cable	Problem Analysis; Symbolic FRU Isolation
FCCODE	Gateway device Licensed Internal Code	Problem Analysis; Symbolic FRU Isolation
FCDEV	Fibre Channel device	Problem Analysis; Symbolic FRU Isolation
FCGATE	Gateway device	IBM SAN Data Gateway Service Guide
FCIOA	Fibre Channel IOA	Problem Analysis; Symbolic FRU Isolation
MHQTMED	Defective tape	Magnetic tape subsystem service information
UHQCLN	Tape unit needs cleaning	Magnetic tape subsystem operator's information
UHQCNFG	Tape configuration detected by I/O processor; not valid	Installation

## (432x, 660x, 671x, 673x) Disk unit reference codes

For use by authorized service providers.

If the error is reported on the control panel, the unit reference code is characters 5 through 8 of the top 16 character line of function 11. If the error is reported on the console, the unit reference code is the 4 rightmost characters of word 1.

Find the unit reference code in the following table. If the failing item is a disk unit, go to Start Disk Service.

**Attention:** The 673x is a read cache. Perform all actions required for 673x as a disk drive and logic card except where separate 673x cache instructions are provided.

For more on the Failing Item column entries, see Table 2. Disk unit failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
102E	Out of alternate sectors for disk storage	DISKDRV
3002	Addressed device failed to respond to selection	DISKDRV STORIOA BACKPLN FI01106 FI01140
3010	Disk device returned wrong response to IOP	DISKDRV STORIOA FI01140 FI01141
3020	Storage subsystem configuration error If an MES is being installed, verify the configuration.	DISKDRV FI01106 STORIOA
		FI01140
3029	A device replacement has occurred	
	No action required. This reference code is logged for information only.	
3100	Tape/CD or disk bus interface error occurred Perform DSKIP03.	DISKDRV STORIOA FI01106 FI01140
3109	IOP timed out a disk command	DISKDRV STORIOA FI01106 FI01140
3110	Disk bus interface error occurred Perform DSKIP03.	STORIOA DISKDRV FI01106 FI01140
3130	Device Licensed Internal Code	SVCDOCS
	The device is not supported with the level of code currently on the system. Contact your next level of support.	
3131	Device or IOA Licensed Internal Code The device does not support a needed attribute and is running with degraded performance. Contact your next level of support.	SVCDOCS
7000	Disk sector read error	DISKDRV
	No action required. This reference code is logged for information only.	
7001	Temporary disk data error	DISKDRV
	A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	
7003	Device format error	
	If the disk has not been formatted by the system, initialize and format the disk. See "Work with disk unit recovery" in the <i>iSeries Service Functions</i> .	

Table 1. (432x, 660x, 671x, 673x) Disk unit reference codes

## 432x, 660x, 671x, 673x

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7004	System log entry only, no service action required	
7050	Data compression failure	SVCDOCS
	Contact your next level of support.	
7051	Compressed device and compression IOA are not compatible	CMPRES1
	The customer should perform the procedure specified in "Recovering From	
	6xxx7051 SRC" in the Backup and Recovery Guide 🐳 .	
7052	Data compression warning	SVCDOCS
	The customer should perform the procedure specified in "Recovering From	
	6xxx7052 SRC" in the Backup and Recovery Guide 🐳 .	
FFF2	Disk motor problem	DISKDRV
FFF3	Disk media format bad	DISKDRV
FFF4	Disk device problem	DISKDRV STORIOA
FFF5	Disk sector read error	DISKDRV
	A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	
FFF6	Disk device detected recoverable error	DISKDRV
	A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	
FFF7	Temporary disk data error	DISKDRV
	No action required. This reference code is logged for information only.	
FFF8 to FFF9	Temporary disk data error	DISKDRV
	A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	
FFFA	Temporary disk bus error	DISKDRV
	A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	STORIOA FI01140 FI01141 BACKPLN
FFFB	SCSI bus reset occurred	
	No action required. This reference code is logged for information only.	
FFFE	Temporary disk bus error	DISKDRV
	A disk unit service action is recommended only if the Service Action Log contains an entry for this reference code. For more information about the Service Action Log, see Use the Service Action Log.	STORIOA FI01106 FI01140

## Table 2. Disk unit failing items details

Failing Item	Description	Document Description
08F5352	Token-ring network adapter	Repair and Parts; removal and installation procedures
08F5361	Communications input/output processor card	Repair and Parts; removal and installation procedures
17G2504	Tape Unit	Repair and Parts; removal and installation procedures
21F1511	Internal power cable	Repair and Parts; removal and installation procedures
21F1512	Internal power cable	Repair and Parts; removal and installation procedures
21F1512	Internal power cable	Repair and Parts; removal and installation procedures
21F1513	Internal signal cable	Repair and Parts; removal and installation procedures
21F1514	Internal power cable	Repair and Parts; removal and installation procedures
21F1519	Internal signal cable	Repair and Parts; removal and installation procedures
21F1530	Card enclosure	Repair and Parts; removal and installation procedures
21F1687	Diskette adapter card	Repair and Parts; removal and installation procedures
21F1688	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
21F1689	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
21F2070	Bus cable	Repair and Parts; removal and installation procedures
21F3986	Tape I/O processor card	Repair and Parts; removal and installation procedures
21F4383	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
21F4493	Ethernet controller card	Repair and Parts; removal and installation procedures
21F4579	Disk drive logic card	Repair and Parts; removal and installation procedures
21F4863	Magnetic storage device IOP card	Repair and Parts; removal and installation procedures
21F4867	Communication adapter	Repair and Parts; removal and installation procedures
21F4868	Communication adapter	Repair and Parts; removal and installation procedures
21F4869	Token-ring controller card	Repair and Parts; removal and installation procedures
21F4882	Diskette adapter card	Repair and Parts; removal and installation procedures
21F4882	Diskette adapter card	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description
21F5620	Disk unit power regulator	Repair and Parts; removal and installation procedures
21F5620	Disk unit power regulator	Repair and Parts; removal and installation procedures
21F5650	AC Module	Repair and Parts; removal and installation procedures
21F5680	AC Module	Repair and Parts; removal and installation procedures
21F5772	Control panel	Repair and Parts; removal and installation procedures
21F5774	Cable assembly	Repair and Parts; removal and installation procedures
21F5774	External signal cable	Repair and Parts; removal and installation procedures
21F5861	Tape Unit	Repair and Parts; removal and installation procedures
21F8566	Tape Unit	Repair and Parts; removal and installation procedures
21F8633	Tape Unit	Repair and Parts; removal and installation procedures
21F8719	Tape Unit	Repair and Parts; removal and installation procedures
21F8872	Cable Carrier	Repair and Parts; removal and installation procedures
21F8890	D/SE Module	Repair and Parts; removal and installation procedures
21F9208	ISDN adapter card	Repair and Parts; removal and installation procedures
21F9215	Power regulator card	Repair and Parts; removal and installation procedures
21F9586	Cable assembly	Repair and Parts; removal and installation procedures
21F9907	Cable assembly	Repair and Parts; removal and installation procedures
21F9937	Cable assembly	Repair and Parts; removal and installation procedures
21F9951	Tape Unit	Repair and Parts; removal and installation procedures
21F9987	Tape unit IOP card	Repair and Parts; removal and installation procedures
2452557	Fan	9346 Service Guide; Installation and Removal, SY31-0688
26F5028	Communication adapter	Repair and Parts; removal and installation procedures
375892	Power cord; U.S.A., Asia-Pacific group, Americas group	
4234002	Test diskette (8 inch)	System operation information

Failing Item	Description	Document Description
46F4115	Ethernet network adapter card	Repair and Parts; removal and installation procedures
46F4239	Token-ring network adapter	Repair and Parts; removal and installation procedures
55F5199	Disk drive logic card	Repair and Parts; removal and installation procedures
55F5209	Disk drive and logic card	Repair and Parts; Recovery Procedures
59X4718	Communications input/output processor card	Repair and Parts; removal and installation procedures
59X4723	Tape I/O processor card	Repair and Parts; removal and installation procedures
59X4723	Token-ring network adapter	Repair and Parts; removal and installation procedures
59X4723	Tape unit IOP card	Repair and Parts; removal and installation procedures
59X4819	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
6369759	Test diskette (5-1/4 inch)	System operation information
6369881	Diskette unit	Repair and Parts; removal and installation procedures
6462385	Power cord; Europe, Mid-East, Asia	
6495268	External signal cable	9346 Service Guide; Installation and Removal, SY31-0688
72X5631	Terminating plug	9346 Service Guide; Installation and Removal, SY31-0688
72X5631	Terminating plug	Repair and Parts; removal and installation procedures
72X5631	Terminating plug	Repair and Parts; removal and installation procedures
72X6361	Diskette unit	Repair and Parts; removal and installation procedures
72X6374	Work station attachment	Repair and Parts; removal and installation procedures
72X6385	Magnetic storage device IOP card	Repair and Parts; removal and installation procedures
72X6386	Diskette adapter card	Repair and Parts; removal and installation procedures
72X6387	Communications I/O processor card	Repair and Parts; removal and installation procedures
72X6388	Communications adapter card	Repair and Parts; removal and installation procedures
72X6389	Multiple interface adapter	Repair and Parts; removal and installation procedures
72X6390	Communications adapter card	Repair and Parts; removal and installation procedures
72X6391	Token-ring network adapter	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description
73F8987	Disk drive and logic card	Repair and Parts; Recovery Procedures
73F8994	Disk drive logic card	Repair and Parts; removal and installation procedures
73F9138	Planar board	Repair and Parts; removal and installation procedures
73F9139	Planar board	Repair and Parts; removal and installation procedures
73F9166	Planar board	Repair and Parts; removal and installation procedures
73F9193	Power regulator card	Repair and Parts; removal and installation procedures
73F9232	Cable assembly	Repair and Parts; removal and installation procedures
73F9244	Disk unit power regulator	Repair and Parts; removal and installation procedures
73F9267	ASCII work station IOP card	Repair and Parts; removal and installation procedures
73F9290	Control panel	Repair and Parts; removal and installation procedures
73F9290	Control panel	Repair and Parts; removal and installation procedures
73F9345	Tape Unit	Repair and Parts; removal and installation procedures
73F9393	Tape Unit	Repair and Parts; removal and installation procedures
74F1541	Card enclosure	Repair and Parts; removal and installation procedures
74F1542	Card enclosure	Repair and Parts; removal and installation procedures
74F1543	Card enclosure	Repair and Parts; removal and installation procedures
74F1544	Card enclosure	Repair and Parts; removal and installation procedures
74F1649	Tape Unit	Repair and Parts; removal and installation procedures
74F1760	DC Bulk Module	Repair and Parts; removal and installation procedures
74F2201	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
74F2232	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
79X3795	Terminating plug	Repair and Parts; removal and installation procedures
8266352	Power supply	9346 Service Guide; Installation and Removal, SY31-0688
85F7295	Multiple function I/O processor card	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description
85F7305	Multiple function I/O processor card	Repair and Parts; removal and installation procedures
85F7405	Base power supply	Repair and Parts; removal and installation procedures
85F7418	Cable assembly	Repair and Parts; removal and installation procedures
85F7646	Magnetic storage device IOP card	Repair and Parts; removal and installation procedures
85F7846	Terminating plug	Repair and Parts; removal and installation procedures
85F9785	Control panel	Repair and Parts; removal and installation procedures
85F9840	Internal signal cable	Repair and Parts; removal and installation procedures
85F9845	Internal power cable	Repair and Parts; removal and installation procedures
92X3030	Feature power supply	Repair and Parts; removal and installation procedures
92X3080	Disk unit power regulator	Repair and Parts; removal and installation procedures
92X4041	Diskette unit	Repair and Parts; removal and installation procedures
92X4044	Cable assembly	Repair and Parts; removal and installation procedures
92X4091	Cable assembly	Repair and Parts; removal and installation procedures
92X4143	Planar board	Repair and Parts; removal and installation procedures
92X6551	Planar board	Repair and Parts; removal and installation procedures
92X7512	Flex cable	9346 Service Guide; Installation and Removal, SY31-0688
92X7514	Internal tape unit signal cable	9346 Service Guide; Installation and Removal, SY31-0688
92X7515	Internal signal cable	9346 Service Guide; Installation and Removal, SY31-0688
92X7516	Internal power cable	9346 Service Guide; Installation and Removal, SY31-0688
93X0901	Disk drive logic card	Repair and Parts; removal and installation procedures
93X0911	Disk drive and logic card	Repair and Parts; Recovery Procedures
93X2520	Disk drive and logic card	Repair and Parts; Recovery Procedures
93X2701	I/O processor card	Repair and Parts; removal and installation procedures
93X2730	9346 IOP card	Repair and Parts; removal and installation procedures
93X2777	I/O processor card	Repair and Parts; removal and installation procedures

Failing Item	Description	Document Description	
A0B00E1	Licensed Internal Code for programmable tape unit	Service Functions; APAR or LICTR	
AJDG301	Vertical Licensed Internal Code	Service Functions; APAR or LICTR	
AJEDA00	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
AJEDA00	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
AJEH901	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
AJGJQ01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
AJSLC01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
AJSLC01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
BACKPLN	Card enclosure or backplane	See the service documentation for instructions.	
CMPRES1	Compressed device and compression IOA are not compatible	See the service documentation for instructions.	
DEVTERM	Device terminator	See the service documentation for instructions.	
DISKDRV	Disk drive and logic card	See the service documentation for instructions.	
DISKDRV	Disk drive and logic card	See the service documentation for instructions.	
DISKDRV	Disk drive and logic card	See the service documentation for instructions.	
DISKDRV	Disk drive and logic card	See the service documentation for instructions.	
DISKDRV	Disk drive and logic card	See the service documentation for instructions.	
DISKDRV	Disk drive and logic card	See the service documentation for instructions.	
DISKDRV	Disk drive and logic card	See the service documentation for instructions.	
DISKLC	Disk drive logic card	See the service documentation for instructions.	
DISKLC	Disk drive logic card	See the service documentation for instructions.	
DISKLC	Disk drive logic card	See the service documentation for instructions.	
DISKLC	Disk drive logic card	See the service documentation for instructions.	
DISKLC	Disk drive logic card	See the service documentation for instructions.	
DISKLC	Disk drive logic card	See the service documentation for instructions.	
DISKLC	Disk drive logic card	See the service documentation for instructions.	
DISKTRY	Disk unit tray	See the service documentation for instructions.	
DISKTRY	Disk unit tray	See the service documentation for instructions.	
DISKTRY	Disk unit tray	See the service documentation for instructions.	
DISKTRY	Disk unit tray	See the service documentation for instructions.	
DISKTRY	Disk unit tray	See the service documentation for instructions.	
DISKTRY	Disk unit tray	See the service documentation for instructions.	
DISKTRY	Disk unit tray	See the service documentation for instructions.	
MFGDMED	Defective diskette	System operation information	
MFGTCAR	Defective tape or damaged cartridge	System operation information	
MFGTFOR	The data format is incorrect; the tape cannot be read	System operation information	
MFGTMED	Defective removable media	System operation information	
STORIOA	Storage I/O adapter	See the service documentation for instructions.	
SVCDOCS	Customer engineer directed to system problem analysis	See the service documentation for instructions.	

Failing Item	Description	Document Description
UFGUSER	System Operator/User	System operation information

# (5700, 5701) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Look at the last 8 characters of the top 16 character line of function 12 (word 3). These 8 characters are the direct select address of the card (BBBBCcbb). The unit address portion of the card address is characters 1 through 8 of the bottom 16 character line of function 11 (Word 4). Card locations can be found using the 16 character address. See SRC Address Formats.
- 3. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Table 1. (5700, 5701) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B9A0	I/O adapter hardware error detected	FI00719 FI00718 AJDGP01 MA BRDG

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDGP01	LIC - Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR
MA_BRDG	Multi-adapter bridge	See the service documentation for instructions.

# (5708, 574F, 575B) Reference codes

If the error is reported on the control panel, the unit reference code is characters 5 through 8 of the top 16 character line of function 11. If the error is reported on the console, the unit reference code is the 4 rightmost characters of word 1.

Find the unit reference code in the following table. For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

Table 1. (5708, 574F, 575B) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3006	System bus error	AUXIOA ANYBRDG IOP
3100	Interface error Error occurred on SCSI bus 0.	AUXCBL AUXIOA PRIMIOA

# 5708, 574F, 575B

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3101	Interface error Error occurred on SCSI bus 1.	AUXCBL AUXIOA PRIMIOA
3400	SCSI resource error	AUXCBL PRIMIOA
6075	I/O processor resource not available	PTFSRCH
8008	A permanent cache battery pack failure occurred	CACHBAT AUXIOA
8009	Impending cache battery pack failure	САСНВАТ
8130	IOA detected recoverable SCSI bus error	
	An error occurred on SCSI bus 0. No action is required. This reference code is logged for information only.	
8131	IOA detected recoverable SCSI bus error	
	An error occurred on SCSI bus 1. No action is required. This reference code is logged for information only.	
8140	IOA detected recoverable SCSI bus error	
	No action is required. This reference code is logged for information only.	
8141	IOA detected recoverable SCSI resource error	
	No action is required. This reference code is logged for information only.	
8145	A recoverable error occurred	AUXIOA
8150	A permanent failure occurred	AUXIOA ANYBRDG
8151	Licensed Internal Code error	PTFSRCH AUXIOA
8155 to 8156	A permanent failure occurred	PTFSRCH AUXIOA
8157	I/O adapter card error	SVCDOCS
	Display the Service Action Log entry for this SRC. If the Failing Item indicates I/O adapter, then replace the I/O adapter. If the Failing Item indicates SVCDOCS, then do NOT replace the I/O adapter. This is a recoverable error. Perform the following for the I/O processor that the I/O adapter is attached to:	
	1. If the I/O Processor is not operable and disk units are attached, use Hardware Service Manager to re-IPL the IOP. Other resources attached to the IOP may then need to be Varied On.	
	2. If disk units are not attached, perform the VRYCFG RESET(*YES) command to reset the IOP and Vary On attached resources.	
8300	IOA hardware or PCI bus error	AUXIOA ANYBRDG PTFSRCH
8301	Not valid condition in Licensed Internal Code	PTFSRCH AUXIOA
8302	Missing Licensed Internal Code	SVCDOCS AUXIOA
	Ensure that the code necessary to support this I/O adapter is loaded.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9055	Write cache data is available for attached storage IOA	
	No service action required.	
9071	Link from IOA to auxiliary cache IOA went operational	
	No service action required.	
9072	Link from IOA to auxiliary cache IOA went non-operational	
	No service action required.	
9073	Disconnected, incompatible, or non-operational storage IOA	SVCDOCS
	Perform IOPIP41.	
FF3D	I/O adapter detected a recoverable error	AUXIOA ANYBRDG

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDGP01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
ANYBRDG	System I/O bus or any attached card	See the service documentation for instructions.
ANYBUS	IOP card bus error	See the service documentation for instructions.
AUXCBL	Cable assembly	See the service documentation for instructions.
AUXIOA	I/O adapter card	See the service documentation for instructions.
BACKPLN	Card Enclosure or Planar Board	See the service documentation for instructions.
САСНВАТ	Cache battery pack	See the service documentation for instructions.
DEVBPLN	Device backplane	See the service documentation for instructions.
DEVTERM	Terminating plug	See the service documentation for instructions.
IOP	I/O processor card	See the service documentation for instructions.
PCIBUS	Any PCI card on the PCI bus	See the service documentation for instructions.
PRIMIOA	Storage I/O adapter	See the service documentation for instructions.
PTFSRCH	Licensed Internal Code	See the service documentation for instructions.
STORIOA	Storage I/O adapter	See the service documentation for instructions.
SVCDOCS	Customer engineer directed to system problem analysis	See the service documentation for instructions.
USER	System Operator/User	See the service documentation for instructions.

# (632x, 6330, 6331, 6333, 6336, 6337) Optical storage unit reference codes

For use by authorized service providers.

An optical storage unit failure occurred.

Notes:

- 1. If the system is available, use online diagnostic tests when possible.
- **2**. Use the Hardware Service Manager (HSM) verify function (via DST or SST) and verify that the unit is operating correctly.

## 632x, 6330, 6331, 6333, 6336, 6337

**3**. Search the problem log (**WRKPRB**) for a recent optical storage entry that may assist in analyzing the problem. The WRKPRB entry will provide a unit reference code that can be found in the following table.

Perform the following:

1. If the system is available, attempt the failing operation again with an optical media that is known to be good.

Does the operation complete successfully?

• **Yes**: The original optical media may be defective, or the problem may be intermittent. Attempt the failing operation again with the original optical media to verify.

This ends the procedure.

• No: Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Optical storage unit failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
C000	System log entry only, no service action required	
	No action is required. This reference code is logged for information only.	
C002	SCSI selection or reselection timeout occurred	FI00870 FI01106 FI01112 MEDIA FI01140 FI01141 DEVTERM CDTRAY
C010	Undefined sense key returned by device	FI00870
C020	Device internal configuration error	FI00870
C100	SCSI bus command error occurred	FI00870 FI01106 FI01112 MEDIA FI01140 FI01141 DEVTERM CDTRAY
C110	SCSI command timeout occurred	FI00870 FI01106 FI01112 MEDIA FI01140 FI01141 DEVTERM CDTRAY
C210	Unexpected device condition recovered	
	The device successfully recovered from a temporary error.	
	No action is required. This reference code is logged for information only.	

#### Table 1. (632x, 6330, 6331, 6333, 6336, 6337) Optical storage unit reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
C300	Media or device error occurred	MEDIA FI00870
	Perform the following:	
	1. Clean the disk.	
	<ol> <li>Attempt the failing operation again.</li> <li>If this does not correct the problem, such and the failing items.</li> </ol>	
C301	<ul><li>3. If this does not correct the problem, exchange the failing items.</li><li>Media or device error occurred</li></ul>	
C301	Dust check encountered. Optical media and/or drive's optical lens is dirty.	
	Clean the optical drive and the media contained in the drive.	
C302	Media or device error occurred	
	While writing to the media, an 'out of spare sectors' condition was encountered. The media can no longer be written to but is still readable.	
	Clean the optical drive and the media contained in the drive.	
C303	Media had an unknown format	
	No action required. This reference code is logged for information only.	
C333	Incompatible media was detected	MEDIA
	Perform the following:	FI00870
	1. Verify that the disk has a format that is given support.	
	2. If the format is given support, clean the disk and attempt the failing operation again.	
	<ol> <li>If the operation fails again with the same reference code, ask your media source for a replacement disk.</li> </ol>	
C400	Interface error detected by device	FI00870 FI01106 FI01112 FI01140 FI01141 DEVTERM CDTRAY
C402	I/O processor internal program error occurred	FI00130
	Ask your next level of support for assistance.	
CFF2	Recovered from device not ready - Start Unit issued	
	The device successfully recovered from a temporary error.	
	No action is required. This reference code is logged for information only.	
CFF4	Internal device error occurred	FI00870
CFF6	Device recovered from error after retries	
	The device successfully recovered from a temporary error.	
	No action is required. This reference code is logged for information only.	
CFF7	Recovered device error	
	The device successfully recovered from a temporary error.	
	No action is required. This reference code is logged for information only.	

### 632x, 6330, 6331, 6333, 6336, 6337

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
CFFE	Recovered SCSI bus error	
	The device successfully recovered from a temporary error.	
	No action is required. This reference code is logged for information only.	
FF09	Licensed Internal Code for optical device was not upgraded	
	This reference code is logged for information only.	
FF3D	Recovered I/O processor error	
	The device successfully recovered from a temporary error.	
	No action is required. This reference code is logged for information only.	
FF6D	Recovered System bus error	
	The device successfully recovered from a temporary error.	
	No action is required. This reference code is logged for information only.	

#### Table 2. Optical storage unit failing items details

Failing Item	Description	ption Document Description	
CDTRAY	Flex cable on tray assembly	Problem Analysis; Symbolic FRU Isolation	
DEVTERM	Bus Terminator	Problem Analysis; Symbolic FRU Isolation	
MEDIA	Optical Media	System operation information	

## (6A59) Workstation adapter console reference codes

For use by authorized service providers.

The workstation adapter console detected a failure.

Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Workstation adapter console failing items Details, which follows the reference code table below.

Table 1. (6A59)	) Workstation	adapter	console	reference	codes
-----------------	---------------	---------	---------	-----------	-------

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0AD2 to 0AD3	Communications adapter card test failed	FI00718
0B25	Communications adapter card test failed	FI00719 FI00718 FI00727
0BA0, 0BAB, 0BB0, 0BD0 to 0BD1	Communications adapter card test failed	FI00719 FI00718
OBEE	I/O card Licensed Internal Code ended abnormally	FI00719 FI00718
0C10	Communications adapter card test failed	FI00719 FI00718 FI00727

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0C20	Communications adapter card test failed	FI00719 FI00718
0C30	Adapter card failed modem interface test	FI00719 FI00718
0C40, 0C43	Synchronous-data-link-control send-receive test failed	FI00719 FI00718
0C50, 0C53	Binary synchronous control send-receive test failed	FI00719 FI00718
0C60, 0C63	Asynchronous send-receive test failed	FI00719 FI00718
0C70, 0C80	Communications adapter card test failed	FI00719 FI00718
0C90	Communications adapter card X.21 test failed	FI00719 FI00718
0CA1, 0CC0	Communications adapter card test failed	FI00719 FI00718
5007	Diagnostic wrap test completed; no errors detected	
5008	Diagnostic wrap test completed; error was detected	FI00719 DPAC FI00718
FFFF	User suspected communications problem.	UNAUPPR

#### Table 2. Workstation adapter console failing items details

Failing Item	Description	Document Description
DPAC	Communications two-port adapter cable	Problem Analysis; Symbolic FRU Isolation
UNAUPPR	User suspected problem	

# (7208) Tape drive reference codes

For use by authorized service providers.

An 8mm tape drive failure occurred.

Note: For tape device and IOP reset procedures, see TU-PIP4.

- 1. Is the operating system available and can you enter commands from the command line?
  - Yes: Is OS/400 available on the system (see "Determining the Dominant Operating System" in the *iSeries Service Functions*)?
    - Yes: Use the online problem analysis procedures to isolate the problem. Use the Work with Problem (WRKPRB) command to determine if a recent problem was entered in the problem log, or use the Verify Tape (VFYTAP) command to run verification tests.
    - No: Continue with the next step.
  - No: Go to step 4 of this procedure.
- 2. Clean the recording head in the tape unit. Use the correct IBM® Cleaning Cartridge Kit:
  - In Canada, the United States, and all other countries use part 16G8467.
- **3**. Attempt the failing operation again.

Does the operation complete successfully?

- Yes: The original data cartridge is defective. The problem has been corrected. This ends the procedure.
- No: Continue with the next step.
- 4. Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code.

Is the failing tape unit located in a type 9427 Tape Library device?

- Yes: Go to "(9427) Tape unit reference codes" on page 226.
- No: Does the label on the front of the 7208 Tape Drive show 7208-002?
  - Yes: See Table 1. (7208) Model 002 tape drive reference codesand find the unit reference code.
  - No: The label shows 7208-012. See Table 3. (7208) Model 012 tape drive reference codes and find the unit reference code.

Table 1. (7208) Model 002 Tape drive reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0001	<ul> <li>Tape unit failure</li> <li>1. Look at the In-use lights. If the green light is off and the yellow light is on, the tape unit is indicating an error condition.</li> <li>MLVTME 91F0914</li> </ul>	
	<ol> <li>Switch off power to the tape unit.</li> <li>Switch on power to the tape unit.</li> </ol>	
	<ul><li>4. Clean the recording head in the tape unit. Use the IBM Cleaning Cartridge Kit (part 21F8593).</li></ul>	
	5. Use a new data cartridge if saving data.	
	Also see the procedure for reference code FFFF.	
0002	<ul><li>Tape unit formatter failure</li><li>1. Look at the In-use lights. If the green light is off and the yellow light is on, the tape unit is indicating an error condition.</li></ul>	91F0914 MLVTMED
	<ol> <li>Switch off power to the tape unit.</li> <li>Switch on power to the tape unit.</li> </ol>	
	4. Clean the recording head in the tape unit. Use the IBM Cleaning Cartridge Kit (part 21F8593).	
	5. Use a new data cartridge if saving data.	
	Also see the procedure for reference code FFFF.	
0003	<ul><li>Tape unit servo failure</li><li>1. Look at the In-use lights. If the green light is off and the yellow light is on, the tape unit is indicating an error condition.</li></ul>	91F0914 MLVTMED
	2. Switch off power to the tape unit.	
	<b>3</b> . Switch on power to the tape unit.	
	4. Clean the recording head in the tape unit. Use the IBM Cleaning Cartridge Kit (part 21F8593).	
	5. Use a new data cartridge if saving data.	
	Also see the procedure for reference code FFFF.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0004	Tape unit motion failure	MLVTMED
	1. Look at the In-use lights. If the green light is off and the yellow light is on, the tape unit is indicating an error condition.	91F0914
	2. Switch off power to the tape unit.	
	3. Switch on power to the tape unit.	
	4. Clean the recording head in the tape unit. Use the IBM Cleaning Cartridge Kit (part 21F8593).	
	5. Use a new data cartridge if saving data.	
	Also see the procedure for reference code FFFF.	
3002	I/O processor addressed the tape unit; no response	91F0914
	The tape unit did not respond to a command sent by the IOP.	81F9128 FI00830
	<ol> <li>Ensure that the tape unit is powered on. If the tape unit does not become powered on, refer to the "Maintenance Analysis Procedures" in the 7208 Model 2 8 mm Tape Drive Service Guide, SA23-2640, to analyze the problem.</li> </ol>	FI00141 91F0721 53F3861 42F7300
	2. Switch off power to the tape unit.	
	3. Reseat the signal cable to the tape unit.	
	4. Reseat the signal cable to the IOP.	
	5. Switch on power to the tape unit.	
3005	Blank tape or BOT encountered	MLVTMED
	The tape unit has found blank tape or BOT.	91F0914 AJEDA00
	When using a new data cartridge, the tape must first be initialized.	
	This error can also occur when reading a tape if the tape was removed from the tape unit before writing was complete.	
	Also see the procedure for reference code FFFF.	
3010	Illegal or unsupported tape unit response	91F0914
	1. Look at the In-use lights. If the green light is off and the yellow light is on, the tape unit is indicating an error condition.	AJEDA00
	2. Switch off power to the tape unit.	
	3. Switch on power to the tape unit.	
	4. Clean the recording head in the tape unit. Use the IBM Cleaning Cartridge Kit (part 21F8593).	
	5. Use a new data cartridge if saving data.	
	Also see the procedure for reference code FFFF.	
3100	IOP to tape unit interface error	91F0914
	<ol> <li>Ensure that the tape unit is powered on. If the tape unit does not become powered on, refer to the "Maintenance Analysis Procedures" in the 7208 Model 2 8 mm Tape Drive Service Guide, SA23-2640, to analyze the problem.</li> </ol>	FI00141 FI00830 91F0721 42F7300 52F2861
	2. Switch off power to the tape unit.	53F3861 81F9128
	3. Reseat the signal cable to the tape unit.	AJEDA00
	4. Reseat the signal cable to the IOP.	
	5. Switch on power to the tape unit.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3110	Tape unit command timeout	91F0914
	The tang unit did not complete a command cant by the IOP in the time	FI00141
	The tape unit did not complete a command sent by the IOP in the time allowed.	FI00830 91F0721
	1. Ensure that the tape unit is powered on. If the tape unit does not	42F7300
	become powered on, refer to the "Maintenance Analysis Procedures" in the 7208 Model 2 8 mm Tape Drive Service Guide, SA23-2640, to analyze the problem.	53F3861 81F9128 AJEDA00
	2. Switch off power to the tape unit.	
	<b>3</b> . Reseat the signal cable to the tape unit.	
	4. Reseat the signal cable to the IOP.	
	5. Switch on power to the tape unit.	
FF4D	IOP to tape unit interface error; logged only	
	No action required. This reference code is logged for information only.	
FF5D	Tape unit response error; logged only	
	No action required. This reference code is logged for information only.	
FFF6	Volume statistics; logged only	
	No action required. This reference code is logged for information only.	
FFFE	Read data error: tape path dirty	MLVTMED 91F0914
	This error may be caused by a dirty recording head, poor or damaged tapes, worn or damaged data cartridges, or using a format that is not correct.	/110/14
	1. Switch off power to the tape unit.	
	2. Switch on power to the tape unit.	
	<b>3</b> . Clean the recording head in the tape unit. Use the IBM Cleaning Cartridge Kit (part 21F8593).	
	4. Visually inspect the data cartridge. If it is damaged, discard it.	
	5. Check the lifetime statistics on the system for this tape volume ID. If the cartridge has a history of tape errors, discard it.	
	If the data on the tape was not written using OS/400, the format may not be correct.	
	Do not use the cleaning cartridge more than 12 times.	
	Each data cartridge must have a unique volume ID label. The user must assign a volume ID when the tape is initialized (INZTAP).	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
FFFF	Write data error: tape path dirty	MLVTMED 91F0914
	This error may be caused by a dirty recording head, poor or damaged tapes, worn or damaged data cartridges, or using a format that is not correct.	
	1. Switch off power to the tape unit.	
	2. Switch on power to the tape unit.	
	<ol> <li>Clean the recording head in the tape unit. Use the IBM Cleaning Cartridge Kit (part 21F8593).</li> </ol>	
	4. Visually inspect the data cartridge. If it is damaged, discard it.	
	5. Check the lifetime statistics on the system for this tape volume ID. If the cartridge has a history of tape errors, discard it.	
	If the data on the tape was not written using OS/400, the format may not be correct.	
	Do not use the cleaning cartridge more than 12 times.	
	Each data cartridge must have a unique volume ID label. The user must assign a volume ID when the tape is initialized (INZTAP).	

## Table 2. Model 002 Tape drive failing items

Failing Item	Description	Document Description
42F7300	Fan	7208 8mm Tape Drive service information
53F3861	Internal signal cable	7208 8mm Tape Drive service information
81F9128	Power supply	7208 8mm Tape Drive service information
91F0721	Terminating plug	7208 8mm Tape Drive service information
91F0914	Tape drive	7208 8mm Tape Drive service information
AJEDA00	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
MLVTMED	Defective tape	7208 8mm Tape Drive service information

## Table 3. (7208) Model 012 Tape drive reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0001	Tape unit failure The tape drive reported a hardware error to the IOP; the amber light on the tape drive may be blinking. Perform TU-PIP2.	46G2227 ML2TMED

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
030B	Tape unit detected a read error on the tape medium	ML2TMED 46G2227
	Read (or write) errors may be caused by:	46G3934
	Poor or damaged tape	42F7300
	Dirty read/write heads	
	Damaged data cartridges	
	• Using a data cartridge previously recorded in a format or density that is not correct	
	• Using the wrong data cartridge (for example, one in a different format or density from another set of data cartridges)	
	If the data on the tape was not written by OS/400, the format or the density may not be correct. Get or make a new copy of the data cartridge.	
	If you are performing a write or a save operation, initialize the tape. See the note below.	
	If you are performing a read or a restore operation, the tape may be worn or the device that wrote the tape may be the cause of the problem.	
	Perform TU-PIP2.	
	When the system is available, perform the following:	
	• Verify the operation of the tape drive. Use the VFYTAP system command.	
	<b>Note:</b> When a tape is initialized, a new label is recorded at the beginning of the tape, and any data recorded previously is erased and overwritten. To initialize used tapes, use the INZTAP system command with "Check for active files" option of *NO.	
	Use of the INZTAP "Clear" (security erase) option is not recommended. The 7208 Tape Drive performs a write operation to erase all of the tape; writing (erasing) a full-size tape takes up to 3.5 hours.	
0311, 0316	Tape unit detected a read error on the tape medium	ML2TMED
	Perform the Action for reference code 030B.	46G2227 46G3934 42F7300
031C	The data format is incorrect; the tape cannot be read	ML2TMED 46G2227
	The tape format is not known or not compatible. The data cartridge may not have been recorded using OS/400.	
	Get another copy of the data cartridge recorded in a format and density given support by OS/400.	
0336	The data format is incorrect; the tape cannot be read	ML2TMED
	The tape format is not known or not compatible. The data cartridge may not have been recorded using OS/400.	46G2227 46G3934 42F7300
	Get another copy of the data cartridge recorded in a format and density given support by OS/400.	
0337 to 0338, 033D	Tape unit detected a read error on the tape medium	ML2TMED
	Perform the Action for reference code 030B.	46G2227 46G3934 42F7300

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0395 to 0397, 039D to 039F	Tape unit detected a write error on tape medium	ML2TMED 46G2227
	Perform the Action for reference code 030B.	
03AE, 03B0	Tape unit detected a read or write error on tape medium	ML2TMED 46G2227
	Perform the Action for reference code 030B.	
03B3 to 03B4	Tape unit detected a write error on tape medium	ML2TMED 46G2227
	Perform the Action for reference code 030B.	
)3B5	Tape unit detected a read error on the tape medium	ML2TMED 46G2227
	Perform the Action for reference code 030B.	
0417 to 0419, 0458, 045A, 0467 to 0468, 046D, 0498 to 049A, 049C, 04A1 to 04A8, 04AB to 04AD,	Tape unit failure The tape drive reported a hardware error to the IOP; the amber light on the tape drive may be blinking. Perform TU-PIP2.	46G2227 ML2TMED 46G3934 42F7300
94AB to 04AD, 94FA, 04FC to 94FD		
3002	I/O processor addressed the tape unit; no response	46G2227
	The tape drive did not respond to commands from the IOP. Perform the following:	46G3934 FI00830 FI00141
	1. Ensure that the system interface cable is connected.	46G2599
	2. Ensure that power is on.	17G1500 42F7300
	If the above items are correct, perform the following: 1. TU-PIP1	
	2. TU-PIP3	
3004	Tape unit failed after Licensed Internal Code was loaded	46G2227
000 <del>1</del>	The tape drive does not respond to IOP commands after new Licensed Internal Code was transferred to the tape drive.	4032227
	Perform TU-PIP4.	
3005	Blank tape or BOT encountered	ML2TMED
	The tape drive has found a blank tape or BOT.	46G2227 AJEDA00
	When using a new data cartridge, the tape must first be initialized.	
	This error can also occur when reading a tape if that tape was removed from the tape drive before writing was complete.	
	Also see the Action for reference code 030B.	
8010	Illegal or unsupported tape unit response	46G2227
	The tape drive returned a response to the IOP that is illegal or is not given support.	AJEDA00
	Perform the following:	
	1. TU-PIP1	
	2. TU-PIP3	

7208	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3100	Interface error detected by I/O processor or by tape unit	46G2227
	The IOP or the device detected a permanent error on the interface to the system.	FI00141 FI00830 46G2599 42F7300
	Perform the following:	17G1500
	1. TU-PIP1	46G3934
	2. TU-PIP3	AJEDA00
3110	Tape unit command timeout	46G2227
	The tape drive did not complete a command sent by the IOP in the time allowed.	FI00141 FI00830 46G2599 42F7300
	Perform the following:	17G1500
	1. TU-PIP1	46G3934
	2. TU-PIP2	AJEDA00
4016 to 4017	Licensed Internal Code for the tape unit is not correct	AJEDA00
9020	I/O processor detected a SCSI bus configuration error	UL2CNFG
	Before exchanging any parts, verify that the following conditions are not present:	46G2227 FI00130
	• Tape and DASD devices attached to an I/O Processor that does not support attachment of both tape and DASD devices at the same time.	
	• A device type or model that is not given support.	
9100	Interface error detected by I/O processor or by tape unit	46G2227 FI00131
	Before exchanging any parts, do the following:	46G3934
	1. Ensure that the device is powered on.	FI00830
	2. Ensure that the SCSI cable between the device and the I/O Processor or I/O Adaptor is seated correctly, and that there are no bent or damaged pins on the SCSI cable.	46G2599 17G1500
	<b>3.</b> Ensure that a terminating plug is attached to the device.	
9200	I/O processor addressed the tape unit; no response	46G2227
	Before exchanging any parts, do the following:	46G3934
	<ol> <li>Ensure that the device is powered on.</li> </ol>	FI00830 FI00131
	<ol> <li>Ensure that the device is powered on.</li> <li>Ensure that the SCSI cable between the device and the I/O Processor or</li> </ol>	46G2599
	2. Ensure that the SCSI cable between the device and the I/O Processor of I/O Adaptor is seated correctly, and that there are not bent or damaged	17G1500
	pins on the SCSI cable.	42F7300
	3. Ensure that the terminating plug is attached to the device.	
9201	Tape unit command timeout	46G2227
	Before exchanging any parts, do the following:	46G3934 FI00830
	1. Ensure that the device is powered on.	FI00131
	2. Ensure that the SCSI cable between the device and the I/O Processor or I/O Adaptor is seated correctly, and that there are not bent or damaged pins on the SCSI cable.	46G2599 17G1500 42F7300
	3. Ensure that the terminating plug is attached to the device.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9202	<ul> <li>Tape unit failed after Licensed Internal Code was loaded</li> <li>Before exchanging any parts, do the following:</li> <li>1. Ensure that the device is powered on.</li> <li>2. Ensure that the SCSI cable between the device and the I/O Processor or I/O Adaptor is seated correctly, and that there are not bent or damaged pins on the SCSI cable.</li> </ul>	46G2227 46G3934 FI00830 FI00131 46G2599 17G1500 42F7300
	3. Ensure that the terminating plug is attached to the device.	
9210	Illegal or unsupported tape unit response	46G2227 FI00130 FI00131
9300	Tape unit failure The tape drive reported a hardware error to the IOP; the amber light on the tape drive may be blinking. Perform TU-PIP2.	46G2227 ML2TMED 46G3934 42F7300
9301	Tape device failure, redundancy lost The tape device detected a hardware failure that does not prevent the tape unit from completed the current operation.	46G2227 ML2TMED 46G3934 42F7300
9302	Refer to the Tape unit service information to determine the failing item.         Tape device failure or media error         The tape unit detected a failure that may be caused by a hardware failure or a media error.         Refer to the tape unit service information for possible information on diagnostic tests that can be run to isolate between hardware and media failures.	ML2TMED 46G2227 46G3934 42F7300
9310	Licensed Internal Code for the tape unit is not correct	46G2227 FI00130
9320	Tape device Licensed Internal Code failure	FI00130 46G2227
9350	<ul><li>Tape unit detected a read or write error on tape medium</li><li>A permanent read or write error occured. Clean the tape unit and retry the operation.</li><li>If cleaning the tape unit does not correct the problem, exchange the tape media.</li></ul>	ML2TMED 46G2227 46G3934 42F7300
9351	Tape with excessive error rate was mounted in tape device.The tape unit detected that the mounted tape cartridge has a history of excessive read and write errors. It is recommended that you exchange the tape cartridge.	ML2TMED UL2CLN 46G2227
9355	The data format is incorrect; the tape cannot be read The tape unit has detected that the data format on the tape media is not supported.	UL2USR1 ML2TMED UL2CLN 46G2227
	Clean the tape unit and retry the operation.	
	If the operation continues to fail, use a different tape cartridge.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9500	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, take a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i> information or ask your next level of support for assistance.	
9800 to 9803	I/O processor successfully recovered from temporary error	
	No action required. This reference code is logged for information only.	
9810	Problem analysis has determined a part should be replaced.	
	This reference code is used for ending Online Problem Analysis with a list of failing items. (Information only)	
9899	Problem analysis completed, the problem has been corrected.	UL2FIXD
	This reference code is used for ending Online Problem Analysis when no problem was found or the problem was corrected.	
9900, FF09	Licensed Internal Code for tape unit was not upgraded	UL2WAIT
	The I/O processor loading of Licensed Internal Code (LIC) to the programmable tape drive was not completed.	
	The tape drive will continue to operate with the previous LIC. You may do either of the following:	
	• Wait for next IPL when the system will attempt to load the LIC for the tape drive again.	
	• Perform TU-PIP4 to reset the IOP and the tape drive. When the IOP is reset, if the device has the wrong level of LIC, the IOP will attempt to load the new LIC.	
FF4D	I/O processor successfully recovered from temporary error	46G2227
	No action required. This reference code is logged for information only.	FI00141 FI00830
	When the system is available, display the operator messages, find message CPI946B, and press F14 to run online problem analysis to see if the error threshold has been exceeded.	46G2599 46G3934 17G1500 42F7300 AJEDA00
FF5D	I/O processor successfully recovered from temporary error	46G2227
	No action required. This reference code is logged for information only.	46G3934 FI00830
	When the system is available, display the operator messages, find message CPI946B, and press F14 to run online problem analysis to see if the error threshold has been exceeded.	FI00141 46G2599 17G1500 42F7300
FFF6	Tape volume statistics logged (no action required)	
	No action required. This reference code is logged for information only.	
FFF8	Asynchronous device attached; synchronous device expected	46G2227
	The attached device is operational and working in the asynchronous mode of data transfer.	
	The IBM tape unit uses the synchronous mode of data transfer; if the attached device is an IBM tape unit, exchange the tape unit.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
FFFE	Tape unit detected a read error on the tape medium Perform the Action for reference code 030B.	ML2TMED 46G2227 46G3934 42F7300
FFFF	Tape unit detected a write error on tape medium Perform the Action for reference code 030B.	ML2TMED 46G2227

#### Table 4. Model 012 Tape drive failing items

Failing Item	Description	Document Description
17G1500	Internal signal cable	7208 Model 012 5.0GB External 8mm Tape Drive Service Guide
42F7300	Fan	7208 Model 012 5.0GB External 8mm Tape Drive Service Guide
46G2227	Tape drive	7208 Model 012 5.0GB External 8mm Tape Drive Service Guide
46G2599	Terminating plug	7208 Model 012 5.0GB External 8mm Tape Drive Service Guide
46G3934	Power supply	7208 Model 012 5.0GB External 8mm Tape Drive Service Guide
AJEDA00	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
ANYBUS	IOP card bus error	Problem Analysis; Symbolic FRU Isolation
ML2TMED	Defective tape	7208 Model 012 5.0GB External 8mm Tape Drive Service Guide
UL2CLN	Tape unit needs cleaning	Magnetic tape subsystem operator's information
UL2CNFG	Tape configuration detected by I/O processor; not valid	Magnetic tape subsystem operator's information
UL2USR1	Operator action required	Magnetic tape subsystem operator's information
UL2WAIT	Wait to next IPL or perform TU-PIP4	Problem Analysis

## (9348) Tape unit reference codes

For use by authorized service providers.

A tape or a 9348 Tape Unit failure occurred.

- **Note:** If the system is available, use the online diagnostic tests when possible. Use the Work with Problem (**WRKPRB**) command to determine if a recent problem has been entered in the problem log, or use the Verify Tape (**VFYTAP**) command. Other helpful commands are Work with Hardware Resources (**WRKHDWRSC \*STG**) and Work with Configuration Status (**WRKCFGSTS \*DEV \*TAP**). For tape device and IOP reset procedures, see TU-PIP4.
- 1. Verify that the 9348 Tape Unit is powered on and that the interface cable connections are correct for each 9348 Tape Unit.
- 2. Clean the tape path as described in the 9348 Tape Unit Service Information.
- **3.** Load the first tape and start a type "D" IPL from the system unit control panel. Does the IPL complete successfully?
  - Yes: The problem has been corrected.

This ends the procedure.

- No: Obtain another copy of the tape. Repeat this step using the new tape. If this does not correct the problem, continue with the next step.
- 4. Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code.
- 5. If the tape unit indicator panel shows an error condition, see the 9348 *Tape Unit Service Information* and find the unit reference code.

# (9427) Tape unit reference codes

For use by authorized service providers.

The tape library detected a failure.

- 1. Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Tape unit failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0001	Tape unit failure	
	Refer to the 9427 8mm Tape Cartridge Library Service Guide.	
03xx	Tape unit detected an error on the tape medium	
	Read (or write) errors may be caused by:	
	Poor or damaged tape	
	Dirty read/write heads	
	Damaged data cartridges	
	• Using a data cartridge previously recorded in a format or density that is not correct	
	• Using the wrong data cartridge (for example, one in a different format or density from another set of data cartridges)	
	Do the following:	
	1. Clean the tape unit and retry the operation.	
	2. If cleaning the tape unit does not correct the problem, exchange the tape media.	
04xx	Tape unit failure	
	The tape drive reported a hardware error to the IOP; the amber light on the tape drive may be blinking.	
	Refer to the 9427 8mm Tape Cartridge Library Service Guide.	
3xxx	Device or interface error.	
	Refer to the 9427 8mm Tape Cartridge Library Service Guide.	
4016 to 4017	Licensed Internal Code for the tape unit is not correct	AJEDA00

Table 1. (9427) Tape unit reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9020	I/O processor detected a SCSI bus configuration error	ULYCNFG
	P. Gran and the state of the first day (11) is a set of the state of t	86G9251
	Before exchanging any parts, verify that the following conditions are not present:	FI00130
	*	86G9254
	• Tape and DASD devices attached to an I/O Processor that does not support attachment of both tape and DASD devices at the same time.	
	<ul> <li>A device type or model that is not given support.</li> </ul>	
9100		86C02E1
9100	Interface error detected by I/O processor or by tape unit	86G9251 FI00131
	Before exchanging any parts, do the following:	86G9254
	1. Ensure that the device is powered on.	EXTSCSI
	2. Ensure that the SCSI cable between the device and the I/O Processor or	86G9255
	I/O Adaptor is seated correctly, and that there are no bent or damaged	86G9274
	pins on the SCSI cable.	17G9134
	<b>3</b> . Ensure that a terminating plug is attached to the device.	FI00130
9200	I/O processor addressed the tape unit; no response	86G9251
		86G9274
	Before exchanging any parts, do the following:	86G9254
	1. Ensure that the device is powered on.	FI00131
	2. Ensure that the SCSI cable between the device and the I/O Processor or	EXTSCSI
	I/O Adaptor is seated correctly, and that there are not bent or damaged	17G9134
	pins on the SCSI cable.	87G1531
	3. Ensure that the terminating plug is attached to the device.	86G9255
9201	Tape unit command timeout	86G9251
		FI00131
	Before exchanging any parts, do the following:	86G9254
	1. Ensure that the device is powered on.	EXTSCSI
	2. Ensure that the SCSI cable between the device and the I/O Processor or	17G9134
	I/O Adaptor is seated correctly, and that there are not bent or damaged	86G9255
	pins on the SCSI cable.	86G9274
	3. Ensure that the terminating plug is attached to the device.	FI00130
9202	Tape unit failed after Licensed Internal Code was loaded	86G9251
		86G9274
	Before exchanging any parts, do the following:	86G9254
	1. Ensure that the device is powered on.	
	2. Ensure that the SCSI cable between the device and the I/O Processor or	
	I/O Adaptor is seated correctly, and that there are not bent or damaged	
	pins on the SCSI cable.	
	<b>3</b> . Ensure that the terminating plug is attached to the device.	
9210	Illegal or unsupported tape unit response	86G9251
		FI00130
		FI00131
9300	Tape unit failure	86G9251
		LIBDEV
	The tape drive reported a hardware error to the IOP; the amber light on	MLYTMED
	the tape drive may be blinking.	86G9274
	Perform TU-PIP2.	86G9255

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
9301	Tape device failure, redundancy lostThe tape device detected a hardware failure that does not prevent the tape	86G9251 LIBDEV MLYTMED
	unit from completed the current operation.	86G9274 86G9255
	Refer to the Tape unit service information to determine the failing item.	0007200
9302	Tape device failure or media error The tape unit detected a failure that may be caused by a hardware failure	MLYTMED 86G9251
	or a media error.	
	Refer to the tape unit service information for possible information on diagnostic tests that can be run to isolate between hardware and media failures.	
9310	Licensed Internal Code for the tape unit is not correct	86G9251 FI00130
9320	Tape device Licensed Internal Code failure	FI00130 86G9251
9350	Tape unit detected a read or write error on tape medium	MLYTMED 86G9251
	A permanent read or write error occured. Clean the tape unit and retry the operation.	0007231
	If cleaning the tape unit does not correct the problem, exchange the tape media.	
9351	Tape with excessive error rate was mounted in tape device.	MLYTMED ULYCLN
	The tape unit detected that the mounted tape cartridge has a history of excessive read and write errors. It is recommended that you exchange the tape cartridge.	86G9251
9355	The data format is incorrect; the tape cannot be read	ULYUSR1 MLYTMED
	The tape unit has detected that the data format on the tape media is not supported.	ULYCLN 86G9251
	Clean the tape unit and retry the operation.	
	If the operation continues to fail, use a different tape cartridge.	
9500	I/O processor Licensed Internal Code error	FI00130
	If the system is operational, perform a dump of the I/O processor data. For more information, see the <i>iSeries Service Functions</i>	
9600	Equipment Check Failure on Library Device.       LIBDE	
	See library device service information to resolve the error.	
9800 to 9803 I/O processor successfully recovered from temporary error		
	No action required. This reference code is logged for information only.	
9810	Problem analysis has determined a part should be replaced.	
	This reference code is used for ending Online Problem Analysis with a list of failing items. (Information only)	
9899	Problem analysis completed, the problem has been corrected.	ULYFIXD
	This reference code is used for ending Online Problem Analysis when no problem was found or the problem was corrected.	

Reference Code	rence Code Description/Action Perform all actions before exchanging Failing Items	
9900	Licensed Internal Code for tape unit was not upgraded	ULYWAIT
	The I/O processor loading of Licensed Internal Code (LIC) to the programmable tape drive was not completed.	
	The tape drive will continue to operate with the previous LIC. You may do either of the following:	
	• Wait for next IPL when the system will attempt to load the LIC for the tape drive again.	
	• Perform TU-PIP4 to reset the IOP and the tape drive. When the IOP is reset, if the device has the wrong level of LIC, the IOP will attempt to load the new LIC.	
FF09	Licensed Internal Code for tape unit was not upgraded	ULYWAIT
	The I/O processor loading of Licensed Internal Code (LIC) to the programmable tape drive was not completed.	
	The tape drive will continue to operate with the previous LIC. You may do either of the following:	
	• Wait for next IPL when the system will attempt to load the LIC for the tape drive again.	
	• See the system service documentation to reset the IOP and the tape drive. When the IOP is reset, if the device has the wrong level of LIC, the IOP will attempt to load the new LIC.	
FF4D	I/O processor successfully recovered from temporary error	86G9251
	No action required. This reference code is logged for information only.	FI00141 EXTSCSI 17G9134
	When the system is available, display the operator messages, find message CPI946B, and press F14 to run online problem analysis to see if the error threshold has been exceeded.	86G9253 86G9255 AJSLC01
FF5D	I/O processor successfully recovered from temporary error	86G9251
	No action required. This reference code is logged for information only.	86G9253 EXTSCSI FI00141
	When the system is available, display the operator messages, find message CPI946B, and press F14 to run online problem analysis to see if the error threshold has been exceeded.	17G9134 86G9255
FFF6	Tape volume statistics logged (no action required)	
	No action required. This reference code is logged for information only.	
FFF8	Asynchronous device attached; synchronous device expected	86G9251
	The attached device is operational and working in the asynchronous mode of data transfer. The IBM tape unit uses the synchronous mode of data transfer; if the attached device is an IBM tape unit, exchange the tape unit.	
FFFE	Tape unit detected a read error on the tape medium	MLYTMED
	Perform the Action for reference code 03xx.	86G9251 86G9253
FFFF	Tape unit detected a write error on tape medium	MLYTMED
	Perform the Action for reference code 03xx.	86G9251

## Table 2. Tape unit failing items details

Failing Item	Description	Document Description
17G9134	Terminating plug	Magnetic tape subsystem service information
86G9251	Tape Drive	7208 Model 012 5.0GB External 8mm Tape Drive Service Guide
86G9251	Tape drive	Magnetic tape subsystem service information
86G9253	Power supply	Magnetic tape subsystem service information
86G9254	Controller logic card	Magnetic tape subsystem service information
86G9255	Internal signal cable	Magnetic tape subsystem service information
87G1531	Operator Panel/LCD Assembly	Magnetic tape subsystem service information
AJSLC01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR
EXTSCSI	Cable assembly	Problem Analysis; Symbolic FRU Isolation
LIBDEV	Media Library Device	Magnetic tape subsystem service information
MLYTMED	Defective tape	System operation information
ULYCLN	Tape unit needs cleaning	Magnetic tape subsystem operator's information
ULYCNFG	Tape configuration detected by I/O processor; not valid	Magnetic tape subsystem operator's information
ULYUSR1	Operator action required	Magnetic tape subsystem operator's information
ULYWAIT	Wait to next IPL or perform TU-PIP4	Problem Analysis

# (A1xx, B1xx) Service processor reference codes

For use by authorized service providers.

If the SRC is A1xx 3xxx, see Working with Storage Dumps in the iSeries Service Functions information.

If the SRC is A1xx 8xxx, go to Powering Off the System.

- 1. Look at the 4 rightmost characters of the Data display for word 1. These 4 characters are the unit reference code.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Service processor failing items details, which follows the reference code table below.

Table 1. (A1xx, B1xx) Service processor reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1000, 1002, 1005	Service processor card failure	SVCPROC
1007 to 1008	Service processor real time clock problem	SVCPROC
100E to 100F, 1300	Service processor card failure	SVCPROC
1360	Service processor reset was issued LIC has detected a problem with the Service processor and has reset it but has not initiated reload of the Service processor. Some system service operations have been suspended and the system should be scheduled for power down as soon as possible. Perform a system IPL. If no PTFs are available to fix this problem, send the Service processor dump in to IBM.	AJDGP01 AJDG301 SVCPROC
1370, 1380	Service processor card failure	SVCPROC

Reference Code         Description/Action Perform all actions before exchanging Failing Items		ms Failing Item	
1381	Service processor card failure		
1384	Service processor card failure	SVCPROC	
1387	Service processor card failure	SVCPROC	
	The Licensed Internal Code could not allocate resources on the Service processor.		
1400 to 1401, 1670, 1672, 1675, 1681 to 1683, 4600	Service processor card failure	SVCPROC	
4601	System Card(s) or BackPlane	SYSUNIT	
4602	Any device attached to Bus 1	BUS1	
4603	Service processor card failure	AJDGP01 SVCPROC	
4604	Any device attached to Bus 1 or the Load Source IOP	IPLINTF	
	Perform SP-PIP45.		
4605	Problem with load source device media	LSMEDIA	
4606	Problem detected with control panel	CTLPNL	
4607	Alternate load source device (tape/optical)	LSMEDIA	
4608	Service Processor Problem Isolation Procedure	AJDGP01	
	Perform SP-PIP42.	SVCPROC	
4609	Service Processor Problem Isolation Procedure	AJDGP01	
	Perform SP-PIP43.		
460A	Service processor real time clock problem	SVCPROC	
	The system time and date has been lost. The correct time and date must be entered on the system.		
460B	Battery not working correctly	TOD	
	A problem was detected with the battery supplying power to the time-of-day clock. The battery is either weak or is not connected securely. <b>Note:</b> This is not a critical failure. However, if there is a power failure, the time of day will be lost.		
460C	Power supply	IOPWR	
4611	System processor card failure	SVCPROC SYSUNIT	
4612	Service Processor Problem Isolation Procedure	AJDGP01 SVCPROC	
4613	Service Processor Problem Isolation Procedure	SVCPROC	
4614	Service Processor Problem Isolation Procedure SYSU		
4622	Problem detected with control panel CTLPN SVCPR		
4633	SPCN to CSP interface error.     SPCNCRE       SVCPROC     SVCPROC		
4644	CSP to VPD Collector interface error.		

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4645 to 4646	CSP to VPD Collector interface error.	VPDCONC SVCPROC SYSUNIT
4647	CSP to VPD Collector interface error. SVCPROC CTLPNL	
4648	CSP to VPD Collector interface error. SVC SYSU	
4650	System processor card failure	PROC
4651	System processor card failure	PROC0
4652	System processor card failure	PROC1
4653	System processor card failure	PROC2
4654	System processor card failure	PROC3
4660	Main storage failure	JTPORT MSTORE
4661 to 4662	Main storage failure	MSTORE
4680	System processor card failure	HSLCTLR
4681	System processor card failure	CLKCARD
4682	Problem detected with control panel	CTLPNL
	For Model 825, perform SP-PIP44.	
	For all other models, replace the items in the failing item list.	
4690	Service processor LIC problem	AJDG301
	If this SRC is displayed at the control panel, then record all of the SRC data words. Perform a main storage dump using control panel function 22, and report the problem to the next level of support. If this SRC is displayed at the system console dump manager screen then save the main storage dump and report the problem to service.	
4691 to 4697	Service processor Licensed Internal Code     AJDGP01       Perform INT-PIP24.     AJDGP01	
4698	Operator/User Error	OPUSR
4699	Service processor Licensed Internal Code	AJDGP01
-	Perform INT-PIP24.	,
469A	Service processor Licensed Internal Code	AJDGP01
	Perform INT-PIP24.	AJDG301
469B	Service processor LIC problem	AJDG301
	Record all the SRC data words, attempt a main storage dump, and replace the FRUs listed if necessary.	
469C	Service processor Licensed Internal Code	AJDGP01
	Perform INT-PIP24, then replace the FRUs listed if necessary.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
469D	Service processor Licensed Internal Code	AJDGP01
	If this SRC is displayed at the system console dump manager screen then save the main storage dump and report the LIC failure to service. If this SRC is displayed at the control panel then perform INT-PIP24.	
469E	Service processor Licensed Internal Code AJDGPC SYSUNI Perform INT-PIP24. SVCPRC	
469F		SVCPROC AJDGP01
4091	Service processor Licensed Internal Code Perform INT-PIP24.	SVCPROC SYSUNIT
4998	Operator/User Error	UCSUSER
6010	Any device attached to Bus 1	JTPORT
8FF0	Information only, no service action required Service processor error log entry.	
	If the secondary refcode is 806A, a successful download of control panel code has occured.	
	If the secondary refcode is 8EEE, one of the following conditions may have occured.	
	Operation was successful but current keylock position was not in Auto or normal.	
	The Time-of-Day (TOD) chip had to be reset due to an invalid power-up state. TOD requests will not work successfully until a write TOD is done (CHGSYSVAL QDATE).	
	Timed-Power-On request has been acknowledged. Power on sequences must be set for valid months, days, hours, minutes, and seconds, for future times, and for times when the system will be powered off.	
8FF1	System down, condition reported	

## Table 2. Service processor failing items details

Failing Item	Description	Document Description
AJDG301	Licensed Internal Code	Service Functions; APAR or LICTR
AJDGP01	Service processor Licensed Internal Code	Service Functions; APAR or LICTR
ALTINTF	System bus	Problem Analysis; Symbolic FRU Isolation
AUSTIN0	RESERVED - Austin Only code - flash update by diskette	Problem Analysis; Symbolic FRU Isolation
BACKPLN	Back Plane Unit	Problem Analysis; Symbolic FRU Isolation
BUS1	System bus	Problem Analysis; Symbolic FRU Isolation
CECPWR	Power supply	Problem Analysis; Symbolic FRU Isolation
CLCKCRD	Clock Card	Problem Analysis; Symbolic FRU Isolation
CLKCARD	Clock Card	Problem Analysis; Symbolic FRU Isolation

Failing Item	Description	Document Description
CTLPNL	Control Panel, or the interface to the Control Panel	Problem Analysis; Symbolic FRU Isolation
HSLCTLR	System processor card	Problem Analysis; Symbolic FRU Isolation
IOPWR	Power Supply	Problem Analysis; Symbolic FRU Isolation
IPLINTF	System bus	Problem Analysis; Symbolic FRU Isolation
JTPORT	System Interconnect cable, connection or interposer card	Problem Analysis; Symbolic FRU Isolation
LSMEDIA	Tape, DASD or Optical Media	Problem Analysis; Symbolic FRU Isolation
MSTORE	Main storage cards	Problem Analysis; Symbolic FRU Isolation
OPUSR	Operator/User Error	System Operations: Operator's Guide SC41-8082
PROC	System processor card	Problem Analysis; Symbolic FRU Isolation
PROC0	System processor card	Problem Analysis; Symbolic FRU Isolation
PROC1	System processor card	Problem Analysis; Symbolic FRU Isolation
PROC2	System processor card	Problem Analysis; Symbolic FRU Isolation
PROC3	System processor card	Problem Analysis; Symbolic FRU Isolation
SPCNCRD	SPCN card	Problem Analysis; Symbolic FRU Isolation
STORIOA	Storage I/O Adapter	Problem Analysis; Symbolic FRU Isolation
SVCPROC	Service Processor Card	Problem Analysis; Symbolic FRU Isolation
SYSUNIT	System unit	Problem Analysis; Symbolic FRU Isolation
TOD	Control Panel Battery	Problem Analysis; Symbolic FRU Isolation
TWRCARD	Card enclosure or backplane	Problem Analysis; Symbolic FRU Isolation
UCSPIP	Service Processor Problem Isolation Procedure	
UCSUSER	Option not valid at this time	Service Functions; Working with Storage Dumps
VPDCONC	The system vital product data has failed	Problem Analysis; Symbolic FRU Isolation

# (A6xx, B6xx) Licensed Internal Code reference codes

For use by authorized service providers.

Use this table for both A6xx and B6xx reference codes. Bus errors are of the form B600 69xx. Other subsystems that produce Licensed Internal Code errors are also represented in the B6xx Reference Code Table.

Perform the following:

- 1. Find the SRC in the SRC column of the following table.
- 2. Perform the actions in the What You Should Do column of the table.

In all cases, after you determine the failing item, go to the locations table for the system or tower you are working on to determine the location, and to the removal and replacement procedure for the failing item.

## Table 1. General description of recommended actions

SRC	What You Should Do
11 A6xx xxxx	Licensed Internal Code intervention is needed.
	<ol> <li>Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.</li> </ol>
	2. See the following table (Table 2) and find the unit reference code.
11 B6xx xxxx	The Licensed Internal Code detected a failure.
	<ol> <li>Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.</li> </ol>
	2. See the following table (Table 2) and find the unit reference code.
	<ol> <li>When working with the Product Activity Log, System Licensed Internal Code entries often occur as a secondary effect of other hardware related entries. The following list is a suggested method of isolating these kinds of problems.</li> </ol>
	a. Examine the date and time of the informational reference codes.
	<ul> <li>b. Determine if any other reference codes were logged at or before the same date and time.</li> </ul>
	<b>c.</b> Start the service approach based on these other logged errors.

For more on the Failing Item column entries, see Table 3. Licensed Internal Code failing items details, which follows the reference code table below.

Table 2. (A6xx,	B6xx)	Licensed	Internal	Code	reference	codes
-----------------	-------	----------	----------	------	-----------	-------

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0000	Operating system status code	
	This reference code is for information only. It is shown in the Product activity log as a side effect of a condition that was detected by LIC.	
	Normally, no action should be taken as a result of information reference codes. However, to isolate the root cause, use these suggestions:	
	1. Examine the date and time of the informational reference code.	
	2. Determine if any other reference codes have been logged at or before the same date and time.	
	3. Begin the service approach based on these other logged errors.	
0102	A machine check occurred during IPL	
	Words 2 to 9 of this SRC contain additional diagnostic information. Record SRC words 1 through 9 before attempting to IPL again and report the problem to your Software Service Provider.	
0103	Main storage dump must be copied for service.	
	Perform LICIP01.	
0104	Terminate Immediate reference code is bad	AJDG301
	Perform LICIP08.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0105	More than one request to terminate the system was issued	AJDG301
	Perform LICIP08.	
0106	Terminate Immediate data is not valid	AJDG301
	Perform LICIP08.	
0107	Main storage dump must be copied for service.	
	The server detected an unrecoverable machine check condition.	
	Collect all the words of the SRC and the main store dump and send to your system manufacturer for analysis.	
)202	Unrecoverable read error	
	Restore the Licensed Internal Code using "Licensed Internal Code Install and Restore" in the <i>iSeries Service Functions</i> information.	
)210	The system ASP has run out of disk storage	
	The out of storage condition in the system ASP can be caused by an allocation failure in some other system software. This could be a looping condition that continues to allocate storage. Contact your service representative for assistance with the Main Storage Dump.	
0244, 0255, 0266	Contact was lost with the device indicated	FI00580
	Do not power off the system.	FI00500 FI00302
	Perform LICIP13.	FI00301 AJDG301
)277	A compression disk unit cannot complete an operation.	
	Note: Do not power off the system when performing this procedure.	
	Look at the 4 leftmost characters of the Data display for word 7. These four characters indicate the type of problem that exists and the recovery action to perform.	
	If these characters are 8402 or 2002, the compression disk unit is temporarily full of data. The command to the compression disk is being held. When the storage subsystem controller has created sufficient space on the compression disk unit to contain the data, the command which is being held will be released and the system will resume normal processing. If the system does not resume normal processing within 20 minutes, contact your next level of support.	
	If these characters are 8400 or 2000, the compression disk unit is full of data. The command to the compression disk is being held.	
	The customer should perform the recovery actions specified in "Disk Unit	
	Full Considerations" in the Backup and Recovery Guide 🐳 .	
0302	Recursion in exception handler	AJDG301
	Perform LICIP08.	
0304	Component specific exception handler return code not valid	AJDG301
	Perform LICIP08.	
0305	Exception while storage management lock is held	AJDG301
	Perform LICIP08.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0307 to 0308	LIC exception code detected a problem	AJDG301
	Component Specific Exception Handler recursion is detected in an OS/400 process.	
	Perform LICIP08.	
0317	Traceback for code not found	AJDG301
	Perform LICIP08.	
0323 to 0329	LIC exception code detected a problem	AJDG301
	Perform LICIP08.	
0333	A branch to a bad address was attempted	AJDG301
	Perform LICIP08.	
0334	Exception Handler could not be removed	AJDG301
	Perform LICIP08.	
0335	Code resumed to not valid address following exception	AJDG301
	Perform LICIP08.	
0401	A machine check occurred during IPL	AJDG301
	Perform LICIP08.	
0402	A machine check occurred during authority initialization	AJDG301
	Perform LICIP08.	
0403	Unhandled exception during IPL or install	AJDG301
	Perform LICIP08.	
0405	Unhandled exception in authority recovery	AJDG301
	Perform LICIP08.	
0406	Unhandled exception in data base recovery	AJDG301
	Perform LICIP08.	
0407	Unhandled exception in data base initialization	AJDG301
	Perform LICIP08.	
0408	Unhandled exception in journal recovery	AJDG301
	Perform LICIP08.	
0409	Unhandled exception in journal synchronization	AJDG301
	Perform LICIP08.	
0410	Unhandled exception in journal clean up	AJDG301
	Perform LICIP08.	
0411	Unhandled exception in commit recovery	AJDG301
	Perform LICIP08.	
0412	Unhandled exception in commit initialization	AJDG301
	Perform LICIP08.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0413	Rebuild of recovery object index failed	AJDG301
	Perform LICIP08.	
0414	Install of operating system failed on read from media	FI00300
	Perform LICIP08.	
0415	Create user profile failed	AJDG301
	Perform LICIP08.	
0417	Initiating the initial process failed	AJDG301
	Perform LICIP08.	
0418 to 0419, 0420	The information loaded from the install media is not valid	AJDG301
	Perform LICIP08.	
0421	Bad return code creating a queue or message	AJDG301
	Perform LICIP08.	
0422	The Load/Dump command failed	AJDG301
	Perform LICIP08.	
0439	Opening the IPCF connection failed	AJDG301
	Perform LICIP08.	
0440	Termination code is not valid	AJDG301
	Perform LICIP08.	
0441	Power off system command failed	AJDG301
	Perform LICIP08.	
0443	Programmed IPL command failure	AJDG301
	Perform LICIP08.	
0446	Error during machine termination	AJDG301
	Perform LICIP08.	
0447	Failure to reach MI boundary	AJDG301
	Perform LICIP08.	
0449	Exception in MI boundary manager	AJDG301
	Perform LICIP08.	
0506	Attempt to destroy a task with critical flag on	AJDG301
	Perform LICIP08.	
0607	Maximum stack size exceeded in process or task	AJDG301
	Perform LICIP08.	
0620	Event management index is not usable	AJDG301
	Perform LICIP08.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0650	Resource management segment could not be created or extended	AJDG301
	A main store dump was initiated.	
	Words 2 to 9 of this SRC contain additional diagnostic information. Record SRC words 1 through 9.	
	Perform a system IPL and collect the Product activity log and main store dump and provide them along with the recorded SRC information to IBM Service Support.	
	The problem may also be that there is not enough auxiliary storage.	
0801	Invalid LID directory detected	FI00070
	During system IPL, the LIDMgr detected an I/O failure or media failure while trying to read the LID directory.	FI00300 AJDG301
	Perform LICIP08.	
0802	LID directory unusable	AJDG301
	During system IPL, the LIDMgr detected that the LID directory and associated load source is not usable.	
	Reinstall the Licensed Internal Code using "Licensed Internal Code Install and Restore" in the <i>iSeries Service Functions</i> information.	
	For more information, contact IBM Service Support.	
0901	The LinkLoader has found its bad flag ON	
	This reference code is usually the result of a system termination while the LinkLoader is performing its work.	
	Reinstall the Licensed Internal Code using "Licensed Internal Code Install and Restore" in the <i>iSeries Service Functions</i> information.	
0902	Unable to perform programmed IPL	
	The LinkLoader was not successful in performing a programmed IPL.	
	Perform a system IPL. If the problem persists, examine the main storage dump and determine the reason for the failure of the programmed IPL.	
1001	Enqueuing a task to the TDQ which is already enqueued on TDQ	AJDG301
	Perform LICIP08.	
1103	MISR not readable; must be readable for Normal Mode install	
	MISR is not readable. Perform a manual install to reinitialize the system.	
1104	Failure reading media or not install media	
	Determine that correct install media is loaded. If correct install media is installed, media could be corrupt. Obtain another copy of the install media and reattempt the install. If the install still fails, contact your service representative.	
1201	Critical database segment could not be created	AJDG301
	Perform LICIP08.	
1204	Error in constraint enforcement	AJDG301
	Perform LICIP08.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1210	Object not found in the in-use table	AJDG301
	Perform LICIP08.	
1215	Error in critical code sequence	AJDG301
	Perform LICIP08.	
1219	A back leveled driver has been detected	AJDG301
	Perform LICIP08.	
1604	Not able to create APPN task	AJDG301
	An error occurred during task creation which requires a power off of the system.	
	Perform LICIP08.	
1724	An attempt to create a segment failed	AJDG301
	The create could fail for two reasons:	
	A code problem	
	Perform LICIP08.	
	No free auxiliary storage on the system	
	Add additional DASD if the create failed because no auxiliary storage	
	was available.	
1730	An IPL is needed to restore system performance	GG4PL01
	Licensed Internal Code has detected a condition that is impacting system performance. System operation can continue, but system performance may be noticeably reduced until the next IPL.	
	Look at the Product Activity Log entry, and find the value at offset x'000180'. If the value equals x'0000122', the error was caused by too much processor memory being installed.	
	For more information, contact IBM Service Support.	
3000	Logical partition service function Main Storage Dump.	AJDG301
	Copy the current main storage dump to media. For more information on how to copy a Main Storage Dump, refer to the <i>iSeries</i> Service Functions Information (see "Copying a Main Storage Dump" under "Working with Storage Dumps").	
4401	Missing DASD units.	
	Copy the current main storage dump to media.	
	For more information on how to perform a Main Storage Dump, refer to <i>iSeries</i> Service Functions information (see "Copying a Main Storage Dump" under "Working with Storage Dumps").	
4402	Missing DASD units.	
	Copy the current main storage dump to media. Then exit the Main Storage Dump Manager.	
	For more information on how to perform a Main Storage Dump, refer to <i>iSeries</i> Service Functions information (see "Copying a Main Storage Dump" under "Working with Storage Dumps").	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4403	Storage Management failed to reach full paging.	
	Copy the current main storage dump to media.	
	For more information on how to perform a Main Storage Dump, refer to <i>iSeries</i> Service Functions information (see "Copying a Main Storage Dump" under "Working with Storage Dumps").	
4404	Auto copy failed or not attempted.	
	Copy the current main storage dump. If copying to system ASP, existing copies may need to be deleted or renamed. Then exit the Main Storage Dump Manager.	
	For more information on how to perform a Main Storage Dump, refer to <i>iSeries</i> Service Functions information (see "Copying a Main Storage Dump" under "Working with Storage Dumps").	
4405	System ASP threshold exceeded after auto copy done.	
	Delete other system ASP copies or exit the Main Storage Dump Manager and then from DST copy the Auto Copy to media and then delete the Auto Copy in system ASP.	
4420	MSD Manager not configured to save dump information	
	The platform produced dump data, but the Main Storage Dump (MSD) Manager was not configured to automatically copy the dump to an Auxiliary Storage Pool (ASP). The dump will be lost if the system power is lost. Use MSD Manager to manually copy the current platform dump to media or an ASP.	
4421	Insufficient space in the ASP to store a platform dump	
	The platform produced dump data, and the Main Storage Dump (MSD) Manager was configured to automatically copy the dump to an Auxiliary Storage Pool (ASP), but there was not sufficient free space available in the ASP. The dump will be lost if the system power is lost. Manually copy the current platform dump from the platform by performing one of the following:	
	• Make room in the designated ASP and then use the MSD Manager to copy the current platform dump to ASP.	
	• Use the MSD Manager to delete other dump copies, then copy the current platform dump to ASP.	
	• Use the MSD Manager to copy the current platform dump to a different ASP.	
	Use the MSD Manager to copy the current platform dump to media.	
4422	A platform dump is saved in MSD Manager	PLDUMP
	The platform produced dump data. The dump data was copied to the Main Storage Dump (MSD) Manager.	
4700	Processor On Demand error detected.	CTLPNCD
	Processor on Demand Data Block key is not valid.	
	Replace the Processor Capacity card.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4701	Processor On Demand error detected.	AJDG301
	Processor On Demand Data Block contains data that does not match the expected data.	
	Contact your service provider.	
4703	Processor On Demand error detected.	AJDG301
	Processor On Demand Serialization has failed during IPL.	
	Contact your service provider.	
4710	Processor On Demand error detected.	SPNLCRD
	SPCN communication failure during Processor On Demand.	
	Look in the Product Activity Log for other SPCN errors and perform the actions indicated for those errors.	
1712	Processor On Demand error detected.	CTLPNCD
	Correct any Processor Capacity card or SPCN failures.	
4713	Incorrect Processor Capacity Card installed.	CTLPNCD
	The Processor Capacity Card is the failing item since it has been swapped in from a different system.	
	Put the Processor Capacity Card back in the system it came from, and reinstall this system's original Processor Capacity Card.	
1714	The CUoD data is not present. A problem may exist.	
	The Processor Capacity Card was changed and there may be a problem.	
	If the system did have any activated standby processors before the Processor Capacity Card was replaced, then new processor on demand activation codes must be obtained to restore the previous activations.	
	Contact your service provider.	
4715	Processor On Demand error detected.	CTLPNCD
	Correct any Processor Capacity card or SPCN failures.	
1730	Processor On Demand error detected.	AJDG301
	Processor On Demand standby processors are in use.	
	Contact your service provider.	
4731	Processor On Demand error detected.	AJDG301
	The Processor On Demand Trial Activation period is not valid. Contact your next level of support.	
4733	Processor On Demand error detected.	AJDG301
	Contact your service provider.	
1740	Processor On Demand error detected.	AJDG301
	The Processor On Demand Activation code just entered is not valid.	
	Contact your next level of support.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4741	Processor On Demand error detected.	AJDG301
	An invalid Processor On Demand Activation code has been entered more than 5 consecutive times. Contact your service provider.	
4745	Processor Capacity card replaced on activated POD system.	
	Contact IBM Support to order a replacement Processor On Demand activation code.	
4747	1 hour left in POD 14 day Trial Activation Period.	
	If a new activation code was purchased, it should be entered now. Otherwise, the system will revert back to its previous activation state at the end of the Trial Activation Period.	
5001	DST received no response from a work station controller	FI00380
	The workstation I/O processor for the system or partition console did not respond.	AJDG301
	Perform RTRIP01 to determine which Isolation procedure to perform.	
5002	DST problem attempting to use the system console	AJDG301
	A code problem occurred during an attempt to use the system console.	FI00380
	Perform LICIP03.	
5003	Service program failed The ASCII system console failed to respond.	FI00320 FI00602 UG4USR1 AJDG301 FI00380
5004	DST console failed to respond	FI00320
0001	*	FI00602
	The system console failed to respond.	UG4USR1 AJDG301
	Perform RTRIP02 to determine which isolation procedure to perform.	FI00380
5005	Service program failed	FI00320 FI00602
	The workstation adapter system console failed to respond.	UG4USR1
	Perform WSAIP01.	AJDG301 FI00380
5007	Service program failed	FI00320
	The workstation adapter console failed to respond.	FI00602 UG4USR1
	Perform RTRIP07 to determine which isolation procedure to perform.	AJDG301 FI00380
5008	DST console failed to respond	FI00380 FI00719
	Perform Operations Console-PIP3.	
5010	IPL service function ended abnormally	AJDG301
	Perform LICIP04.	
5082	DST lost contact with the console	AJDG301
	A service program lost contact with the system console.	UG4USR1
	Perform RTRIP03 to determine which isolation procedure to perform.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5083	IPL service function ended abnormallyA service program lost contact with the system console.	AJDG301 UG4USR1
	Perform TWSIP01.	
5090	<ul> <li>System startup failed in unattended IPL mode</li> <li>Perform the following:</li> <li>If reference code A6005090 is displayed on the control panel for more than 10 minutes, perform LICIP11.</li> <li>For reference code B6005090, perform LICIP11.</li> </ul>	FI00580 FI00500 FI00301 FI00021 FI00065 AJDG301
5092	System is in DASD migration mode	
	"Install Licensed Internal Code" and "Upgrade Load Source" was specified but the key is not in the manual position. Change the key position to manual and perform a system IPL.	
5094	IASP detected a failure during the vary on operation Perform LICIP12.	SVCDOCS
50FF	DST unrecoverable program error Perform LICIP03.	AJDG301 FI00380
5120	System LIC detected a program exception         System LIC detected a programming problem. If performance or other system degradation is occurring, the system may be operating with reduced resources.         Check the Product activity log for related entries. If this reference code is logged with a <i>Class</i> of Informational, then no action is required.	AJDG301 FI00130
	Otherwise, perform LICIP01.	
5121	<ul> <li>System LIC program exception occurred</li> <li>System LIC detected a programming problem for which a main storage dump may have been initiated.</li> <li>A problem log entry may be generated for this ref code.</li> <li>Perform LICIP01.</li> </ul>	AJDG301
5122	System LIC program exception occurred System LIC detected an IOP programming problem for which an IOP dump may have been initiated.	FI00130 AJDG301 FI00131
	Perform LICIP01.	
5123	System LIC program exception occurred System LIC detected an interface problem with the IOP or an IOP programming problem for which an IOP and main storage dump may have been initiated.	FI00130 AJDG301 FI00131
	Perform LICIP01.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5126	Addressed device failed to respond to selection	DISKDRV STORIOA DISKTRY FI01106 FI01140 FI01141 DEVTERM BACKPLN
5127	IOP timed out a disk command	DISKDRV STORIOA FI01106 DISKTRY FI01140 FI01141 DEVTERM BACKPLN
5128	I/O processor failure	FI01112 FI01107
512D	An IOP dump was initiated	
	Copy the IOP dump entry and any related entries from the Product Activity Log to suitable media, and give to an IBM service representative.	
512E	System LIC program exception occurred The system was in a D IPL mode when the problem was detected. A main storage dump was not taken. Perform LICIP01.	AJDG301 FI00130
5206	System LIC detected a missing IOP LIC code load System LIC detected a missing IOP LIC code load during IPL of the IOP. This indicates that either the IOP code load is not installed on the system load source device or that system LIC was unable to successfully read that load from the load source device. Perform LICIP01.	UG4USR1
5209	System LIC detected an IOP timeout during IOP IPL Verify that all IOP cable connections are secure, and check tape and other non-disk devices and media to verify that they are in a ready state. Perform LICIP01.	UG4USR1 FI00130 AJDG301
5219	System LIC program exception occurredAn IOP signalled to system LIC that it had entered a critical internal state.LIC automatically attempted to restart the IOP.This reference code is logged for information only. No action is required.	FI00310 FI00318 FI00065 FI00130 AJDG301

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5275	The system issued a reset/reload to the IOP.	
	System Licensed Internal Code detected that an IOP Reset/Reload has occurred, and that the IOP successfully recovered.	
	Users who were signed on to a Workstation device under the IOP will need to sign back on. Any LAN/WAN communications lines under the IOP will need to be restarted. Tape/Optical devices under the IOP may need to be varied back on.	
	To determine the cause of the IOP Reset/Reload, check the Product Activity Log for additional entries logged with the same System Log ID, and perform any actions indicated for those errors.	
5276	IOP Reset was issued	AJGLD01
	LIC has detected a problem with the Service Processor IOP and has reset it but has not initiated reload of the Service Processor.	AJDG301 FI00021
	If the load source is mirrored, some system operations may be able to continue normally. However, some system service operations have been suspended and the system should be scheduled for power down as soon as possible.	
	Perform RTRIP08.	
5310	System LIC program exception occurred	LPARSUP
	System LIC detected a logical partition configuration data consistency error. Copy the Product Activity Log data for this error and any related entries and contact your next level of hardware service support.	
5311	System LIC program exception occurred	LPARSUP
	LPAR configuration data does not match current system configuration. The system will not IPL past DST until the problem is corrected.	
	Following is a list of problems which may have caused this SRC to be reported:	
	• Non-configured disk unit which was previously a load source on a partitioned system.	
	• Load source configuration data does not match partition for which it is being used.	
	• Load source configuration data does not match system serial number for which it is being used.	
	• Load source configuration data is newer than primary partition configuration data.	
	Perform LPRIP01.	
5312	System LIC program exception occurred	
	LPAR configuration data informational error.	
	The LPAR configuration data was found to be or inconsistent on a secondary partition's load source. The data was automatically updated to the current system level.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5313	System LIC program exception occurred	LPARCFG
	LPAR configuration data informational error.	
	The LPAR configuration data was found to be inconsistent on a primary partition and could only be corrected with an older copy of the data.	
5320	Incorrect hardware configuration detected.	
	An I/O Adapter used by a guest partition is located in a card slot on the same PCI bridge set as an I/O Processor. Guest partition data may be lost if any of the following occur:	
	• A primary partition Type D IPL is performed.	
	• The I/O Adapter is moved to an operating system partition.	
	• An error causes the logical partition (LPAR) configuration to not be used.	
	To correct the hardware configuration, either the I/O Adapter or the I/O Processor must be moved to a new location. Use the LPAR Validation Tool (LVT) to create a valid configuration. For more information about the LPAR Validation Tool, see the following web site:	
	http://www.ibm.com/eserver/iseries/lpar	
5340	Secondary partition not running at optimum.	
	Check the Primary partition's Product Activity Log for system processor entries from approximately the same time. Perform the actions indicated for those entries.	
5341	Secondary partition not running at optimum.	
	Check the primary partition Product Activity Log for system memory entries from approximately the same time. Perform the actions indicated for those entries.	
5342	Secondary partition not running at optimum.	
	Check the Primary partition's Product Activity Log for system processor entries from approximately the same time. Perform the actions indicated for those entries.	
5343	Secondary partition not running at optimum.	
	Check the Primary partition's Product Activity Log for system memory errors from approximately the same time. Perform the actions indicated for those entries.	
5344	Secondary partition not running at optimum.	LPARSUP
	The interactive performance specified in the configuration data for this partition could not be met.	
	Contact your next level of support.	
5350	Secondary partition software release not supported.	
	The logical partition software version is outside the supported release delta. Check the Release Delta from the Primary partition "Display Partition Release Level" screen.	
	Check the LPAR documentation for the release level of the Primary partition and determine what the supported Release Delta is.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5380	System LIC program exception occurred	LPARSUP
	Record the Product Activity Log (PAL) hex data for this SRC or print the PAL entry.	
	Contact your next level of support.	
5390	System LIC program exception occurred	LPARSUP
	Record the Product Activity Log (PAL) hex data for this SRC or print the PAL entry.	
	Contact your next level of support.	
5505	The copying of DASD log data to the IOP log was successful	
	IOP log data can be copied to a spool file for examination by the development lab.	
5555	SLIC I/O DASD subsystem error recovery in progress.	
5600	Unrecoverable read error	SVCDOCS
	VPD data could not be read.	
	Look for other errors implicating hardware. There is no way to know what VPD read has failed, but the resource is not useable and should generate an error.	
	If no such error occurred, call your next level of support.	
6900	System bus error The copper bus, bus 4 in the SPD migrated tower, is inoperative due to a stuck line or a parity error. Any SPD system bus-related hardware on bus 4 may have failed including the HSL I/O bridge or HSL cable connecting SPD bus 4 to the HSL loop. Perform BUS-PIP1.	FI00065 AJDG301
6901	Bus Expansion Adapter card failed The copper bus, the first SPD bus in the system unit or migrated tower, has failed due to an internal chip error on the local bus adapter. Perform BUS-PIP1. If a Service Action Log entry is available for this error, use the failing item list presented there for servicing this reference code.	LBUSADP AJDG301
6902	Bus Expansion Adapter card failed An optical bus has failed due to an internal chip error on one of the remote bus adapters. Perform BUS-PIP1.	FI00203 AJDG301
6905	Optical bus failed An optical bus is inoperative due to a stuck line or an invalid bus command. Any bus-related hardware may have failed. Perform BUS-PIP1. If a Service Action Log entry is available for this error, use the failing item list presented there for servicing this reference code.	FI00065 LBUSADP AJDG301

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6906	High Speed Link (HSL) I/O bridge failure	SIIOADP OPT_CLN
	LIC could not access part of the HSL I/O bridge VPD. The bridge and HSL loop may be prevented from becoming operational.	
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event viewer you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log (SAL) or serviceable event view on the HMC is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
	NOTE: A fiber optic cleaning kit may be required for optical HSL connections.	
6907	High Speed Link (HSL) I/O bridge failure	SIIOADP
	LIC detected invalid data in the HSL I/O bridge VPD. The bridge and HSL loop may not have become operational.	OPT_CLN
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log (SAL) or serviceable event view on the HMC, is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
	NOTE: A fiber optic cleaning kit may be required for optical HSL connections.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6908	High Speed Link (HSL) I/O bridge failure	SIIOADP OPT_CLN
	LIC data in the I/O bus vpd could not be accessed. The I/O Bus identified in the SRC may not have become operational.	
	If there is a B600 6906 reference code, close this problem in the serviceable event view you are working with and work the 6906 error.	
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log or serviceable event view on the HMC or service processor is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
	NOTE: A fiber optic cleaning kit may be required for optical HSL connections.	
6909	High Speed Link (HSL) I/O bridge failure	SIIOADP
	LIC detected invalid data in the I/O bus VPD. The bus and resources associated with it may not be operational.	OPT_CLN
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log (SAL) or serviceable event viewer on the HMC is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
	If the serviceable event view only indicated a frame or enclosure see the locations section for the frame or enclosure type. The location of the HSL I/O Bridge will be given in the locations tables.	
	NOTE: A fiber optic cleaning kit may be required for optical HSL connections.	
6910	I/O processor failure An I/O processor timed out, returned bad status, or is not following the system bus protocol.	FI00310 FI00318 FI00065 FI00130
	Perform LICIP07.	AJDG301

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6938	Not valid system configuration detected	
	This system model does not allow a configuration of more than three (non-OptiConnect) I/O Processors.	
	Power down the system and remove the extra (non-OptiConnect) I/O Processor(s) so that there are three or less. Restart the system.	
6944	Missing or failed I/O processor cards A system bus appears to be empty. If the bus is not empty, two I/O processors in consecutive slots may be missing or broken. If there are broken I/O processors, then another more serious SRC has occurred. Otherwise find the bus number for this failure from the Product activity	FI00317 FI00316 AJDG301
	log and use the system configuration list to verify the configuration of the I/O processors on that bus.	
6960	Multi-adapter bridge card slot error, do not use card slot	SLOTERR
	Slot unavailable due to 64 bit card in adjacent slot.	
	One of the messages documented with the symbolic FRU will describe the problem. See the SLOTERR symbolic FRU for a list of messages and corrective actions.	
6961	Multi-adapter bridge card slot error, do not use card slot	SLOTERR MASBUS
	LED control failure, do not use slot.	
	The card location is not available for use. The Failing Item with the card slot error is in the Failing Item list for this reference code.	
	See the SLOTERR symbolic FRU for the list of messages and a further description of the problem detected by Licensed Internal Code.	
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log or a serviceable event viewer on the HMC is available for this problem then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6962	Multi-adapter bridge card slot error, do not use card slot	SLOTERR MASBUS
	Power control failure, do not use slot. If there is a Linux partition in the system, any IOPs plugged into slots owned by a Linux partition will not power on. This error will be logged. Correct the situation by removing the IOP cards.	
	The card location is not available for use. The Failing Item with the card slot error is in the Failing Item list for this reference code.	
	See the SLOTERR symbolic FRU for the list of messages and a further description of the problem detected by Licensed Internal Code.	
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log, or serviceable event view on the HMC is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
6963	Multi-adapter bridge card slot error, do not use card slot	SLOTERR
	Power control failure, do not use slot.	MASBUS
	The card location is not available for use. The Failing Item with the card slot error is in the Failing Item list for this reference code.	
	See the SLOTERR symbolic FRU for the list of messages and a further description of the problem detected by Licensed Internal Code.	
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event viewer you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log or serviceable event viewer on the HMC is available then use the failing item list presented there for servicing this reference code.	
	If serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6964	Multi-adapter bridge configuration change or error	MABRCFG
	One of several errors or configuration problems has occurred under a Multi-adapter bridge. If you are using the Service Action Log (SAL), or the serviceable event viewer on the HMC or the service processor, then the correct FRU, description and card position(s) will be listed. Use the FRUs and descriptions in the serviceable event view you are working with to determine the problem.	
	If you do not have access to the Service Action Log, or serviceable event view on the HMC or service processor, then word 4 of the SRC has more information. Examine the last 4 digits in word 4 to determine the problem by comparing them to the list below and using the FRU(s) listed here.	
	<ol> <li>xxxx2022 - IOP found in slots owned by a Linux partition. The Mutli-adapter Bridge and PCI Bridge set that it controls are assigned to a Linux partition. The IOP found in the SLOT indicated by the DSA in word 7 will not be configured.</li> </ol>	
	<ol> <li>xxxx2014 - I/O adapters were found under the Multi-adapter Bridge but there is no IOP to support them. The adapters cannot be used.</li> </ol>	
	<b>3</b> . xxxx2015 - An card type was found that cannot be supported in the card position where it is located.	
	See the MABRCFG symbolic FRU for the list of messages, a further description of the problem detected by Licensed Internal Code and the corrective action.	
6965	Multi-adapter bridge configuration change or error	MABRCFG
	Card type not supported in this slot.	
	An I/O processor or I/O adapter card type is installed in the location indicated in word 7 of the SRC. The card type is not supported in that slot under the Multi-adapter bridge. The card is unavailable.	
	See the MABRCFG symbolic FRU for the list of messages, a further description of the problem detected by Licensed Internal Code and the corrective action.	
6966	Multi-adapter bridge configuration change or error	MABRCFG
	I/O processor removed from multi-adapter bridge card slot.	
	On the previous IPL an I/O processor was in the card location specified in word 7 of the SRC. The I/O processor was not detected on this IPL.	
	See the MABRCFG symbolic FRU for the list of messages, a further description of the problem detected by Licensed Internal Code and the corrective action.	
6967	Multi-adapter bridge configuration change or error	MABRCFG
	I/O adapter unavailable due to moved I/O processor card.	
	The I/O adapter specified in word 7 of the SRC is not available. On the previous IPL there was an I/O processor card the adapter was assigned to. The I/O processor was not detected on this IPL.	
	See the MABRCFG symbolic FRU for the list of messages, a further description of the problem detected by Licensed Internal Code and the corrective action.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6968	Multi-adapter bridge configuration change or error	MABRCFG
	IOA removed from multi-adapter bridge slot.	
	On the previous IPL an I/O adapter was in the card slot specified in word 7 of the SRC. That I/O adapter was not detected on this IPL.	
	See the MABRCFG symbolic FRU for the list of messages, a further description of the problem detected by Licensed Internal Code and the corrective action.	
6969	Multi-adapter bridge configuration change or error	MABRCFG
	I/O adapter replaced by I/O processor card.	
	On the previous IPL there was an I/O adapter in the location specified in word 7 of the SRC. This IPL LIC detected that the IOA was replaced by an IOP in that location.	
	See the MABRCFG symbolic FRU for the list of messages, a further description of the problem detected by Licensed Internal Code and the corrective action.	
696A	Card slot test failed	FI00131
	Perform LICIP14.	BACKPLN
696B	Card slot could not be validated	
	This can be caused by "PCI error injection policy" being set to "YES" and an I/O Processor being installed on the same Multi-adapter bridge domain as the I/O Adapter. Do one of the following:	
	Using the HMC or a customer PC with a Web browser access the Advanced System Management Interface (ASMI) and disable PCI error injection policy.	
	OR	
	Vary off the I/O Adapter. Using Hardware Service manager in SST/DST, locate the I/O Adapter resource. Using concurrent maintenance on the associated packaging resource, remove the I/O Adapter and install it in a location that does not have I/O Processors on the same Multi-adapter bridge domain.	
	OR	
	Vary off the I/O Adapter. Use the concurrent maintenance option in Hardware Service Manager in SST/DST to power off all I/O Processors located on the same Multi-adapter bridge domain as the I/O Adapter. Use concurrent maintenance to power off and power on the I/O Adapter. Then use concurrent maintenance to power on the I/O Processors located on the same Multi-adapter bridge domain as the I/O Adapter.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6970	High Speed Link (HSL) resource failure A system PCI bus failure was detected. Word 7 of the SRC contains the bus	SI_PHB PRI_PCI
	number.	MA_BRDG BRDGSET OPT_CLN
	This failure can occur when a tower in an HSL loop is powered off using concurrent maintenance. If this is the case, close this problem.	OF I_CEN
	This error is most likely in the hardware that makes up the PCI bus, the PCI bus side of the HSL I/O bridge or the multi-adapter bridge. In some cases it may be caused by a failing IOP in the multi-adapter bridge's domain. When an IOP is causing the problem, the failing IOP cannot be identified.	
	NOTE: This SRC can occur for the PCI bus resource on a PCI bus in an I/O expansion unit when the unit is powered off for a concurrent maintenance action.	
	Exchange the failing items, one at a time, in the order they are listed in the serviceable event view or this document until you get to the BRDGSET or BRDGSTx symbolic FRU. If the problem still exists after exchanging the failing items up to, but not including, BRDGSET or BRDGSTx then perform MABIP03 to determine the failing I/O processor card.	
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log, or serviceable event view on the HMC or service processor, is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
	NOTE: A fiber optic cleaning kit may be required for optical HSL connections.	
6971	High Speed Link (HSL) resource failure	MA_BRDG
	Failure in a multi-adapter bridge or on the bus to the card location it controls.	MASBUS PIOCARD
	For this reference code the failing item list presented in the Service Action Log (SAL) or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log (SAL) or serviceable event viewer is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
	Perform MABIP02	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6972	High Speed Link (HSL) resource failure	MA_BRDG
	Multi-adapter Bridge (MaB) failure detected.	
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event viewer you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log (SAL) or serviceable event viewer on the HMC is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event view is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	
6973	High Speed Link (HSL) resource failure	BRDGSET
	Multi-adapter Bridge has detected a problem in the card installed in the location specified in word 7 of the SRC. Use the FRU list in the Service Action Log (SAL), or serviceable event view you are working with. If you are working from this document's FRU list use the Symbolic FRU BRDGSET to determine the failing items.	SIIOADP MA_BRDG
6974	Multi-adapter bridge configuration change or error	MABRCFG
	PCI I/O processor rejected the assignment of or the removal of an I/O adapter.	
	The direct select address in word 7 of the SRC specifies the location of the IOA. The direct select address of the IOP is in word 5 of the SRC.	
	Use the DSA breakdown table and the Card positions table to determine the card locations for the IOA and the IOP.	
	Use slot concurrent maintenance under HSM to assign or remove the IOA.	
6975	The system issued a reset/reload to the service processor	AJDGP01
6976	Service processor error. Service processor failure	SVCPROC
	For this reference code the failing item list presented in the Service Action Log (SAL), or serviceable event view you are working with, can be different from the failing item list documented here. That is due to the differences in system models and features installed.	
	If the Service Action Log (SAL) or a serviceable event viewer on the HMC is available then use the failing item list presented there for servicing this reference code.	
	If a serviceable event viewer is not available then use the failing item list documented here. By following the procedures in the symbolic FRUs listed here you will isolate to the correct FRU list based on system model and features installed.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6980	<ul> <li>Network Interface Controller (NIC) resource failure</li> <li>The FRU list displayed in the Service Action Log (SAL) or serviceable event view you are working with, may vary from the failing item list given in this document. Use the FRU list in the serviceable event view if it is available to you.</li> <li>NOTE: A fiber optic cleaning kit may be required for optical HSL connections.</li> </ul>	SICNTRL OPT_CLN
6981	High Speed Link (HSL) I/O bridge failure         Cycle power on the frame identified as the frame with failed HSL I/O         Bridge prior to replacing FRUs.	SIIOADP OPT_CLN
	The FRU list displayed in the Service Action Log (SAL), or serviceable event view you are using, may vary from the failing item list given in this document. Use the FRU list in the serviceable event view if it is available to you.	
	If you find either a B600 6982 or B600 6984 SRC logged at approximately the same time as this SRC then they were caused by the same failure. If you find a 6982 SRC logged at approximately the same time then close this problem and service the 6982 SRC. The failing item listed for this SRC is one of the failing items listed for B600 6982. If the serviceable event view's entry for this SRC has a location listed then record the location for use in servicing the 6982 SRC.	
	NOTE: This SRC can occur for the HSL I/O Bridge resource in an I/O expansion unit when the unit is powered off for a concurrent maintenance action.	
	NOTE: A fiber optic cleaning kit may be required for optical HSL connections.	
6982	High Speed Link (HSL) connection failure If this SRC is not in the Service Action Log (SAL), or serviceable event view you are using, then it is informational and/or statistical only. It does not require a service action.	HSL_LNK SIIOADP SICNTRL REM_NIC OPT_CLN
	Otherwise: This is a connection failure on an HSL link. Perform RIOIP09 to determine the service action.	
6983	An invalid High Speed Link (HSL) configuration was detected An HSL loop has an invalid configuration. Word 4 of the SRC contains the program return code (PRC) which identifies the problem with the loop's configuration. Use the PRC and the FRU listed to determine the problem.	SIRGCFG
	If you are using the Service Action Log (SAL) or serviceable event view you are working with, the FRU description may already indicate the configuration problem.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6984	High Speed Link (HSL) loop status message	
	An HSL loop has switched to its alternate path. This is an informational SRC only.	
	Word 7 of the SRC contains the loop number in the leftmost 4 digits. The loop number is in hexadecimal format. You must convert the hexadecimal loop number into decimal format to recognize the loop number in HSM.	
	This SRC can be caused by a tower on the HSL loop powering off.	
	This SRC may also appear in the Service Action Log (SAL), or serviceable event viewer you are using, with a B600 6982 or B600 6981 logged at approximately the same time. In that case the other SRC is reporting a failure and this SRC is reporting that the alternate HSL path is now being used. Service the other SRC if present.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6985	High Speed Link (HSL) loop status message	SIRSTAT
	If this SRC is not in the Service Action Log (SAL), or serviceable event view you are using, then it is informational. Use FRU SIRSTAT to determine what this SRC means. Otherwise, continue with the following steps:	HSL_LNK SIIOADP SICNTRL OPT_CLN
	This error can appear as a serviceable event when a tower, or I/O unit or another system in the loop did not complete powering on before LIC on this system checked this loop for errors. Search the Product Activity Log (PAL) for the last B600 6985 SRC logged for this loop and use FRU SIRSTAT to determine if this error requires service. If the last entry indicates the loop is functioning (determined by FRU SIRSTAT) then no service action is required, close this problem	
	There may be multiple B600 6985 logs with xxxx 3205 in word 4 errors for the same loop resource in the serviceable event view. This is caused by retry and recovery attempts. If there is a B600 6985 with xxxx 3206 or xxxx 3208 in word 4 after the above B600 6985 entries in the PAL, then the recovery efforts were successful. If this is the case, close all the B600 6985 entries for that loop resource in the serviceable event view.	
	1. If you find a B600 6981 in the serviceable event view then close that problem and go to step 2. Otherwise perform the following:	
	• Perform RIOIP06 to determine if any other systems are connected to this loop and return here. (HSL_LNK or HSLxxxx FRU in the Service Action Log (SAL) entry, or serviceable event view you are working with, indicates the loop number.) If there are other system(s) then continue with the steps that follow, otherwise go to step 2.	
	• Check for HSL failures on the other system(s) before replacing parts. HSL failures are serviceable event entries with HSL I/O Bridge and Network Interface Controller (NIC) resources. Ignore B600 6982 and B600 6984 entries. If there are HSL failures on other system(s) then continue with the steps that follow, otherwise go to step 2.	
	• Repair the problems on the other systems and return to this step. After making repairs on the other system(s) check the Product Activity Log (PAL) of this system for a B600 6985 logged after the repairs you made on the other system(s). If you find one then continue with the steps that follow, otherwise go to step 2.	
	• For the B600 6985 log you found, use FRU SIRSTAT to determine if the loop is now complete. If the loop is complete then this problem has been resolved. Use RIOIP01 to verify that the loop is now working properly. Otherwise, go to step 2.	
	<ol> <li>Use the serviceable event's FRU list when it is available.</li> <li>If this SRC appears in the Service Action Log (SAL), or the serviceable event view you are using, with the Symbolic FRU HSL_LNK or HSLxxxx listed as a FRU, then perform problem isolation procedure RIOIP01. Otherwise exchange the FRUs listed in the serviceable event view.</li> </ol>	
	NOTE: A fiber optic cleaning kit may be required for optical HSL connections.	

Reference Code	eDescription/Action Perform all actions before exchanging Failing ItemsFSystem bus errorIDuring IPL, system LIC detected an HSL I/O bridge that was already initialized. The bridge should have been in a flushed and unintialized state after powering on. There is a problem with SPCN components that prevented the tower from powering off after a previous power off was issued. The tower will not be configured for this IPL.IThis reference code is equivalent to 1xxx 90F0. When referring to the "CBLALL" symbolic FRU in the Failing Item list, perform the "CBLALL" procedure using reference code "90F0".Word 5 of the SRC identifies the frame. Determine the frame by breaking down word 5:Word 5 -> xxxx xxNN where: NN is the frame number in hexadecimal format.Failing Item 1	
5986		
6987	<ul> <li>High Speed Link (HSL) connection failure</li> <li>Failures are occurring on the HSL link.</li> <li>There may be B600 6982 errors logged on the same loop and about the same time as this error. Close those errors and continue to correct the problem by working this error.</li> <li>If there is a cable FRU in the serviceable event entry: <ol> <li>If the connection is copper and either end has a loose connection, reseat the cable. To do this, disconnect the connection and wait a minimum of 30 seconds. Then reconnect the cable and complete the tightening process in at most 30 seconds. Repeat the process at the other end of the cable. If the error persists, replace the FRUs in the Service Action Log (SAL), or serviceable event view you are using.</li> </ol> </li> <li>If the error persists, replace the FRUs in the Service Action Log (SAL), serviceable event view you are using.</li> <li>If the error persists, replace the FRUs in the Service Action Log (SAL), serviceable event view you are using.</li> <li>If the error persists, replace the FRUs in the Service Action Log (SAL), serviceable event view you are using.</li> </ul>	HSL_LNK OPT_CLN
6990	Service processor failure The FRU list displayed in the Service Action Log (SAL), or serviceable event view you are working with, may vary from the failing item list given in this document. Use the FRU list in the serviceable event view if it is available to you.	SVCPROC
6991 to 6992	Service processor failure	AJDGP01
6993	Service processor failure A failure occurred with the service processor hardware or the service processor LIC. The FRU list displayed in the Service Action Log (SAL), or serviceable event view you are working with, may vary from the failing item list given in this document. Use the FRU list in the serviceable event view if it is	SVCPROC AJDGP01

Reference Code	Description/Action Perform all actions before exchanging Failing Items		
6994	Service processor failure	SVCPROC	
	The FRU list displayed in the Service Action Log (SAL) or serviceable event view you are working with, may vary from the failing item list given in this document. Use the FRU list in the serviceable event view if it is available to you.		
699C	Wrap plug is installed on Bus Expansion Adapter card		
	This reference code is for information only. It indicates the presence of a wrap plug on the local optical link card.		
69A8	Informational bus reference code		
	This reference code is for information only and might include the following:		
	Optical speed encode		
	Broken optical links now operational     Other information		
(0 <b>D</b> 0	Other information	Proof of	
69B8	Bus hardware configuration problem The optical bus cabling is not connected correctly. Perform BUS-PIP1.	FI00187 AJDG301	
69C1	A failure occurred on another system Perform BUS-PIP1.	FI01040 FI00206 FI00182 AJDG301	
69C2	Information only, no service action required. HSL OptiConnect normal connection to another system or partition.		
	This reference code is informational only.		
	HSL OptiConnect has established connection normally. The local system or partition is participating in HSL Opticonnect with other systems or partitions on the same HSL loop.		
69C3	Information only, no service action required. Opticonnect normal remote disconnection from OptiConnect participation.		
	This reference code is informational only.		
	HSL Opticonnect disconnected normally from a remote node. The local system or partition has stopped participating in HSL Opticonnect with the remote system or partition on the same HSL loop. Possible reasons include:		
	• A remote system or partition went off line due to a normal power off or disable of HSL Opticonnect.		
69C5	I/O processor failure The OptiConnect/400 card which connects this system to another system has failed. The failing card is located in an I/O processor card slot. Perform BUS-PIP1.	FI00206 FI01040 AJDG301	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
69C6	Abnormal or unexpected HSL OptiConnect disconnection from a remote system or partition.	REM_SYS
	The local system or partition disconnected from a remote system or partition due to an unexpected event or failure. The problem is most likely with the remote system or partition. Intervention at the remote system is most likely required. Examine both the local and remote HSL OptiConnected systems or partitions for problems on this HSL loop.	
	Possible reasons include: A fatal error in software or hardware in the remote system or partition or a power failure in the remote system.	
	If there was not a complete HSL loop before this error occurred then a failure or power down in an HSL component between the local system or partition and the remote system or partition could have caused this error. Check for a problem with: an HSL cable, HSL I/O bridge or a power problem in an expansion I/O tower or unit on this loop.	
	Examine the Service Action Log (SAL), or serviceable event view you are using on the local system or partition for HSL failures on the same HSL loop at approximately the same time this error occurred.	
	Examine the remote system or partition for problems. If the remote system or partition is powered on and IPL'd then examine the Service Action Log (SAL), or serviceable event view you are using, on the remote system or partition for problems on the same HSL loop at approximately the same time this error occurred.	
	Correct any problems you find with the remote and local systems or partitions that happened at approximately the same time and involve HSL Opticonnect or HSL loop components or Network Interface Controllers. When the remote system is IPL'd it will automatically reconnect with this system or partition.	
	If there are no problems with the remote system or partition and there are no problems with the local system or partition then collect all the Product Activity Log information for this failure on both systems. Be sure to record all words in the SRC. Contact your next level of support.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
69C7	Abnormal or unexpected HSL OptiConnect disconnection from a remote system or partition.	REM_SYS LOC_SYS
	The local system or partition disconnected from a remote system or partition due to an unexpected event or failure. LIC will attempt to recover from the error. Intervention at the local or remote system or partition may be required.	
	Possible causes are: time out, hang or hardware failure. The problem may be with: the local system or partition or the remote system or partition.	
	If there was not a complete HSL loop before this error then a failure or power down in an HSL component between the local system or partition and the remote system or partition could have caused this error. Check for SRCs with FRUs like: HSL cables, HSL I/O bridge or a power problem in an expansion I/O tower or unit on this loop.	
	Examine the SAL or serviceable event view you are working with on the local system or partition for failures on the same loop, or with the Network Interface Controller at approximately the same time.	
	Examine the remote system or partition for problems. Correct any HSL or NIC problems you find with the remote and local systems or partitions.	
	If there are no problems with the remote system or partition and there are no problems with the local system or partition then collect all the Product Activity Log (PAL) information for this failure on both systems. Be sure to record all words in the SRC. Contact your next level of support.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
69C8	Abnormal or unexpected HSL OptiConnect disconnection from a remote system or partition. The local system or partition disconnected from a remote system or	REM_SYS LOC_SYS AJDG301
	partition due to an unexpected event or failure. All of the HSL OptiConnect connections on this loop will be in a failed state. LIC will attempt to recover from the error. Intervention at the local or remote system or partition may be required. Possible causes are:	
	<ul> <li>time out of a critical message</li> <li>LIC code ( table problem)</li> </ul>	
	<ul><li>LIC code / table problem</li><li>Network deadlock detected</li></ul>	
	The problem may be with:	
	The local system or partition	
	The remote system or partition	
	Examine the Service Action Log (SAL), or serviceable event view you are using, on the local system or partition for HSL failures on the same HSL loop, or with the Network Interface Controller at approximately the same time this error occurred.	
	Examine the remote system or partition for problems. Examine the Service Action Log (SAL), or serviceable event view you are using, on the remote system or partition for problems on the same HSL loop or with the Network Interface Controller at approximately the same time this error occurred.	
	Correct any problems you find with the remote and local systems or partitions that happened at approximately the same time and involve HSL Opticonnect or HSL loop components or Network Interface Controllers.	
	If there are no problems with the remote system or partition and there are no problems with the local system or partition then collect all the Product Activity Log information for this failure on all systems or partitions. Be sure to record all words in the SRCs. Contact your next level of support.	
69C9	Abnormal or unexpected HSL OptiConnect disconnection from a remote system or partition.	AJDG301 REM_SYS
	The local system or partition disconnected from a remote system or partition due to an failure in a LIC virtualized bus unit. LIC will attempt to recover from the error. Possible causes are:	LOC_SYS
	<ul><li> LIC problem where the local bus unit is off line.</li><li> LIC problem where the remote bus unit is off line.</li></ul>	
	Examine the Service Action Log (SAL), or serviceable event view you are using, on the local system or partition for HSL Opticonnect failures that occurred at approximately the same time this error occurred.	
	Examine the remote system or partition for problems. Examine the Service Action Log (SAL), or the serviceable event view you are using, on the remote system or partition for HSL Opticonnect problems that occurred at approximately the same time this error occurred.	
	Collect all the Product Activity Log information for this failure on all systems and partitions on this HSL loop. Be sure to record all words in the SRCs. Contact your next level of support with the information you have collected.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items Failing Item	
69CF	Abnormal or unexpected HSL OptiConnect disconnection from a remote system or partition.	AJDG301
	LIC internal error. All systems participating in HSL OptiConnect will be disconnected. The system must be re-IPL'd to recover. Before re-IPL'ing the system initiate a main store dump.	
	After getting the dump, examine the Service Action Log (SAL), or serviceable event view you are using, on the local system or partition for HSL Opticonnect failures that occurred at approximately the same time this error occurred.	
	Examine the remote systems or partitions for problems. Examine the Service Action Log (SAL), or serviceable event view you are using, on the remote systems or partitions for HSL Opticonnect problems that occurred at approximately the same time this error occurred.	
	Collect all the Product Activity Log information for this failure on all systems and partitions on this HSL loop. Be sure to record all words in the SRCs. Contact your next level of support with the information you have collected.	
69D0	Bus Expansion Adapter card failed An internal error was detected on a local optical link card. Perform BUS-PIP1.	FI00182 FI00055 AJDG301
69D8	Bus Expansion Adapter failed A primary optical link had a failure. Contact with the bus may still be possible through this link or through a redundant link. Perform BUS-PIP1. If a Service Action Log entry is available for this error, use the failing item list presented there for servicing this reference code.	FI00182 FI00203 FI00055 LBUSADP AJDG301
69D9	Host Ethernet Adapter (HEA) failure	HEA
	Firmware detected a hardware failure in the Host Ethernet Adapter (HEA).	
69DA	System log entry only, no service action required	
69DB	LIC failure	SVCDOCS
	A Licensed Internal Code error occurred. The partition will continue to run with this Host Ethernet Adapter (HEA) disabled. Perform a partition dump and then IPL the partition to recover the HEA. Send the partition dump to your next level of support.	
69DC	The HEA is not connected to the Ethernet switch	
	The Host Ethernet Adapter (HEA) is not connected to the Ethernet switch. If the HEA connection is not needed, no service action is required.	
	If the HEA connection is needed, verify that the cable is connected and the switch is powered on. After repairing the problem, verify that the connection has been restored.	
69DD	The HEA connection to the Ethernet switch has been restored	
	System log entry only, no service action required.	
69DE	HEA Media Interface Adapter Failure	HEA
	Firmware detected a failure in the HEA Media Interface Adapter.	AJDG301
69E0	Bus Expansion Adapter card failed	FI00203 AJDG301
	An internal error was detected on a remote bus adapter card. Perform BUS-PIP1.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items Failing Item		
69E8	Bus Expansion Adapter failed Redundancy has been lost due to a secondary optical link failure. Contact with the bus may still be possible through the primary optical link. Perform BUS-PIP1.FI00203 FI00205 FI00057 AJDG301		
69F0	Bus Expansion Adapter failed Contact has been lost to the bus. Perform BUS-PIP1. F100182 F100203 F100205 LBUSADF AJDG301		
69F8	Bus Expansion Adapter failed An optical link initialization failure occurred. The number and configuration of the system buses can not be determined. Perform BUS-PIP1.	FI00180 FI00203 FI00182 FI00186 FI00057 AJDG301	
7001	ISDN call in rejected	GG4COMM	
7002	Lines not selected	GG4COMM	
7003	Network interfaces not selected	GG4COMM	
	This reference code is logged when the TCP/IP Attribute "Log Protocol Errors" is set, and the TCP/IP System LIC "silently discards" an inbound datagram. "Silently discard" is defined to mean discard the received datagram without reporting an error to the originating host device. Examples of such datagrams are those with checksums or destination addresses which are not valid. This reference code is for information only. Normally no action should be taken as a result of this reference code. It is generated in order to assist with remote device or TCP/IP network problem determination.		
7055	Statistics were logged, no service action required This reference code is logged for information only.		
7100	<ul> <li>APPN session initiation attempt has timed out</li> <li>This reference code is used to indicate that LIC timed out on a request to initiate a session.</li> <li>The user must run problem analysis for this reference code. If this indicates a software problem, the user should dial IBM Software Support for assistance.</li> <li>The Problem Determination Procedure (PDP) will indicate whether the</li> </ul>	AJDG301 GG4PL03 GG4PL01 GG4PL02	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item	
7101	APPN session initiation attempt has failed	GG4PL04 GG4PL05	
	This reference code is used to indicate that LIC attempted to satisfy a session initiation request, but some failure condition was detected by LIC. The failure condition could be a configuration or operational problem in the network.	GG4PL06 AJDG301	
	The user must run problem analysis for this reference code. If this indicates a software problem, the user should dial IBM Software Support for assistance.		
	The Problem Determination Procedure (PDP) will indicate whether the original timeout condition still exists and what the corrective actions should be.		
7102	APPN CP-CP session ended.		
7201	A utility failure occurred.		
	This reference code is for information only. The Uninterruptible Power System (UPS) is reporting a utility failure.		
7202	Utility power restored.		
	This reference code is for information only. The Uninterruptible Power System (UPS) is reporting that utility power has been restored.		
7203	A battery low condition was detected.		
	This reference code is for information only. The Uninterruptible Power System (UPS) is reporting a battery low condition.		
7204	Uninterruptible Power System reported a bypass active		
	This reference code is for information only. The Uninterruptible Power System (UPS) is reporting a bypass is active.		
7205	Battery low condition was reset.		
	This reference code is for information only. The Uninterruptible Power System (UPS) is no longer reporting a battery low condition.		
7206	UPS reported bypass no longer active		
	This reference code is for information only. The Uninterruptible Power System (UPS) is no longer reporting a bypass active condition.		
7207	Battery Power Unit needs service	FI00315	
	The replacement period for BPU 1, installed in the System Unit, has been exceeded.		
7208	Battery Power Unit needs service	FI00315	
	The replacement period for BPU 2, installed in the System Unit, has been exceeded.		
7209	Battery Power Unit needs service	FI00315	
	The replacement period for BPU 1, installed in the Expansion Unit, has been exceeded.		
720A	Battery Power Unit replacement dates do not match		
	The replacement dates for one of the Battery Power Units do not match. Run "Display Hardware Configuration" and verify that the dates match the labels on the batteries.		

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7701	SCSI jumper card was not detected.     21H7625       BACKPLN	
7702	Incorrect SCSI jumper card detected	21H7625
7703	System LIC detected a program exception	
	Storage Management detected a DASD datacheck condition and the defective sector was reallocated.	
	Perform a system IPL to restart the system.	
7704	General failure detected by HRI component.	AJDG301
7777	Hardware configuration change detected	
	A hardware resource is missing. The resource reported in to the system on a previous IPL, but has not reported in on the current IPL. This could occur for several different reasons.	
	1. It could be a normal situation where the resource is currently powered off. In this case, when the resource is powered back on, it will no longer be missing.	
	2. The hardware resource could also be missing if it has been removed from the system, for example, a tape drive that was replaced with a different tape drive. The service representative should use the Hardware service manager to remove the entry for this resource.	
	<b>3</b> . The resource may not have reported in on this IPL because it is failing. Perform problem analysis to determine why the resource is failing.	
8000	An external storage subsystem disk unit connection failed	
	Look for other errors in the Service Action Log (SAL), or serviceable event view you are working with, and fix them.	
8001	An external storage subsystem disk unit connection failed	
	Look for other errors in the Service Action Log, or serviceable event view you are working with, and fix them.	
8002	Maximum number of redundant connections exceeded	
	An attempt to activate a connection from another I/O adapter to an external storage subsystem disk unit failed because the maximum number of connections are already active for this disk unit. No action required.	
8003	External storage subsystem disk unit connection was restored	
	No action required.	
8004	An external storage subsystem disk unit connection failed	
	Could not read configuration information from the disk unit. Look for other errors in the Service Action Log, or serviceable event view you are working with, and fix them.	
8005	High performance connection failed	
	A high performance connection to an external storage subsystem disk unit failed.	
	There are still two or more external storage subsystem disk unit connections, but performance might be degraded.	
	Look for other errors in the Service Action Log, or serviceable event view you are working with, and fix them.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
8006	High performance connection failed	
	A high performance connection to an external storage subsystem disk unit failed.	
	There is still one more external storage subsystem disk unit connection, but performance might be degraded.	
	Look for other errors in the Service Action Log, or serviceable event view you are working with, and fix them.	
8007	High performance connection was restored	
	A high performance connection to an external storage subsystem disk unit was restored.	
	Performance is no longer degraded.	
	No action required.	
CF00	Permanent error on optical device.	SVCDOCS
	A type D IPL terminated because of an optical load source device failure. If the optical load source is an external optical device, check the cables. If that does not correct the problem, replace the optical device. If the optical load source is an internal optical device, replace the optical device. If the optical load source is a virtual device, ensure it is set up correctly.	
CFFC	Optical library device condition not expected	OPTLCBL
	The optical disk drive addressing within the optical library is incorrect. This error is likely to be the result of faulty cabling or switch setting following service to an optical library.	DRVSWCH
	Contact your hardware service provider.	
CFFD	Optical drive failure	OPTLDRV
CFFF	Media determined to be bad in Optical library	
F103	Main storage dump must be copied for service. Perform LICIP01.	
F104	Logical partition service function Main Storage Dump.	
	The hypervisor terminated a partition with an unresponsive Operating System. A Main Store Dump must be done for service. Call your next level of support when the dump is complete.	
	Perform LICIP01.	
F105	Licensed Internal Code detected error	NEXTLVL
FDC0	LIC program reported informational error	
	This reference code is logged for information only. No action required.	
FDC5	LIC program failed and data was captured	GG4FFDC
	This reference code indicates first failure data capture (FFDC) data was collected for a problem reported by licensed internal code.	
	The user should dial IBM Software Support for assistance.	

#### Table 3. Licensed Internal Code failing items details

Failing Item	Description	Document Description
21H7625	Incorrect, defective or missing SCSI jumper card	Repair and Parts; removal and installation procedures
AJDG301	Licensed Internal Code	Service Functions; APAR or LICTR
AJDGP01	Service Processor LIC	Repair and Parts; removal and installation procedures
AJGLD01	I/O card Licensed Internal Code	Service Functions; APAR or LICTR
BACKPLN	Card enclosure or backplane	See the service documentation for instructions.
BRDGSET	PCI Bridge set, Multi-adapter bridge domain cards	See the service documentation for instructions.
BSTWRPL	FC 9074, FC 9079 Base I/O tower card with service processor	See the service documentation for instructions.
CBLALL	SPCN cable to HSL connected I/O tower	See the service documentation for instructions.
CTLPNCD	System Unit Control Panel Card Assembly	See the service documentation for instructions.
CVTCARD	HSL (SI) I/O Adapter for FC 5076 SPD migrated tower	See the service documentation for instructions.
DEVTERM	Terminating plug	See the service documentation for instructions.
DISKDRV	Disk Drive and Logic Card	See the service documentation for instructions.
DISKTRY	Disk unit tray	See the service documentation for instructions.
DRVSWCH	Drive address switch	See the service documentation for instructions.
GG4COMM	Communications failure	
GG4FFDC	LIC program failed and data was captured	
GG4PL01	System performance problem	
GG4PL02	Network performance problem	
GG4PL03	Switched link activation failure message not answered	
GG4PL04	Transmission groups in the network must be activated	
GG4PL05	Class-of-service specified does not provide a route	
GG4PL06	COS acceptable TGs and nodes do not exist for the route	
HEA	Host Ethernet Adapter	See the service documentation for instructions.
HSL_LNK	HSL (SI) cable or connection or interposer	See the service documentation for instructions.
LBUSADP	SPD local bus adapter, where optical daughters plug	See the service documentation for instructions.
LOC_SYS	Local HSL Opticonnect system or partition.	Local HSL OptiConnect system
LPARCFG	"LPARCFG" LPAR configuration - processors, memory or ld src	See the service documentation for instructions.
LPARSUP	"LPARSUP" LPAR complex problem, call next level of support.	See the service documentation for instructions.
MABRCFG	Multi-adapter bridge configuration error or change	See the service documentation for instructions.
MASBUS	Multi-adapter bridge secondary bus or card slot	See the service documentation for instructions.
MA_BRDG	Multi-adapter bridge high level symbolic	See the service documentation for instructions.
NEXTLVL	Call your next level of support for assistance	Rio PIP 55

Failing Item	Description	Document Description
OPTDRIV	Optical Disk Drive	See the service documentation for instructions.
OPTLCBL	Optical Library drive cabling	See the service documentation for instructions.
OPTLDRV	Optical Library optical drive	See the service documentation for instructions.
OPT_CLN	Fiber optic cleaning kit	Fiber optic cleaning kit
PIOCARD	PCI nodes adapter card, IOP or IOA	See the service documentation for instructions.
PLDUMP	Platform dump occurred	See the service documentation for instructions.
PPCIMIN	Primary PCI bus in 5075 I/O tower	See the service documentation for instructions.
PPCISYS	Primary PCI bus in a system unit	See the service documentation for instructions.
PPCITWR	Primary PCI bus in a 5074 I/O tower	See the service documentation for instructions.
PRI_PCI	Primary system PCI bus to a MaB, high level symbolic	See the service documentation for instructions.
REM_NIC	A remote NIC in a cluster.	
REM_SYS	HSL opticonnect remote system or partition.	Remote HSL OptiConnect system
SIADPCD	High Speed Link (SI) I/O adapter card in FC 5074 I/O tower	See the service documentation for instructions.
SICNTRL	HSL (SI) controller, high level symbolic	See the service documentation for instructions.
SIIOADP	High Speed Link (SI) I/O adapter, high level symbolic	See the service documentation for instructions.
SIRGCFG	SI ring invalid configuration	See the service documentation for instructions.
SIRSTAT	System Interconect ring status	See the service documentation for instructions.
SI_CARD	HSL (SI) controller card on a system unit	See the service documentation for instructions.
SI_PHB	PCI host bridge adapter, high level symbolic	See the service documentation for instructions.
SLOTERR	Multi-adapter bridge slot error	See the service documentation for instructions.
SPNLCRD	SPCN panel card	See the service documentation for instructions.
STORIOA	Active I/O processor	See the service documentation for instructions.
SVCDOCS	Equipment failure; not isolated	Service Functions; APAR or LICTR
SVCDOCS	Customer engineer directed to system problem analysis	See the service documentation for instructions.
SVCPROC	Service Processor	See the service documentation for instructions.
SYSBKPL	System unit backplane	See the service documentation for instructions.
TWRBKPL	FC 5075 I/O tower backplane	See the service documentation for instructions.
TWRCARD	SPCN failing component in HSL I/O tower	See the service documentation for instructions.
TWRPLNR	FC 5074, FC 9074, FC 9079 I/O tower PCI card planar	See the service documentation for instructions.
UG4USR1	Operator response required	

# (A9xx, B9xx) Reference codes

For use by authorized service providers.

The A9xx and B9xx SRCs and their associated unit reference codes give information about the user program.

1. Refer the user to Analyze and handle problems. For additional help, the user should contact their next level of support.

Note: A brief description of some of the C9xx codes can be found in iSeries<sup>™</sup> Service Functions <sup>™</sup> (see "IPL Status SRC Sequence" under "Initial Program Load Information").

2. If a Licensed Internal Code error is suspected and the recovery action recommends an IPL, then take a main storage dump to save the error conditions (see "Working with Storage Dumps" in iSeries Service

Functions) *before* the user performs an IPL. Support personnel might need the information saved in this dump.

3. Have the user continue with the recommended recovery action.

### (B003) Asynchronous communications reference codes

For use by authorized service providers.

The Asynchronous Communications detected a failure.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Asynchronous Communications Failing Items Details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
2321	Procedure error in Licensed Internal Code	UJE34
2322	Data-set-ready error on modem interface	UJE34
2340	Data-set-ready changed to not active; for information only	FI00704 CNGTHRS FI00701 FI00719
3200	Clear-to-send state changed; error limit per 256 reached	FI00704 CNGTHRS FI00701 FI00719
3201	Data-set-ready state changed; error limit per 256 reached	FI00704 CNGTHRS FI00701 FI00719
3202	Clear-to-send state changed; error limit per 256 reached	FI00704 CNGTHRS FI00701 FI00719
3203	Carrier-detect state changed; error limit per 256 reached	FI00704 CNGTHRS FI00701 FI00719
3204	Call not completed; error limit per 256 reached	UJC36 GNGLINK FI00705 FI00703
3205	Call completed with error; error limit per 256 reached	CNGTHRS

Table 1. (B003) Asynchronous communications reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
3206	Data-line-occupied error; error limit per 256 reached	FI00703 CNGTHRS GNGLINK FI00702
3207	Abandon-call-retry error; error limit per 256 reached	FI00703 CNGTHRS GNGLINK FI00702 UJC36
3208	Present-next-digit error; error limit per 256 reached	FI00703 CNGTHRS FI00702 FI00719
3209	Distant-station-connected error; error limit per 256 reached	FI00703 CNGTHRS GNGLINK FI00702 UJC36
320B	Data-set-ready state changed; error limit per 256 reached	FI00704 CNGTHRS FI00701 FI00719
320C	Incorrect number dialed; error limit per 256 reached	UJC36 CNGTHRS
4200	Break character received; error limit per 256 reached	GNGLINK CNGTHRS
4202	Received storage overrun; error limit per 256 reached	FI00730 CNGTHRS
4203	Incorrect stop bit; error limit per 256 reached	GNGLINK CNGLBPS CNGTHRS
4204	Receive-time-out error; error limit per 256 reached	CNGTHRS GNGLINK
4205	Number of characters discarded; error limit per 256 reached	GNGLINK CNGLBPS UJB37 CNGTHRS
4206	Procedure error in Licensed Internal Code	FI00730 AJDG301
4209	Wrong data received; error limit per 256 reached	GNGLINK CNGTHRS
4220	Port already in use	AJDG301 FI00719 CNGSLPT
4240	Port not installed	AJDG301 FI00719 CNGSLPT
4340	Automatic call unit port is not installed	AJDG301 UJC35 FI00719 FI00702

### B003

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4376	Automatic call unit already in use	AJDG301 GNGRESC UJC35
4502	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
4503	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730 UJC35
4504	Wrong configuration value sent by Licensed Internal Code	AJDG301 UJC35 CNGSLPT
4505 to 4506	Wrong configuration value sent by Licensed Internal Code	AJDG301 UJC35 FI00730 CNGSLPT
4507	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730 UJC35
4508	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
4509	Wrong configuration value sent by Licensed Internal Code	AJDG301 UJC35 FI00730
450A	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730 UJC35
450B to 450C	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
450D	Wrong configuration value sent by Licensed Internal Code	UJC35 CNGBCHR FI00730 AJDG301
450E	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730 CNGMCFL
4549	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
4590	Wrong number specified in controller description	UJC36 FI00703 FI00701 UJC35 FI00719
4592	No number specified in controller description	AJDG301 UJC36
4594	Wrong number specified in controller description	UJC36 FI00730 AJDG301 UJC35
5410	Switched line already in use	FI00704 UJC35 FI00701 FI00719

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5472	Data-line-occupied error at time of starting	FI00703 GNGRESC FI00719 FI00702
5474	Automatic call unit line connection error	FI00702 FI00703 FI00719 GNGLINK
5476	Present-next-digit error	FI00702 FI00703 FI00719
5501	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
5502 to 5503, 5510	Wrong configuration value sent by Licensed Internal Code	AJDG301 UJC35 FI00730
5511 to 5512	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
5513	Wrong configuration value sent by Licensed Internal Code	AJDG301 UJC35 FI00730
5514	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
5515	Wrong configuration value sent by Licensed Internal Code	AJDG301 UJC35 FI00730
5549	Wrong configuration value sent by Licensed Internal Code	AJDG301 FI00730
5590	Wrong length for number dialed	AJDG301
5630	Automatic call unit distant-station-connected time out	FI00700 GNGLINK UJC35 FI00701 FI00719
5632	Automatic call unit had data-set-ready time out	FI00700 UJC36 FI00703 CNGDRTY UJC35 FI00701 FI00719 GNGLINK
5684	Time-out on call-clear-request	FI00704 FI00701 AJDG301 FI00719
5886	Automatic call unit line connection error	FI00704 FI00719 FI00701
5A18	Clear-to-send signal failed to drop on modem interface	FI00704 FI00701 FI00719

### B003

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5A1C	Clear-to-send signal dropped on modem interface	GNGLINK UJC35 FI00704 FI00701 FI00719
5A20	Clear-to-send not active on modem interface	GNGLINK UJC35 FI00704 FI00701 FI00719
5A24	Carrier-detect dropped on modem interface	FI00701 FI00704 GNGLINK FI00719
5A54	Time-out; data-set-ready did not drop	FI00704 UJC35 FI00701 FI00719
5A58	Time-out; data-set-ready not received	FI00701 FI00704 FI00719 AJDG301
5C68	Procedure error in Licensed Internal Code	AJDG301 FI00730
5E00	Wrong or no external communications cable installed	FI00701 UJC35 CNGSLPT FI00719
5E01	Call received during dialing procedure	GNGRESC FI00704 FI00701 FI00719
6210	Resource or storage not available	CNGMAXI FI00730
6212, 6214	Communications controller error	FI00730 FI00718
6288	Port not operational	FI00719 AJDG301 CNGSLPT
6320	Abandon-call-retry	FI00700 UJC36 FI00703 FI00719 FI00702
6322	Abandon-call-retry; not all numbers dialed	UJC36 FI00703 FI00702 FI00719 FI00730
6870	Automatic call unit power turned off	FI00703 FI00702 FI00719

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6890	Data-set-ready dropped on modem interface No action is required if Operations Console is attached.	GNGLINK FI00701 FI00704 FI00719
6C05	I/O card Licensed Internal Code error	FI00730 AJDG301
6C0A	Hardware detected failure	FI00719 FI00718
7200	Communications Configuration	CNGSLPT
7210	Resource or storage not available	CNGMAXI FI00730
7212	Procedure error in Licensed Internal Code	AJDG301 FI00730
7C00	Asynchronous server program ended abnormally	FI00730
7C02	Wrong command sent by Licensed Internal Code	FI00730
7C03	Resource or storage not available	UJB37 F100730 UJC35 UJC35 UJC35 UJC35 UJC35
7C04	Wrong internal routing information	FI00730
7C05, 7C09	Error in I/O card Licensed Internal Code	FI00730
8011	IOP activation failed. The MDMCNTRYID parameter in Network Attributes is not set. Use the CHGNETA command to set MDMCNTRYID value.	CNGCONF
8013	IOP activation failed. The MDMCNTRYID parameter in Network Attributes is not valid for this adapter. Use the CHGNETA command to change MDMCNTRYID.	CNGCONF
8020	System log entry only, no service action required	
FFFF	User suspected communications problem.	UNGUPPR

#### Table 2. Asynchronous communications failing items details

Failing Item	Description	Document Description
21F4325	Locally attached external cable	System Problem Analysis information
21F4333	Locally attached external cable	System Problem Analysis information
21F9345	Communications two-port adapter cable	Cable Attachment
24F8549	Multifunction I/O processor storage expansion	Repair and Parts; removal and installation procedures
AJDG301	Licensed Internal Code	Service Functions; APAR or LICTR
CNGBCHR	BITSCHAR value in CRTLINASC command	Communications Configuration
CNGCATL	THRESHOLD value in CRTLINASC command	Communications Configuration
CNGCCEL	THRESHOLD value in CRTLINASC command	Communications Configuration
CNGCONF	Configuration or OS/400 licensed program	Communications Configuration

Failing Item	Description	Document Description
CNGDRTY	DIALRTY value in CRTCTLASC command	Communications Configuration
CNGLBPS	LINESPEED, BITSCHAR, PARITY, STOPBITS values in CRTLINASC	Communications Configuration
CNGMAXI	MAXBUFFER value in CRTLINASC command	Communications Configuration
CNGMCFL	DUPLEX, CNN, MODEMRATE values in CRTLINASC command	Communications Configuration
CNGSLPT	RSRCNAME value in CRTLINASC command	Communications Configuration
CNGTHRS	THRESHOLD value in CRTLINASC command	Communications Configuration
GNGALDC	Any adapter card attached to this I/O processor card	
GNGIOAB	System unit or I/O card enclosure	
GNGLINK	External devices or network	
GNGLNKI	Line, modems, remote equipment	
GNGLNKM	Line, modems, remote equipment	
GNGLNKR	Remote computer and data communications equipment	
GNGLNKT	Remote computer and data communications equipment	
GNGOTHR	Another adapter card on the same IOP to IOA Bus	
GNGRESC	Line or automatic call unit already in use	
GNGTP	Communications line	
UJB37	System processor workload heavy	Communications Configuration
UJC35	ACRSRCNAME value in CRTLINASC command	Communications Configuration
UJC35	CTSTMR value in CRTLINASC command	Communications Configuration
UJC35	CALLNBR value in CRTLINASC command	Communications Configuration
UJC35	DSRDRPTMR value in the CRTLINASC command	Communications Configuration
UJC35	LINESPEED value in CRTLINASC command	Communications Configuration
UJC35	STOPBITS value in CRTLINASC command	Communications Configuration
UJC35	DUPLEX, ECHO, FLOWCNTL value in CRTLINASC command	Communications Configuration
UJC35	AUTOANS, AUTODIAL, DIALCMD, SWTCNN, CNN in CRTLINASC	Communications Configuration
UJC35	PARITY value in CRTLINASC command	Communications Configuration
UJC35	CNN value in CRTLINASC command	Communications Configuration
UJC35	ECHO value in CRTLINASC command	Communications Configuration
UJC35	EORTBL value in CRTLINASC command	Communications Configuration
UJC35	FLOWCNTL value in CRTLINASC command	Communications Configuration
UJC35	RMTANSTMR value in CRTLINASC command	Communications Configuration
UJC36	CNNNBR value in CRTCTLASC command	Communications Configuration
UJE34	No failure found	Communications Configuration
UNGUPPR	User suspected communications problem.	

# (B006) Common Licensed Internal Code reference codes

For use by authorized service providers.

The common Licensed Internal Code detected a failure.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Common Licensed Internal Code failing items details, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1201	I/O processor resource not available A deactivation failed to get a resource controlled by Licensed Internal Code.	AJEQU00 AJDG301
1202	Not valid condition in I/O Processor Licensed Internal Code         An error in an activation or deactivation occurred.	AJEQU00 AJDG301 FI00131
1203	I/O processor resource not available A resource needed to perform a requested function is not available in the Licensed Internal Code.	AJEQU00 AJDG301
1204	Not valid condition in I/O Processor Licensed Internal Code         The Licensed Internal Code has recovered from a condition that was not expected.	AJEQU00 AJDG301 FI00131
1205 to 1206	I/O processor card or Licensed Internal Code error A microprocessor exception occurred on the I/O processor.	AJEQU00 FI00131 FI00132
1207	I/O processor resource not available The Licensed Internal Code could not allocate memory resources on the I/O processor card.	AJEQU00 AJDG301
1208	Not valid condition in I/O Processor Licensed Internal Code         The Licensed Internal Code found a condition that should not have occurred.	AJEQU00 AJDG301 FI00131
1209	I/O processor was not ready for interrupt that occurred	AJEQU00 FI00131
1210	I/O processor resource not available The I/O processor error log is being filled faster than the errors are being reported to the system. Check other errors reported to the system and correct them.	
1211	System bus error	FI00131 ANYBUS AJEQU00 AJDG301

Table 1. (B006) Common Licensed Internal Code reference codes

#### B006

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1212	A permanent I/O processor failure occurred	FI00131 AJEQU00
1213	System bus error	AJDG301 AJEQU00 FI00131
1214 to 1215	I/O processor card or Licensed Internal Code error	FI00131 AJEQU00
1301	I/O processor resource not available An activation or deactivation failed to get a resource controlled by Licensed Internal Code.	CDAWKLD AJDGP01 AJDG301
1302	Not valid condition in I/O Processor Licensed Internal Code An error in an activation or deactivation occurred.	AJDGP01 AJDG301 FI00131 FI00132
1303	I/O processor resource not available A resource needed to perform a requested function is not available in the Licensed Internal Code.	IOACNFG AJDGP01 AJDG301
1304	Not valid condition in I/O Processor Licensed Internal Code The Licensed Internal Code has recovered from an unexpected condition.	AJDGP01 AJDG301 FI00131 FI00132
1305 to 1306	I/O processor card or Licensed Internal Code error A microprocessor exception occurred on the I/O processor.	AJDGP01 FI00131 FI00132 BACKPLN
1307	I/O processor resource not available The Licensed Internal Code could not allocate memory resources on the I/O processor card.	AJDGP01 AJDG301 IOACNFG FI00132
1308	Not valid condition in I/O Processor Licensed Internal Code         The Licensed Internal Code found a condition that should not have occurred.	AJDGP01 AJDG301 FI00131
1309	I/O processor was not ready for interrupt that occurred	AJDGP01 FI00131 FI00132 FI01117
1310	I/O processor resource not available The I/O processor error log is being filled faster than the errors are being reported to the system. Check other errors reported to the system and correct them.	
1311	System bus error	FI00131 ANYBUS AJDGP01 AJDG301
1312	A permanent I/O processor failure occurred	FI00131 AJDGP01
1313	System bus error	AJDG301 AJDGP01 FI00131

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1316	I/O processor card or Licensed Internal Code error	AJDGP01 FI00132 FI00131
1317	<ul><li>I/O processor card error</li><li>Display the Service Action Log entry for this SRC. If the Failing Item indicates IOP, then replace the IOP. If the Failing Item indicates SVCDOCS, then do NOT replace the IOP. This is a recoverable error. Perform the following:</li></ul>	SVCDOCS
	following: 1. If the I/O Processor is not operable and disk units are attached, use Hardware Service Manager to re-IPL the IOP. Other resources attached to the IOP may then need to be Varied On.	
	2. If disk units are not attached, perform the VRYCFG RESET(*YES) command to reset the IOP and Vary On attached resources.	
1318	I/O processor card error	FI00131
1403	Service processor Licensed Internal Code error A resource needed to perform a requested function is not available in the	AJDGP01 SVCPROC
	Licensed Internal Code.	
1404	Service processor Licensed Internal Code error	AJDGP01 SVCPROC
	The Licensed Internal Code has recovered from an unexpected condition.	
1405	Service processor Licensed Internal Code error A recoverable microcode condition occurred on the Service processor.	AJDGP01 SVCPROC
1406	Service processor Licensed Internal Code failed	AJDGP01
1100	A microprocessor exception occurred on the Service processor.	SVCPROC AJDG301
1407	Service processor Licensed Internal Code failed	AJDGP01
	The Licensed Internal Code could not allocate resources on the Service processor.	SVCPROC AJDG301
1408	Service processor Licensed Internal Code failed	AJDGP01 AJDG301 SVCPROC
1409	Service processor Licensed Internal Code failed The Service processor was not ready for an interrupt that occurred.	AJDGP01 SVCPROC
1A01	I/O processor resource not available	CDAWKLD
	A deactivation failed to get a resource controlled by Licensed Internal Code.	FI00130 AJDG301
1A02	Not valid condition in I/O Processor Licensed Internal Code	FI00130 FI00131
	An error in an activation or deactivation occurred.	FI00132
1A03	I/O processor resource not available A resource that is needed to perform a requested function is not available in the Licensed Internal Code.	FI00130 AJDG301 CDAWKLD
1A04	Recovered from condition in Licensed Internal Code.	FI00130
1704	The Licensed Internal Code has recovered from a condition that was not expected.	AJDG301 FI00131 FI00132

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1A05 to 1A06	I/O processor card or Licensed Internal Code error A microprocessor exception occurred on the I/O processor.	FI00130 FI00131 FI00132
1A07	I/O processor resource not available The Licensed Internal Code could not allocate memory resources on the I/O processor card.	CDAWKLD FI00132 FI00130 AJDG301
1A08	Not valid condition in I/O Processor Licensed Internal Code The Licensed Internal Code found a condition that should not have occurred.	FI00130 FI00131 FI00132
1A09	Threshold overflow The I/O processor card has detected a threshold of recoverable error conditions. The errors are either wrong interruptions or memory error corrections. If in communications, the line is still running. <b>Note:</b> If a large number of these errors occur during a short time, they may be caused by an electrically noisy environment, a defective communications I/O processor card or modem, or a communications I/O processor code problem.	FI00131 FI00132 FI01117 FI00130
1A10	Error reported to system The I/O processor error log is being filled faster than the errors are being reported to the system. Check other errors reported to the system and correct them.	

#### Table 2. Common Licensed Internal Code failing items details

Failing Item	Description	Document Description	
AJDG301	Licensed Internal Code	Service Functions; APAR or LICTR	
AJDGP01	Licensed Internal Code	Service Functions; APAR or LICTR	
AJDGP01	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
AJEQU00	I/O processor Licensed Internal Code	Service Functions; APAR or LICTR	
ANYBUS	System bus	Problem Analysis; Symbolic FRU Isolation	
BACKPLN	Card enclosure or backplane	Problem Analysis; Symbolic FRU Isolation	
CDAWKLD	Too many communications lines in use		
IOACNFG	Configuration error	Problem Analysis; Symbolic FRU Isolation	
SVCDOCS	Customer engineer directed to system problem analysis	Problem Analysis; Symbolic FRU Isolation	
SVCPROC	Service Processor Card	Problem Analysis; Symbolic FRU Isolation	

# (B070) Reference codes

For use by authorized service providers.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Failing items details, which follows the reference code table below.

#### Table 1. (B070) Reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0000	Device no response time-out; temporary error	FI00601 FI00602 FI00610
0001	<ul> <li>WS IOP detected error when transmitting data</li> <li>Is the problem intermittent?</li> <li>Yes: Perform the following procedures:</li> <li>1. INT-PIP5</li> <li>2. INT-PIP14</li> </ul>	FI00602 FI00601 GAU7777 GAU8888 FI00610 FI00615
	No: Perform TWSIP01.	
0003	<ul> <li>WS IOP detected parity error from device</li> <li>Is the problem intermittent?</li> <li>Yes: Perform the following procedures:</li> <li>1. INT-PIP5</li> <li>2. INT-PIP14</li> <li>No: Perform TWSIP01.</li> </ul>	FI00602 FI00601 GAU7777 FI00610
0004	<ul> <li>Device detected parity error from WS IOP</li> <li>Is the problem intermittent?</li> <li>Yes: Perform the following procedures:</li> <li>1. INT-PIP5</li> <li>2. INT-PIP14</li> <li>No: Perform TWSIP01.</li> </ul>	FI00602 FI00601 GAU7777 FI00610
0005	<ul> <li>WS IOP detected error when transmitting data</li> <li>Is the problem intermittent?</li> <li>Yes: Perform the following procedures:</li> <li>1. INT-PIP5</li> <li>2. INT-PIP14</li> <li>No: Perform TWSIP01.</li> </ul>	FI00602 FI00601 GAU8888 FI00610 FI00615
0006	<ul> <li>WS IOP detected wrong data from device</li> <li>Is the problem intermittent?</li> <li>Yes: Perform the following procedures: <ol> <li>INT-PIP5</li> <li>INT-PIP14</li> </ol> </li> <li>No: Perform TWSIP01.</li> </ul>	FI00601 FI00602 GAU8888 FI00610

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0007	WS IOP detected wrong address from device	FI00601
	Is the problem intermittent?	GAU8888 GAU7777
	Yes: Perform the following procedures:	FI00610
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0008	WS IOP detected device power turned off, and then on	GAUEEEE FI00601
	Perform TWSIP01.	1100001
0009	WS IOP detected wrong device response to start command	FI00601
	Perform TWSIP01.	FI00610
0020	Device detected wrong command or device ID from WS IOP	FI00601
	Perform TWSIP01.	AJLYD01 FI00610
0021	Device detected not valid value from WS IOP	FI00601
	Perform TWSIP01.	AJLYD01 FI00610
0022	Device detected storage or data overrun	FI00601
	Perform TWSIP01.	AJLYD01 FI00610
0023	Device detected null or attribute exception error	FI00601
	Perform TWSIP01.	FI00610
0024	Device detected wrong start command from WS IOP	FI00601
	Perform TWSIP01.	AJLYD01 FI00610
0025	WS IOP detected wrong exception response from device	FI00601
	Perform TWSIP01.	FI00610
0026	WS IOP detected not valid pass-through command	GAU9999
	Perform TWSIP01.	FI00610
0049	WS IOP detected wrong request or response from device	FI00601
	Perform TWSIP01.	FI00610
0082	WS IOP detected wrong device type from device	FI00601
	Perform TWSIP01.	
0090	WS IOP detected no status change from device	FI00601
	Perform TWSIP01.	FI00610
0091	WS IOP detected busy time-out from device	FI00601
	Perform TWSIP01.	FI00610
0100	Device no response time-out; temporary error	FI00601
		FI00602 FI00610

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0101	WS IOP detected error when transmitting data	FI00602 FI00601
	Is the problem intermittent? Yes: Perform the following procedures:	GAU7777 GAU8888 FI00610
	<ol> <li>INT-PIP5</li> <li>INT-PIP14</li> </ol>	FI00615
	No: Perform TWSIP01.	
0103	WS IOP detected parity error from device	FI00602
	Is the problem intermittent?	FI00601 GAU7777
	Yes: Perform the following procedures:	FI00610
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0104	Device detected parity error from WS IOP	FI00602
	Is the problem intermittent?	FI00601 GAU7777
	Yes: Perform the following procedures:	FI00610
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0105	WS IOP detected error when transmitting data	FI00602
	Is the problem intermittent?	FI00601 GAU8888
	Yes: Perform the following procedures:	FI00610 FI00615
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0106	WS IOP detected wrong data from device	FI00601
	Is the problem intermittent?	FI00602 GAU8888
	Yes: Perform the following procedures:	FI00610
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0107	WS IOP detected wrong address from device	FI00601
	Is the problem intermittent?	GAU8888 GAU7777
	Yes: Perform the following procedures:	FI00610
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	

#### **B070**

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0108	WS IOP detected device power turned off, and then on Perform TWSIP01.	GAUEEEE FI00601
0100		F100(01
0109	WS IOP detected wrong device response to start command Perform TWSIP01.	FI00601 FI00610
0111	WS IOP detected wrong keyboard scan code from display	FI00601
	Perform TWSIP01.	AJLYD01
0100		FI00610
0120	Device detected wrong command or device ID from WS IOP	FI00601 AJLYD01
	Perform TWSIP01.	FI00610
0121	Device detected not valid value from WS IOP	FI00601
	Perform TWSIP01.	AJLYD01 FI00610
0122	Device detected storage or data overrun	FI00601
	Perform TWSIP01.	AJLYD01 FI00610
0123	Device detected null or attribute exception error	FI00610 FI00601
0120	* 	FI00610
	Perform TWSIP01.	
0124	Device detected wrong start command from WS IOP	FI00601 AJLYD01
	Perform TWSIP01.	FI00610
0125	WS IOP detected wrong exception response from device	FI00601
	Perform TWSIP01.	FI00610
0126	WS IOP detected not valid pass-through command	GAU9999
	Perform TWSIP01.	FI00610
0149	WS IOP detected wrong request or response from device	FI00601
	Perform TWSIP01.	FI00610
0170	WS IOP detected error downloading printer definition table	AJDG301
0170	wo for delected erfor downloading printer deminion table	FI00601
0171	WS IOP detected error downloading printer definition table	FI00601
		AJLYD01
0172	WS IOP detected error downloading printer definition table	CAUPDT AJDG301
		FI00601
0173	WS IOP detected error downloading printer definition table	CAUPDT
0124		FI00601
0174	WS IOP detected error unloading printer definition table	FI00601 AJLYD01
0175	WS IOP detected device configuration error	FI00601
	Č Contraction of the second se	AJLYD01
0176 to 0177	WS IOP detected error downloading LIC to device	GAUDMCC FI00601
0181	Wrong magnetic stripe reader response	FI00605
	Perform TWSIP01.	MAUFFFF FI00601
		FI00610

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0182	WS IOP detected wrong device type from device	FI00601
	Perform TWSIP01.	
0183	WS IOP detected wrong display size value	FI00601
	Perform TWSIP01.	
0184	WS IOP detected wrong keyboard identification	FI00601
	Verify that the correct keyboard is attached correctly to the workstation.	
	If the correct keyboard is attached correctly to the workstation, perform TWSIP01.	
0189	Wrong magnetic stripe reader or light pen status	FI00601
	Perform TWSIP01.	FI00605 FI00607 FI00610
0190	WS IOP detected no status change from device	FI00601
	Is the problem intermittent?	FI00610 GAU7777
	Yes: Perform the following procedures:	
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0191	WS IOP detected busy time-out from device	FI00601
	Perform TWSIP01.	FI00610
0200	Device no response time-out; temporary error	FI00604
		FI00602 FI00610
0201	WS IOP detected error when transmitting data	FI00602
	Is the problem intermittent?	FI00604 GAU7777
	Yes: Perform the following procedures:	GAU8888 FI00610
	1. INT-PIP5	FI00615
	2. INT-PIP14	
	No: Perform TWSIP01.	
0203	WS IOP detected parity error from device	FI00602
	Is the problem intermittent?	FI00604 GAU7777
	Yes: Perform the following procedures:	FI00610
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0204	Device detected parity error from WS IOP	FI00602 FI00604
	Is the problem intermittent?	GAU7777 FI00610
	Yes: Perform the following procedures:	F100010
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0205	WS IOP detected error when transmitting data	FI00602
	Is the problem intermittent?	FI00604 GAU7777 FI00610
	Yes: Perform the following procedures:	FI00615
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0206	WS IOP detected wrong data from device	FI00604
	Is the problem intermittent?	FI00602 GAU8888 FI00610
	Yes: Perform the following procedures:	1100010
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0207	WS IOP detected wrong address from device	FI00604
	Is the problem intermittent?	GAU8888 GAU7777
	Yes: Perform the following procedures:	FI00610
	1. INT-PIP5	
	2. INT-PIP14	
	No: Perform TWSIP01.	
0208	WS IOP detected device power turned off, and then on	GAUEEEE
	-	FI00604
0209	WS IOP detected wrong device response to start command	FI00604 FI00610
0210	Printer detected equipment error	FI00604
0211	Printer detected equipment error	FI00604
		AJLYD01 FI00610
0212	Printer detected equipment error	FI00604
0220	Device detected wrong command or device ID from WS IOP	FI00604
	0	AJLYD01
		FI00610
0221	Device detected not valid value from WS IOP	FI00604 AJLYD01
		FI00610
0222	Device detected storage or data overrun	FI00604
	-	AJLYD01

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0223	WS IOP detected start command to printer was lost	FI00604 FI00602 FI00610
0224	Device detected wrong start command from WS IOP	FI00604 AJLYD01 FI00610
0225	WS IOP detected wrong exception response from device	FI00604 FI00610
0226, 0230 to 0239, 0240 to 0248	Printer detected equipment error	FI00604
0249	WS IOP detected wrong request or response from device	FI00604 FI00610
026X, 027X, 028X	Printer detected equipment error	FI00604
	See printer documentation for more information.	
0290	WS IOP detected no status change from device	FI00604 FI00610
0291	WS IOP detected busy time-out from device	FI00604 FI00610
02A0 to 02AF, 02FF	Printer detected equipment error	FI00604
	Consult the printer's manual for additional information.	
A000	Too many devices active on the workstation IOP This error occurs if you attempted to activate more workstations than allowed.	GAUBBBB
	Switch off power to (or remove) one or more of the display stations (except for the console) that are attached to this workstation I/O processor. Perform an initial program load (IPL) from the control panel to correct the problem.	
	Refer to the local workstation diagrams for the location of workstations if necessary.	
B000	WS IOP fails to report part, model and serial number	FI00610
	Perform TWSIP01.	
C000	WS IOP error not known	AJLYD01 FI00610
D000	Work Station IOA start-up test error	FI00610
D010	WS IOP storage failure corrected	FI00610
	Perform TWSIP01.	
D011	WS IOP card storage failure	FI00610
D021	WS IOP detected errors on all cables	FI00602 FI00601 FI00610 FI00615
D022	WS IOP parity errors detected on all cables	FI00602 FI00601 FI00610 FI00615

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
D023	WS IOP detected errors on some, but not all cables Perform TWSIP01.	FI00602 FI00601 FI00610
E000	WS IOP or IOA error during working operation	AJLYD01 FI00610
F000	WS IOP or IOA operating system program error	AJLYD01 FI00719

#### Table 2. Failing items details

Failing Item	Description	Document Description
AJDG301	OS/400 licensed program	Service Functions; APAR or LICTR
AJDGP01	LIC - Input/Output Processor Licensed Internal Code	Service Functions; APAR or LICTR
AJLYD01	Work Station IOP or IOA system Licensed Internal Code	Service Functions; APAR or LICTR
CAUPDT	Device Licensed Internal Code change	Communications Configuration
GAU7777	Electrical interference	
GAU8888	Other work station on port is failing	
GAU9999	Error occurred with pass-through command	
GAUBBBB	Too many work stations are active on the workstation IOP	
GAUDMCC	Device Licensed Internal Code change	
GAUEEEE	Active device turned off	
MAUFFFF	Magnetic stripe	Refer to I/O device service information
UAUFF00	User suspected problem.	

# (B075) Workstation adapter console reference codes

For use by authorized service providers.

The workstation adapter console detected a failure.

- 1. Look at characters 5 through 8 of the top 16 character line of function 11 (4 rightmost characters of word 1). These 4 characters are the unit reference code.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Table 2. Workstation adapter console failing items details, which follows the reference code table below.

Table 1. (B075) Workstation adapter console reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0101	WS IOP detected error when transmitting data Perform WSCIP01.	FI00601 GXC7777 FI00631 FI00730

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0103	WS IOP detected parity error from device Perform WSCIP01.	FI00601 GXC7777 FI00631
0104		FI00730
0104	Device detected parity error from WS IOP Perform WSCIP01.	FI00601 GXC7777 FI00631 FI00730
0105	WS IOP detected error when transmitting data Perform WSCIP01.	FI00601 GXC7777 FI00631 FI00730
0106	WS IOP detected wrong data from device Perform WSCIP01.	FI00601 FI00631 GXC7777 FI00730
0107	WS IOP detected wrong address from device Perform WSCIP01.	FI00601 GXC7777 FI00730
0108	WS IOP detected device power turned off, and then on Perform WSCIP01.	GXCEEEE FI00601
0109	WS IOP detected wrong device response to start command Perform WSCIP01.	FI00601 FI00615
0111	WS IOP detected wrong keyboard scan code from display Perform WSCIP01.	FI00601 FI00730
0120	Device detected wrong command or device ID from WS IOP Perform WSCIP01.	FI00601 FI00730
0121	Device detected not valid value from WS IOP Perform WSCIP01.	FI00601 FI00730
0122	Device detected storage or data overrun Perform WSCIP01.	FI00601 FI00730
0123	Device detected null or attribute exception error Perform WSCIP01.	FI00601 FI00730
0124	Device detected wrong start command from WS IOP Perform WSCIP01.	FI00601 FI00730
0125	WS IOP detected wrong exception response from device Perform WSCIP01.	FI00601 FI00730
0126	WS IOP detected not valid pass-through command Perform WSCIP01.	GXC9999 FI00730
0149	WS IOP detected wrong request or response from device	FI00601 FI00730

#### B075

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
0190	WS IOP detected no status change from device	FI00601
	Perform WSCIP01.	GXC7777 FI00730
0191	WS IOP detected busy time-out from device	FI00601
01/1		FI00730
	Perform WSCIP01.	
0201	WS IOP detected error when transmitting data	FI00604 GXC7777
	Perform WSCIP01.	FI00631
		FI00730
0203	WS IOP detected parity error from device	FI00604 GXC7777
	Perform WSCIP01.	FI00631
		FI00730
0204	Device detected parity error from WS IOP	FI00604
	Perform WSCIP01.	GXC7777 FI00631
		FI00730
0205	WS IOP detected error when transmitting data	FI00604
	Perform WSCIP01.	GXC7777
		FI00631 FI00730
0206	WS IOP detected wrong data from device	FI00604
		FI00631
	Perform WSCIP01.	FI00730
0207	WS IOP detected wrong address from device	FI00604 GXC7777
	Perform WSCIP01.	FI00730
0208	WS IOP detected device power turned off, and then on	GXCEEEE
		FI00604
0209	WS IOP detected wrong device response to start command	FI00604 FI00730
0211	Printer detected equipment error	FI00604
0211		FI00730
0221	Device detected not valid value from WS IOP	FI00604
		FI00730
0224	Device detected wrong start command from WS IOP	FI00604 FI00730
0225	WS IOP detected wrong exception response from device	FI00750
0225	wis for detected wrong exception response from device	FI00730
0290	WS IOP detected no status change from device	FI00604
		FI00730
0291	WS IOP detected busy time-out from device	FI00604
E000		FI00730
5000	Wrong command sent by Licensed Internal Code	AJDG301
5001	Procedure error in Licensed Internal Code	AJDG301
5002	Procedure error in Licensed Internal Code	CXCTEMP AJDG301
	Procedure error in machine instructions	
5006	Procedure error in Licensed Internal Code	AJDG301

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5007	Procedure error in Licensed Internal Code	AJDG301 CXCMSTA
5009	Incorrect command value sent by Licensed Internal Code	AJDG301
500A	Procedure error in Licensed Internal Code	AJDG301
500D	Incorrect command value sent by Licensed Internal Code	AJDG301 CXCMAXI
5022	Procedure error in Licensed Internal Code	AJDG301
5206	Communications controller storage not available	CXCBUSY
56EA	Clear-to-send signal dropped on modem interface	GXCLINK FI00704 CXCCTSV FI00719 FI00701
56ED	Data-set-ready turn-on time-out on modem interface	FI00701 FI00704 FI00719 AJLAG01
56F1	Data-set-ready dropped on modem interface	FI00704 FI00701 GXCLINK FI00719
5710	Nonproductive receive time-out while receiving from remote	CXCNPRT FI00700 FI00705 FI00704 GXCLINK FI00701 FI00719
5712	No data received from remote equipment; time-out	AJLAG01 CXCENCD CXCINAT GXCLINK F100704 F100705 F100700 CXCSTAD F100701 CXCDTAR F100719 CXCMRTY
5715	Remote equipment did not respond causing an idle-time-out	GXCLINK CXCRPTO FI00701 FI00704 CXCMRTY FI00705 CXCENCD FI00700 CXCDTAR FI00719

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5718	Retry limit reached for sending frames to remote equipment	GXCLINK FI00705 FI00704 FI00700 CXCMRTY FI00719 FI00701
5719	Retry limit reached for sending frames to remote equipment	FI00700
5720	Retry limit reached for sending poll frame to remote	FI00700 CXCMODU
5721	Could not send frame to remote equipment; local problem	FI00704 CXCDTAR FI00701 FI00719 FI00730
5722	Wrong command value sent by OS/400 licensed program	AJLAG01 CXCSTAD
A000	Too many devices active on the workstation IOP	GXCBBBB
B000	WS IOP fails to report part, model and serial number Perform WSCIP01.	FI00615
C000, D000	WS IOP error not known	AJLAG01
D001	Wrong or no external communications cable installed	FI00631 AJLAG01
F003	WS IOA buffer utilization threshold exceeded temporarily	AJLAG01
FFFF	User believes there is a problem Reference code FFFF is assigned by the ANZPRB (Analyze Problems) for user-detected errors. Run ANZPRB again if the problem still exists or look in the problem log (WRKPRB) for possible failing FRUs.	UXCFF00

### Table 2. Workstation adapter console failing items details

Failing Item	Description	Document Description
AJDG301	Vertical Licensed Internal Code	Service Functions; APAR or LICTR
AJLAG01	Licensed Internal Code	Service Functions; APAR or LICTR
CXCBUSY	Too many communications lines in use	Communications Configuration
CXCCONF	Configuration or OS/400 licensed program	Communications Configuration
СХССРТО	CNNPOLLTMR value in CRTLINSDLC command	Communications Configuration
CXCCTSV	CTSTMR value in CRTLINSDLC command	Communications Configuration
CXCDTAR	LINESPEED value in CRTLINSDLC command	Communications Configuration
CXCENCD	NRZI value in CRTLINSDLC command	Communications Configuration
CXCINAT	INACTTMR value in CRTLINSDLC command	Communications Configuration
CXCMAXI	MAXFRAME value in CRTLINSDLC command	Communications Configuration
CXCMODU	MODULUS value in CRTLINSDLC command	Communications Configuration
CXCMRTY	FRAMERTY value in CRTLINSDLC command	Communications Configuration
CXCMSTA	MAXCTL value in CRTLINSDLC command	Communications Configuration

Failing Item	Description	Document Description
CXCNPRT	NPRDRCVTMR value in CRTLINSDLC command	Communications Configuration
CXCRPTO	IDLTMR value in CRTLINSDLC command	Communications Configuration
CXCSNDT	SHMNODE value in CRTLINSDLC command	Communications Configuration
CXCSTAD	STNADR value in CRTCTLcommand	Communications Configuration
CXCTEMP	No failure found	Communications Configuration
GXC7777	Electrical interference	
GXC8888	Other workstation on port is failing	
GXC9999	Error occurred with pass-through command	
GXCBBBB	Too many devices are active on the workstation IOP	
GXCEEEE	Active device turned off	
GXCLINK	Communications network equipment	
UXCFF00	User suspected problem	

## (B2xx) Logical partition reference codes

For use by authorized service providers.

The platform code that monitors the behavior of logical partitions detected an error. These reference codes are posted in the Partition Status screens under the SST/DST **Work with system partitions** option.

- 1. Characters 3 and 4 of word 1 are the partition ID of the logical partition with the problem.
- 2. Find the unit reference code in the following table.

For more on the Failing Item column entries, see Logical partition failing items details, which follows the reference code table below.

Table 1. (B2xx) Logical partition reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1210	A problem occurred during the IPL of a secondary partition	FI00580
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Look in the Primary partition's Service Action Log for a B6005090 during the secondary partition IPL. Use that SRC and go to List of system reference codes.	
	If you do not find a B6005090 in the Service Action Log of the Primary partition then look for any SRC which was logged during the IPL of the Primary partition. Search the Service Action Log first and if you do not find an SRC there then search the Product Activity Log. Use the new SRC and go to List of system reference codes.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1220	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Initiate a Primary partition main storage dump then contact your next level of support.	
1230	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. See the <i>iSeries Service Functions</i> information.	LPARCFG
	This is a partitioning configuration problem. The partition is lacking the necessary resources to IPL. Refer the customer to their software support.	
1250	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	The primary partition's IPL mode does not allow the secondary partition to IPL in the mode the secondary partition attempted to IPL in. If the primary partition is IPL'd in 'C' mode then secondary partitions can only IPL in 'C' mode. Other modes are not allowed.	
	IPL the primary partition in either 'A' mode or 'B'. Then retry the IPL of the secondary partition.	
1260	A problem occurred during the IPL of a secondary partition	LPARSUP
	The secondary partition identified in the xx field of the B2xx SRC could not IPL at the Timed Power On setting because the IPL mode of the secondary partition was not set to Automatic or Normal.	
	Go into the "Work With System Partitions" option of SST/DST and reset the IPL mode to Normal/Automatic, then re-IPL the secondary.	
1270	A problem occurred during the IPL of a secondary partition	
	The guest partition identified in the xx field of the B2xx SRC could not IPL because the Primary partition was not in a full paging environment.	
	IPL the Primary partition past the Storage Management full paging IPL step. Re-IPL the guest partition.	
1310	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. No alternate (D-mode) IPL IOP was selected. The IPL will attempt to continue, but there may not be enough information to find the correct D-mode load source.	
	Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Have the customer configure an alternate IPL IOP for the secondary partition. Then retry the secondary partition IPL.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
1320	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. No default load source IOP was selected for an A/B-mode IPL. The IPL will attempt to continue, but there may not be enough information to find the correct load source.	
	Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Have the customer configure a load source IOP for the secondary partition. Then retry the secondary partition IPL.	
3110	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Contact your next level of support.	
3113	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Look in the Service Action Log of the Primary partition for B600xxxx SRCs that were logged when the secondary partition was IPLing. Correct the B600xxxx problem, then retry the secondary partition IPL.	
	If there are no B600xxxx SRCs in the Service Action Log of the Primary partition from the secondary partition's IPL then contact your next level of support.	
3114	A problem occurred during the IPL of a secondary partition	FI00096
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Look in the Service Action Log of the Primary partition for B600xxxx SRCs with the same bus/board/card numbers identified in the B2xx xxxx SRC words. Use the new SRC and go to List of system reference codes.	
	The B2xx xxxx SRC Format is Word 1: B2xx3114, Word 3: Bus, Word 4: Board, Word 5: Card.	
3120	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Retry count exceeded. Contact your next level of support.	
3123	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Due to the multi-adapter bridge configuration the IOA with the load source device for the secondary partition does not belong to the IOP it was assigned to when the secondary partition was configured.	
	Contact your next level of support.	

#### B2xx

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
125	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information on logical partitions. See the <i>iSeries Service Functions</i> information.	
	Primary partition main store utilization problem. The Primary partition code could not obtain a segment of main storage within the Primary partition's main store to use for managing the creation of a secondary partition.	
3128	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. An unexpected failure return code was returned when attempting to query the IOA slots that are assigned to an IOP.	
3130	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. If word 3 is zero, then this SRC is informational and can be ignored.	
	Otherwise there is a problem in the Primary partition. A non-zero bus number has no associated bus object.	
	Contact your next level of support.	
3135	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. An unknown bus type was detected.	
3140	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. The load-source IOP is not owned by the secondary partition. This is a configuration problem in the secondary partition. Have the customer re-configure the partition to have the intended load-source IOP.	
	If there is not a configuration problem then contact your next level of support.	
3200	A problem occurred during the IPL of a secondary partition	FI00098
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	FI00096
	• If the IPL source (load source) is a tape device look for a PERM SRC in the Product Activity Log of the Primary partition logged at the time the secondary partition was IPLing. Use the new SRC and go to List of system reference codes.	
	• Look for an SRC in the Service Action Log of the Primary partition logged at the time the secondary partition was IPLing. Use the new SRC and go to List of system reference codes.	
4310	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Initiate a Primary partition main storage dump and contact your next level of support.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4311	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Initiate a primary partition main storage dump and contact your next level of support.	
4312	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Received an unexpected Direct Select Address.	
	Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Initiate a Primary partition main storage dump and contact your next level of support.	
4315	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Storage in the Primary partition could not be allocated for the LID manager. The IPL of the secondary partition is failed. Increase the allocated storage to the Primary partition.	
4320	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Configuration error. Expected a disk unit and got some other kind of adapter or device.	
	See the <i>iSeries Service Functions</i> information.	
4321	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Configuration error. Expected a tape or optical unit and received some other kind of adapter or device.	
	See the <i>iSeries Service Functions</i> information.	
5106	Problem detected during main storage dump	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Not enough space in the Primary partition's ASP to contain the dump.	
	Contact your next level of support.	
5114	Problem detected during main storage dump	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. There is not enough space on the secondary partition's load-source to contain the dump.	
5115	Problem detected during main storage dump	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. There was an error reading the secondary partition's main storage dump from the secondary partition's load-source into the Primary partition's main storage.	

B2xx		

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
5117	Problem detected during main storage dump LPA	
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. A main storage dump has occurred but cannot be written to the load source device because a valid dump already exists.	
	Contact your next level of support.	
5121, 5135, 5145	Problem detected during main storage dump	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. There was an error writing the secondary partition's main storage dump to the secondary partition's load-source.	
5148	Problem detected during main storage dump	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. An error occurred while doing a main storage dump that would have caused another main storage dump.	
	Contact your next level of support.	
6012	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. The secondary partition's LID failed to completely load into the the partition's mainstore area.	
	Contact your next level of support.	
6015	A problem occurred during the IPL of a secondary partition	MEDIA
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	FI00099
	The load-source media is corrupted or invalid. A SLIP install of the secondary partition is required to recover.	
6025	A problem occurred during the IPL of a secondary partition	MEDIA
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	FI00099
	This is a problem with the load-source media being corrupt or invalid. A SLIP install of the secondary partition is required to recover.	
6027	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	A failure occurred when allocating memory for an internal object used for LID load operations.	

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
6110	A problem occurred during the IPL of a secondary partition	FI00098
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Error on load-source device.	
	See the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Record the SRC. The Direct Select Address of the device IOP in the SRC. Word 3: Bus, Word 4: Board, Word 5: Card.	
6900	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. The guest partition's allocated memory is not large enough for the kernel specified to load. Increase the size of the secondary partition's memory allocation. Word 3 of the SRC is the allocated size of the secondary partition and word 4 of the SRC is the required size of the kernel.	
6905	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. There is no valid kernel to load for the specified IPL Mode of the guest partition. Either the kernel is not valid or there is not a kernel in the selected IPL Mode. Verify that the kernel specified to load is valid and the IPL mode specified is where the kernel is located. If the problem persists then record all words of the SRC and contact your next level of support.	
6910	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. A storage management problem occurred loading the guest partition. Record all the words of the SRC and contact your next level of support.	
6920	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. A problem occurred while loading the guest partition. Record all the words of the SRC and contact your next level of support.	
6930	A problem occurred during the IPL of a secondary partition	LPARCFG
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. A problem occurred while loading the guest partition. Record all of the words in the SRC and contact your next level of support.	
7111	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Load-source device driver does not point to an IOP hardware driver.	
	Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.	
	Initiate a Primary partition main storage dump, and contact your next level of support.	

#### B2xx

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7115	<ul> <li>A problem occurred during the IPL of a secondary partition</li> <li>The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. The IOP identified in word 5 is not reporting to the secondary partition. Removing an IOP hardware driver (not the load source for the current IPL) from the Primary partition failed. The IPL will continue, but the secondary partition will not be able to establish connections to this IOP.</li> <li>Word 3: Bus, Word 4: Board, Word 5: Card.</li> </ul>	FI00099 LPARSUP
7117	<ul> <li>A problem occurred during the IPL of a secondary partition</li> <li>The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. The IOP identified in word 5 is not reporting to the secondary partition. Removing the IOP hardware driver that is associated with the current load-source has failed. The IPL will fail.</li> <li>Read and understand the information about logical partitions. See the <i>iSeries Service Functions</i> information.</li> <li>Record the SRC. The location of the IOP is in SRC words 3, 4 and 5. Word 3: Bus, Word 4: Board, Word 5: Card.</li> </ul>	FI00099 LPARSUP
7200	A problem occurred during the IPL of a secondary partition The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. An error condition was encountered when communicating with the load source IOP for the partition identified in the xx field of the B2xx SRC.	LPARSUP
8081	A problem occurred during the IPL of a secondary partition The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. An internal LIC timeout has occurred. The partition may continue to IPL but it may experience problems while running.	LPARSUP
8105	A problem occurred during the IPL of a secondary partition The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. There was a failure loading the VPD areas of the secondary partition. The load-source media has been corrupted. A SLIP install of the partition is required.	MEDIA FI00099
8107	A problem occurred during the IPL of a secondary partition The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. There was a problem getting a segment of main storage in the Primary partition's main store.	FI00099
8115	A problem occurred during the IPL of a secondary partition The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. There was a low level partition to partition communication failure. A secondary partition re-IPL is necessary to recover. If this SRC appears again when the partition is re-IPLed contact your next level of support.	LPARSUP

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
F000	A problem occurred during the IPL of a secondary partition	LPARSUP
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. An operation has timed out. Look in the Service Action Log of the Primary partition for a failure during the last IPL of the secondary partition. Use the new SRC and go to List of system reference codes. If you do not find a failure in the Service Action Log from the last IPL of the partition then record all words of this SRC and call your next level of support. See the <i>iService Functions</i> information.	
F001	A problem occurred during the IPL of a secondary partition	FI00098 FI00096
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. A bus time out occurred on a command to the load source IOP.	F100090
F002	A problem occurred during the IPL of a secondary partition LPARS	
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Timeout waiting for the load source hardware driver.	
	Initiate a main store dump of secondary partition.	
F003	A problem occurred during the IPL of a secondary partition	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. Partition processors did not start LIC within the timeout window.	
F004 to F005	A problem occurred during power off of secondary partition.	FI00099
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. From the "Work with partition status screen" the primary partition issued a power down message to the secondary partition but the message response from the secondary timed out.	
	Initiate a main store dump of the secondary partition.	
F006	A problem occurred during the IPL of a secondary partition	FI00098
	The partition ID is characters 3 and 4 of the B2xx reference code in word 1 of the SRC. The LID load operation for the secondary partition's IPL timed out.	FI00096

#### Logical partition failing items details

If the system has logical partitions, perform this procedure from the logical partition that reported the problem.

Failing Item	Description	Document Description
LPARCFG	LPAR configuration, processors, memory, console or load-src	See the service documentation for instructions.
LPARSUP	LPAR complex problem, call next level of support	See the service documentation for instructions.
MEDIA	Load source media corrupted	See the service documentation for instructions.

#### Table 2. Logical partition failing items

### (B427) System processor reference codes

For use by authorized service providers.

The system processor detected a failure.

These reference codes are for the Models 270, 800, 810, 820, and 825.

Collect data from Functions 11, 12, and 13 of the system panel, or words 1 through 9 from the Main Store Dump (MSD) screen. This SRC, beginning with "**B4**", may contain up to five FRUs. Eight characters of this data represent a single FRU. The FRU characters have two parts: a unit reference code, and a type number. The location of this data is shown below:

PANEL FUNC 11:	B4xx RC02RC03	RC01TP01 RC04RC05
PANEL FUNC 12:	DATA0012 <b>TP02TP03</b>	DATA0013 <b>TP04TP05</b>
PANEL FUNC 13:	DATA0016 DATA0018	DATA0017 DATA0019

The FRU information for FRU 1 would be RC01 and TP01, for FRU 2 would be RC02 and TP02, etc.

Characters	Description / Meaning	Length	
RC01	FRU 1 - Ref Code	4 Characters	
TP01	FRU 1 - Type	4 Characters	
RC02	FRU 2 - Ref Code	4 Characters	
TP02	FRU 2 - Type	4 Characters	
RC03, TP03, RC04, TP04, RC05, TP05 same as above.			
DATA012, DATA013, DATA016, DATA017, DATA018, DATA019	Miscellaneous Data - Not applicable, but may be needed for your next level of support.	8 Characters	

The example below shows relevant data for three FRUs: RC01=4300, TP01=244A, RC02=8200, TP02=2884, RC03=8100, TP03=2884, the remaining values are zeroes.

PANEL	FUNC	11:	B427 <b>82008100</b>	4300244A 00000000
PANEL	FUNC	12:	xxxxxxxx 28842884	xxxxxxxx 00000000
PANEL	FUNC	13:	xxxxxxxx	xxxxxxx

XXXXXXXX	XXXXXXXX

Characters	Description / Meaning	Length
4300	FRU 1 - Ref Code = 4300	4 Characters
244A	FRU 1 - Type = 244A	4 Characters
8200	FRU 2 - Ref Code = 8200	4 Characters
2884	FRU 2 - Type = 2884	4 Characters
8100	FRU 3 - Ref Code = 8100	4 Characters
2884	FRU 3 - Type = 2884	4 Characters

Below is the information as shown in a MSD SCREEN:

1 - B4xx **RC01TP01RC02RC03RC04RC05** 2 - DATA0012 3 - DATA0013 4 - **TP02TP03** 5 - **TP04TP05** . . . . 9 - DATA0019

The FRU information for FRU 1 would be **FI1A** and **FI1B** or for FRU 2 it would be **FI2A** and **FI2B**, and so forth.

Each reference code has an associated Failing Item, given in the table below. Here the failing item is a Symbolic FRU. When you use the reference code and description when following the procedure described in the Symbolic FRU documentation, you should end up with a hardware FRU, code update, or directions to call your next level of support.

Each reference code also has an associated Priority Code. The first digit of the reference code in the table below gives the priority.

- **Mandatory** priority reference codes start with either a **4**, **5**, or **7**. You should replace all mandatory failing items before the next IPL.
- **High** priority reference codes start with either a **8**, **9**, or **B**. A FRU with a high priority has a high probability of resolving the problem. Replace high priority failing items in order, one at a time with an IPL in between.
- Low priority reference codes start with either a C, D, or F. A FRU with a low priority has a low probability of resolving the problem. Replace low priority failing items after replacement of mandatory and high priority items.

The second part of the FRU information is the type number. This will be used in combination with the Failing Item information to determine the Part Number from the Type, Model, and Part Number list. If the failing item is given as a Symbolic FRU, go to the Symbolic FRU section to determine the failing part. Then go to the tables in the Locations and Addresses section for the physical mapping of the information in the Location column.

For more on the Failing Item column entries, see Table 2. System processor failing items details, which follows the reference code table below.

Reference Code	Description	Failing Item
4001	System processor card failure	CCIN
4003	System Card(s) or BackPlane	ANYPROC
4004 to 4005	System Sub-Card(s)	CTLPNCD
4009 to 400D, 4010 to 4017	Main storage failure	ANYMEM
40A0	Service processor Licensed Internal Code	AJDGP01
40A1	Licensed Internal Code error	AJDG301
40A2	Service processor Licensed Internal Code	AJDGP01
40A4	Rio PIP 55	NEXTLVL
40A6	Main storage failure	NOMSUSE

#### Table 1. (B427) System processor reference codes

Reference Code	Description	Failing Item
40A9	System memory card configuration problem detected	MEMCFG
40E1	Service processor Licensed Internal Code	AJDGP01
4100	System Card(s) or BackPlane	CCIN
4101 to 4104, 410D to 410E, 4111 to 4114, 411D, 4121 to 4124, 412D, 4131 to 4134, 413D	System Sub-Card(s)	CCIN
4200	System Card(s) or BackPlane	CCIN
4201 to 4204, 420D to 420E, 4211 to 4214, 421D to 421E, 4221 to 4224, 422D to 422E, 4231 to 4234, 423D to 423E	System Sub-Card(s)	CCIN
4300	System Card(s) or BackPlane	CCIN
4301 to 4302, 430D, 4311 to 4312, 431D, 4321 to 4322, 432D, 4331 to 4332, 433D	System Sub-Card(s)	CCIN
7102, 7140, 7282 to 7283	System bus error	RIOPORT
7401	System Card(s) or BackPlane	FI00017
7402	Bus expansion card	FI00017
7404 to 7406	Optical link on Bus Expansion Adapter card failed	FI00017
7408	Bus expansion card	FI00017
7409 to 740D	Optical link on Bus Expansion Adapter card failed	FI00017
8001	System Card(s) or BackPlane	CCIN
8003	System Card(s) or BackPlane	ANYPROC
8004 to 8005	System Sub-Card(s)	CTLPNCD
8009	System Card(s) or BackPlane	ANYMEM
800A to 800D, 8010 to 8017	Main storage failure	ANYMEM
80A0	Service processor Licensed Internal Code	AJDGP01
80A1	Licensed Internal Code error	AJDG301
80A2	Service processor Licensed Internal Code	AJDGP01
80A4	Rio PIP 55	NEXTLVL
80A6	Main storage failure	NOMSUSE
80A9	System memory card configuration problem detected	MEMCFG
80E1	Service processor Licensed Internal Code	AJDGP01
8100	System Card(s) or BackPlane	CCIN

Reference Code	Description	Failing Item
8101 to 8104, 810D to 810E, 8111 to 8114, 811D, 8121 to 8124, 812D, 8131 to 8134, 813D	System Sub-Card(s)	CCIN
8200	System Card(s) or BackPlane	CCIN
8201 to 8204, 820D to 820E, 8211 to 8214, 821D to 821E, 8221 to 8224, 822D to 822E, 8231 to 8234, 823D to 823E	System Sub-Card(s)	CCIN
8300	System Card(s) or BackPlane	CCIN
8301 to 8302, 830D, 8311 to 8312, 831D, 8321 to 8322, 832D, 8331 to 8332, 833D	System Sub-Card(s)	CCIN
B102, B140, B282 to B283	System bus error	RIOPORT
B401	System Card(s) or BackPlane	FI00017
B402	Bus expansion card	FI00017
B404 to B406	Optical link on Bus Expansion Adapter card failed	FI00017
B408	Bus expansion card	FI00017
B409 to B40D	Optical link on Bus Expansion Adapter card failed	FI00017
C001	System Card(s) or BackPlane	CCIN
C003	System Card(s) or BackPlane	ANYPROC
C004 to C005	System Sub-Card(s)	CTLPNCD
C009 to C00D, C010 to C017	Main storage failure	ANYMEM
C0A0	Service processor Licensed Internal Code	AJDGP01
C0A1	Licensed Internal Code error	AJDG301
C0A2	Service processor Licensed Internal Code	AJDGP01
C0A4	Rio PIP 55	NEXTLVL
C0A6	Main storage failure	NOMSUSE
C0A9	System memory card configuration problem detected	MEMCFG
C0E1	Service processor Licensed Internal Code	AJDGP01
C100	System Card(s) or BackPlane	CCIN
C101 to C104, C10D to C10E, C111 to C114, C11D, C121 to C124, C12D, C131 to C134, C13D	System Sub-Card(s)	CCIN
C200	System Card(s) or BackPlane	CCIN

Reference Code	Description	Failing Item
C201 to C204, C20D to C20E, C211 to C214, C21D to C21E, C221 to C224, C22D to C22E, C231 to C234, C23D to C23E	System Sub-Card(s)	CCIN
C300	System Card(s) or BackPlane	CCIN
C301 to C302, C30D, C311 to C312, C31D, C321 to C322, C32D, C331 to C332, C33D	System Sub-Card(s)	CCIN
F102, F140, F282 to F283	System bus error	RIOPORT
F401	System Card(s) or BackPlane	FI00017
F402	Bus expansion card	FI00017
F404 to F406	Optical link on Bus Expansion Adapter card failed	FI00017
F408	Bus expansion card	FI00017
F409 to F40D	Optical link on Bus Expansion Adapter card failed	FI00017

### System processor failing items details

Use this table for details on the Failing Item column in the Reference Codes table(s) above.

Failing Item	Description	Document Description
AJDG301	Slic Code	Service Functions; APAR or LICTR
AJDGP01	Processor Runtime Diags	Service Functions; APAR or LICTR
AJDGP01	Service Processor Code	Service Functions; APAR or LICTR
ANYMEM		Problem Analysis; Symbolic FRU Isolation
ANYMEM	Main Storage Card - Location Unknown	Problem Analysis; Symbolic FRU Isolation
ANYPROC	Processor Unknown	Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN	System Backplane	Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation

 Table 2. System processor failing items details

Failing Item	Description	Document Description
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN	Card	Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation

Failing Item	Description	Document Description
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CCIN		Problem Analysis; Symbolic FRU Isolation
CTLPNCD		Problem Analysis; Symbolic FRU Isolation
CTLPNCD	Control Panel Card	Problem Analysis; Symbolic FRU Isolation
MEMCFG	Memory configuration error	Problem Analysis; Symbolic FRU Isolation
NEXTLVL	Contact your next level of support	Problem Analysis; Symbolic FRU Isolation
NOMSUSE	No usable main storage	Problem Analysis; Symbolic FRU Isolation
RIOPORT		Problem Analysis; Symbolic FRU Isolation
RIOPORT	MUM RIO IO PORT	Problem Analysis; Symbolic FRU Isolation
RIOPORT		Problem Analysis; Symbolic FRU Isolation
RIOPORT		Problem Analysis; Symbolic FRU Isolation

# (B428, B448) System processor reference codes

For use by authorized service providers.

The system processor detected a failure.

These reference codes are for Models 825, 870, and 890.

If the system is operational, look in the Service Action Log for a list of failing items. If the failing item is a Symbolic FRU, go to that section of the documentation and follow the procedure. If the failing item is

hardware, go to the locations tables for the model on which you are working. The table will match a FRU to the failing component, direct you to the proper remove and replace procedure, and provide location information.

The following gives background information regarding processor / memory SRC formats and control panel functions.

Collect data from Functions 11, 12, and 13 of the system panel, or words 1 through 9 from the Main Store Dump (MSD) screen. This SRC, beginning with "**B4**", may contain up to five FRUs. Eight characters of this data represent a single FRU. The FRU characters have two parts: a unit reference code, and a type number. The type number is usually a CCIN. If the number is 0000, either the fix will involve software, or the CCIN for the failed hardware cannot be determined without using the procedure to which you will be directed. The location of this data is shown below:

PANEL FUNC 11:	B4xx RC02RC03	RC01TP01 RC04RC05
PANEL FUNC 12:	DATA0012 <b>TP02TP03</b>	DATA0013 <b>TP04TP05</b>
PANEL FUNC 13:	DATA0016 DATA0018	DATA0017 DATA0019

The FRU information for FRU 1 would be RC01 and TP01, for FRU 2 would be RC02 and TP02, etc.

Characters	Description / Meaning	Length
RC01	FRU 1 - Ref Code	4 Characters
TP01	FRU 1 - Type	4 Characters
RC02	FRU 2 - Ref Code	4 Characters
TP02	FRU 2 - Type	4 Characters
RC03, TP03, RC04, TP04, RC0		
DATA012, DATA013, DATA016, DATA017, DATA018, DATA019	Miscellaneous Data - Not applicable, but may be needed for your next level of support.	8 Characters

The example below shows relevant data for three FRUs: RC01=4300, TP01=244A, RC02=8200, TP02=2884, RC03=8100, TP03=2884, the remaining values are zeroes.

PANEL	FUNC	11:	B427 <b>82008100</b>	4300244A 00000000
PANEL	FUNC	12:	xxxxxxxx 28842884	xxxxxxxx 00000000
	FUNC	12.	~~~~~	~~~~~

Characters	Description / Meaning	Length
4300	FRU 1 - Ref Code = 4300	4 Characters
244A	FRU 1 - Type = 244A	4 Characters
8200	FRU 2 - Ref Code = 8200	4 Characters
2884	FRU 2 - Type = 2884	4 Characters
8100	FRU 3 - Ref Code = 8100	4 Characters
2884	FRU 3 - Type = 2884	4 Characters

Below is the information as shown in a MSD SCREEN:

```
1 - B4xx____RC01TP01RC02RC03RC04RC05

2 - DATA0012

3 - DATA0013

4 - TP02TP03

5 - TP04TP05

.

.

.

.

.

.

.

.

.

.

.
```

The FRU information for FRU 1 would be **FI1A** and **FI1B** or for FRU 2 it would be **FI2A** and **FI2B**, and so forth.

The first part of the FRU information is the unit reference code. Find the reference codes in the table below to determine the Priority and Location of the failing items. See the tables in the Locations and addresses topic for the physical mapping of the information in the Location column.

Each reference code also has an associated Priority Code. The first digit of the reference code in the table below gives the priority.

- **Mandatory** priority reference codes start with a **4**. You should replace all mandatory failing items before the next IPL.
- **High** priority reference codes start with an **8**. A FRU with a high priority has a high probability of resolving the problem. Replace high priority failing items in order, one at a time with an IPL in between.
- Low priority reference codes start with a C. A FRU with a low priority has a low probability of resolving the problem. Replace low priority failing items after replacement of mandatory and high priority items.

The second part of the FRU information is the type number. This will be used in combination with the Failing Item information to determine the Part Number from the Type, Model, and Part Number list. If the failing item is given as a Symbolic FRU, go to the Symbolic FRU topic to determine the failing part. Then go to the tables in the Locations and Addresses topic for the physical mapping of the information in the Location column.

Reference Code	Description	Failing Item
4001	Clock Card	CCIN
4002	Processor Backplane	CCIN
4003 to 4006	Processor Card	ANYPROC
4007	Processor Cache Card	CCIN
4009	Processor Backplane	CCIN
	The backplane extender in location MB2 has failed. See the locations section for the model you are working on for additional information.	
400A to 400D	Network Interface Controller	CCIN
	If this error occurs at IPL time, clean the cable connections (if optical), then reseat the cables. If that does not correct the problem, replace the cable prior to continuing with the FRU list.	
400E to 400F	Processor Configuration Card	CCIN

#### Table 1. (B428, B448) System processor reference codes

Reference Code	Description	Failing Item
4010 to 401F, 4020 to 4027, 4100 to 4101, 4110 to 4111, 4120 to 4121	Memory Card	ANYMEM
4A03 to 4A06	Contact your next level of support	NEXTLVL
4B00 to 4B03, 4B10 to 4B17, 4B20 to 4B27, 4B30 to 4B37	I/O Port	RIOPORT
4BE0	I/O Port	RIOPORT
	See the Locations Section for the system on which you are working. The HSL I/O Bridge in the base I/O tower may have failed.	
4BF0 to 4BFD	I/O Port	RIOPORT
4C03	Processor Card	ANYPROC
4C09	Memory Card	ANYMEM
4C0A	I/O Port	CCIN
4C10 to 4C13	Configuration Mismatch	PROCMM
4CA5	Configuration Mismatch	NEXTLVL
	<ul><li>First, check the locations section for the system on which you are working for base system components and processor and memory configuration rules.</li><li>If that does not correct the problem, replace the Network Interface Controller. See the loactions section for the model on which you are working for further information.</li><li>If the problem is not corrected, contact your next level of support.</li></ul>	
4CA6	Invalid memory configuration	NOMSUSE
4CA9	Invalid memory configuration	MEMCFG
4D00 to 4D0F	Processor Cache Card	CCIN
4EA0 to 4EA2	Code Error	PROCODE
4EA4	Contact your next level of support	NEXTLVL
	<ul> <li>If word 3 starts with 9250 and word 6 is A30A0000 then do the following:</li> <li>1. Change the ipl type to "fast boot"</li> <li>2. Change the Mode to MANUAL (you only need to do this once)</li> <li>3. ReIPL the system</li> <li>4. Replace the FRU indicate by the PRD error (word 3 is 7xxxxxx)</li> <li>5. Change the ipl type to "slow boot"</li> <li>6. ReIPL the system.</li> <li>7. If there is an error like the one that sent you here, then repeat step 1 to step 6 (skip step 2) until all FRUs has been replaced.</li> </ul>	
4EAF	Code Error	PROCODE
4EB0	I/O Port	JTPORT
4EB1 to 4EBC	I/O Port	PRCLINE
4EBF	Contact your next level of support	REDH
	Code Error	PROCODE

Reference Code	Description	Failing Item
4EE5	Contact your next level of support	NEXTLVL PROCODE
8001	Clock Card	CCIN
8002	Processor Backplane	CCIN
8003 to 8006	Processor Card	CCIN
8007	Processor Cache Card	CCIN
800A to 800D	Network Interface Controller	CCIN
	If this error occurs at IPL time, clean the cable connections (if optical), then reseat the cables. If that does not correct the problem, replace the cable prior to continuing with the FRU list.	
800E to 800F	Processor Configuration Card	CCIN
8010 to 801F, 8020 to 8027, 8100 to 8101, 8110 to 8111, 8120 to 8121	Memory Card	ANYMEM
8A03 to 8A06	Contact your next level of support	NEXTLVL
8B00 to 8B03, 8B10 to 8B17, 8B20 to 8B27, 8B30 to 8B37	I/O Port	RIOPORT
8BE0	I/O Port	RIOPORT
	See the Locations section for the model on which you are working. The HSL I/O Bridge card in the base I/O tower may have failed.	
8BF0 to 8BFD	I/O Port	RIOPORT
8C03	Processor Card	ANYPROC
8C09	Memory Card	ANYMEM
8C0A	I/O Port	CCIN
8C10 to 8C13	Configuration Mismatch	PROCMM
8CA5	Configuration Mismatch	NEXTLVL
	First, check the locations section for the system on which you are working for base system components and processor and memory configuration rules.	
	If that does not correct the problem, replace the Network Interface Controller. See the locations section for the model on which you are working for further information.	
	If the problem is not corrected, contact your next level of support.	
8CA6	Invalid memory configuration	NOMSUSE
8CA9	Invalid memory configuration	MEMCFG
8D00 to 8D0F	Processor Cache Card	CCIN
8EA0 to 8EA2	Code Error	PROCODE

Reference Code	Description	Failing Item
8EA4	Contact your next level of support	NEXTLVL
	If word 3 starts with 9250 and word 6 is A30A0000 then do the following:	
	1. Change the ipl type to "fast boot"	
	2. Change the mode to MANUAL (you only need to do this once)	
	3. ReIPL the system	
	4. Replace the FRU indicate by the PRD error (word 3 is 7xxxxxx)	
	5. Change the ipl type to "slow boot"	
	6. ReIPL the system.	
	<ol> <li>If there is an error like the one that sent you here, then repeat step 1 to step 6 (skip step 2) until all FRUs has been replaced.</li> </ol>	
8EAF	Code Error	PROCODE
8EB0	I/O Port	JTPORT
8EB1 to 8EBC	I/O Port	PRCLINE
8EBF	Contact your next level of support	REDH
8EE1 to 8EE2	Code Error	PROCODE
8EE5	Contact your next level of support	NEXTLVL PROCODE
C001	Clock Card	CCIN
C002	Processor Backplane	CCIN
C003 to C006	Processor Card	CCIN
C007	Processor Cache Card	CCIN
C00A to C00D	Network Interface Controller	CCIN
	If this error occurs at IPL time, clean the cable connections (if optical), then reseat the cables. If that does not correct the problem, replace the cable prior to continuing with the FRU list.	
C00E to C00F	Processor Configuration Card	CCIN
C010 to C01F, C020 to C027, C100 to C101, C110 to C111, C120 to C121	Memory Card	ANYMEM
CA03 to CA06	Contact your next level of support	NEXTLVL
CB00 to CB03, CB10 to CB17, CB20 to CB27, CB30 to CB37	I/O Port	RIOPORT
CBE0	I/O Port	RIOPORT
	See the Locations section for the model on which you are working. The HSL I/O Bridge card in the base I/O tower may have failed.	
CBF0 to CBFD	I/O Port	RIOPORT
CC03	Processor Card	ANYPROC
CC09	Memory Card	ANYMEM
CC0A	I/O Port	CCIN
CC10 to CC13	Configuration Mismatch	PROCMM

Reference Code	Description	Failing Item
CCA5	Configuration Mismatch	NEXTLVL
	First, check the locations section for the system on which you are working for base system components and processor and memory configuration rules.	
	If that does not correct the problem, replace the Network Interface Controller. See the locations section for the model on which you are working for further information.	
	If the problem is not corrected, contact your next level of support.	
CCA6	Invalid memory configuration	NOMSUSE
CCA9	Invalid memory configuration	MEMCFG
CD00 to CD0F	Processor Cache Card	CCIN
CEA0 to CEA2	Code Error	PROCODE
CEA4	Contact your next level of support	NEXTLVL
	If word 3 starts with 9250 and word 6 is A30A0000 then do the following:	
	1. Change the ipl type to "fast boot"	
	2. Change the mode to MANUAL (you only need to do this once)	
	3. ReIPL the system	
	4. Replace the FRU indicate by the PRD error (word 3 is 7xxxxxx)	
	5. Change the ipl type to "slow boot"	
	<ul><li>6. ReIPL the system.</li><li>7. If there is an error like the one that sent you here, then repeat step 1 to step 6 (skip step 2) until all FRUs has been replaced.</li></ul>	
CEAF	Code Error	PROCODE
CEB0	I/O Port	JTPORT
CEB1 to CEBC	I/O Port	PRCLINE
CEBF	Contact your next level of support	REDH
CEE1 to CEE2	Code Error	PROCODE
CEE5	Contact your next level of support	NEXTLVL PROCODE

## (B437) System processor reference codes

For use by authorized service providers.

The system processor detected a failure.

Note: This procedure applies only to system Models 830, and SB2.

Collect data from Functions 11, 12, and 13 of the system panel, or words 1 through 9 from the Main Store Dump (MSD) screen. This SRC, beginning with "**B4**", may contain up to five FRUs. Eight characters of this data represent a single FRU. The FRU characters have two parts: a unit reference code, and a type number. The location of this data is shown below:

PANEL FUNC 11:B4xx<br/>RC02RC03RC01TP01<br/>RC04RC05PANEL FUNC 12:DATA0012DATA0013

#### TP02TP03 TP04TP05

PANEL FUNC 13:	DATA0016	DATA0017
	DATA0018	DATA0019

The FRU information for FRU 1 would be RC01 and TP01, for FRU 2 would be RC02 and TP02, etc.

Characters	Description / Meaning	Length		
RC01	FRU 1 - Ref Code	4 Characters		
TP01	FRU 1 - Type	4 Characters		
RC02	FRU 2 - Ref Code	4 Characters		
TP02	FRU 2 - Type	4 Characters		
RC03, TP03, RC04, TP04, RC05, TP05 same as above.				
DATA012, DATA013, DATA016, DATA017, DATA018, DATA019	Miscellaneous Data - Not applicable, but may be needed for your next level of support.	8 Characters		

The example below shows relevant data for three FRUs: RC01=4300, TP01=245C, RC02=8200, TP02=2881, RC03=8600, TP03=2732, the remaining values are zeroes.

 
 PANEL FUNC 11:
 B437\_ 82008600
 4300245C 00000000

 PANEL FUNC 12:
 XXXXXXXX 28812732
 XXXXXXXX 00000000

Characters	Description / Meaning	Length
4300	FRU 1 - Ref Code = 4300	4 Characters
245C	FRU 1 - Type = 245C	4 Characters
8200	FRU 2 - Ref Code = 8200	4 Characters
2881	FRU 2 - Type = 2881	4 Characters
8600	FRU 3 - Ref Code = 8600	4 Characters
2732	FRU 3 - Type = 2732	4 Characters

Below is the information as shown in a MSD SCREEN:

1 - B4xx\_RC01TP01RC02RC03RC04RC05 2 - DATA0012 3 - DATA0013 4 - TP02TP03 5 - TP04TP05 . . . 9 - DATA0019

Each reference code has an associated Failing Item, given in the table below. Here the failing item is a Symbolic FRU. When you use the reference code and description when following the procedure described in the Symbolic FRU documentation, you should end up with a hardware FRU, code update, or directions to call your next level of support.

### B437

Each reference code also has an associated Priority Code. The first digit of the reference code in the table below gives the priority.

- Mandatory priority reference codes start with either a 4, 5, or 7.
- High priority reference codes start with either a 8, 9, or B.
- Low priority reference codes start with either a C, D, or F.

You should replace all mandatory failing items before the next IPL. A FRU with a high priority has a high probability of resolving the problem. Replace high priority failing items in order, one at a time with an IPL in between. A FRU with a low priority has a low probability of resolving the problem. Replace low priority failing items after replacement of mandatory and high priority items.

For more on the Failing Item column entries, see Table 2. System processor failing items details — Models 830 & SB2, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4001	System Card(s) or BackPlane	CCIN
4003	System Card(s) or BackPlane	ANYPROC
4004 to 4005	System Sub-Card(s)	CTLPNCD
4009	System Card(s) or BackPlane	ANYMEM
40A0	Service processor Licensed Internal Code	AJDGP01
40A1	Licensed Internal Code error	AJDG301
40A2	Service processor Licensed Internal Code	AJDGP01
40A4	Call your next level of support for assistance	NEXTLVL
40A6	Main storage failure	NOMSUSE
40E1	Service processor Licensed Internal Code	AJDGP01
4200	System Card(s) or BackPlane	CCIN
4201 to 4208, 420D to 420F, 4211 to 4218, 421D to 421F, 4221 to 4228, 422D to 422F, 4231 to 4238, 423D to 423F	System Sub-Card(s)	CCIN
42FF	System Sub-Card(s)	ANYMEMX
4300, 4400, 4500	System Card(s) or BackPlane	CCIN
4501 to 4508, 450D to 450F, 4511 to 4518, 451D to 451F, 4521 to 4528, 452D to 452F, 4531 to 4538, 453D to 453F	System Sub-Card(s)	CCIN
45FF	System Sub-Card(s)	ANYMEMX
4600 to 4601	System Card(s) or BackPlane	CCIN
7101 to 7108, 7140 to 7141	System bus error	RIOPORT
7201, 7280	Bus expansion card	MUMIOCD

Table 1. (B437) System processor reference codes

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7281 to 7283	System bus error	RIOPORT
7301	Bus expansion card	FI00015
7302 to 7305	Optical link on Bus Expansion Adapter card failed	FI00017
7306	Bus expansion card	FI00015
7307 to 730A	Optical link on Bus Expansion Adapter card failed	FI00017
730B	Bus expansion card	FI00015
730C to 730F	Optical link on Bus Expansion Adapter card failed	FI00017
73FF	Bus expansion card	FI00015
7401	System Card(s) or BackPlane	FI00017
7402	Bus expansion card	FI00017
7404 to 7406	Optical link on Bus Expansion Adapter card failed	FI00017
7408	Bus expansion card	FI00017
7409 to 740D	Optical link on Bus Expansion Adapter card failed	FI00017
3001	System Card(s) or BackPlane	CCIN
8003	System Card(s) or BackPlane	ANYPROC
8004 to 8005	System Sub-Card(s)	CTLPNCD
3009	System Card(s) or BackPlane	ANYMEM
30A0	Service processor Licensed Internal Code	AJDGP01
30A1	Licensed Internal Code error	AJDG301
30A2	Service processor Licensed Internal Code	AJDGP01
80A4	Call your next level of support for assistance	NEXTLVL
30A6	Main storage failure	NOMSUSE
30E1	Service processor Licensed Internal Code	AJDGP01
3200	System Card(s) or BackPlane	CCIN
8201 to 8208, 820D to 820F, 8211 to 8218, 821D to 821F, 8221 to 8228, 822D to 822F, 8231 to 8238, 823D to 823F	System Sub-Card(s)	CCIN
82FF	System Sub-Card(s)	ANYMEMX
3300, 8400, 8500	System Card(s) or BackPlane	CCIN
8501 to 8508, 850D to 850F, 8511 to 8518, 851D to 851F, 8521 to 8528, 852D to 852F, 8531 to 8538, 853D to 853F	System Sub-Card(s)	CCIN
85FF	System Sub-Card(s)	ANYMEMX
8600 to 8601	System Card(s) or BackPlane	CCIN
B101 to B108, B140 to B141		
B201, B280	Bus expansion card	MUMIOCD

# B437

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
B281 to B283	System bus error	RIOPORT
B301	Bus expansion card	FI00015
B302 to B305	Optical link on Bus Expansion Adapter card failed	FI00017
B306	Bus expansion card	FI00015
B307 to B30A	Optical link on Bus Expansion Adapter card failed	FI00017
B30B	Bus expansion card	FI00015
B30C to B30F	Optical link on Bus Expansion Adapter card failed	FI00017
B3FF	Bus expansion card	FI00015
B401	System Card(s) or BackPlane	FI00017
B402	Bus expansion card	FI00017
B404 to B406	Optical link on Bus Expansion Adapter card failed	FI00017
B408	Bus expansion card	FI00017
B409 to B40D	Optical link on Bus Expansion Adapter card failed	FI00017
C001	System Card(s) or BackPlane	CCIN
C003	System Card(s) or BackPlane	ANYPROC
C004 to C005	System Sub-Card(s)	CTLPNCD
C009	System Card(s) or BackPlane	ANYMEM
C0A0	Service processor Licensed Internal Code	AJDGP01
C0A1	Licensed Internal Code error	AJDG301
C0A2	Service processor Licensed Internal Code	AJDGP01
C0A4	Call your next level of support for assistance NEXT	
C0A6	Main storage failure NG	
C0E1	Service processor Licensed Internal Code AJDGF	
C200	System Card(s) or BackPlane	CCIN
C201 to C208, C20D to C20F, C211 to C218, C21D to C21F, C221 to C228, C22D to C22F, C231 to C238, C23D to C23F	System Sub-Card(s)	CCIN
C2FF	System Sub-Card(s)	ANYMEMX
C300, C400, C500	System Card(s) or BackPlane	CCIN
C501 to C508, C50D to C50F, C511 to C518, C51D to C51F, C521 to C528, C52D to C52F, C531 to C538, C53D to C53F	System Sub-Card(s)	CCIN
C5FF	System Sub-Card(s)	ANYMEMX
C600 to C601	System Card(s) or BackPlane	CCIN

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
F101 to F108, F140 to F141	System bus error	RIOPORT
F201, F280	Bus expansion card	MUMIOCD
F281 to F283	System bus error	RIOPORT
F301	Bus expansion card	FI00015
F302 to F305	Optical link on Bus Expansion Adapter card failed	FI00017
F306	Bus expansion card	FI00015
F307 to F30A	Optical link on Bus Expansion Adapter card failed	FI00017
F30B	Bus expansion card	FI00015
F30C to F30F	Optical link on Bus Expansion Adapter card failed	FI00017
F3FF	Bus expansion card	FI00015
F401	System Card(s) or BackPlane	FI00017
F402	Bus expansion card	FI00017
F404 to F406	Optical link on Bus Expansion Adapter card failed	FI00017
F408	Bus expansion card	FI00017
F409 to F40D	Optical link on Bus Expansion Adapter card failed	FI00017

Table 2. System processor failing items details — Models 830 & SB2

Failing Item	Description	Document Description
AJDG301	Slic Code	Service Functions; APAR or LICTR
AJDGP01	Service Processor Code	Service Functions; APAR or LICTR
ANYMEM	Main Storage Card - Location Unknown	Problem Analysis; Symbolic FRU Isolation
ANYMEMX	Card	Problem Analysis; Symbolic FRU Isolation
ANYPROC	Processor Unknown	Problem Analysis; Symbolic FRU Isolation
CCIN	Card	Problem Analysis; Symbolic FRU Isolation
CCIN	System Backplane	Problem Analysis; Symbolic FRU Isolation
CTLPNCD	Control Panel Card	Problem Analysis; Symbolic FRU Isolation
MUMIOCD	MUM IO CARD TO CEC	Problem Analysis; Symbolic FRU Isolation
NEXTLVL	Contact your next level of support	Problem Analysis; Symbolic FRU Isolation
NOMSUSE	No usable main storage	Problem Analysis; Symbolic FRU Isolation
RIOPORT	MUM RIO IO PORT	Problem Analysis; Symbolic FRU Isolation

# (B467) System processor reference codes

For use by authorized service providers.

The system processor detected a failure.

Note: This procedure applies only to system Models 840 and SB3.

# B467

Collect data from Functions 11, 12, and 13 of the system panel, or words 1 through 9 from the Main Store Dump (MSD) screen. This SRC, beginning with "B4", may contain up to five FRUs. Eight characters of this data represent a single FRU. The FRU characters have two parts: a unit reference code, and a type number. The location of this data is shown below:

PANEL FUNC 11:	B4xx RC02RC03	RC01TP01 RC04RC05
PANEL FUNC 12:	DATA0012 <b>TP02TP03</b>	DATA0013 <b>TP04TP05</b>
PANEL FUNC 13:	DATA0016 DATA0018	DATA0017 DATA0019

The FRU information for FRU 1 would be RC01 and TP01, for FRU 2 would be RC02 and TP02, etc.

Characters	Description / Meaning	Length	
RC01	FRU 1 - Ref Code	4 Characters	
TP01	FRU 1 - Type	4 Characters	
RC02	FRU 2 - Ref Code	4 Characters	
TP02	FRU 2 - Type	4 Characters	
RC03, TP03, RC04, TP04, RC05, TP05 same as above.			
DATA012, DATA013, DATA016, DATA017, DATA018, DATA019	Miscellaneous Data - Not applicable, but may be needed for your next level of support.	8 Characters	

The example below shows relevant data for three FRUs: RC01=5200, TP01=245E, RC02=8100, TP02=3197, RC03=9300, TP03=25AA, the remaining values are zeroes.

PANEL I	FUNC	11:	B467 <b>81009300</b>	5200245E 00000000
PANEL I	FUNC	12:	xxxxxxxx 319725AA	xxxxxxxx 00000000
PANEL I	FUNC	13:	xxxxxxxx xxxxxxxx	xxxxxxxx xxxxxxxx

Characters	Description / Meaning	Length
5200	FRU 1 - Ref Code = 5200	4 Characters
245E	FRU 1 - Type = 245E	4 Characters
8100	FRU 2 - Ref Code = 8100	4 Characters
3197	FRU 2 - Type = 3197	4 Characters
9300	FRU 3 - Ref Code = 9300	4 Characters
25AA	FRU 3 - Type = 25AA	4 Characters

Below is the information as shown in a MSD SCREEN:

#### 1 - B4xx RC01TP01RC02RC03RC04RC05

- 2 DATA0012
- 3 DATA0013
- 4 **TP02TP03** 5 **TP04TP05**

9 - DATA0019

The FRU information for FRU 1 would be **FI1A** and **FI1B** or for FRU 2 it would be **FI2A** and **FI2B**, and so forth.

Each reference code has an associated Failing Item, given in the table below. Here the failing item is a Symbolic FRU. When you use the reference code and description when following the procedure described in the Symbolic FRU documentation, you should end up with a hardware FRU, code update, or directions to call your next level of support.

Each reference code also has an associated Priority Code. The first digit of the reference code in the table below gives the priority.

- Mandatory priority reference codes start with either a 4, 5, or 7.
- High priority reference codes start with either a 8, 9, or B.
- Low priority reference codes start with either a C, D, or F.

You should replace all mandatory failing items before the next IPL. A FRU with a high priority has a high probability of resolving the problem. Replace high priority failing items in order, one at a time with an IPL in between. A FRU with a low priority has a low probability of resolving the problem. Replace low priority failing items after replacement of mandatory and high priority items.

For more on the Failing Item column entries, see Table 2. System processor failing items details — Models 840 & SB3, which follows the reference code table below.

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
4001	System Card(s) or BackPlane	CCIN
4002	Control panel	CTLPNL
4003	System Card(s) or BackPlane	ANYPROC
4004 to 4005	System Sub-Card(s)	CTLPNCD
4009	System Card(s) or BackPlane	ANYMEM
400A to 400D	System Card(s) or BackPlane	CCIN
40A0	Service processor Licensed Internal Code	AJDGP01
40A1	Licensed Internal Code error	AJDG301
40A2	Service processor Licensed Internal Code	AJDGP01
40A4	Call your next level of support for assistance	NEXTLVL
40A6	Main storage failure	NOMSUSE
40E1	Service processor Licensed Internal Code	AJDGP01
4100, 4200, 4300, 4500, 4600, 4800, 4900, 4A00, 4800, 4C00, 4D00, 4E00, 4F00, 5000, 5100, 5200, 5300, 5400, 5500, 5600, 5700, 5800	System Card(s) or BackPlane	CCIN
7101 to 710F, 7110, 7140 to 7143	System bus error	RIOPORT

Table 1. (B467) System processor reference codes

# B467

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
7201, 7280	Bus expansion card	MUMIOCD
7281 to 7283	System bus error	RIOPORT
7301	Bus expansion card	FI00015
7302 to 7305	Optical link on Bus Expansion Adapter card failed	FI00017
7306	Bus expansion card	FI00015
7307 to 730A	Optical link on Bus Expansion Adapter card failed	FI00017
730B	Bus expansion card	FI00015
730C to 730F	Optical link on Bus Expansion Adapter card failed	FI00017
73FF	Optical link on Bus Expansion Adapter card failed	FI00015
8001	System Card(s) or BackPlane	CCIN
8002	Control panel	CTLPNL
8003	System Card(s) or BackPlane	ANYPROC
8004 to 8005	System Sub-Card(s)	CTLPNCD
8009	System Card(s) or BackPlane	ANYMEM
800A to 800D	System Card(s) or BackPlane	CCIN
80A0	Service processor Licensed Internal Code	AJDGP01
80A1	Licensed Internal Code error	AJDG301
80A2	Service processor Licensed Internal Code	AJDGP01
80A4	Call your next level of support for assistance	NEXTLVL
80A6	Main storage failure	NOMSUSE
80E1	Service processor Licensed Internal Code	AJDGP01
8100, 8200, 8300, 8500, 8600, 8800, 8900, 8A00, 8B00, 8C00, 8D00, 8E00, 8F00, 9000, 9100, 9200, 9300, 9400, 9500, 9600, 9700, 9800	System Card(s) or BackPlane	CCIN
B101 to B10F, B110, B140 to B143	System bus error	RIOPORT
B201, B280	Bus expansion card	MUMIOCD
B281 to B283	System bus error	RIOPORT
B301	Bus expansion card	FI00015
B302 to B305	Optical link on Bus Expansion Adapter card failed	FI00017
B306	Bus expansion card	FI00015
B307 to B30A	Optical link on Bus Expansion Adapter card failed	FI00017
B30B	Bus expansion card	FI00015
B30C to B30F	Optical link on Bus Expansion Adapter card failed	FI00017
B3FF	Bus expansion card	FI00015
C001	System Card(s) or BackPlane	CCIN
C002	Control panel	CTLPNL
	System Card(s) or BackPlane	ANYPROC

**324** iSeries: iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

Reference Code	Description/Action Perform all actions before exchanging Failing Items	Failing Item
C004 to C005	System Sub-Card(s)	CTLPNCD
C009	System Card(s) or BackPlane	ANYMEM
C00A to C00D	System Card(s) or BackPlane	CCIN
C0A0	Service processor Licensed Internal Code	AJDGP01
C0A1	Licensed Internal Code error	AJDG301
C0A2	Service processor Licensed Internal Code	AJDGP01
C0A4	Call your next level of support for assistance	NEXTLVL
C0A6	Main storage failure	NOMSUSE
C0E1	Service processor Licensed Internal Code	AJDGP01
C100, C200, C300, C500, C600, C800, C900, CA00, CB00, CC00, CD00, CE00, CF00, D000, D100, D200, D300, D400, D500, D600, D700, D800	System Card(s) or BackPlane	CCIN
F101 to F10F, F110, F140 to F143	System bus error	RIOPORT
F201, F280	Bus expansion card	MUMIOCD
F281 to F283	System bus error	RIOPORT
F301	Bus expansion card	FI00015
F302 to F305	Optical link on Bus Expansion Adapter card failed	FI00017
F306	Bus expansion card	FI00015
F307 to F30A	Optical link on Bus Expansion Adapter card failed	FI00017
F30B	Bus expansion card	FI00015
F30C to F30F	Optical link on Bus Expansion Adapter card failed	FI00017
F3FF	Bus expansion card	FI00015

# Table 2. System processor failing items details — Models 840 & SB3

Failing Item	Description	Document Description
AJDG301	Slic Code	Service Functions; APAR or LICTR
AJDGP01	Service Processor Code	Service Functions; APAR or LICTR
ANYMEM	Main Storage Card - Location Unknown	Problem Analysis; Symbolic FRU Isolation
ANYPROC	Processor Unknown	Problem Analysis; Symbolic FRU Isolation
CCIN	System Backplane	Problem Analysis; Symbolic FRU Isolation
CTLPNCD	Control Panel Card	Problem Analysis; Symbolic FRU Isolation
MUMIOCD	MUM IO CARD TO CEC	Problem Analysis; Symbolic FRU Isolation
NEXTLVL	Contact your next level of support	Problem Analysis; Symbolic FRU Isolation
NOMSUSE	No usable main storage	Problem Analysis; Symbolic FRU Isolation
RIOPORT	MUM RIO IO PORT	Problem Analysis; Symbolic FRU Isolation

# (B4FF) System processor reference codes

For use by authorized service providers.

Follow the instructions for the model you are working on:

- Models 270, 820, 830, 840, SB2, or SB3
- Models 800, 810, 825, 870, or 890

#### (B4FF) System processor reference codes — Instructions for Models 270, 820, 830, 840, SB2, or SB3

A major system problem has occurred.

The reference code is the first eight characters of the display data for panel function 11.

- 1. Is the reference code B4FF 0003?
  - Yes: The System cannot find any processors. If you are working on a Model 830 or Model 840, the PCI drawer may be the failing item. See the Symbolic FRU TWRPLNR. If that fails to correct the problem, exchange the J-Tag cable. See the Power and signal cables table for the system on which you are working. If that fails to correct the problem, any processor may be the failing item. Refer to Symbolic FRU ANYPROC, for the procedure to determine processor location and part information.

If this does not fix the problem, contact your next level of support.

This ends the procedure.

- No: Continue with the next step.
- 2. Is the reference code B4FF 00B7?
  - Yes: The system did not pass a check for a minimum amount of hardware present in order for the IPL to continue. There may be a hardware failure causing the problem. Please choose from the following actions:
    - For Models 270 and 820: Replace the System Unit Backplane (see Locations Model 270 or Locations – Model 820).
    - For Models 830 and SB2: Replace the Bridge card in C08 of the FC 9074 Base I/O Tower (see Locations – Model 830).
    - For Models 840 and SB3: Replace the Bridge card in C08 of the FC 9079 Base I/O Tower (see Locations – Model 840.

If the problem is not resolved after replacing the part listed above, contact your next level of support. They will need the step code in word 13 of the SRC to proceed.

- No: Continue with the next step.
- 3. Is the reference code B4FF 80A0?
  - Yes: There was a failed attempt to call the SRC function instruction start or instruction stop. This may be caused by a code problem. Replace the Service Processor. Use the following list to display the appropriate location table, which contains location information and a link to the remove and replace instructions:
    - For Model 270: See Locations Model 270
    - For Model 820: See Locations Model 820
    - For Models 830 and SB2: See Locations Model 830
    - For Models 840 and SB3: See Locations Model 840

If the problem is not corrected, contact your next level of support.

- No: Continue with the next step.
- 4. Choose one of the following:
  - If you are working on a system Model 270 or 820, then continue with the next step.
  - If you are working on a system Model 830, 840, SB2, or SB3, then go to step 6 of this procedure.

- 5. Is the reference code B4FF 00B0 or B4FF 00B1?
  - No: Contact your next level of support.
    - This ends the procedure.
  - Yes: If the reference code is B4FF00B1, then the System Unit Backplane may be the failing item. If the reference code is B4FF00B0, then the System Unit Backplane may be the failing item, or the failure may be caused by the Licensed Internal code. For either reference code, perform the following:

**Note:** If the reference code B4FF 00B1 occurred after a power outage, try removing incoming power, reapplying it, and then retrying the IPL.

- **a**. Before exchanging any parts, verify that all connections to the System Unit Backplane are secure.
- b. Exchange the System Unit Backplane in position MB1.
  - For Model 270: To determine the location, CCIN, part number, and remove and replace procedure for the System Unit Backplane, locate card position MB1 in the FRU Locations and Failing Components table for the processor feature code of the Model 270 you are working on. Use Locations -- Model 270 and the processor feature code to determine which Model 270 locations diagram and FRU Locations and Failing Components table to use.
  - For Model 820: To determine the location of the System Unit Backplane, see Model 820 locations. To determine the CCIN, part number, and remove and replace procedure for the System Unit Backplane, locate card position MB1 and FRU name "System Unit Backplane" in Model 820.

If this does not fix the problem, contact your next level of support.

#### This ends the procedure.

- 6. Is the reference code B4FF 00B0 or B4FF 00B1?
  - Yes: Continue with the next step.
  - No: Go to step 8 of this procedure.
- 7. If the SRC B4FF 00B1 occurred after a power outage, remove the incoming power, wait 30 seconds, reapply the power and retry the IPL. If the system IPLs without the error, the procedure is complete. If the reference code is B4FF00B1, then the HSL I/O bridge card may be the failing item. If the reference code is B4FF00B0, then the HSL I/O bridge Card may be the failing item, or the failure may be caused by the Licensed Internal code. For either reference code, exchange HSL I/O bridge card in location C08. To determine the CCIN, part number, and remove and replace procedure, locate card position C08 and FRU name "HSL I/O bridge card" from the following:
  - For Models 830 and SB2, see Locations -- Models 830, SB2 System Unit with FC 9074 Base I/O Tower.
  - For Models 840 and SB3, see Locations -- Models 840, SB3 System Unit with Processor Tower and FC 9079 Base I/O Tower.

Did this fix the problem?

- Yes: This ends the procedure.
- No: Exchange the Tower Card in position CB1. To determine CCIN, part number, and remove and replace procedure, locate card position CB1 and FRU name " Tower Card" from the following:
  - For Model 830, SB2 see Locations -- Models 830, SB2 System Unit with FC 9074 Base I/O Tower.
  - For Model 840, SB3 see Locations -- Models 840, SB3 System Unit with Processor Tower and FC 9079 Base I/O Tower.

If the problem still has not been fixed, contact your next level of support.

#### This ends the procedure.

- 8. Is the reference code B4FF00B3?
  - No: Contact your next level of support.

# B4FF

## This ends the procedure.

- Yes: Continue with the next step.
- 9. Choose one of the following:
  - The system cannot find any processors. If you are working on a Model 830 or a Model 840, the PCI drawer may be the failing item. See Symbolic FRU TWRPLNR . If that fails to correct the problem, exchange the J-Tag cable. See the Power and Signal cables table for the system on which you are working. If that fails to correct the problem, any processor may be the failing item. Refer to Symbolic FRU ANYPROC for the procedure to determine processor location and part information.
  - For system Models 830 and SB2: The Clock card in location M06A may be the failing item. To determine the CCIN, part number, and remove and replace procedure, locate card position M06A and FRU name "Clock Card" in Locations -- Models 830, SB2 System Unit with FC 9074 Base I/O Tower. Exchange the failing item.

Did this fix the problem?

- Yes: This ends the procedure.
- No: Exchange the network interface controller (NIC) card. To determine the CCIN, part number, and remove and replace procedure, locate card position M06 and FRU name "network interface controller (NIC) card" in Locations -- Models 830, SB2 System Unit with FC 9074 Base I/O Tower.

If the problem still is not fixed, contact your next level of support.

# This ends the procedure.

• For system Models 840 and SB3: The network interface controller (NIC) card in location M17, or the clock card in location M19 may be the failing item. To determine the CCIN, part number, and remove and replace procedure, locate the card position and FRU name in Locations -- Models 840, SB3 System Unit with Processor Tower and FC 9079 Base I/O Tower. Exchange the failing item.

If this did not fix the problem, contact your next level of support.

## This ends the procedure.

## (B4FF) System processor reference codes — Instructions for Models 800, 810, 825, 870, and 890

An SRC starting with B4FF indicates the system failed to complete an IPL because of a processor related problem. Find the full SRC from the list below and take the indicated action to correct the problem.

**B4FF00B0 or B4FF00B1**: Indicates a problem with either the Service Processor code or the load source RIO Bridge.

- 1. If the SRC B4FF 00B1 occurred after a power outage, remove the incoming power, wait 30 seconds, reapply the power and retry IPL. If the system IPLs without the error, the procedure is complete.
- 2. Replace the Service Processor. Use the following list to display the appropriate location table, which contains location information and a link to the remove and replace instructions:
  - For Models 800 and 810: See Locations Models 800 and 810.
  - For Model 825: See Locations Model 825.
  - For Models 870 and 890: See Locations Models 870 and 890.

If the problem is not corrected, continue with the next step.

- **3**. Replace the load source RIO Bridge.
  - For **Models 800 and 810**: Replace the System Unit Backplane. See Locations Models 800 and 810 for location information, and a link to the remove and replace instructions.
  - For **Model 825**: Replace the System Unit Backplane. See Locations Model 825 for location information, and a link to the remove and replace instructions.
  - For **Models 870 and 890**: Replace the Tower card in the base I/O Unit. See Locations Models 870 and 890.

B4FF00B3: Indicates a problem with a processor or Service Processor code.

- 1. Replace the Service Processor. Use the following list to display the appropriate location table, which contains location information and a link to the remove and replace instructions:
  - For Models 800 and 810: See Locations Models 800 and 810.
  - For Model 825: See Locations Model 825.
  - For Models 870 and 890: See Locations Models 870 and 890.

If the problem is not corrected, continue with the next step.

- 2. Follow the instructions for the Model you are working on.
  - For **Models 800 and 810**: Replace the System unit backplane. See Locations Models 800 and 810 for location information, and a link to the remove and replace instructions.
  - For **Model 825**: Replace the MCM module. See Locations Model 825 for location information, and a link to the remove and replace instructions.
  - For **Models 870 and 890**: Replace the MCM module in location M21. See Locations Models 870 and 890 for location information, and a link to the remove and replace instructions.

B4FF00B4: Indicates a problem with a processor or Service Processor code.

- 1. Replace the Service Processor. Use the following list to display the appropriate location table, which contains location information and a link to the remove and replace instructions:
  - For Models 800 and 810: See Locations Models 800 and 810.
  - For Model 825: See Locations Model 825.
  - For Models 870 and 890: See Locations Models 870 and 890.

If the problem is not corrected, continue with the next step.

- 2. Follow the instructions for the Model you are working on.
  - For **Models 800 and 810**: Replace the System unit backplane. See Locations Models 800 and 810 for location information, and a link to the remove and replace instructions.
  - For **Model 825**: Replace the Processor in location C13. See Locations Model 825 for location information, and a link to the remove and replace instructions.
  - For **Models 870 and 890**: Replace the MCM module in location M11. See Locations Models 870 and 890.

B4FF00B5: Indicates a problem with a processor or Service Processor code.

- 1. Replace the Service Processor. Use the following list to display the appropriate location table, which contains location information and a link to the remove and replace instructions:
  - For Models 800 and 810: See Locations Models 800 and 810.
  - For Model 825: See Locations Model 825.
  - For Models 870 and 890: See Locations Models 870 and 890.

If the problem is not corrected, continue with the next step.

- 2. Follow the instructions for the Model you are working on.
  - For **Models 800 and 810**: Replace the System unit backplane. See Locations Models 800 and 810 for location information, and a link to the remove and replace instructions.
  - For **Model 825**: Replace the Processor in location C13. See Locations Model 825 for location information, and a link to the remove and replace instructions.
  - For **Models 870 and 890**: Replace the MCM module in location M16. See Locations Models 870 and 890 for location information, and the link to the remove and replace instructions.

B4FF00B6: Indicates a problem with a processor or Service Processor code.

1. Replace the Service Processor. Use the following list to display the appropriate location table, which contains location information and a link to the remove and replace instructions:

# B4FF

- For Models 800 and 810: See Locations Models 800 and 810.
- For Models 870 and 890: See Locations Models 870 and 890.
- 2. If the problem is not corrected, follow the instructions for the Model you are working on.
  - For **Models 800 and 810**: Replace the System unit backplane. See Locations Models 800 and 810 for location information, and a link to the remove and replace instructions.
  - For **Models 870 and 890**: Replace the MCM module in location M14. See Locations Models 870 and 890 for location information, and a link to the remove and replace instructions.

**B4FF00B7**: The system did not pass a check for a minimum hardware configuration present in order for the IPL to continue. The group of chips failed to meet the requirement are given in word 13 of the SRC. Check to see if the PCI cards are properly seated in the card slots, and that any cables are cleaned and properly connected to the cards. Then re-IPL the system. If that does not correct the problem, replace the Service Processor. See the Locations and addresses page for the model you are working on. If that does not correct the problem, call your next level of support.

**B4FF0EAF**: Indicates a problem with Service Processor code. Replace the Service Processor. See the Locations and addresses page for the model you are working on. If that does not correct the problem, contact your next level of support.

# (C1xx) Service processor IPL status reference codes

This is a normal reference code during the IPL of the system. You might suspect that the IPL is not advancing correctly when the 6 rightmost characters do not change for 2 minutes. The IPL can take longer with more I/O units and main storage. Perform the "IPL Status SRCs" procedure in iSeries Service Functions if you suspect a problem.

If, after performing that procedure, there is still a problem, ask your next level of support for assistance.

This ends the procedure.

# (D1xx 3xxx) Service processor main storage dump status reference code

This is a normal reference code showing the status of the system when performing a main storage dump. You might suspect that the system is not operating correctly when the rightmost characters do not change for 2 minutes.

**Note:** It takes approximately 1 minute to dump each 20MB of main storage. For more information about main storage dumps and about these SRCs in general, see "Working with Storage Dumps" or "General Status SRCs" in iSeries Service Functions.

# Chapter 2. List of system reference codes

For use by authorized service providers.

The system reference codes (SRCs) in this list are organized by their first character, with numbers coming before letters. To navigate this list, click the number or letter below that matches the first character of your system reference code (SRC). Then, select your SRC from the list provided. To return to the top of the page, click the number or letter that serves as the heading for the list you are viewing.

For information about using this list, see Chapter 1, "System reference codes," on page 1. If you do not find the SRC that you are looking for in this list, ask your next level of support for assistance.

0 1 2 3 4 5 6 7 8 9 A B C D E F

0
0000
1
1xxx
1750
2
2105
2107
2629
2689
2718
2724
2726
2728
2729
2740
2740 2741
2741 2742
2743
2744
2745
2746
2748
2749
2750
2751
2757
2760
2761
2763
2765

2766
2767
2768
2771
2772
2778
2780
2782
2787
2793
2805
2809
280D
280E
2810
281x
2824
282C
2838
283C
283D
283F
2842
2843
2844
2849
284B
284C
284D
284E
286C
286D
286E
286F
287F
28B9
28BC
28CB
28CC
28CD
3
3490
3494
3570
358x

iSeries: iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)

3590
3592
4
432x
4685
5
506D
506E
5306
5700
5701
5702
5703
5704
5708
571A
571B
571E
571F
574F
5755
575B
(
6
<b>6</b> 6149
-
6149
6149 6279
6149 6279 632x
6149 6279 632x 6330
6149 6279 632x 6330 6331
6149 6279 632x 6330 6331 6333
6149 6279 632x 6330 6331 6333 6336
6149 6279 632x 6330 6331 6333 6336 6337
6149 6279 632x 6330 6331 6333 6336 6336 6337 6381 6382
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6382 6383 6384
6149 6279 632x 6330 6331 6333 6336 6337 6381 6381 6382 6383 6384 6386
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6382 6383 6384 6386 6387
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383 6384 6384 6386 6387 63A0
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383 6384 6384 6386 6387 63A0 6532
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383 6384 6384 6386 6387 6380 6387 63A0 6532 6533
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383 6384 6386 6387 6380 6532 6533 6534
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383 6384 6384 6386 6387 6380 6532 6533 6534 660x
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383 6384 6386 6387 6380 6532 6533 6534 660x 671x
6149 6279 632x 6330 6331 6333 6336 6337 6381 6382 6383 6384 6384 6386 6387 6380 6532 6533 6534 660x

6A59
7
7207
7208
9
9348
9427
Α
A1xx
A6xx
A9xx
В
B003
B006
B070
B075
B1xx
B2xx
B427
B428
B437
B448
B467
B4FF
B6xx
B9xx

С

C1xx

C6xx - For information about this SRC, see IPL Status SRCs in iSeries Service Functions.

C9xx - For information about this SRC, see IPL Status SRCs in iSeries Service Functions.

D

D1xx xxxx - This is a service processor general status SRC. If you suspect a problem, ask your next level of support for assistance. For more information about this SRC, see General Status SRCs in iSeries Service Functions.

D1xx 3xxx

D6xx - For information about this SRC, see General Status SRCs in iSeries Service Functions.

Ε

EE60

F

F000

# **Appendix. Notices**

This information was developed for products and services offered in the U.S.A.

IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing IBM Corporation 500 Columbus Avenue Thornwood, NY 10594-1785 U.S.A.

For license inquiries regarding double-byte (DBCS) information, contact the IBM Intellectual Property Department in your country or send inquiries, in writing, to:

IBM World Trade Asia Corporation Licensing 2-31 Roppongi 3-chome, Minato-ku Tokyo 106, Japan

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law: INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATION "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.

Any references in this information to non-IBM Web sites are provided for convenience only and do not in any manner serve as an endorsement of those Web sites. The materials at those Web sites are not part of the materials for this IBM product and use of those Web sites is at your own risk.

IBM may use or distribute any of the information you supply in any way it believes appropriate without incurring any obligation to you.

Any performance data contained herein was determined in a controlled environment. Therefore, the results obtained in other operating environments may vary significantly. Some measurements may have been made on development-level systems and there is no guarantee that these measurements will be the

same on generally available systems. Furthermore, some measurements may have been estimated through extrapolation. Actual results may vary. Users of this document should verify the applicable data for their specific environment.

Information concerning non-IBM products was obtained from the suppliers of those products, their published announcements or other publicly available sources. IBM has not tested those products and cannot confirm the accuracy of performance, compatibility or any other claims related to non-IBM products. Questions on the capabilities of non-IBM products should be addressed to the suppliers of those products.

The drawings and specifications contained herein shall not be reproduced in whole or in part without the written permission of IBM.

IBM has prepared this publication for use by hardware service representatives in the maintenance or repair of the specific machines indicated. IBM makes no representations that it is suitable for any other purpose.

# Trademarks

The following terms are trademarks of International Business Machines Corporation in the United States, other countries, or both:

Application System/400 AS/400 e (logo) IBM iSeries Netfinity Operating System/400 OS/400 Retain xSeries 400

Other company, product or service names may be trademarks or service marks of others.

# Terms and conditions for downloading and printing publications

Permissions for the use of the publications you have selected for download are granted subject to the following terms and conditions and your indication of acceptance thereof.

**Personal Use:** You may reproduce these Publications for your personal, noncommercial use provided that all proprietary notices are preserved. You may not distribute, display or make derivative works of these Publications, or any portion thereof, without the express consent of IBM.

**Commercial Use:** You may reproduce, distribute and display these Publications solely within your enterprise provided that all proprietary notices are preserved. You may not make derivative works of these Publications, or reproduce, distribute or display these Publications or any portion thereof outside your enterprise, without the express consent of IBM.

Except as expressly granted in this permission, no other permissions, licenses or rights are granted, either express or implied, to the Publications or any information, data, software or other intellectual property contained therein.

IBM reserves the right to withdraw the permissions granted herein whenever, in its discretion, the use of the Publications is detrimental to its interest or, as determined by IBM, the above instructions are not being properly followed.

You may not download, export or re-export this information except in full compliance with all applicable laws and regulations, including all United States export laws and regulations. IBM MAKES NO GUARANTEE ABOUT THE CONTENT OF THESE PUBLICATIONS. THE PUBLICATIONS ARE PROVIDED "AS-IS" AND WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE

All material copyrighted by IBM Corporation.

By downloading or printing a publication from this site, you have indicated your agreement with these terms and conditions.

# **Electronic Emission Notices**

# Federal Communications Commission (FCC) Statement

**Note:** This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case the user will be required to correct the interference at his own expense.

Properly shielded and grounded cables and connectors must be used in order to meet FCC emission limits. IBM is not responsible for any radio or television interference caused by using other than recommended cables and connectors or by unauthorized changes or modifications to this equipment. Unauthorized changes or modifications could void the user's authority to operate the equipment.

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Responsible Party:

International Business Machines Corporation New Orchard Road Armonk, NY 10504

Telephone: 1-919-543-2193

#### Industry Canada Compliance Statement

This Class A digital apparatus meets the requirements of the Canadian Interference-Causing Equipment Regulations.

#### Avis de conformité à la réglementation d'Industrie Canada

Cet appareil numérique de la classe A respecte toutes les exigences du Règlement sur le matériel brouilleur du Canada.

## **European Community Compliance Statement**

This product is in conformity with the protection requirements of EU Council Directive 89/336/EEC on the approximation of the laws of the Member States relating to electromagnetic compatibility. IBM cannot accept responsibility for any failure to satisfy the protection requirements resulting from a non-recommended modification of the product, including the fitting of non-IBM option cards.

#### Australia and New Zealand Class A Statement

**Attention:** This is a Class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

**338** iSeries: iSeries 270, 800, 810, 820, 825, 830, 840, 870, 890, SB2, and SB3 Analyze Hardware Problems (System Reference Codes)



Printed in USA