Item 1

Hot-Swap Fans

Fan Access Cover

Fan Error LED

1 2 3 4 5

NOTE: For optimal cooling performance, do not run the system with the fan access cover removed for an extended period of time. Replace the fan access cover immediately after replacing a fan.

User Information

NOTE: Replaceable parts list is on underside of this cover.

Item 2

ATTENTION:
Lifting the cover release latch will power down the system.

>240VA

For additional service information, see underside of this top cover.

MANUFACTURING NOTES:

1. Graphics shall conform to the Artwork above.
2. Ink colors to match PMS BlackC, PMS 1525C and PMS 108C.
3. Font: Helvetica
4. Refer to label print part number 80Y9925 for manufacturing and material notes.

IBM ®

Art Part number
69Y2313

EC number
N24806N

Date
4/2/10

ID approval
RA

Eng approval
JB

Title Labels, Top Cover Sheet

Must conform to Eng. Spec: 80X2324

Tolerances unless noted: Linear ± 0.3

SI metric

0   mm   25