

maximo®

Release 2.0
May 2006

Maximo Calibration Release Notes

mro software™

make it *all* count

This document and its publication do not constitute or create a contract. MRO Software, Inc. makes no warranties, express or implied, as to the accuracy or completeness of this document or with respect to the related software.

© 2006 MRO Software, Inc. All rights reserved. This document contains confidential and trade secret information of MRO Software, Inc. Use, transfer, disclosure, or copying without MRO Software, Inc.'s express written permission is strictly forbidden.

Patents: United States Patent Nos. 6,324,522 B2, 6,519,588 B1, and Aust. Pat. No. 758001. Multiple foreign patents pending.

U.S. Restricted Rights: If Customer is a government agency, Customer acknowledges and agrees that the Licensed Software is provided with RESTRICTED RIGHTS. Subparagraph (c)(1)(ii) of The Rights in Technical Data and Computer Software clause at 252.227-7013 of the Department of Defense FAR Supplement and FAR clause 52.227-19 entitled Commercial Computer Software Restricted Rights, apply and use, duplication, or disclosure by the Government is subject to restrictions as set forth in this Agreement. The aforementioned restrictions shall prevail over any similar "Rights" provisions under the laws of any country. Contractor/Manufacturer: MRO Software, Inc., 100 Crosby Drive, Bedford, MA 01730.

Trademarks: Maximo® is a registered trademark of MRO Software, Inc. The following table contains a list of MRO Software's trademarks and service marks:

Maximo® Enterprise	Maximo® SLA Manager	Maximo® OCS
Maximo® Enterprise/SP	Maximo® Navigator	Maximo® Mobile Suite
Maximo® Enterprise IT	Maximo® Project Manager	Maximo® Mobile Auditor
Maximo® Asset Center	Maximo® Calibration	Maximo® Mobile Inventory Manager
Maximo® Service Center	Maximo® Enterprise Adapter	Maximo® Mobile Work Manager
Maximo® Discovery	Maximo® Fusion	Maximo® Mobile Calibration
Maximo® Enterprise IT/SP		

IBM® and WebSphere® are registered trademarks of IBM Corporation. WebLogic® is a registered trademark of BEA Systems, Inc. Broadvision® and related marks are registered trademarks or trademarks of Broadvision, Inc. webMethods® is a registered trademark of webMethods, Inc. Snowbound™ and RasterMaster™ are trademarks of Snowbound Software Corporation. Syclo® and Agentry® are registered trademarks of Syclo, LLC.

Other products and brand names are trademarks or registered trademarks of their respective companies.

Third-Party Technology: Certain MRO Software, Inc. products contain technology provided under license from third parties, as noted in the following table:

MRO Software Products	Third-Party Information
Maximo	Portions © 1995-2004 Actuate Corporation. Portions © 2003 BEA Systems, Inc. BEA WebLogic® Server™ provided by BEA Systems, Inc. Portions © 1996-2004 IBM Corporation. IBM® WebSphere® provided by IBM Corporation. Portions © 1996-2005, i-net software GmbH.
All Products	Portions © 1996-2003 Visual Mining, Inc. Visual Mining™ NetCharts Server™ provided by Visual Mining, Inc.
Maximo® Discovery	©1988-2004 Centennial Software Limited. MSDE © Microsoft Corporation.
Maximo Navigator	Portions © 1993-2002 Snowbound Software Corporation. RasterMaster™ Raster imaging technology provided by Snowbound Software Corporation. Portions © 1989-1998 Cimmety Systems, Inc.
Maximo Mobile Suite	Portions © 2002-2003 Syclo LLC.

Open Source: Maximo contains computer software obtained from the public domain, known as "Open Source." A complete listing of all Open Source contained in Maximo may be viewed at <http://www.mro.com/support/opensource>, ownership of which is attributed as follows: Portions © 2005, International Business Machines Corporation and others. Portions © 2002, Steve Souza (admin@jamonapi.com). Portions © 2000 by Jef Poskanzer (jef@acme.com). Portions © 2000-2004 Jason Hunter & Brett McLaughlin. Portions © 2004-2005, The Apache Software Foundation (<http://www.apache.org/>). All Rights Reserved.

Contents

About This Guide	v
Why Read This Guide?	v
Who Should Read This Guide?	v
How to Use This Guide	v
Chapter Contents	v
Related Documentation	vi
Support	vi
Applying Maximo Calibration 2.0 Patch 04	1
Prerequisites	1
Update Process	1
Checklist	1
Detailed Process	2
Applying the Patch	2
Running the Database Scripts	2
Post Installation	2
Patch 04 Fixed Issues	3

About This Guide

This section briefly summarizes this document and how it can help you as a Maximo® user. It also provides information on other MRO Software resources available to you, such as additional documentation and support.

Why Read This Guide?

The guide provides instructions for applying Maximo Calibration Release 2.0 Patch 04. It also includes important information about steps you need to complete both before and after applying the patch.

Who Should Read This Guide?

Anyone planning to apply Maximo Calibration Release 2.0 Patch 04 should read this guide. Applying this patch requires system administrator rights and privileges.

How to Use This Guide

Read this guide in its entirety prior to applying Maximo Calibration Release 2.0 Patch 04. This guide includes important information about steps you need to complete both before and after applying the patch.

Chapter Contents

The following table briefly describes each chapter in this document. Read the chapters in the order they appear and perform the tasks in sequence as written.

Chapter Name	Chapter Contents
About this Guide	This section briefly summarizes this document and how it can help you as a Maximo user.
Applying Maximo Calibration Release 2.0 Patch 04	Describes how to apply Maximo Calibration Release 2.0 Patch 04.

Related Documentation

You can find more information regarding *Maximo Calibration* in the following documents:

Document	Description
<i>Maximo System Administrator's Guide</i>	The guide provides information on setting up and configuring Maximo, including managing the Application Server.
<i>User's Guide—Calibration Addendum</i>	The guide provides information on the calibration specific features of Maximo.

Support

MRO Software, Inc. customers with an active and valid Annual Customer Support Plan (ACSP) maintenance agreement can obtain technical information, including product updates, on the MRO Software Support Online website at <http://support.mro.com>.

Support Online includes technical information on MRO Software products, software downloads and documentation updates. Each product release has a specific Version page that includes specific information on that version including the latest update and documentation availability.

Applying Maximo Calibration 2.0 Patch 04

This chapter describes how to apply Maximo Calibration 2.0 Patch 04.

Prerequisites

You must install this patch on a system where you have already installed:

- ▼ Maximo 5.2 Patch 06 or higher
- ▼ Maximo Calibration 2.0 Patch 03

Update Process

Applying Maximo Calibration 2.0 Patch 04 is a two-part process:

- ▼ Applying the patch
- ▼ Updating the database

Checklist

This checklist provides an overview of the process you should follow to apply Maximo Calibration 2.0 Patch 04. You will find detailed instructions later in this chapter.

-
- | | | |
|-----|---|--|
| [] | 1 | Backup your Maximo Calibration folder and database |
| [] | 2 | Stop the Maximo application server(s)/service(s). |
| [] | 3 | Download the installation executable. |
| [] | 4 | Run the executable to apply the patch |
| [] | 5 | Run the database scripts |
| [] | 6 | Re-build and Deploy the EAR files. |
-

Detailed Process

You can obtain the Maximo Calibration 2.0 Patch 04 software from the Calibration main page on the MRO Software Support Online website.

Applying the Patch

To apply Patch 04, follow these steps:

- 1 Make a backup of your local Maximo Calibration folder and database.
- 2 Shut down your Maximo instance.
- 3 Download the appropriate installation executable, based on your system's platform.
- 4 Run the installation executable. If you have not installed Calibration 2.0 Patch 03, you will get an error message saying the Maximo Calibration Release 2.0 Patch 03 was not found.
- 5 Follow the on-screen instructions to apply the patch.

Running the Database Scripts

The database scripts create and update the database tables necessary for this patch.

To run the database scripts, follow these steps:

- 1 Back up your database, if you have not already done so.
- 2 Connect to the database as the Maximo schema owner (for example: Maximo).
- 3 Run the appropriate database script to create and update the tables:
 - ▼ For Oracle:
<MAXIMO dir>/database/indsol/calibration/oracle/calib2_p04.ora
 - ▼ For SQL Server
<MAXIMO dir>/database/indsol/calibration/sqlserver/
calib2_p04.sql

Post Installation

When you have completed the patch application, you must manually build and deploy the EAR files. For more information, see the *Maximo 5.2 Installation Guide*.

Patch 04 Fixed Issues

This chapter lists the issues corrected in this patch.

Issue	Description
06-10353	Calculating %READING with a MFR output of 0 causes the Tolerance To value to not round off.
06-10966	Issue with the Status Select Value display on the Data Sheet tab in Work Orders (Cal).
06-12628	When values are in decreasing direction, the %SPAN tolerance From/To are 'flipped' and Fail a WO when should be Pass.
74182	Cannot delete a datasheet from Work Order (Cal) when the work order was generated by a PM.
79485	When trying to delete an equipment that has the IS TOOL field selected, getting the error message "Field Equipment # is Read Only". **With Calibration 2.0
83112	When Points for all Functions Shown, duplicating the Data Sheet results in all calibration points displayed with last asset function.
84663	Data Sheets - when you go through WorkFlow and set the status to WAPPR or APPR the user is set to the originating user, not the user who has changed the status.
88754	Incorrect rounding on tolerance limits.
8900	In all applications, the From and To date fields when performing a search always copy the same date.
89839	Values are not deleting on the work order when entering in data on the row.
92155	When the Clipped Limits field is selected on the Data Sheet, the Range Limits are not getting clipped.

Printing History

Edition	Date
1	05/2006

