

IBM System Storage DS4000/DS5000 Drive Enclosure HDD Blanks



In previous versions of the HDD carrier blank (FRU PN 42D3315), when the blank was inserted it latched and would sit flush with the adjacent blanks as shown in Figure 1. In the newest version of the HDD carrier blank with finger grip, when the blank is inserted, it can be pushed in further than the previous versions as shown in Figure 2 on page 2. While this will not hinder the functionality, for optimal performance all HDD blanks should be flush.




Figure 1. Correct placement of HDD blank




Figure 2. Incorrect placement of HDD blank

August 2008

References in this publication to IBM® products, programs, or services do not imply that IBM intends to make these available in all countries in which IBM operates.

IBM is a trademark of the International Business Machines Corporation.

Printed in *country_of_origin*

© Copyright International Business Machines Corporation 2008.

US Government Users Restricted Rights – Use, duplication or disclosure restricted by GSA ADP Schedule Contract with IBM Corp.

(1P) P/N: 49Y4010

