

Option Packaging Instruction: Packaging BOM 59Y3808 - Plus 8 HDD Driver Kit No. SG-P-02130 Rev. 0 Status: In Production

0 1	London	47
General	Intorr	nation

General Information	
Document Number	SG-P-02130
Revision Number	0
Category	ISC-Global Engineering
Document Type	Procedure
Date In Production	四月-12-2010
	If this document contains technology, technical data, or source code, you must Restrict the document access.
	 For further assistance and guidance on this topic, please visit the Export Regulation Office web site and review the IBM Collaboration Environments Export Evaluation Checklist.
Author(s)	Brian CH Lee/Taiwan/IBM, Frank SF Chen/Taiwan/IBM
Header Text	
Document Owner	Jeffrey Miller/Raleigh/IBM
Location	Taiwan/Taipei
Department	GQBA
IBM_Confidential?	○ Yes ● No
Last Updated	四月-08-2010
Last Modified By	Brian CH Lee/Taiwan/IBM

QMX is located at http://d01db034.pok.ibm.com/q_dir/qmx/serv/qroweb.nsf Users of this document are responsible for obtaining the latest revision and ensuring the completeness of the document prior to use .

Do not edit or type above this line!

Section 1: Option P/N Reference

For latest level where used on this packaging BOMS reference Product Manager

BOM COMPONENTS FOR ITEM NUMBER 69Y5043

Comp number	Quantity	Basic name	Description
13H6475	1.0000	LABEL	Unit Security
6937292	1.0000	LABEL	
25P1013	1.0000	SHIP MATL	Carton
69Y5043	2.0000	SHIP MATL	Convoluted

Section 2: Packaging Procedure:


- 2.1 Take and assemble if not already assembled option carton P/N 25P1013.
- 2.2 Place the cushion P/N 69Y5043 in the carton with the convoluted side up in the box.



2.3 - Center the supplier prepared bagged parts into the box as shown.




2.4 - Place convoluted urethane cushion P/N 69Y5043 on top with the convoluted side facing the hardware as shown below.- Place the user manual or other document in top side of the cushion.





2.5 - Close carton 25P1013 using the front locking tabs as shown and seal the flap by using IBM security seal 13H6475.






Section 3: Palletization Instructions

3.1 US Shipments Only:
3.1.1 - Place up to 120 systems on a full size pallet P/N 6038887 or 60 on a half pallet P/N 6038888 in even quantities.

Quantity	Half Pallet 6038888	Full Pallet 6038887	Overpack TBD	No Pallet - Ship Individual
1				X
2-29			X	
30-60	X			
61-120		Х		



- 3.1.2 Secure load to pallet utilizing "Best of Breed" palletization methods. See 92F6168 -"Best of Breed" Pallet Unitization.
- 3.1.3 Place two pallet labels (33G6283) on the front and left sides of the pallet load.

3.2 WW Excluding US Shipments: 3.2.1 - Place up to 104 options on a full size pallet P/N 7310275 or 54 on a half pallet P/N 7373961 in even quantities.

Quantity	Half Pallet 7373961	Full Pallet 7310275	Overpack TBD	No Pallet - Ship Individual
----------	------------------------	------------------------	-----------------	-----------------------------------

1				X
2-29			X	
30-54	X			
55-104		X		

- 3.2.2 Secure load to pallet utilizing "Best of Breed" palletization methods. See 92F6168 "Best of Breed" Pallet Unitization.
- 3.2.3 Place two pallet labels (33G6283) on the front and left sides of the pallet load.

Records and Controlled Documents

References
Document Management
Revision History
Approval Information
Frank SF Chen/Taiwan/IBM - Approved on 4/12/10 6:23:21

Editors History Log

c 2010 IBM Corporation, All Rights Reserved Worldwide WW SG Document Library Control / D01DB034 / q_dir\qmx\serv\qrodlc.nsf

End of Document