


Instructions for installing QRadar FIPS Mylar pieces

Overview

Physical security labels are intended to overlap seams, vulnerable locations, and prevent tampering with your QRadar FIPS appliance. This document is intended to instruct you on how to prepare your IBM Security QRadar FIPS appliance with the mylar pieces. The addition of the mylar pieces are to meet the opacity requirements in FIPS 140-2 Level 2.

These are the instructions for attaching the seven mylar pieces on the server. Mylar pieces have adhesive on them. You will need to open the server to attach the mylar pieces.


Mylar Location 1:



Use the stand out connectors to position the Mylar.

* When you press down the Mylar, ensure the edge is sealed tight.

Mylar Location 2 and 3:



Ensure the Mylar is on


Use the connector for location 2 alignment

Ensure the Mylar is on

Use the connector for location 3 alignment,


Ensure the Mylar is positioned on parts that can enhance the Mylar's holding strength

Mylar Location 4 - on Riser




Use the 3 points to align the Mylar

Mylar Location 5 - on RAID Card




Place the Mylar as shown in red box

Mylar on RAID Card – Location 6



Use the screw for alignment support, note upper part should be folded to another side to fit properly.

Mylar Location 7 on chassis



Place the Mylar as shown

