

### Customer Replaceable Units (CRUs)

39Y7415	2980W Power Supply	68Y8205	Enhanced Blower
31R3304	Power Supply Filler	25R9934	Module Filler, Slots 1-6
68Y8208	System Service Cards	31R3303	Single Module Filler, Slots 7-10
60Y0621	Advanced Management Module	31R3311	Double Module Filler, Slots 8/10
39M3256	Rack Kit	44X2290	Media Tray, Edge Connector
39M3317	Blade Filler	43X0458	DVD Filler
31R3300	Bezels	44W3256	DVD Multi-burner Drive
		44W3254	DVD-ROM Drive

### Field Replaceable Units (FRUs)

68Y8214	Chassis	31R3307	Rear System Lightpath
68Y8213	Rear Chassis	31R3306	Miscellaneous Parts Kit
44X2302	Midplane, Edge Connector		

**<http://www.ibm.com/support/>**

Download files, hints & tips, create custom profiles, and frequently asked questions

**<http://www.ibm.com/systems/bladecenter/>**

IBM BladeCenter<sup>®</sup> home page

**<http://www.ibm.com/servers/eserver/serverproven/compat/us/>**

Compatibility information

**<http://www.ibm.com/systems/management/>**

IBM Systems Management home page

**<http://www.ibm.com/servers>**

IBM Server home page



\*P 6 8 Y 8 2 0 6 \*

138 mm

146 mm

Item 1


Item 2

MANUFACTURING NOTES:

1. Graphics shall conform to the Artwork above.
2. Refer to label print part number 68Y8206 for manufacturing and material notes.

Must conform to Eng. Spec: 80X2324

Tolerances unless noted: Linear  $\pm$  0.3



Art Part number

68Y8207

EC number

N28348

Date

6/8/10

ID approval

JM

Eng approval

SR

Title CRU/FRU Label

This document is the property of IBM. Its use is authorized only for responding to a request for quotation or for the performance of work for IBM. All questions must be referred to the IBM purchasing department.