

Item 1

Hot-Swap Fans

Fan Access Cover

1

2

Fan Error LED

3

4

1

2

3

4

5

NOTE:

For optimal cooling performance, do not run the system with the fan access cover removed for an extended period of time. Replace the fan access cover immediately after replacing a fan.

User Information

NOTE:

Replaceable parts list is on underside of this cover.

Item 2

System Installation

1

2

1

3


ATTENTION:

Lifting the cover release latch will power down the system.


>240VA

For additional service information, see underside of this top cover.

Item 3



Item 4



195 mm

Red Outline is for Kiss Cut ONLY!

342 mm

Red Outline is for Kiss Cut ONLY!

MANUFACTURING NOTES:

1. Graphics shall conform to the Artwork above.
2. Ink colors to match PMS BlackC, PMS 2718C, PMS 1525C and PMS 108C.
3. Font: Helvetica
4. Refer to label print part number 80Y9925 for manufacturing and material notes.

Must conform to Eng. Spec: 80X2324
Tolerances unless noted: Linear \pm 0.3

SI
metric

0 mm 25

IBM®

Art Part number
69Y2313

EC number

N24806T
N24806N

Date

5/24/10
4/2/10

ID approval

RA

Eng approval

JB

Title Labels, Top Cover Sheet

This document is the property of IBM. Its use is authorized only for responding to a request for quotation or for the performance of work for IBM. All questions must be referred to the IBM purchasing department.